


**Invoice
281974**



281974

Bill To:

HAROLD

~~403 872 0488~~



Local: (780) 955-7266
 Fax: (780) 955-2473
 Toll-Free: 1-800-661-5628

2106 - 7 Street
 Nisku AB T9E 7Y2

IMPORT AUTO PARTS LTD.

Ship To:

HAROLD

~~403 872 0488~~

Phone Number:

Date Ordered 2020-10-20	Date Shipped 2020-10-19	Due Date 2020-10-20	Ordering Dept	Customer PO	Dismantler	Core	R/O	Truck CPU	Salesperson CURTISMHAL
----------------------------	----------------------------	------------------------	---------------	-------------	------------	------	-----	--------------	---------------------------

Tag Number



8462

Item Detail	Stock Number	Amount
TRANSMISSION ASSY. (KNDJC733755356191)		
1 SORENT AUTO 05 Int.61971 *-4X4- 54K, NT/LT/IMB LZR	Z156P R40D #0001	350.00 T

Invoice Notes

THANKS....CURTIS

Parts	\$350.00
Warranty	\$0.00
Cores	\$0.00
Total Shipping	\$0.00
GST	\$17.50
PST	\$0.00
Total	\$367.50
Deposit	\$0.00
Amount Paid	\$367.50
Amount Due	\$0.00

Payments Credit Card : \$367.50

Invoice

From :-		Date:-	Vehicle Specifications:-	
CARLINE MUFFLER /M+M Mufflers BOX 7170, 5308-56AVE DRAYTON VALLEY, AB, T7A 1S4, Tel: 780-542-5477 Fax:		03/27/19	Make:	KIA
		Invoice #:-	Model:	SORENTO
		94023	Serial #:	
Bill To :- LOWE HAROLD DRAYTON VALLEY, AB,		Due:-	Plate #:	
			Year:	2006
		Acct #:-	Colour:	N/A
Ship To :-			Engine #:	N/A
		Page #:-	Odometer:	
		001	PO. #:	VERBAL
		Rep #:-	Contact:	
		1	Terms:	
			Phone:	
		Comments:-		
			PICK UP	

G S T	P S T	Part/Model #	Description	Serial #	Quant	List	Price	Total
Y	N	LABOR FE INSTALL SWAY BAR LINKS	LABOR SUPPLIED		0.50	106.00	106.00	53.00

Invoice Summary :-			Tendered By :-		Thank you for your Patronage	
Parts Total	\$	53.00	Charge to A/R	\$	0.00	
Labour Total	\$	0.00	Credit Card	\$	0.00	
Sub Total	\$	53.00	Other 1	\$	0.00	
Less Discounts	\$	0.00	Other 2	\$	0.00	
Other Taxes	\$	0.00	Cheque	\$	0.00	
GST 5.00 %	\$	2.65	Debit Card	\$	55.65	
PST 0.00 %	\$	0.00	Cash	\$	0.00	
Grand Total	\$	55.65	Your Change	\$	0.00	
GST Registration # : R103729372						

Invoice

From :-		Date:-	Vehicle Specifications:-	
CARLINE MUFFLER /M+M Mufflers BOX 7170, 5308-56AVE DRAYTON VALLEY, AB, T7A 1S4, Tel: 780-542-5477 Fax:		03/01/19	Make:	KIA
		Invoice #:-	Model:	SORENTO
Bill To :-		93904	Serial #:	
		Due:-	Plate #:	
LOWE HAROLD DRAYTON VALLEY, AB,			Year:	2006
		Acct #:-	Colour:	N/A
Ship To :-			Engine #:	N/A
			Odometer:	
		Page #:-	PO. #:	VERBAL
		001	Contact:	
		Rep #:-	Terms:	
		1	Phone:	
			Comments:-	
			PICK UP	

G P S T	Part/Model #	Description	Serial #	Quant	List	Price	Total
Y N	ROLFT22508N	GOR 8845		1.00	94.95	66.47	66.47
Y N	LABOR INSTALL FLEX JOINT	LABOR		0.75	106.00	106.00	79.50

Invoice Summary :-		Tendered By :-		Thank you for your Patronage	
Parts Total	\$ 145.97	Charge to A/R	\$ 0.00		
Labour Total	\$ 0.00	Credit Card	\$ 0.00		
Sub Total	\$ 145.97	Other 1	\$ 0.00		
Less Discounts	\$ 0.00	Other 2	\$ 0.00		
Other Taxes	\$ 0.00	Cheque	\$ 0.00		
GST 5.00 %	\$ 7.30	Debit Card	\$ 153.27		
PST 0.00 %	\$ 0.00	Cash	\$ 0.00		
Grand Total	\$ 153.27	Your Change	\$ 0.00		
				GST Registration # : R103729372	

Kelvin's Car Care Ltd.
 Site 416, Box 2, Comp 3, RR3
 Drayton Valley, AB. T7A 2A3
 Phone: 780-542-2056 Fax: 780-542-2061

INVOICE

28754

Date: 05/29/2018

INVOICE

Lowe, Harold
 RR1, SIDE 4, COMP 28
 Winfield, AB T0C 2X0
 Cellular 403-872-0488

2006 Kia - Sorento EX - 3.5L, V6 (213CI) VIN(3)
 Lic # : Odometer In : 228527

VIN # : KNDJC7339 65565336

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Oxygen sensor upstream passenger side at cost 25158	1.00	93.18	93.18	R&R oxygen sensor right bank upstream No Charge		nc
Spark plugs NGK7090	6.00	8.02	48.12	Replace Timing Belt . Evac and recharge A/C Replace timing belt tensioner and waterpump after tensioner failed and new belt had jumped a cog No Charge	7.50	825.00 nc
Timing Belt T323	1.00	157.26	157.26			
Ignition Coil UF-431	3.00	166.85	500.55	Diagnose #5 misfire. Compression test. R&R spark plugs and ignition coils and plug wires. Misfire gone but won't idle properly. Diagnose to intake gasket. Replace gasket Roadtest. Clear codes	3.80	418.00
Ignition Wire 55809	1.00	85.03	85.03			
Throttle Body Gasket 3510139000	1.00	9.77	9.77			
Timing belt tensioner T43194.	1.00	109.61	109.61			
Upper intake gasket MS96460-1	1.00	91.33	91.33			
Global Coolant Extended Life Coolant	4.00	4.99	19.96			
Water Pump 8523905	1.00	189.02	189.02			

additions to quote

[Recommendations]

front stab links and bushings, right rear stab link
 4X4 encoder motor

Org. Estimate 0.00 Revisions 2,332.85 Current Estimate 2,332.85

Revision # 1. Previous Estimate Amount: 0.00, Additional Cost: 186.77, Revised Estimate: 186.77, Parts: \$93.18 Labor: \$77.00 Sublet: \$0.00 Taxes & Fees: \$16.59 Authorized by - Lowe, Harold, Date - 5/8/2018, Time - 2:26 PM, Initiated By - Shop

Revision # 2. Previous Estimate Amount: 301.79, Additional Cost: 1092.32, Revised Estimate: 1394.11, Parts: \$215.30 Labor: \$825.00 Sublet: \$0.00 Taxes & Fees: \$52.02 Authorized by - Lowe, Harold, Date - 5/14/2018, Time - 12:24 PM, Initiated By - Shop

Revision # 3. Previous Estimate Amount: 1817.72, Additional Cost: 1053.76, Revised Estimate: 2871.48, Parts: \$585.58 Labor: \$418.00 Sublet: \$0.00 Taxes & Fees: \$50.18 Authorized by - Lowe, Harold, Date - 5/24/2018, Time - 8:03 AM, Initiated By - Shop

Labor:	1,243.00
Parts:	1,303.83
SubTotal:	2,546.83
Tax:	127.34
Total:	2,674.17
Bal Due:	\$2,674.17

[Payments -]

Vehicle Received: 5/29/18

Customer Number : 6091

*** Wheel nuts must be retorqued within 100 kms whenever they have been removed for service. ***

Labour Warranty: 1 year or 12,000 kilometers, whichever comes first.

Parts Warranty: manufacturer warranties apply. No warranty on used or 'supplied' parts. No warranty due to loss of vehicle use. Warranty has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web : www.kelvinscarcare.ca

Our Email Address: kelvin@kelvinscarcare.ca

Kelvin's Car Care Ltd.

Site 416, Box 2, Comp 3, RR3
 Drayton Valley, AB. T7A 2A3
 Phone: 780-542-2056 Fax: 780-542-2061

Sub Estimate For OI

028278

Estimate for Services

Estimate Date : 2/05/18

Lowe, Harold
 RR1, SITE 4, COMP 28
 Winfield, AB T0C 2X0
 Cellular: 403-872-0488

2006 Kia - Sorento EX - 3.5L,V6 (213CI) VIN(3)
 Lic # : - AB

Odom. In: 0

VIN # : KNDJC7339 65565336

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
Encoder motor <i>apd</i>	1.00	452.00	452.00	Replace encoder motor, clear codes, road test to recheck 4X4 operation	1.00	110.00
Shop Supplies			11.00			

Parts/Supplies: 463.00

Labor: 110.00

HazMat/Fees: 0.00

Tax: 28.65

Total : \$ 601.65

I hereby authorize the above work to be done with the necessary materials and hereby authorize you and/or your employees permission to operate the vehicle described for testing and/or inspection. An express Lien under the Repair and Storage Lien Act is hereby acknowledged on the above vehicle to secure the amount of the repairs thereto. It is also understood that Kelvin's Car Care is NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Kelvin's Car Care Ltd.

Site 416, Box 2, Comp 3, RR3
 Drayton Valley, AB. T7A 2A3
 Phone: 780-542-2056 Fax: 780-542-2061

Sub Estimate For O

028278

Estimate for Services

Estimate Date : 2/05/18

Lowe, Harold

~~RR1, SITE 4, COMP 28~~
~~Winfield, AB T0C 2X0~~
~~Cellular: 403-872-0488~~

2006 Kia - Sorento EX - 3.5L V6 (213CI) VIN(3)
 Lic # : - AB

Odom. In: 0

VIN # : KNDJC7339 65565336

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
AC Del front wheel bearings <i>apd</i>	2.00	61.10	122.20	R&R both front wheel bearings	4.40	484.00
Moog front stabilizer bushing kit <i>apd</i>	2.00	10.38	20.76	R&R F stabilizer bar bushings	1.40	154.00
Moog front stabilizer links - L&R <i>apd</i>	2.00	65.27	130.54	R&R RR stabilizer link	0.50	55.00
Moog RR stabilier link <i>apd</i>	1.00	53.44	53.44	Replace exhaust hanger	0.20	22.00
Ray Rel front brake pads with hardware <i>apd</i>	1.00	87.40	87.40	R&R rear brake pads.	1.20	132.00
Ray Rel rear brake pads with hardware <i>apd</i>	1.00	86.62	86.62	Replace hardware, clean slides and mechanism. Inspect brake calipers. Check brake fluid. Road test vehicle.		
exhaust hanger - rubber <i>apd</i>	1.00	17.50	17.50	Replace front disc brake pads. (calipers removed)	0.60	66.00
Shop Supplies			20.00	Check front brake disc rotor condition. Clean and lubricate brake calipers and slide mechanisms. Check brake fluid.		

~~_____~~

1090

Parts/Supplies: 538.46 Labor: 913.00 HazMat/Fees: 0.00 Tax: 72.57 Total: \$ 1,524.03

I hereby authorize the above work to be done with the necessary materials and hereby authorize you and/or your employees permission to operate the vehicle described for testing and/or inspection. An express Lien under the Repair and Storage Lien Act is hereby acknowledged on the above vehicle to secure the amount of the repairs thereto. It is also understood that Kelvin's Car Care is NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

INVOICE

Lowe, Harold

Date: 02/07/2018

RR1, SITE 4, COMP 28
 Winfield, AB T0C 2X0
 Cellular 403-872-0488

2006 Kia - Sorento EX - 3.5L, V6 (213CI) VIN(3)

Lic # :

Odometer In : 223572

VIN # : KNDJC7339 65565336

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
AC Del front wheel bearings 513058	2.00	61.10	122.20	4X4 not engaging	2.00	220.00
Ray Rel front brake pads with hardware MGD995CH	1.00	87.40	87.40	Perform various tests. Got working for now by moving encoder motor with manual power. Confirm encoder motor is the problem. However it is working intermittently for now. Do not recommend using 4X4.		
Ray Rel rear brake pads with hardware MGD945CH	1.00	86.62	86.62	Check shocks/front end. No charge		nc
Used RF steering knuckle 515-58863R	1.00	192.30	192.30	Front struts and rear shocks are weak but still serviceable. Badly needed are front wheel bearings, front stab links, and bushings, right rear stab link, Cat Converter rubber hanger, front and rear brake pads.		
exhaust hanger - rubber WLK 35229 Shop Supplies	1.00	17.50	17.50	R&R both front wheel bearings	4.40	484.00
			20.00	Had to replace spindle. Extra time to remove seized ABS sensor		
				Replace exhaust hanger	0.20	22.00
				R&R rear brake pads	1.20	132.00
				Replace hardware, clean slides and mechanism. Inspect brake calipers. Check brake fluid. Road test vehicle.		
				Replace front disc brake pads (calipers removed)	0.60	66.00
				Check front brake disc rotor condition. Clean and lubricate brake calipers and slide mechanisms. Check brake fluid.		
				Freight		26.50
				[Recommendations]		
				front stab links and bushings, right rear stab link		
				4X4 encoder motor		

Org. Estimate 252.00 Revisions 1,524.03 Current Estimate 1,776.03

Revision # 1, Previous Estimate Amount: 252.00, Additional Cost: 1524.03, Revised Estimate: 1776.03, Parts: \$518.46 Labor: \$913.00 Sublet: \$0.00
 Taxes & Fees: \$92.57 Authorized by - Lowe, Harold. Date - 2/5/2018. Time - 2:36 PM. Initiated By - Shop

Labor:	924.00
Parts:	526.02
Sublet:	26.50
SubTotal:	1,476.52
Tax:	73.83
Total:	1,550.35
Bal Due:	\$1,550.35

Customer Number : 6091

[Payments -]

Vehicle Received: 2/07/18

*** Wheel nuts must be retorqued within 100 kms whenever they have been removed for service. ***

Labour Warranty: 1 year or 12,000 kilometers, whichever comes first.

Parts Warranty: manufacturer warranties apply. No warranty on used or 'supplied' parts. No warranty due to loss of vehicle use. Warranty has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web : www.kelvinscarcare.ca

Our Email Address: kelvin@kelvinscarcare.ca

INVOICE

Date: 05/02/2018

Lowe, Harold

2006 Kia - Sorento EX - 3.5L, V6 (213CI) VIN(3)

RR1, SITE 4, COMP 28

Lic # :

Odometer In : 0

Winfield, AB T0C 2X0

Cellular 403-872-0488

VIN # : KNDJC7339 **65565336**

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

Camshaft position sensor PC632	1.00	224.51	224.51	Towed in - no start. <i>Refunded</i> →	1.00	110.00
-----------------------------------	------	--------	--------	--	------	--------

Shop Supplies			20.00	Scan - P0134 - oxygen sensor, P0700 transmission control system, P0342 cam position sensor, P0102 MAFF sensor low circuit, P0716 input turbine speed	2.00	220.00
---------------	--	--	-------	--	------	--------

Removed timing belt cover found that the belt is severely cracked. Removed old cam position sensor. Installed new cam sensor, reinstalled timing cover.
 Reassembled engine covers and road tested.

All good.

[Recommendations]

front stab links and bushings, right rear stab link
 4X4 encoder motor

*PAID
Debit*

Org. Estimate 0.00 Revisions 186.77 Current Estimate 186.77

Revision # 1, Previous Estimate Amount: 0.00, Additional Cost: 186.77, Revised Estimate: 186.77, Parts: \$93.18 Labor: \$77.00 Sublet: \$0.00 Taxes & Fees: \$16.59 Authorized by - Lowe, Harold, Date - 4/26/2018, Time - 4:15 PM, Initiated By - Shop

Labor:	330.00
Parts:	244.51
SubTotal:	574.51
Tax:	28.73
Total:	603.24
Bal Due:	\$603.24

Customer Number : 6091

[Payments -]

Vehicle Received: 5/2/2018

*** Wheel nuts must be retorqued within 100 kms whenever they have been removed for service. ***

Labour Warranty: 1 year or 12,000 kilometers, whichever comes first.

Parts Warranty: manufacturer warranties apply. No warranty on used or 'supplied' parts. No warranty due to loss of vehicle use. Warranty has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web : www.kelvinscarcare.ca

Our Email Address: kelvin@kelvinscarcare.ca

INVOICE

Work Completed : 08/15/2018 Date: 08/15/2018

Lowe, Harold

2006 Kia - Sorento EX - 3.5L, V6 (213CI) VIN(3)
 Lic # : Odometer In : 233386

RR1, SITE 4, COMP 28
 Winfield, AB TOC 2X0
 Cellular 403-672-0488

VIN # : KNDJC7339 **65565336**

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Upstream O2 Sensor 25158	1.00	52.21	52.21	Replace left upstream Bank 2 O2 sensor	1.00	110.00
THROTTLE POSITION SENSOR TH409	1.00	86.68	86.68	No power when launching Replace throttle position sensor. Roadtest	1.00	110.00
Shop Supplies			20.00			

[Recommendations]
 front stab links and bushings, right rear stab link
 4X4 encoder motor

Org. Estimate 397.83 Revisions 0.00 Current Estimate 397.83

Labor:	220.00
Parts:	158.89
SubTotal:	378.89
Tax:	18.94
Total:	397.83
Bal Due:	\$397.83

[Payments -]
 Vehicle Received: 8/15/18

Customer Number : 6091

*** Wheel nuts must be retorqued within 100 kms whenever they have been removed for service. ***
 Labour Warranty: 1 year or 12,000 kilometers, whichever comes first.
 Parts Warranty: manufacturer warranties apply. No warranty on used or 'supplied' parts. No warranty due to loss of vehicle use. Warranty has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web : www.kelvinscarcare.ca

Our Email Address: kelvin@kelvinscarcare.ca