

Vehicle History Report #: 38236450 Report Date: March 9, 2022 | 10:39 AM EST

Report Status: Complete

2012 DODGE RAM 5500 ST

Cab chassis | 6 Cylinders | Diesel 3C7WDNEL5CG246155
Country of Assembly: Mexico
Last Reported Odometer: n/a





Please note: This vehicle has been registered in British Columbia but this report does not include information from ICBC, the province's insurance provider. Please contact CARFAX Canada at 1.866.835.8612 or you can visit our Customer Support Portal, and we can assist you in obtaining this information.



No Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



0 Service Records Found



No U.S. History Found



5 Open Recalls Found




Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Open Recalls

Recall #: N26 | FRONT AXLE TUBE WELDS Recall Date: 2013 Jul 27

Recall Description

THE FRONT AXLE TUBE WELDS MAY NOT HAVE BEEN WELDED CORRECTLY DURING THE MANUFACTURING PROCESS. IMPROPERLY WELDED FRONT AXLE TUBES COULD ALLOW THE DIFFERENTIAL HOUSING TO ROTATE UNDER HIGH TORQUE OPERATING CONDITIONS WHILE IN FOUR WHEEL DRIVE. SHOULD THE FRONT AXLE TUBE WELDS BREAK, THE DIFFERENTIAL COULD ROTATE AND CAUSE THE FRONT PROPELLER SHAFT UNIVERSAL JOINT TO BREAK.

Remedy

FOR VEHICLES EQUIPPED WITH AN AUTOMATIC TRANSMISSION, THE FRONT AXLE MUST BE INSPECTED. FRONT AXLES THAT HAVE BROKEN WELDS WILL HAVE A NEW FRONT AXLE ASSEMBLY INSTALLED. FRONT AXLES THAT ARE NOT DAMAGED WILL HAVE REINFORCEMENT BRACKETS INSTALLED. FOR VEHICLES EQUIPPED WITH A MANUAL TRANSMISSION, THE FRONT AXLE MUST BE REPLACED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact DODGE or visit Dodge's website.

Recall #: P65 | DIESEL FUEL HEATER ELECTRICAL CONNECTOR Recall Date: 2014 Dec 01

Recall Description

THE DIESEL FUEL HEATER ELECTRICAL CONNECTOR MAY OVERHEAT AND CAUSE A FUEL LEAK. THE DIESEL FUEL HEATER HOUSING AT THE FUEL HEATER ELECTRICAL CONNECTOR MAY OVERHEAT, LEADING TO THE FAILURE OF THE O-RINGS THAT SEAL THE MALE ELECTRICAL TERMINALS IN THE DIESEL FUEL FILTER/HEATER ASSEMBLY.

Remedy

THE DIESEL FUEL HEATER WIRE HARNESS ELECTRICAL CONNECTOR MUST BE REPLACED ON ALL VEHICLES.ALSO, THE DIESEL FUEL FILTER/HEATER HOUSING MUST BE INSPECTED FOR FUEL LEAKS. IF A FUEL LEAK IS FOUND, THE DIESEL FUEL FILTER/HEATER ASSEMBLY MUST BE REPLACED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact DODGE or visit Dodge's website.

Recall #: T79 | BRAKE TRANSMISSION SHIFT INTERLOCK Recall Date: 2018 Jan 04

Recall Description

The Brake Transmission Shift Interlock (BTSI) locking pin may become stuck in the open position. A BTSI locking pin stuck in the open position may allow the transmission to be shifted out of PARK and to or from any gear position without depression of the brake pedal and/or without the key in the ignition, if a key is applicable.

Remedy

For 2013-2017 model year; Inspect the Brake Transmission Shift Interlock (BTSI) operation and replace if necessary. The Body Control Module (BCM) software will also be updated. For 2009-2012 model year; replace the BTSI, BCM software update not applicable.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact DODGE or visit **Dodge**'s website.

Recall #: Y26 | 2012-21 D TRUCK M14 WHEEL STUDS Recall Date: 2021 Jun 08

Recall Description

Torque specification information included in vehicle Service and Owner's Manuals may cause flanged lug nuts to be torqued to a level that may cause the wheel stud to yield and eventually break during vehicle operation.

Remedy

FCA US will conduct a voluntary safety recall on all affected vehicles. For vehicles in Y26 and Y60, FCA US will inspect the wheel studs and update the torque specification in owner's information and published service documents. Vehicles found with studs that are potentially yielded will have a new stud installed and the lug nuts tightened to the updated torque specification. For vehicles in Y36, FCA US will update the torque specification in owner's information and published service documents

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact DODGE or visit **Dodge**'s website.

Recall #: U89 | 2011-2015 D2 6.7L CUMMINS SCR WASHCOAT - CANADA Recall Date: 2018 Oct 03

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact DODGE or visit **Dodge**'s website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Oct 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2012 Dec 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Feb 16	- 14 mm (44) (mm) (mm) (mm) (mm) (mm) (mm)	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Jul 27		DODGE	Recall	Manufacturer Recall Issued Recall # N26
2014 Dec 1		DODGE	Recall	Manufacturer Recall Issued Recall # P65
2017 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jan 4		DODGE	Recall	Manufacturer Recall Issued Recall # T79
2018 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Oct 3		DODGE	Recall	Manufacturer Recall Issued Recall # U89
201 9 Jun 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jun 8		DODGE	Recall	Manufacturer Recall Issued Recall # Y26
2021 Jul 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner Badge
The CARFAX Canada One Owner badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEL