

 <p>Canada's Tournament Capital</p>	<p>City of Kamloops Inspection: 24025 FLEET_Decommission Inspection Parent Work Order <u>4092338</u></p>
--	--

Inspection Summary

Object Inspected	FLEETEQUIPMENT 5725
Location	86346
Status	
Inspected By	SINCLAIR, TAYLOR
Date	5/16/2023 2:03:44 PM
Summary	
Repairs Made	
Recommendations	

Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	Green	
Colour - Interior	Black, yellow, green	
Wheel Drive	2x4	
Body Style		
Engine Size		
Damage Declaration over \$2,000		
Estimated Damage Amount		
Body Condition	Fair	
Body Damage	No	
Mechanical	Unknown	
Transmission Operable	Yes	
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Good	
Jack Assembly		
Spare Tire		
Check all Vehicle Options that	Air Conditioning	

apply		
Check all Vehicle Options that apply	Air Conditioning	
Check all Vehicle Options that apply	Tilt Steering	
Hours or Odometer (Blank if N/A)		

Add Signature and Date Fields Here?

Work Order Details

Assigned To: Supervisor: Work Status: WORK IN PROGRESS Scheduled Start: 5/16/2023 1:56:31 PM Scheduled Finish: 5/16/2023 1:56:31 PM	Location: 86346 [Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details:
FLEETEQUIPMENT	
Name	Value
OBJECTID	454
ASSETID	5725
UNITNO	86346
MAKE	JOHN DEERE
MODEL	
MODELYEAR	2012
VIN	1TC1445DECT120441
DESCRIPTION	2012 JDEERE 72" MOWER
EQUIPMENTTYPE	PARKS/FACILITIES EQUIPMENT
FUELTYPE	DIESEL
METERTYPE	HOURS
FLEETSTATUS	ACTIVE
NSCCLASSIFICATION	NON NSC
LINKEDUNITNO	
AXELCOUNT	
LICENSEPLATE	07344X
GVW	
LICENSEDGVW	2145
ACQUIREDATE	5/25/2012 12:00:00 AM
ACQUIRECOST	35800
DEPARTMENT	CIVIC OPERATIONS
DIVISION	FLEET
SUBDIVISION	MECHANICAL LOANER
LOCATION	86346
ADDRESS	
WARRANTYDATE	

	WARRANTYODOMETERHRS	
	WARRANTYNOTES	
	CONDITION	6
	CONDITIONDATE	
	CONDITIONCOMMENT	
	SECURELINK	
	DOCUMENTATIONLINK	
	ODOMETER	
	HOURSMETER	
	AGE	10
	USEFULLIFE	6
	REMAININGLIFE	-4
	DISPOSALDATE	
	DISPOSALVALUE	
	DEPRECIATIONLIFE	6
	REPLACEMENTYEAR	0
	CURRENTREPLACEMENTCOST	40096