PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 11852

 1010307 Alberta Ltd
 DATE
 13/10/2022

TERMS Net 30
DUE DATE 12/11/2022

 UNIT #
 MILEAGE
 P/O # W/O #

 PROJECT PETE #2
 DARREN/ TOM
 XX
 11852

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
24/09/2022	LABOUR HD	PAINT 5EK ENGINE	0.50	135.00	67.50
24/09/2022	SPRAY PAINT CAN - CAT YELLOW	SPRAY PAINT CAN - CAT YELLOW	1	39.93	39.93
06/10/2022	LABOUR HD	REMOVE LINES FILTERS HOUSING THATS NOT NEEDED INSTALL PILOT BEARING ORGANIZE AND CLEAN UP WIRING ON TRUCK PREPING FOR ENGINE INSTALL REMOVE REAR RUBBER ENGINE MOUNTS ORDER MOUNTS ORDER BOLTS FOR ENGINE MOUNTS AND ORDER BOLTS FOR BELL HOUSING AND CLUTCH	2	135.00	270.00
07/10/2022	LABOUR HD	PRIME AND PAINT 2WS ENGINE	1.50	135.00	202.50
07/10/2022	SPRAY PAINT CAN - CAT YELLOW	SPRAY PAINT CAN - CAT YELLOW	2	44.87	89.74
07/10/2022	PRIMER SPRAY CAN	SPRAY	1.50	27.80	41.70
07/10/2022	LABOUR HD	REOVE WIRING FROM ENGINE THAT IS ALREADY INSTALLED ON TRUCK CUT OFF ALL OTHER UNECESSARY WIRING	1.50	135.00	202.50
08/10/2022	LABOUR HD	REMOVE BLOCK HEATER INSTALL NEW REMOVE FLY WHEEL AND REMOVE PILOT BEARING INSTALL FLY WHEEL BACK ON ENGINE INSTALL ENGINE INTO TRUCK	2	135.00	270.00
08/10/2022	BLOCK HEATER W/CORD	BLOCK HEATER W/CORD	0.50	74.18	37.09
08/10/2022	LABOUR HD	INSTALL CAT ENGINE INTO TRUCK	2	135.00	270.00
09/10/2022	LABOUR HD	MOVE A FRAME & HOOK UP TO ENGINE LIFT ENGINE AND TRANNY INSTALL TRANSMISSION ONTO ENGINE	2.50	135.00	337.50

		INSTALL REAR MOTOR MOUNTS (RUBBER)			
12/10/2022	LABOUR HD	REOVE 2 AIR TANKS FOR POLISHING GET ENGINE AND TRANNY LINED UP PUT 4 BOLTS IN TO KEEP THEM TOGEHTER	0.875	135.00	118.13
13/10/2022	LABOUR HD	GO OVER BELL HOUSING BOLTS BOLT CLUTCH TO FLYWHEEL BROKE BOLT REMOVED BOLTS REMOVED BELL HOUSING BOLTS SPLIT ENGINE AND TRANNY TO LIFT ENGINE	1.50	135.00	202.50
13/10/2022	SHOP SUPPLIES	SHOP SUPPLIES	0.07	2,149.09	150.44
		SUBTOTAL			2,299.53
		GST @ 5%			115.01
		TOTAL			2,414.54
		BALANCE DUE			\$2,414.54

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 11875

 1010307 Alberta Ltd
 DATE
 19/10/2022

TERMS Net 30
DUE DATE 18/11/2022

\$1,209.09

 UNIT #
 MILEAGE
 P/O # W/O #

 PROJECT PETE #2
 CARTER
 XX
 11875

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
14/10/2022	LABOUR HD	FINISH LIFTING ENGINE OUT AND MOVING AWAY FROM TRANSMISSION TRY TO EXTRACT BROKEN BOLT REMOVE FLY WHEEL REMOVE CLUTCH INSTALL NEW FLY WHEEL	2	135.00	270.00
15/10/2022	LABOUR HD	REMOVE FLY WHEEL TO INSTALL REAR MAIN	0.25	135.00	33.75
16/10/2022	LABOUR HD	REMOVE OLD REAR MAIN SEAL INSTALL NEW REAR MAIN INSTALL FLYWHELL INSTALL PILOT BEARING REMOVE CLUTCH LINAGE	2.25	135.00	303.75
16/10/2022	CUSTOMER PROVIDED PART	DARREL SUPPLIED FLY WHEEL LONG TIME AGO WOULD BE PAID FOR ALREADY	1	0.00	0.00
19/10/2022	LABOUR HD	RREPLACE FRONT MOTOR MOUNT RUBBERS BOLT ENGINE AND TRANNY TOGETHER INSTALL CLUTCH AND CLUTCH BRAKE	2.375	135.00	320.63
19/10/2022	CLUTCH BRAKE	CLUTCH BRAKE	1	26.40	26.40
19/10/2022	TIE ROD END	TIE ROD END	1	66.33	66.33
19/10/2022	HEX JAM NUT	HEX JAM NUT	1	1.96	1.96
19/10/2022	MOTOR MO MR1001	MOTOR MO MR1001	2	26.675	53.35
19/10/2022	SHOP SUPPLIES	SHOP SUPPLIES	0.07	1,076.17	75.33
		SUBTOTAL			1,151.50
		GST @ 5%			57.59
		TOTAL			1,209.09

BALANCE DUE

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

BILL TO

1010307 Alberta Ltd

INVOICE DATE TERMS 11898 31/10/2022

TERMS Net 30
DUE DATE 30/11/2022

UNIT # Project Pete2 P/O # W/O # xx 11898

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
26/10/2022	BLOCK HEATER W/CORD	BLOCK HEATER W/CORD	0.50	141.70	70.85
26/10/2022	WASHERS GR8 7/16	WASHERS GR8 7/16	4	0.30	1.20
26/10/2022	LABOUR HD	START INSTALL OF CLUTCH BOLTS INSTALL REAR ENGINE MOUNTS CHARGE BATTERIES	1.50	135.00	202.50
26/10/2022	7/16 X 2 1/2 BOLTS GR8	7/16 X 2 1/2 BOLTS GR8	4	1.87	7.48
26/10/2022	LABOUR HD	FINISH INSTALLING CLUTCH BOLTS AND REAR ENGINE MOUNTS	1.50	135.00	202.50
27/10/2022	LABOUR HD	INSTALL WIRING ON THE ECM REMOVE HOSES OFF ENGINE NOT NEEDED. INSTALL FUEL LINES REMOVE AIR LINES FROM AIR TANK DRYER TO GOVERNOR THAT WERE RUBBED THROUGH. FIGURE OUT WHERE WIRING GOES	2.75	135.00	371.25
28/10/2022	LABOUR HD	REMOVED RUBBED LINES AIR FUEL AND BATTERY WIRES	0.75	135.00	101.25
28/10/2022	LABOUR HD	REMOVE AND REPLACE DS3 BRAKE SHOES AND DRUM REMOVE PS 3 BRAKE SHOES	1	135.00	135.00
31/10/2022	LABOUR HD	INSTALL FUEL LINES ON FUEL PUMP AND FILTER ON TO ENGINE INSTALL POWER STEERING PUM AND HOSES INSTALL BATTERY CABLE ENDS FOR THE ALTENATOR LOAD TEST BATTERIES	3.50	135.00	472.50
31/10/2022	SHOP SUPPLIES	SHOP SUPPLIES	0.07	1,564.53	109.52
		SUBTOTAL			1,674.05
		GST @ 5%			83.71
		TOTAL			1,757.76

BALANCE DUE \$1,757.76

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 11908

 1010307 Alberta Ltd
 DATE
 14/11/2022

TERMS Net 30
DUE DATE 14/12/2022

UNIT # PROJECT PETE #2 P/O # W/O # XX 11908

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
01/11/2022	LABOUR HD	INSTALL AIR LINES AND P CLAMPS ON DS FRAME FOR WIRING HARNESS AND FUEL/OIL LINES	0.50	135.00	67.50
03/11/2022	LABOUR HD	INSTALL NEW COOLANT SENSOR AND OIL TEMP SENSOR INSTALL OIL PAN HEATER INSTALL BALL VALVES ON COOLANT LINES	1.75	135.00	236.25
03/11/2022	CAT TEMPERATURE SENSOR 2644297	CAT TEMPERATURE SENSOR 2644297	0.50	122.00	61.00
03/11/2022	OIL PAN HEATER W/CORD	OIL PAN HEATER W/CORD	0.50	146.66	73.33
03/11/2022	1/2 IN BRAS BALL VALVE W/SHORT HANDLE	1/2 IN BRAS BALL VALVE W/SHORT HANDLE	1.50	29.62	44.43
03/11/2022	HEATER FITTING 805	HEATER FITTING 805	1	13.82	13.82
03/11/2022	HEATER FITTING 886	HEATER FITTING 886	0.50	14.35	7.18
03/11/2022	FUEL FILTER 1R0749	FUEL FILTER 1R0749	0.50	36.96	18.48
03/11/2022	REAR SEAL CAT	REAR SEAL CAT	0.50	265.87	132.94
03/11/2022	PILOT BEARING		0.50	27.23	13.62
04/11/2022	LABOUR HD	INSTALL BLOCK HEATER INSTALL BATTERY CABLES TO STARTERWIRED TO SENSORS REPAIR BAD WIRING IN ENGINE HARNESS	2.50	135.00	337.50
07/11/2022	LABOUR HD	INSTALL AIR DRYER AND PLUMB ALL OLD AIR FITTINGS. FIX SOME WIRING FOR ENGINE	1	135.00	135.00
07/11/2022	AIR DRYER ASSY AD-9 PURAGUARD	AIR DRYER ASSY AD-9 PURAGUARD	0.50	435.89	217.95
07/11/2022	LABOUR HD	PULLED HUB AND CLEANED. REMOVE AND REPLACE WHEEL SEAL AND HUB GASKET. FILLED WITH OIL	1	135.00	135.00

07/11/2022	AXLE GASKET 8 HOLE 5/8	AXLE GASKET 8 HOLE 5/8	0.50	2.84	1.42
07/11/2022	WHEEL SEAL D5F5	WHEEL SEAL D5F5	0.50	85.41	42.71
07/11/2022	75W90 SYN 18.9L SOLD PER LITRE	75W90 SYN 18.9L SOLD PER LITRE	0.50	22.05	11.03
08/11/2022	LABOUR HD	REMOVED S-CAM AND BRAKE POT. HAMMERED OUT BROKEN BOLTS	1.125	135.00	151.88
08/11/2022	LABOUR HD	INSTALL ALL BATTERY CABLES TO STARTER AND BATTERIES. CLEAN THE COLD AIR SIDE OF TURBO. PUT TURBO BACK TOGETHER. INSTALL AIR LINES TO ENGINE. TRIED TO START TRUCK. TRUCK WILL NOT STAY RUNNING	1.50	135.00	202.50
09/11/2022	LABOUR HD	INSTALL S-CAM BUSHINGS AND S-CAM PS 3	1	135.00	135.00
14/11/2022	LABOUR HD	WENT THROUGH ALL WIRING TO GET TRUCK RUNNING FOUND WIRE FROM BATTERY TO ECM BROKE FIXED WIRE TRUCK NOW RUNS STARTED REMOVING HORNS ON FRONT OF TRUCK	3	135.00	405.00
14/11/2022	SHOP SUPPLIES	SHOP SUPPLIES	0.07	2,443.54	171.05
		SUBTOTAL			2,614.59
		GST @ 5%			130.74
		TOTAL			2,745.33
		BALANCE DUE			\$2,745.33

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 11960

 1010307 Alberta Ltd
 DATE
 30/11/2022

TERMS Net 30
DUE DATE 30/12/2022

 UNIT #
 MILEAGE
 P/O # W/O #

 PROJECT PETE #2
 TOM
 XX
 11960

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
15/11/2022	LABOUR HD	REMOVE DS AND PS FRAME HORN INSTALL NEW ONES WAITING FOR A FEW NEW FRAME BOLTS	3.25	135.00	438.75
16/11/2022	LABOUR HD	TRIED TO FINISH PS FRAME HORN STILL WAITING FOR BOLTS PREP RAD FOR PRESSURE TESTING ORDER RAD SUPPORTS RUBBERS AND RAD MOUNT RUBBERS	1	135.00	135.00
17/11/2022	LABOUR HD	FINISH BOTH FRAME HORNS GET RAD READY TO INSTALL PULL ALL HOSES OUT OF SLEEPER AND ALL PIPING	2	135.00	270.00
17/11/2022	NUT-HEX SL NY	NUT-HEX SL NY	1.50	4.41	6.62
17/11/2022	RAD MOUNT	RAD MOUNT	2	25.76	51.52
17/11/2022	RUBBER-MOUNT	RUBBER-MOUNT	1	68.00	68.00
20/11/2022	LABOUR HD	REMOVE DS 3 WHEELS BACK DS 2 WHEELS ON INSTALL NEW BRAKE SHOES ON PS 3 AND BRAKE DRUM INSTALL NEW BRAKE SHOES ON PS 2 PUT DS 2 DS 3 AND PS 3 INNER AND OUTER WHEELS BACK ON	1.375	135.00	185.63
20/11/2022	BRAKE DRUM 16.5X7	BRAKE DRUM 16.5X7	1	197.62	197.62
20/11/2022	BRAKE KIT EXCH 16.5X7 QP 4707Q+	BRAKE SHOES	1	97.93	97.93
21/11/2022	LABOUR HD	CLEAN SLACK ADJUSTER AND TEST FUNCTION INSTALL BACK ON TRUCK PS 3 REMOVE PS 3 BRAKE POT INSTALL NEW BRAKE POT PUT WHEELS BACK ON PS 3 RUN ABS WIRE BACK OUT TO HUB AND ZIP TIE INTO PLACE	1.625	135.00	219.38
21/11/2022	SPRING BRAKE	SPRING BRAKE PREMIUM SHORT	0.50	60.13	30.07

	PREMIUM SHORT STROKE	STROKE			
23/11/2022	LABOUR HD	INSTALL RAD WITH NEW BUSHINGS INSTALL RAD SUPPORT ARMS	2	135.00	270.00
24/11/2022	BRAKE DRUM 16.5X7	BRAKE DRUM 16.5X7	0.50	188.98	94.49
24/11/2022	BRAKE KIT EXCH 16.5X7 QP 4707Q+	BRAKE SHOES	0.50	71.33	35.67
24/11/2022	LABOUR HD	CLEANED AND PAINTED ENGINE PIPING TIGHTEN BACK MOTOR MOUNTS	0.50	135.00	67.50
24/11/2022	LABOUR HD	FOUND ALL COOLANT AND PIPING UPPER AND LOWER PAINTED	1	135.00	135.00
30/11/2022	RAD HOSE1548	RAD HOSE1548	0.50	98.91	49.46
30/11/2022	PIVOT LOWER A	PIVOT LOWER A	0.50	403.83	201.92
30/11/2022	PIVOT LOWER A-R	PIVOT LOWER A-R	0.50	403.83	201.92
30/11/2022	LABOUR HD	INSTALL BOTTOM RAD HOSE INSTALL PIVOT FOR HOOD AND ALL HARDWARE	2	135.00	270.00
30/11/2022	HOOD MOUNT PIVIOT	HOOD MOUNT PIVIOT	1	34.97	34.97
30/11/2022	HOOD MOUNT	HOOD MOUNT	3	25.80	77.40
30/11/2022	TORQUE CLAMP 3.5"	TORQUE CLAMP 3.5"	1	15.40	15.40
30/11/2022	FILTER AS SE	FILTER AS SE	0.50	42.90	21.45
30/11/2022	FILTER AS-LU	FILTER AS-LU	0.50	55.99	28.00
30/11/2022	SHOP SUPPLIES	SHOP SUPPLIES	0.07	3,203.70	224.26
		SUBTOTAL			3,427.96
		GST @ 5%			171.40
		TOTAL			3,599.36
		BALANCE DUE			\$3,599.36

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 12007

 1010307 Alberta Ltd
 DATE
 15/12/2022

TERMS Net 30
DUE DATE 14/01/2023

UNIT # P/O # W/O # XX 12007

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
01/12/2022	LABOUR HD	INSTALL NEW A/C CONDENSOR	0.25	135.00	33.75
01/12/2022	AC CONDENSER	AC CONDENSER	0.50	918.19	459.10
01/12/2022	LABOUR HD	INSTALL AIRLINES ON GOVERNOR FIX WIRING FOR OIL TEMP ON PAN TIE UP OTHER MISC WIRES	1	135.00	135.00
02/12/2022	LABOUR HD	USE GENIE TO GET HOOD OUT OF WHAREHOUSE AND BRING INTO SHOP PLACE ON PALLET POSITION ON TRUCK AND START INSTALLATION	1.25	135.00	168.75
02/12/2022	LABOUR HD	INSTALL HOOD PIVOTS AND ALL HARDWARE THAT GOES WITH HOOD. INSTALL CROSSOVER BAR UNDER ENGINE AND BOTTOM HOOD LINES. GOT HOOD CLOSED. HAVE TO SET UP AND STRAIGHTEN AND TIGHTEN ALL BOLTS. RESEARCH REQUIRED PARTS	2	135.00	270.00
06/12/2022	LABOUR HD	INSTALL CABLES AND SPRINGS ON HOOD MEASURE BOLTS FOR NEW HEAD LIGHT MOUNTS LOOK AT INTAKE FOR TURBO SIDE AND GET RIGHT CLAMPS COMING	0.75	135.00	101.25
07/12/2022	LABOUR HD	INSTALL HOOD ROLLERS AND BUMPERS TOP AND BOTTOM FIND ALL AC LINES CLEAN AND GET READY FOR INSTALL GET RETURN PARTS READY TO RETURN	3	135.00	405.00
07/12/2022	HOOD BUMPER-V15A	HOOD BUMPER-V15A	1	37.19	37.19
07/12/2022	HOOD COWL SEAL	HOOD COWL SEAL	0.50	139.77	69.89
07/12/2022	LOWER PETERBILT HOOD LATCH	LOWER PETERBILT HOOD LATCH	0.50	37.25	18.63
07/12/2022	ACCUMLATOR	ACCUMLATOR	0.50	89.60	44.80
07/12/2022	HOOD CABLE	HOOD CABLE	1	24.93	24.93

07/12/2022	HOOD ROLLER 2A2	HOOD ROLLER 2A2	2	16.21	32.42
07/12/2022	TUBE-ROLLER	TUBE-ROLLER	2	33.53	67.06
07/12/2022	HOOD ROLLER 2A2	HOOD ROLLER 2A2	2	16.21	32.42
07/12/2022	HOOD SPRING STUD	HOOD SPRING STUD	0.50	143.91	71.96
08/12/2022	LABOUR HD	INSTALL UPPER RAD HOSE S AND PIPE . INSTALL ALL A/C HOSES. INSTALL RAD HOSE TO OIL COOLER INSTALL P/S CABLE STUD FOR HOOD INSTALL IR TO AIR PIPING INSTALL AIR INTAKE PIPING TO TURBO EXCEPT ONE PIPE WAS WRONG MIDDLE SECTION INSTALL NEW BARREL FOR IGINITION AND D/S SLEEPER DOOR	3.50	135.00	472.50
08/12/2022	SILICONE COOLANT HOSE 3FT (PRICE PER FOOT)	SILICONE COOLANT HOSE 3FT (PRICE PER FOOT)	0.50	82.92	41.46
08/12/2022	1 INCH SILICONE HEATER HOSE	1 INCH SILICONE HEATER HOSE	2.30	32.55	74.87
09/12/2022	LABOUR HD	INSTALL IGNITION AND 4 DOOR LOCK TUMBLERS REPAIR D/S BUNK INSTALL INSTALL AIR TO AIR HOSES INSTALL AIR INTAKE WAITING ON ONE CALMP	3	135.00	405.00
09/12/2022	PETE KEY SET	PETE KEY SET	0.50	502.36	251.18
12/12/2022	LABOUR HD	REMOVE AND REPLACE REMOTE GREASE LINE TO CLUTCH SHAFT REMOVE AND REPLACE SPRING HANGER U-BOLTS AND SPRING SADDLE REOMOVED EXHAUST HEAT SHIELD FOUND MOUNTS RUSTEDED OFF	1.375	135.00	185.63
12/12/2022	LOW AIR LEAF SADDLE	LOW AIR LEAF SADDLE	0.50	52.67	26.34
12/12/2022	LABOUR HD	CLOSE HOOD TIGHTEN ALL BOLTS ONCE HOOD IS SQUARE AND STRAIGHT INSTALL D/S AIR TANK INSTALL INTERIOR DOOR LIGHT	1.50	135.00	202.50
12/12/2022	U-BOLT AIR TANK	U-BOLT AIR TANK	1	43.71	43.71
12/12/2022	PETE INTERIOR DOOR LIGHT	PETE INTERIOR DOOR LIGHT	1	5.00	5.00
13/12/2022	LABOUR HD	ASISIT IN RREMOVAL TORSION BAR ON BACK OF SLEEPER BETWEEN SLEEPER AIR BAGS PULLED SHOCKS OUT OF WAY REMOVE PLATE THAT AIR LINES ARE BOLTED TO	1.50	135.00	202.50
13/12/2022	LABOUR HD	INSTALL IR TANKS ON BOTH SIDES OF TRUCK USE NEW U CLAMPS AND NUTS INSTALL LAST 3 INCH HOSE ON LOWER RAD TO THE ENGINE	3.50	135.00	472.50

		BALAN	CE DUE		\$6,226.72
		TOTAL			6,226.72
		GST @	5%		296.54
		SUBTO	TAL		5,930.18
15/12/2022	SHOP SUPPLIES	SHOP SUPPLIES	0.07	5,542.22	387.96
15/12/2022	CONNECTOR TUBE	CONNECTOR TUBE	0.50	2.51	1.26
15/12/2022	1 INCH SILICONE HEATER HOSE-506	1 INCH SILICONE HEATE	R HOSE-506 2	23.42	46.84
15/12/2022	COUPLING 4GE-4FJX	COUPLING 4GE-4FJX	0.50	16.37	8.19
15/12/2022	HYDRAULIC HOSE 4MXT X 70425	HYDRAULIC HOSE 4MXT (PER FT)	X 70425 0.50	9.96	4.98
15/12/2022	LABOUR HD	COMPLETE INSTALL OF GREASE REMOTE GREAINSTALL A/C LINES ORFIFIND LAST 2 A/C LINES ZINTO PLACE INSTALL PY WIRING START INSTALL CLIGHT BRACKETS WORK WEBASCO FOR BOTH EN SLEEPER PROVEN IN/OF	SE LINES CE TUBE IP TIE LINES RO TO THE DF HEAD ED ON IGINE AND	135.00	405.00
14/12/2022	ANTIFREEZE PRESTONE 4L YELLOW 50/50	ANTIFREEZE PRESTONE 50/50	4L YELLOW 10	16.79	167.90
14/12/2022	LABOUR HD	INSTALL NEW T ON THE OIL COOLER PRESSURE FOUND ANOTHER COOL ON BUNK HEATER REPL PRESSURE UP AGAIN NO INSTALL CLUTCH REMO HOSE WITH NEW FITTING WITH 40 LITRES PRESTO YELLOW	UP AGAIN ANT LEAAK ACED LINE D LEAKS TE GREASE GS FILL	135.00	371.25
13/12/2022	COUPLING 4GE-4FJX	COUPLING 4GE-4FJX	1	18.33	18.33
13/12/2022	3 INCH 3 PLY BLUE SILICONE COOLANT HOSE	3 INCH 3 PLY BLUE SILIC COOLANT HOSE	ONE 0.25	57.08	14.27
13/12/2022	LABOUR HD	JACK UP SLEEPER RREI BOLTS ON TORSSION BA SIEZED ON BOTH ENDS SLEEPER AIR BAGS	R BOLTS	135.00	67.50
13/12/2022	HOSE CLAMP 705-1235	HOSE CLAMP 705-1235	1	1.93	1.93
13/12/2022	FLAT WASHER STAINLESS STEEL 5/16	FLAT WASHER STAINLES 5/16	S STEEL 4	0.098	0.39
13/12/2022	5/16 UNF NYLON	5/16 UNF NYLON	4	0.31	1.24
13/12/2022	U-BOLT AIR TANK	UNHOOKED) U-BOLT AIR TANK	2	38.90	77.80
		PRESSURE TEST FOUND LEAK AT TRANSMISSION			

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 12047

 1010307 Alberta Ltd
 DATE
 30/12/2022

TERMS Net 14
DUE DATE 13/01/2023

UNIT # PROJECT 2 P/O # W/O # XX 12047

16/12/2022 LABOUR HD INSTALL HEAD LIGHTS AND BRACKETS START WIRING LIGHTS IN D/S						
BRACKETS START WIRING LIGHTS IN J/S	DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
BUCKETS & MOUNTING AND MOUNTING ARMS SET L/R	16/12/2022	LABOUR HD	BRACKETS START WIRING LIGHTS	2.25	135.00	303.75
19/12/2022 LABOUR HD BUILD WIRING HARNESS FOR CLEARENCE TURN SIGNALS AND HEAD LIGHT INSTALL D/S INSURE WORKING CORRECTLY 2.75 135.00 371.25 20/12/2022 LABOUR HD REMOVED AND REPLACED AXLE STOPS REMOVED DUST SHIELDS 2 135.00 270.00 20/12/2022 AXLE FRAME STOP BLOCK STOPS REMOVED DUST SHIELDS 1 199.97 199.97 20/12/2022 LABOUR HD INSTALL P/S WIRING FOR HEAD LIGHT REPAIRED TRUCK ENDS WITH PLASTIC CONNECTORS 1 135.00 135.00 27/12/2022 LABOUR HD FOUND JAKE AND IDLE NOT WORKING FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TAKE DOWN THE BROKEN WIRE HAD TO TAKE DOWN THE BROKEN WIRE HAD TO TRACK DOWN THE STORE TO HEAD SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH WORKING FOR FAN SWITCH ON TRUCK. ORDERED NEW BRAKE WALVE AS THE OLD ONE IS STUCK DOWN 0.75 135.00 101.25 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 WHEELS TO GET GANTRY IN PLACE 1.25 135.00 168.75	16/12/2022		AND MOUNTING ARMS	0.50	1,090.86	545.43
CLEARENCE TURN SIGNALS AND HEAD LIGHT INSTALL D/S INSURE WORKING CORRECTLY	16/12/2022	EXHAUST PIPE ELBOW	EXHAUST PIPE ELBOW	0.50	170.89	85.45
STOPS REMOVED DUST SHIELDS	19/12/2022	LABOUR HD	CLEARENCE TURN SIGNALS AND HEAD LIGHT INSTALL D/S INSURE	2.75	135.00	371.25
BLOCK 20/12/2022 LABOUR HD INSTALL P/S WIRING FOR HEAD 1 135.00 135.00 LIGHT REPAIRED TRUCK ENDS WITH PLASTIC CONNECTORS 27/12/2022 LABOUR HD FOUND JAKE AND IDLE NOT WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE. JAKE NOW WORKS 28/12/2022 LABOUR HD LOOKED UP AND FOUND WIRING SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH. WORKING FOR FAN SWITCH. STORT FOR FAN SWITCH. WORKING FOR FAN SWITCH. WORKING FOR FAN SWITCH. STORT FAN SWITCH. STORT FOR FAN SWITCH. STORT FAN SWITCH. STORT FOR FAN SWITCH. STORT FAN SWITCH. STORT FOR FAN SWITCH. STORT FOR FAN SWITCH. STORT FOR	20/12/2022	LABOUR HD	STOPS	2	135.00	270.00
LIGHT REPAIRED TRUCK ENDS WITH PLASTIC CONNECTORS 27/12/2022 LABOUR HD FOUND JAKE AND IDLE NOT WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE AND WHERE IT PLUGGED IN. SHORTED ACROSS AND THEN FIXED WIRE. JAKE NOW WORKS 28/12/2022 LABOUR HD LOOKED UP AND FOUND WIRING SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS STUCK DOWN 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 WHEELS TO GET GANTRY IN PLACE	20/12/2022		AXLE FRAME STOP BLOCK	1	199.97	199.97
WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE AND WHERE IT PLUGGED IN. SHORTED ACROSS AND THEN FIXED WIRE. JAKE NOW WORKS 28/12/2022 LABOUR HD LOOKED UP AND FOUND WIRING SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS STUCK DOWN 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 WHEELS TO GET GANTRY IN PLACE	20/12/2022	LABOUR HD	LIGHT REPAIRED TRUCK ENDS	1	135.00	135.00
SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS STUCK DOWN 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 1.25 135.00 168.75 WHEELS TO GET GANTRY IN PLACE	27/12/2022	LABOUR HD	WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE AND WHERE IT PLUGGED IN. SHORTED ACROSS AND THEN	3.50	135.00	472.50
WHEELS TO GET GANTRY IN PLACE	28/12/2022	LABOUR HD	SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS	0.75	135.00	101.25
	29/12/2022	LABOUR HD	WHEELS TO GET GANTRY IN PLACE	1.25	135.00	168.75

SWITCH WIRING AND DS LIGHT WIRING

35 185.73	2,653.35	0.07	SHOP SUPPLIES	SHOP SUPPLIES	30/12/2022
2,839.08			SUBTOTAL		
141.96			GST @ 5%		
2,981.04			TOTAL		
\$2,981.04)UE	BALANCE I		

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 12047

 1010307 Alberta Ltd
 DATE
 30/12/2022

TERMS Net 14
DUE DATE 13/01/2023

UNIT # PROJECT 2 P/O # W/O # XX 12047

16/12/2022 LABOUR HD INSTALL HEAD LIGHTS AND BRACKETS START WIRING LIGHTS IN D/S						
BRACKETS START WIRING LIGHTS IN J/S	DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
BUCKETS & MOUNTING AND MOUNTING ARMS SET L/R	16/12/2022	LABOUR HD	BRACKETS START WIRING LIGHTS	2.25	135.00	303.75
19/12/2022 LABOUR HD BUILD WIRING HARNESS FOR CLEARENCE TURN SIGNALS AND HEAD LIGHT INSTALL D/S INSURE WORKING CORRECTLY 2.75 135.00 371.25 20/12/2022 LABOUR HD REMOVED AND REPLACED AXLE STOPS REMOVED DUST SHIELDS 2 135.00 270.00 20/12/2022 AXLE FRAME STOP BLOCK STOPS REMOVED DUST SHIELDS 1 199.97 199.97 20/12/2022 LABOUR HD INSTALL P/S WIRING FOR HEAD LIGHT REPAIRED TRUCK ENDS WITH PLASTIC CONNECTORS 1 135.00 135.00 27/12/2022 LABOUR HD FOUND JAKE AND IDLE NOT WORKING FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TAKE DOWN THE BROKEN WIRE HAD TO TAKE DOWN THE BROKEN WIRE HAD TO TRACK DOWN THE STORE TO HEAD SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH WORKING FOR FAN SWITCH ON TRUCK. ORDERED NEW BRAKE WALVE AS THE OLD ONE IS STUCK DOWN 0.75 135.00 101.25 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 WHEELS TO GET GANTRY IN PLACE 1.25 135.00 168.75	16/12/2022		AND MOUNTING ARMS	0.50	1,090.86	545.43
CLEARENCE TURN SIGNALS AND HEAD LIGHT INSTALL D/S INSURE WORKING CORRECTLY	16/12/2022	EXHAUST PIPE ELBOW	EXHAUST PIPE ELBOW	0.50	170.89	85.45
STOPS REMOVED DUST SHIELDS	19/12/2022	LABOUR HD	CLEARENCE TURN SIGNALS AND HEAD LIGHT INSTALL D/S INSURE	2.75	135.00	371.25
BLOCK 20/12/2022 LABOUR HD INSTALL P/S WIRING FOR HEAD 1 135.00 135.00 LIGHT REPAIRED TRUCK ENDS WITH PLASTIC CONNECTORS 27/12/2022 LABOUR HD FOUND JAKE AND IDLE NOT WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE. JAKE NOW WORKS 28/12/2022 LABOUR HD LOOKED UP AND FOUND WIRING SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITCH. WORKING FOR FAN SWITCH. STORT FOR FAN SWITCH. WORKING FOR FAN SWITCH. WORKING FOR FAN SWITCH. STORT FAN SWITCH. STORT FOR FAN SWITCH. STORT FAN SWITCH. STORT FOR FAN SWITCH. STORT FAN SWITCH. STORT FOR FAN SWITCH. STORT FOR FAN SWITCH. STORT FOR	20/12/2022	LABOUR HD	STOPS	2	135.00	270.00
LIGHT REPAIRED TRUCK ENDS WITH PLASTIC CONNECTORS 27/12/2022 LABOUR HD FOUND JAKE AND IDLE NOT WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE AND WHERE IT PLUGGED IN. SHORTED ACROSS AND THEN FIXED WIRE. JAKE NOW WORKS 28/12/2022 LABOUR HD LOOKED UP AND FOUND WIRING SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS STUCK DOWN 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 WHEELS TO GET GANTRY IN PLACE	20/12/2022		AXLE FRAME STOP BLOCK	1	199.97	199.97
WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE AND WHERE IT PLUGGED IN. SHORTED ACROSS AND THEN FIXED WIRE. JAKE NOW WORKS 28/12/2022 LABOUR HD LOOKED UP AND FOUND WIRING SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS STUCK DOWN 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 WHEELS TO GET GANTRY IN PLACE	20/12/2022	LABOUR HD	LIGHT REPAIRED TRUCK ENDS	1	135.00	135.00
SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS STUCK DOWN 29/12/2022 LABOUR HD REMOVED DRIVER SIDE AXLE2/3 1.25 135.00 168.75 WHEELS TO GET GANTRY IN PLACE	27/12/2022	LABOUR HD	WORKING. FOUND THE SERVICE BRAKE SEIZED DOWN AND CLUTCH SWITCH HAD A BROKEN WIRE. HAD TO TRACK DOWN THE BROKEN WIRE AND WHERE IT PLUGGED IN. SHORTED ACROSS AND THEN	3.50	135.00	472.50
WHEELS TO GET GANTRY IN PLACE	28/12/2022	LABOUR HD	SCHEMATIC FOR FAN SWITCH. WORKING TO FIND WIRING FOR FAN SWITC ON TRUCK. ORDERED NEW BRAKE VALVE AS THE OLD ONE IS	0.75	135.00	101.25
	29/12/2022	LABOUR HD	WHEELS TO GET GANTRY IN PLACE	1.25	135.00	168.75

SWITCH WIRING AND DS LIGHT WIRING

35 185.73	2,653.35	0.07	SHOP SUPPLIES	SHOP SUPPLIES	30/12/2022
2,839.08			SUBTOTAL		
141.96			GST @ 5%		
2,981.04			TOTAL		
\$2,981.04)UE	BALANCE I		

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 12071

 1010307 Alberta Ltd
 DATE
 12/01/2023

TERMS Net 30
DUE DATE 11/02/2023

UNIT # P/O # W/O # XX 12071

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
02/01/2023	PROJECT TRUCK HD LABOUR	CUT OUT BACK OF BUNK CUT ALUMINUM TO GO BACK IN DRILLED HOLES BIGGER IN BRACKET INSTALL SQUARE TUBING FOR TOP OF BRACKET SUPPORT ON D/S	3.25	135.00	438.75
02/01/2023	PROJECT TRUCK HD LABOUR	TOOK OFF OLD SOUND BARRIER FOAM AND GLUE AND INSTALLED NEW ON P/S OF HOOD	2.50	135.00	337.50
04/01/2023	PROJECT TRUCK HD LABOUR	INSTALL DS AND PS BRACKETS ON SLEEPER. JB WELD STEEL PLATES. BOLTED BRACKETS. REMOVED DUST SHIELDS. REMOVED BOLTS ON PEDAL CLUSTER UNDER DASH. REMOVED BRAKE PEDAL. WORKED ON FAN WIRING.	7.25	135.00	978.75
05/01/2023	PROJECT TRUCK HD LABOUR	MOUNTED NEW 11R22.5 TIRE ONTO REPLACEMENT RIM FOR PS1 WHEEL. FILLED TO 100 PSI INFLATION.	0.25	135.00	33.75
05/01/2023	PROJECT TRUCK HD LABOUR	REMOVED FOOT BRAKE PEDAL FROM TRUCK. TOOK PEDAL APART AND CLEANED ALL MOVING PARTS. REINSTALLED WITH ANTI SEIZE.	2	135.00	270.00
05/01/2023	PROJECT TRUCK HD LABOUR	REMOVED BRAKE CLUSTER. BUFFED UP FLOOR AND BRAKE PLATE. REINSTALLED CAB BRACKET. INSTALLED NEW CAB SHOCKS AND CAB SWAY BAR. REINSTALLED CAB AIR BAGS.	4	135.00	540.00
05/01/2023	SHOCK ABSORBER/SLEEPER	SHOCK ABSORBER	1	112.01	112.01
05/01/2023	SLEEPER TORQUE ARM	SLEEPER TORQUE ARM	0.50	453.20	226.60
05/01/2023	PROJECT TRUCK HD LABOUR	REMOVED MUDFLAP BARS FROM BACK OF TRUCK. CUT STRIPPED THREADS. PUT REPLACEMENT MUDFLAP BARS ON AND INSTALLED	0.625	135.00	84.38

MUDFLAPS AND REFLECTORS

		ONTO MUDFLAP BARS.			
06/01/2023	LABOUR HD	REPLACE FRONT BRAKES ON TRUCK REPLACE BRAKE PEDAL CLUSTER PUT INTERIOR BACK TOGETHER PUT REAR TIRES BACK ON WORKED ON EXHAUST STACKS FOUND AIR LEAK ON FIRE WALL REPAIRED ******** ALL PARTS ON TOMS WORK ORDER***********************************	4	140.00	560.00
06/01/2023	LABOUR HD	INSTALL BOTTOM EXHAUST BRACKET. FOUND FAN STAT LEAKING ORDERED NEW ONE REMOVE INSTALL NEW HEIGHT CONTROL VALVE AIR TRUCK UP START FIXING AIR LEAKS	3	140.00	420.00
06/01/2023	BUSHING-RUBBE	BUSHING-RUBBE	1	2.57	2.57
06/01/2023	DUAL FOOT VAL	BRAKE PETAL	0.50	211.58	105.79
06/01/2023	RIDE HEIGHT VALVE	RIDE HEIGHT VALVE	0.50	233.81	116.91
06/01/2023	SUSPENSION AIR LINK	SUSPENSION AIR LINK	0.50	60.73	30.37
06/01/2023	BOLT-HEX M8-1 HWC06402	BOLT-HEX M8-1 HWC06402	4	1.14	4.56
09/01/2023	LABOUR HD	ALIGN HOOD AND HOOD ROLLERS DRILLED HOLES IN UPPER BRACKET AS SO THEY WOULD ALIGN PUT FRONT TIRES ON AND TORQUED ENTIRE TRUCK RE-INSTALLED UPPER HOOD BRACKETRS AAS TO ALIGN HOOD	4	140.00	560.00
10/01/2023	LABOUR LD	INSTALLED FRONT BUMPER AND WORKED ON HOOD	1.50	130.00	195.00
10/01/2023	LABOUR HD	WORK ON HOOD STILL WONT CLOSE FOUND HOOD IS BENT ON THE P/S SIDE	2	140.00	280.00
10/01/2023	LABOUR HD	WORK ON SKIRT LIGHTS COULD NOT FIND HOT END OF WIRE FOUND IT WAS WIRED DIRECTLY TO BATT THROUGH SWITCH INSTALL FUSE HOOK UP ALL WIRES ALL LIGHTS WORKONG EXCEPT 2 INSTALL 3 NEW LIGHTS ON AIR CLEANERS	2	140.00	280.00
10/01/2023	REFLECTOR 2 1 GRO 40072	REFLECTOR 2 1 GRO 40072	1	2.25	2.25
11/01/2023	LABOUR HD	REMOVED INVERTOR TIED UP WIRING REMOVED OLD WIRING PAINTED ALL OF FRAME GRAVEL GAURDED STEPS REOVED BRAKE POTS	4	140.00	560.00
11/01/2023	LABOUR HD	FIX AND REPAIR ALL SKIRT LIGHTS FIX TAIL LIGHTS SET BUNK RIDE HEIGHT REMOVE AND REPLACE NEW FAN STAT STILL LEAKS NEED	4	140.00	560.00

FAN KIT BRAKES WONT HOLD NEED 3 NEW AIR POTS

		O I I E V V III (I O I O			
11/01/2023	LED PIGTAIL W/.18 BULLET	LED PIGTAIL W/.18 BULLET	1	4.16	4.16
11/01/2023	4" OPEN GROMMET	4" OPEN GROMMET	1.50	3.25	4.88
11/01/2023	CLEAR AMBER LED M3	CLEAR AMBER LED M3	0.50	19.87	9.94
11/01/2023	VALVE SELENOID FAN STAT	VALVE SELENOID FAN STAT	0.50	331.87	165.94
11/01/2023	FLAT BLACK CDA 1605	FLAT BLACK CDA 1605	2.50	25.09	62.73
11/01/2023	GLOSS BLACK CDA1600	GLOSS BLACK CDA1600	1.50	22.42	33.63
11/01/2023	BLACK GRAVEL GAURD	BLACK GRAVEL GAURD	0.50	23.62	11.81
12/01/2023	LABOUR HD	INSTALLED 3 BRAKE POTS ADJUSTEDE BRAKES REMOVED FAN HUB INSTALLED EXHAUST SHIELD	3.50	140.00	490.00
12/01/2023	LABOUR HD	CUT BRAKE POTS WORK ON FAN HUB	2.50	140.00	350.00
12/01/2023	BRAKE POT PREMIUM 3030 SPRING BRAKE	BRAKE POT - SHORT STROKE	1.50	62.24	93.36
12/01/2023	SHOP SUPPLIES	SHOP SUPPLIES	0.07	7,925.64	554.79
		SUBTOTAL			8,480.43
		GST @ 5%			424.05
		TOTAL			8,904.48
		BALANCE DUE			\$8,904.48

PO Box 532

Milk River AB T0K 1M0

GST/HST Registration No.: 744771338RT0001

INVOICE

 BILL TO
 INVOICE
 12106

 1010307 Alberta Ltd
 DATE
 19/01/2023

TERMS Net 30
DUE DATE 18/02/2023

 UNIT #
 MILEAGE
 P/O # W/O #

 PETE 2
 STEVE-TOM
 XX
 12106

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
16/01/2023	LABOUR HD	INSTALLED D/S EXHAUST SHIELD	2	135.00	270.00
17/01/2023	LABOUR HD	REBUILT &INSTALLED FAN CLUTCH ADJUST RADIATOR ADJUST CAB AIR RIDE TORQUE ALL WHEELS	6	135.00	810.00
17/01/2023	FAN HUB KIT	FAN HUB KIT	0.50	908.33	454.17
18/01/2023	LABOUR HD	GREASED TRUCK ADJUSTED BRAKESREPAIR LEAKING BRAKE POT REPAIRED LIGHTS ON BACK OF TRUCK (RE-WIRED) TORQUE DRIVES ON PASSANGER SIDE	3.50	135.00	472.50
18/01/2023	LABOUR HD	NO POWER TO BACK OFF TRUCK CUT OLD WIRING OUT CUT OLD JUNCTION BOX OUT CUT 3 FT OF GARBAGE WIRING OUT AND RE- WIRED	3.50	135.00	472.50
18/01/2023	LIGHT	LIGHT	1	32.82	32.82
18/01/2023	LAMP, CLEAR LED 4 ROUND	LAMP, CLEAR LED 4 ROUND	0.50	72.42	36.21
18/01/2023	JUNCTION BOX 7 TERMINAL	JUNCTION BOX 7 TERMINAL	0.50	21.15	10.58
18/01/2023	LED PL3 ADAPTER PLUG-1	LED PL3 ADAPTER PLUG	0.50	7.59	3.80
18/01/2023	4 CONDUCTOR PRIME WIRE	4 CONDUCTOR PRIME WIRE PRICE PER FT	4	3.32	13.28
18/01/2023	7 WIRE SOW CABLE	7 WIRE SOW CABLE SOLD PER FT	1.50	9.93	14.90
18/01/2023	LABOUR HD	PLUGGED IN COMPUTER TO CLEAR ABS CODES AND SET PARAMETERS	0.50	135.00	67.50
19/01/2023	LABOUR HD	REMOVE PS3 TO ADJUST SENSOR CODE SAYS SENSOR TO FAR AWAY FROM TONE RING AIR UP REVOVE DUALS SET SENSOR POSITION AND	0.50	135.00	67.50

		CLEAN TONE RING PUT BACK TOGETHER			
19/01/2023	LABOUR HD	PS3 BRAKE DRUM VERY HOT REMOVED WHEELS AND BRAKE DRUM BEARING WAS LOOSE REMOVED HUD REPLACED WHEEL SEAL FILLED WITH OIL AND RE-SET BEARIMGS TORQUE WHEELS	0.75	0.00	0.00
19/01/2023	WHEEL SEAL D5F5	WHEEL SEAL D5F5	0.50	76.01	38.01
19/01/2023	LABOUR HD	INSTALLED NEW PIG TAIL AS DS REAR TAIL LIGHT KEPT QUITTING INTERMINTLY TOP OFF POWER STEERING FLUID SET RIDE HEIGHT ON CAB	1.75	135.00	236.25
19/01/2023	LIGHT	LIGHT	0.50	29.21	14.61
19/01/2023	LED PL3 ADAPTER PLUG	LED PL3 ADAPTER PLUG	0.50	6.43	3.22
19/01/2023	MOBIL MULTI-VEHICLE ATF SYN BLEND 4.73L	MOBIL MULTI-VEHICLE ATF SYN BLEND 4.73L - Price per litre	1.50	7.92	11.88
19/01/2023	SHOP SUPPLIES	SHOP SUPPLIES	0.07	3,029.73	212.08
		SUBTOTAL			3,241.81
		GST @ 5%			162.10
		TOTAL			3,403.91
		BALANCE DUE			\$3,403.91

1284194 ALBERTALTO O/ATTORLEY'S UNUMLITED SALES 87 CANYONCREST POWNWEST WETHERIOGE, AR TIKOBY 657# 832069 728 ATOOOL TWOICE 14695

THIS NUMBER MUST APPEAR ON ALL PACK-AGES, INVOICES, AND CORRESPONDENCE CE NUMÉRO DOIT APPARAÎTRE SUR TOUT

COLIS, FACTURE ET LETTRE.

		DATE -	N
	1 17	DECEMBE	MA
SF I	1073	1/FUBILIE	XVII
ا سال			

		1110-	11 -
BILL TO I	BORDER HEAVY DUTY LAD	SHIP TO EXPÉDIER À	ET #d
T D	O. Rox Bal	2000 PETERB	THE 379/ANGUET W/634 M. CRISE
M	LIK RIVER AB TOKI	mo (mepium Bivi	E) SLEEPER
		ATTN. A/S	
VIA TRANSPORT	PREPAID - EN PORT PAYÉ FAB	TERMS CONDITIONS	DATE REQUISE
IRANSFORT	COLLECT - À PERCEVOIR		VILLED BELOW

PLEASE SUPPLY THE FOLLOWING GOODS SUBJECT TO THE CONDITIONS SPECIFIED BELOW. VEUILLEZ FOURNIR LES ARTICLES SUIVANTS AUX CONDITIONS INDIQUÉES CI-DESSOUS

PLEASE SUPPLY THE FOLLOWING GOODS SUBSECT OF SUPPLY THE FOLLOWING GOODS SUPPLY THE FOLLOWING SUPPLY THE
A PAROR PAINT HATERIALS TO REPAINT HOOD FROMS LORGIZ 3403 67
A LABOR PAINT PHINTERIALS TO THE MINT CORDER TOM. 5 1500 00
D TO ME LISED YEARDER OF IA WINCE SO
TO MARKE WILL GOVERN
1 to the second of the second
*135. 0 HR AND PICK UP HOOD AFTERTAINTED TAKING DAIK 18 STOP HOOS KAP STAKEOOK OUT
D-4HOLES @ LOAD UP HOOD RADIATOR+BURNER FROM SHOP AND HAVE FOUNTS
#12 ONLY MULK RIVERSHOP, - MANTRUCK PIRAILER 57000
7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
E-TORLEY'S FORM LINSULATION FOR LINSIDE OFFICE TO \$630 00
THE TANIANG NILL THINK SHOP TO THUCK THE
MANT HOLL TOUR TOUR TOUR TOUR TOUR TOUR TOUR TOUR
Davie RODICTORS LTD-LABOR LARRETTO KOLL BENCHIR INTAKE MOING " 1000
I- HOUR @ TRUCK + MAN (3 trips) TO GET 6" PIPE ROLL BERG @ DON'S RODWICK \$75 00
1- 575 M/HR /RUCK +MAN (3 11 95) 10 001 0 7-NEW 6 "rubbere buse 38.13 ad \$76 26
- TORLEY'S - USED 16"x6" piece of aluminum piper + 6"x6" rubber # 95 oc.
CONTINUE DI PONDE COMMANDE

TERMS & CONDITIONS OF THIS PURCHASE ORDER:

- 1. Acknowledge receipt of this order with specified prices and a definite ship date.
- 2. Do not alter the order without our authorization.
- 3. If shipment will be delayed for any reason, advise us immediately.
- 4. We have the right to cancel this order if shipment cannot be delivered on time.
- 5. This order must retain the original prices that were quoted.
- 6. Goods are subject to our inspection and approval.

CONDITIONS DU BON DE COMMANDE :

- 1. Accusez réception de la commande avec des prix déterminés et une date d'expédition précise.
- 2. Ne modifiez pas la commande sans notre autorisation.
- 3. Si l'envoi est retardé pour une raison ou pour une autre, veuillez nous aviser immédiatement.
- 4. Nous avons le droit d'annuler la présente commande si l'envoi ne peut être livré à temps.
- 5. Les prix figurant dans la présente commande doivent être les mêmes que ceux initialement proposés.
- 6. La marchandise doit d'abord être inspectée et approuvée.

SIGNED - SIGNÉ

STAPLES STC83



1284194 ALEGETA AD OVA TORLEY'S UNLIMITED SALES 89 CAMONCRES, POINT WEST LETHERIOGE, RB TIKOBY

(Continued) INVOICE # 046952

THIS NUMBER MUST APPEAR ON ALL PACK AGES, INVOICES, AND CORRESPONDENCE CE NUMÉRO DOIT APPARAÎTRE SUR TOUT

r: 2		0
LOTT	020 119	778878001
031	83200/	728 KT0001

COLLECT - À PERCEVOIR

PAGE 2 of 3

DECEMBER 29/2022

COLIS, FACTURE ET LETTRE.

· · · · · · · · · · · · · · · · · · ·	I NOC OCO, 2	receired a lange
BILLTO: BORDERHERYY DUTY KILL	SHIP TO EXPÉDIER À PROJEC	7#2
P.O. Box 532	2000 PETERBI	911
MICK RIVER, AB TOK	IMO (MEDIUM BU	E MIDRISE
	AYTN. A/S	32004
VIA TRANSPORT PREPAID - EN PORT PAYÉ FOB	TERMS CONDITIONS	DATE REQUIRED DATE REQUISE

PLEASE SUPPLY THE FOLLOWING GOODS SUBJECT TO THE CONDITIONS SPECIFIED BELOW.

VEUILLEZ FOURNIR LES ARTICLES SUIVANTS AUX CONDITIONS INDIQUEES CI-DESSOUS	
QUANTITY ITEM QUANTITÉ ARTICLE DESCRIPTION UNIT	PRICE PRIX
L- 1 HOURD TRUCK Y-MAN SHOP TO FIAND HICK UP 6" EZBONS	
975.00 HR AND 16"X6" PIECEW/6" TUBBER KINGTH & RUN TO TARA'S SHOP	\$7500 L
M- PETERBICT - FLOOD PIVOTS, MOUNT, PLATES, CHANNEL BOLT, BOLTS, NUTS, WASH	B.
PARTS RADIATOR MOUNTS, BUSHINGS ISOLATORS SPACERS, BUMPER BOUTKIT, HO	9
SPLASH GURROS ETC-PURCHASES-1260.77 RETURNS-777. NET CHARGE	*482,98 V
N-2 HOURS & TRUCK + MAN (5 HOD) TO RUN AROUND + PICKUP + KETURN	#150 00
D- DUE WEST-TIPE 1-11822.5 MICHELIN X-LINE ENDRY	#936 00 V
P- I HOUR BY TRUCKY NEW (ESPOR) PICK UP TIRE INCORDER SHOP FTAKE TO LITE	7500
D-TOOLEY'S 1-USED UR 22.5 POLISHED FRONT RIMFOR PETERBICK 80.	#280 00
R- MEN WESTRUCK CENTRES. IS OLATOR- ENGINE SUPPERTS-LOUBE	*23 18
GREGG DISTRIBUTORS - WASHERS + BOLTS 32.11-2= 16.06	#16 06 V
GREGE DISTRIBUTORS-6-62" Clarge for Air Intake System	2100
1 HOURD TRUCK + MAN (SHOP) TO RUN AROUND + PICK UP TAKE TO TAKE TO TAKE	17500
TERMS & CONDITIONS OF THIS PURCHASE ORDER: CONDITIONS DU BON DE COMMANDE :	

- 1. Acknowledge receipt of this order with specified prices and a definite ship date.
- 2. Do not alter the order without our authorization.
- 3. If shipment will be delayed for any reason, advise us immediately.
- 4. We have the right to cancel this order if shipment cannot be delivered on time.
- 5. This order must retain the original prices that were quoted.
- 6. Goods are subject to our inspection and approval.

- Accusez réception de la commande avec des prix déterminés et une date d'expédition précise.
- Ne modifiez pas la commande sans notre autorisation.
- Si l'envoi est retardé pour une raison ou pour une autre, veuillez nous aviser immédiatement.
- Nous avons le droit d'annuler la présente commande si l'envoi ne peut être livré à temps.
- 5. Les prix figurant dans la présente commande doivent être les mêmes que ceux initialement proposés.
- 6. La marchandise doit d'abord être inspectée et approuvée.

SIGNED - SIGNÉ

STAPLES STC83B

Section 1		_	14.55	CASS REAL OFF			-	-		
					7 4 4	B 4			-	
			_		110/1		/\		1	
			_		_ [•]	1 4 1	$\overline{}$	1 7		L
							-			

Continued)

Continued)

This number must appear on all pack ages, invoices, and correspondence ce number doit appearains sur tout colls, facture et lettre.

Bull To: Border Heavy Duty to supple a form bush proper pare pase transport conditions specified below.

Via. Transport Please supply the following goods subject to the conditions specified below.

Veuillez fournir les articles survants aux conditions indiquees ci-dessous

Description

This number must appear on all pack ages, invoices, and correspondence ce number of all pack ages, invoices, and correspondence ce number of all pack ages.

This number must appear on all pack ages, invoices, and correspondence ce number of all pack ages.

This number must appear on all pack ages, invoices, and correspondence ce number of all pack ages.

This number must appear on all pack ages, invoices, and correspondence ce number of all packs.

The supple of a suppl

QUANTITY ITEM QUANTITÉ ARTICLE	DESCRIPTION	UNITÉ	PRIX	all so	
GOANTIE ARTICLE	EMPIRE TRUCK PARTS - LAIGARY - 2- FROMT FROME HORN'S	50.07)	1100	00	k
1-	EMPIRETRUCKPARTS CRIBBRY - 1-EXPOSS HERT SHIELD		\$ 150	00	1
V- TORLEY'S	2-USED 5'X 5" EXHAUST TIPS @ 200. Obock		400	00	v
W-	PETFORIET-LETUBRIDGE & I COMPLETE SET OF HUCK BO	LISFOR	406	80	
X-TORLEY'S	1-USED PETERBILT GRILLE (CROWN) & KMBLEM (126	100DS +100)	\$1300		v
Y-TORLEY'S	1-20" USED PETERBILIT CHROME FROM BUMPER		\$800	00	ما
7 - TORLEY'S	1-USED INTERIOR TRIM HIECES FOR SLEEDER TOOR		#150	00	,
01- 5 HOURSO, AR	1-TRIP TO EMPIRE + BOCK (TAILLY MAN) TO FICK UP NUMEROUS PROTS		#375	00	~
02-3 HOURS	1-TRIP DOWN TO MILK RIVER+BOCK WITH NUMEROUS PARTS+GOD	RENE PLAN	M 225	00	1
(J. WALLEY)	SUBTOR	_ #	14 175	95	
	14,175.95 - 2 = 7087,98 Total.	-2=	F7087	98	Al S
		-10	- 4-		

TERMS & CONDITIONS OF THIS PURCHASE ORDER

- Acknowledge receipt of this order with specified prices and a definite ship date.
- 2. Do not alter the order without our authorization.
- 3. If shipment will be delayed for any reason, advise us immediately.
- We have the right to cancel this order if shipment cannot be delivered on time.
- 5. This order must retain the original prices that were quoted.
- 6. Goods are subject to our inspection and approval.


SIGNED - SIGNÉ

CONDITIONS DU BON DE COMMANDE :

- Accusez réception de la commande avec des prix déterminés et une date d'expédition précise.
- 2. Ne modifiez pas la commande sans notre autorisation.
- Si l'envoi est retardé pour une raison ou pour une autre, veuillez nous aviser immédiatement.
- Nous avons le droit d'annuler la présente commande si l'envoi ne peut être livré à temps.
- Les prix figurant dans la présente commande doivent être les mêmes que ceux initialement proposés.
- 6. La marchandise doit d'abord être inspectée et approuvée.

STAPLES STC83B

BON DE COMMANDE



CALGARY PETERBILT LTD.

Phone: (403) 235-2550 · Fax: (403) 235-1322

ERBILT RED DEER (403) 342-5153



PETERBILT LETHBRIDGE

Toll-Free: 1-888-777-3112

4110 - 18th Avenue North Lethbridge, AB. TIH 6N7 Tel: 403-328-0500 Fax: 403-328-0225

			γq	CUSTOMER COPY	,	GST NO. R100731918	छा
2.425	\$1,044.86	AL	TOTAL				
Susiness!	49.76		SALES TAX	SA		receive GST credit.	H 6
3	0.00		FREIGHT	7	Corp. To large to	שלי שלי לייני	2
Your	995.10		PARTS	C L	t for details!!	Now offering Mobile Service Department	Se
					- 1		T
the second							
You							
Thank			>				
NO REJURNS ON ELECTRICAS ON ALL SPECIAL ORDER PARTIS. NO RETURNS AFTER 30 DAYS. 20% RESTOCK CHARGE ON ALL RETURNED PARTIS.				L 379	3: 549426 / MODEL 379	Chassis: VISA	
ALL CLAIMS AND REJUNNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE.	12.92	3.23	V16 B	BOLT-HEX 1/2-		0	4
	AMOUNT	NET		DESCRIPTION		SHIP BO PART NUMBER	ORD
ALBT	LETHBRIDGE	F.O.B.		TERMS	BL NO. 14:07:05	SLSM. [1	SHIP VIA
					UNLIMITED SALES LTD N CRESENT PLACE GE, AB T1K 0B4	TORLEY'S UNLI 89 CANYON CRE LETHBRIDGE, F	0-10-
	PAGE 2 OF 2	P.		Ŧσ	T NO. 910803	ACCOUNT NO.	oσ
UNIT#		307395L	NUMBER	INVOICE DATE 21 OCT 22	DATE SHIPPED	NTERED YOUR ORDER NO.	DATE ENTERED 18 OCT

DATE ENTERED SHIP VIA 10100 NNN LETHBRIDGE, AB. T1H 6N7 YOUR ORDER NO. PART NUMBER SLSM. ACCOUNT NO. 00000010 12:34:29 34:5 DATE SHIPPED **Proximity** 910803 SALES CT \$81.52 GUARD-SPLA SCREW-CAP SCREW-CAP INVOICE DATE TERMS 7 1C8 DR2D DR2D NUMBER F.O.B 307912L 2290 HBRI26.14 21.92 28.42 1.16

ALBT

NO RETURNS AFTER 30 DAYS.
20% RE-STOCK CHARGE ON ALL
RETURNED PARTS. NO RETURNS ON ELECTRICAL OF SPECIAL ORDER PARTS. BY THIS INVOICE.

PETERBILT LETHBRIDGE

403-328-0600

SALE

APPROVED

Batch #: 035

Inv/Tkt #: 307912L

*********3327

AMOUNT

VISA CREDIT

S81

AID: A0000000031010

TTQ 32 A0 40 00

THANK YOU /

64

CUSTOMER COPY

APPR CODE: 028937

10/27/22

Trace: 10

VISA

18TH AVENUE NE

REF#:

MERCI

Fax: 403-328-0225 Tel: 403-328-0500

Toll-Free: 1-888-777-3112

רפנושושפי אם. וווו טועו

Phone: (403) 342-5100 · Fax (403) 342-5153 PETERBILT RED DEER

PETERBILT MEDICINE HAT Phone: (403) 526-4460 · Fax: (403) 525-5299



PETERBILT LETHBRIDGE

4110 - 18th Avenue North Lethbridge, AB. TIH 6N7 Tel: 403-328-0500 Fax: 403-328-0225

Toll-Free: 1-888-777-3112

PETERBILT LETHBRIDGE 4110 18TH AVENUE NE LETHBRIDGE, AB. T1H 6N7	DATE ENTERED 2.1 OCT SHIP VIA OBD SHIP 4
403-328-0600 . SALE	TORLEY ETHBR LETHBR 0 M
REF#: 00000038 Batch #: 030 10/21/22 17:41:41 Inv/Tkt #: 307624L	ACCO ACCO YON IDGE SISM. 41 ABI NUI 1741 1741
APPR CODE: 042606 Trace: 38 VISA ***********************************	NO. ITED ENT P TIK
AMOUNT \$98.41	1080 ALES ACE B4
APPROVED VISA CREDIT AID: A0000000031010 TTQ 32 A0 40 00 THANK YOU / MERCI	LTD MA TERMS CASH DESCRIPTION PACER - ROUND HWC01045
CUSTOMER COPY 101AL 93.72 93.72 4.69	PAGE 1 OF 1 WINDSER 307624L PAGE 1 OF 1 PAGE 1 OF 1

LETHBRIDGE **18TH** AVENUE NE LETHBRIDGE, AB. T1H 6N7 403-328-0600

SALE

REF#: 00000018

Batch #: 035 10/27/22

14:48:39

Inv/Tkt #: 307925L APPR CODE: 052024

Trace: 18

AR COPY

VISA *********3327 **Proximity**

AMOUNT

\$11.91

APPROVED

VISA CREDIT A0000000031010 32 A0 40 00 TTQ

> THANK YOU **MERCI** 1





DATE ENTERED

007

S

YOUR ORDER NO.

7

b CT

22

INVOICE DATE

NUMBER

307925L

UNIT#

DATE SHIPPED

ACCOUNT NO.

910803

SHIP VIA

SLSM.

B/L NO.

4:49:00

01000

TORLEY'S UNI 89 CANYON CI LETHBRIDGE,

CRESENT

PLACE

CIT

2000/

ORD D

SH P

18

18

C

HWC05636 PART NUMBER

WASHER-ROUND

DR5B

0.63

DESCRIPTION

TERMS

F.O.B.

CASH

PAID VISA

Phone: (403) 342-5100 · Fax (403) 342-5153

PETERBILT RED DEER

CALGARY PETERBILT LTD.

Phone: (403) 235-2550 · Fax: (403) 235-1322

PETERBILT LETHBRIDGE

4110 - 18th Avenue North Lethbridge, AB. TIH 6N7 Tel: 403-328-0500

Toll-Free: 1-888-777-3112 Fax: 403-328-0225

OH

ETHBRIDGE AMOUNT 11.34ALBT ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED

NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS.
NO RETURNS AFTER 30 DAYS.
20% RE-STOCK CHARGE ON ALL

Blue 2000 Peterbelt 379/minute

W/63" michise speeper

Box 352 T1M 1M4 Box 352 T1M 1M4

admin@duewesttire.ca

Tel.#: (403) 345-0385

Torleys Unlimited Sales

INV # : 10410

Darrell Torris

Plate : LOOSE ODO

Date : 12/14/2022

205011 TWP RD 9-1A Bay 12a LETHBRIDGE, AB

Time

V.I.N.:

Unit #: LOOSE

PO #

REG # : 779296508RT0001

B#:403 588-4309

H#: Engine:

Tot.Parts Labour

Tech. : BEN N/

1.00

Qty

Hrs. Description

Parts Ea. 922.00

Tx Total GST

C

11R22.5 MICHELIN X-LINE ENERGY

922.00

922.00

TIRE RECYCLE- MEDIUM

GST 14.00

WO# 10079

Copyright 2022 Autogence Inc. - LANKAR 11.16.2

Have your wheels retorqued, everytime your wheels come off you need to come back and have them retorqued within 100 km, we provide this as a free service to you. This is your responsibility, should you get your wheels retorqued somewhere else, Due West Tire Co. is not responsible for any consequences.

Shop supply charges are billed to customers to cover costs associated with the inspection and repair of your vehicle as it relates to, but not limited to: consumable items such as solvents, adhesives, lubricants, cleaners, floor liners, rags, seat covers and equipment maintenance.

PAID BY: 12/14/2022 A/R 982.80 ** UNPAID BALANCE **

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of work done and materials supplied whether the vehicle is in Due West Tire Co.'s possession or not, the right to take possession of vehicle, hold it or sell it in order to recover the unpaid cost. All labour Warranties are valid for 90 days or 5000 km, whichever occurs first. occurs rirst. All Parts Warranties are based on Manufacturers Warranty. All parts are new unless otherwise stated.
*All parts and labour warranties are void when parts supplied by

customer

Signature

Sub Tot.

922.00

936.00

GST TX2

Deductible

Total

0.00

Page

1 of 1

0.00

46.80

0.00

982.80

EMPIRE TRUCK PARTS

2820 52 St. SE.

Calgary, AB T2B 1N2

Canada

1-403-272-3319

Fax 1-403-273-2106

truckwreckerpw@gmail.com

http://www.empiretruckparts.ca

Ship To

Sales Receipt E-33376

Bill To

Torley,s Unlimeted Sales

403 588 4309

Torley,s Unlimeted Sales

403 588 4309

Sales Receipt E-33376

Sales Person.

Mark McKervey Payment Method

Sold On

15 October 2022

Paid \$1,680.00

Item On Throck 2002 (1)	Price	Quantity	Line Total
Wire Harness Detroit ECM Vire Harness Detroit ECM	tetre Classic 500.00	Ĭ.	500.00
2 frame horns Madum Blue Zox	o Blow 1 379 1.100.00	l.	1,100.00
Notes		Subtotal	1,600.00
and the same of th	Federal	Tax @ 5.00 %	80.00
		Total Tax	80.00
- A - T		Paid	\$1,680.00
IRE TRUCK PARTS		Ralance	\$0.00

EMPI

2820 52 ST SE CALGARY, AB T2B 1N2 4032723319

Transaction 001314

Total

\$1,680.00

CREDIT CARD AUTH

\$1,680.00

VISA 3327

15-Oct.-20 2 12:56:16p.m. \$1,680.00 | Method: EMV **VISA CREDIT**

XXXXXXXXXXXXX3327

DARRELL TORRIS

Reference ID: 228800517143

Auth ID: 085007 MID: ******7169 AID: A0000000031010

AthNtwkNm: VISA PIN VERIFIED

anty statement can be obtained upon request. ed up after 30 days, will be sold for storage.

sions, and differentials are guaranteed for 30 days.

funds on electrical parts.

ake parts.

EMPIRE TRUCK PARTS

2820 52 St. SE

Calgary, AB T2B 1N2

Canada

1-403-272-3319 Fax 1-403-273-2106

truckwreckerpw@gmail.com

://www.empiretruckparts.ca

Sales Receipt E-33755

Bill To

Torley,s Unlimeted Sales

403 588 4309

Ship To

Torley.s Unlimeted Sales

403 588 4309

Sales Receipt E-33965

Sales Person

Mark McKervey Payment Method

Sold On

Visa

23 November 2022

Paid \$157.50

Item Heat shield	Price 150.00	Quantity 	Line Total
Notes	Federal	Subtotal Tax @ 5.00 % Total Tax Paid	150.00 7.50 7.50 \$157.50
		Balance	\$0.00

- 1. A complete warranty statement can be obtained upon request.
- 2. All items not picked up after 30 days, will be sold for storage.
- 3. Engines, transmissions, and differentials are guaranteed for 30 days.
- 4. No warranty or refunds on electrical parts.
- 5. No warranty on brake parts.

\$157.50

G.S.T. # R101633345

Transaction 100516

EMPIRE TRUCK PARTS

Retain this copy for statement

\$157.50 | Method: CONTACTLESS 23 Nov. 2022 4:52:24p.m.

AID: A0000000031010 AthNtwkNm: VISA

NO CARDHOLDER VERIFICATION

LE MV# 0 /28 Bill To: DAF	ETHBRID BHIGH AUS BRELTORRI ANBROOK, BU	PENTALAD TO BE BILLEY OF	450 3036 e N AB ecks.com Ship To: DARF	Date / Ho Repair Ord Custom Brand Total Invoid	ce: \$ 6,802.85 ***COD*** Page 2 of 2	
Work: 403-	588-4309	C VICETS LOOD MEDIUMBO PETERBILY 379	9 portovase	(W/63 4)	WIORISE SE	EFER
Customer P/O:		rainscough		Orig R/O: 0	Completion Date: 7/	20/2022
Task: 5 13	-200001.01 Tr	ruck Brake Repair			Department: Service	e
7/8/20 BEEEI 7/8/20 the tru 7/20/2	part numbers, and 22 11:28:46 AM 1: EEN REPLACED 22 3:38:18 PM 1: ick. Found a part r !022 1:30:51 PM 1	305 Removed severice brake air line from valve I sent to parts. New valve is in Calgary 2 days aw 305 Recieved new brake valve from parts, inspe NEED NEW VALVE. 305 Went outside to truck and started to remove number on truck and gave to parts. 305 Recieved adapter abs line from parts and valued to the end of one hose as it would not swive	vay. Had to cut broken ected and found to be varie. Found wire goes take Mounted valve or	part of vavle off to wrong. Sent back to all the way to the	be able to remove from o parts. BRAKE VALVE habs modulator near the l	air line. HAS NCT back of
Supp. Part		Description / Ref Number	U/I		Price	Extended Price
	KD2205	VALVE KIT	EA		\$104.90	\$104.90
	472 195 095 0 894 601 132 2	VALVE ABS MODULATOR BU			\$343.68	\$343.68
		CABLE-MOD VLV,MALE SCRE	W ON TO FM BAY EA	P	\$34.05 arts: abor: otals	\$34.05 \$0.00 \$0.00 \$0.00
Customer Tax	1010	93520				
GST/HST Num Detail Tax Info: Alberta GST #		= book \$323.95	Total	Total Pa Total Lat SHOP SUPPL	oor: \$8	\$0.00 5,784.73 \$694.17
DUNLÖP TRUCK (4110 9 A LETHBRIDGE, A 403-317-	CENTRES LET VE N B. T1H 6L9 2450	Daid Datober 11/2022		Invoice Subto Total	tal: \$6	6,478.90 \$323.95
SAL				Total Invo	ice: \$6,	802.85
Batch #: 312 08/24/22 Inv/Tkt #: 215644 APPR CODE: 458600 Trace: 3		Due Date N RECEIPT - INTEREST8/15/2022 PER MO. THEREAFTER ST AT 2% PER MONTH(24% ANNUM) CHARCE SPECIAL ORDER PARTS NO RETURNS AF			5000	
AMOUNT	Manual CP **/** \$6,802.85	SPECIAL ORDER PARTS. NO RETURNS AF (WARRANTIES ON THE PRODUCTS SOLD LAIMS ALL WARRANTIES, EITHER EXPRES)R A PARTICULAR PURPOSE, AND ROCKY IT ANY LIABILITY IN CONNECTION WITH TH	HEREBY ARE THOSI SED OR IMPLIED. IN MOUNTAIN DIESEI	E MADE BY THE M CLUDING ANY IM LTD NEITHER AS	MANUFACTURER, IF AN	NY. THE
APPROV	ED	JING REPAIRS MUST BE DEPORTED WITH	IIN 20 DAYO OF THE	···-		

DING REPAIRS, MUST BE REPORTED WITHIN 30 DAYS OF THE SAME, FOR ANY CONSIDERATION. CUSTOMER RIGINAL REPAIR ORDER INVOICE.

THANK YOU / MERCI _DATE:_

CUSTOMER COPY

TRUCK CENTRES

LETHBRIDGE 403-317-2450

1-888-345-3036

LETHBRIDGE

41109 Ave N Lethbridge, AB T1H6L9

www.dunloptrucks.com

1284194 AUSERTA. BILL TO: OU DARREL TOPPIS

1125 COBHAM AVE W

CRANBROOK, BC V106T3 Work: 403-588-4309

Ship To: DARREL

Customer P/O:

MV# 0

Model Year: 2000

rainscough

Completion Date: 07/20/202

Invoice: 0202S215644

COD

Page 1 of 2

Department: Service

Department: Service

Department: Service

Repair Order: 215644 Customer: 00100

Branch: 2

Total Invoice: \$ 6,802.85

Date / Hour: 7/20/2022 3:43:51PM

Make/Model: Peterbilt 379 <u>VIN: 1XP5DB9X0YN549426</u> Meter: 81287 Kilometers

Type: Heavy Truck

Unit Number: 1

91-100003.01 Frame Set Up And Gauge Complaint: Frame Set Up And Gauge

Department: Service

Correction: 6/17/2022 10:17:22 AM 1305 Truck was towed onto rack. Checked tire pressures and set ton100psi. Had to air up truck, used shop air and found that a brake pot had a damaged port hole and air was leaking out of the hose, blocked off hose and caged pot so brakes could be released.

Measured frame for twist, found 17mm. Placed gauges on frame and checked for sway, found 8mm of sway. Checked for cab frame roll and found 6mm. Checked for diamond and had no diamond. Inspected frame for damge.

6/17/2022 11:00:25 AM 1305 Hooked truck up to yard truck and pulled out of shop.

Supp. Part	Description / Ref Number	U/M	Quantity	Extended Price Price
		Task 1 Subtotals	Parts:	\$0.00
			Labor:	\$570.33
T. 1			Task 1 Subtotals	\$570.22

91-100001.01 Frame Rack Truck Repair

Complaint: REP[AIR FOR 17 MM TWIST

Correction: 7/4/2022 6:04:40 PM 1305 Backed truck onto frame rack. Set up push rams and chains to remove twist.

7/5/2022 9:56:29 AM 1305 Please correct time, forgot to clock off at 6:00pm on Monday July 4/22. 7/6/2022 5:56:53 PM 1305 Continued to remove twist. Once twist was removed, corrected sway. Found twist to come back once sway was

7/8/2022 11:20:31 AM 1305 Once sway removed. Set up the push rams and chians and removed twist. Reinstalled deck plate. 7/8/2022 11:26:36 AM 1305 Hooked yard truck to truck and pull out of shop

Supp. Part	Description / Ref Number	U/M	Quantity	Extended Price Price
	Task 2	Subtotals	Parts:	\$0.00
			Labor.	\$1,955.40
Tack: 2 04 400004 04			Task 2 Subtotals	\$1,955.40

91-100001.01 Frame Rack Truck Repair Complaint: REPAIR 6 MM CAB ROLL

Correction: 7/5/2022 6:12:34 PM 1305 Set up tower and push ram to remove roll on right side rail. Found was not able tomove it. Placed another tower and push ram on the left side rail and moved both rails together

7/6/2022 11:34:27 AM 1305 Pressured both rails up until roll removed from both rails. Removed equipment from truck

	and a separate month at dock					
Supp. Part	Description / Ref Number	U/M	Quantity	Extended Price Price		
		Task 3 Subtotals	Parts:	\$0.00		
			Labor:	\$1,303.60		
Tooks A 04 400004 04 T			Task 3 Subtotals	\$1,303.60		

91-100001.01 Frame Rack Truck Repair

Complaint: REPAIR 8MM SWAY

Correction: 7/6/2022 4:48:39 PM 1305 Set up chains and towers to pull sway out of truck. Had to remove deck plate to put chain in center of truck. 7/7/2022 5:46:11 PM 1305 Once towers set up pulled sway out of truck. Found when sway straight the twist was back. Pulled sway further then the original sway so that when twist is corrected the there would be no more sway. Once sway out of the frame, removed equipment from the truck

Supp.	Part	Description / Ref Number	U/M	Quantity	Extended Price Price	
			Task 4 Subtotals	Parts:	\$0.00	
				Labor:	\$1,955.40	
· .				Task 4 Subtotals	\$1,955.40	

Adam's Diesel

1909 parkside point Coaldale AB T1M1R7 +1 4038927605

a-mcculloch@hotmail.com

GST/HST Registration No.: 842424145RT0001

BILL TO

Darrel Torris Torley's Unlimited Sales 205011 TWP RD 9-1A Bay 12A Lethbridge County AB

TERMS Due on receipt

		*
YEAR & MAKEMedium	VIN NUMBER	MILAGE
2000 Peterbilt (Blue) 379 Kongrose	1XP5DB9X0YN549426	81468 KM

Hours	 Inspect for engine light on, scanned for codes, active code for coolant level sensor, truck does not have coolant level sensor, reprogram ecm for no coolant sensor, cleared code. 	GST	0.50	110.00	55.00
Hours	Download and printout ecm	GST	0.50	110.00	55.00
Hours	Check power settings, set at 500 HP, Re program ecm to 550 HP 1850 FT/LBS	GST	1	500.00	500.00
Hours	LH convex mirror loose and flopping around, remove nut, install washers on mount and tighten up.	GST	0.25	110.00	27.50
FW18.8C516	5/16" Stainless Steel Flat Washer	GST	2	0.12	0.24
Hours	Inspect bunk air ride not working right, sometimes wont go up, other times way over inflates and maxes out bags, valve is new, checked and make sure air lines plumbed to correct ports, air lines proper, unhook linkage and operate arm on valve manually, valve goes wrong way when arm pulled down as if cab down it deflates and with arm pushed up as if height too high it adds air, unbolted valve from mount, flipped valve over, hooked up linkage and adjusted, valve now works properly.	GST	0.50	110.00	55.00
Hours	Transmission oil cooler lines leaking bad, dripping all over exhaust pipe, removed oil cooler lines, removed reusable ends off old old hoses, new ends are very expensive, old hose hard and crusty, had to break out of a couple ends, clean and inspect reusable ends, ends in good shape, built new hoses, installed, checked oil level, still at plug., cleaned oil off transmission and exhaust pipe.	GST	2	110.00	220.00
1503-10	#10 Air Brake Hose Steel Braided / FT	GST	3.50	18.85	65.98
1013	1 Liter Bottle Brake Clean	GST	2	8.50	17.00
76- <mark>294</mark> 7	Double Ended Zip Tie 19.5"	GST	1	3.00	3.00

Hours	Fan solenoid valve at firewall leaking air, made sure plumbing correct, valve is new, plumbing is proper, remove old solenoid valve, swap out fittings and install new valve, had to wire on proper plug to plug into truck.	GST	1	110.00	110.00
Parts	customer supplied solenoid valve	GST	1	0.00	0.00
884.122-A	1/8 Pipe Coupling	GST	1	3.75	3.75
884.103E-A	Pipe Hex Fitting 1/8 X 1/8 Female	GST	1	3.45	3.45
884.X115-A	1/8" Pipe 90 Degree Extruded Street Elbow	GST	1	3.90	3.90
Parts	Weather pack plug socket, 2 pins, 2 seals, 1 lock	GST	1	15.00	15.00
Hours	R&R both #2 axle (front diff) air bags (cords showing) removed both old bags, cleaned up rust on frame and lower brace on springs, noticed 1 bolt broken holding brace to RH spring, had to use air hammer to remove rest of rusty old bolt, installed new bolt and tightened, replaced both bags, had one very good barely used bag here, installed on RH side, customer got new bag, installed new bag on LH side, swapped fittings over from old bags, hook up lines, air up, check for leaks, all good.	GST	2.50	110.00	275.00
Parts	customer supplied new air bag	GST	1	0.00	0.00
Parts	Very good used air bag #W01-358-8852	GST	1	90.00	90.00
074.12.212	1/2" x 2.5" UNC Hex Bolt	GST	1	1.05	1.05
422.12	1/2" Flat Washer	GST	4	0.45	1.80
335.12	1/2" UNC Stover Locknut	GST	1	0.65	0.65
444.12	1/2" Lock Washer	GST	2	0.25	0.50
074.12	1/2" Gr8 Hex Nut	GST	2	0.80	1.60
074.38.114	3/8" x 1.25" UNC Hex Bolt	GST	4	0.50	2.00
444.38	3/8" Lock Washer	GST	4	0.20	0.80
422.38	3/8" Flat Washer	GST	4	0.20	0.80
Hours	Front cab mounts cracked, failed safety, removed panels on bottom of cab in front of steps, unbolt cab mounts one at a time, lift and support cab, replace mount, set down and bolt up, cleaned up old bolts and re used, repeat for other side, install panels on bottom of cab with new stainless bolts.	GST	3	110.00	330.00
Parts	Cab Mount Bushing #20-08257	GST	4	37.29	149.16
Parts	Cab Mount Spacer #20-08867	GST	2	55.62	111.24
H18.8C38.12	5 3/8" x 1.25" Stainless Steel Bolt	GST	4	0.48	1.92
SLCC38	3/8" Stainless Steel Nylock Nut	GST	4	0.35	1.40
FW18.8C38	3/8" Stainless Steel Flat Washer	GST	8	0.20	1.60
074.38.114	3/8" x 1.25" UNC Hex Bolt	GST	2	0.50	1.00
422.38	3/8" Flat Washer	GST	4	0.20	0.80
335.38	3/8" UNC Stover Locknut	GST	2	0.30	0.60
553.55040	Regular Zip Ties	GST	2	0.25	0.50
Hours	Re torque all wheels at 500 Ft LBS, install all 6 hub cover/nut cap sets	GST	1	110.00	110.00
Hours	Pick truck up from Dunlop after safety.	GST	0.50	110.00	55.00

Hours	Inspect for clutch pedal not return to all the				
	Inspect for clutch pedal not returning all the way, can pull up but is catching bad, found air line going to	GST	0.25	110.00	27.50
	positive all strut off was catching bolt on clutch				
553.59001	illikage, tied line over away from linkage.				
	Large Zip Ties	GST	3	0.40	1.00
Hours	Bolts missing in crossmember to frame on LH side	GST	0.50	110.00	1.20
	Defill to Dunk, looks like had step there previously	401	0.50	110.00	55.00
	installed flew bolts, also noticed one bolt on each				
	side of fifth wheel plate to frame side rails missing, installed bolts.				
074.58.2	5/8" x 2" Hex HD Cap Screw				
074.58.212	5/8" x 2.5" Hex HD Cap Screw	GST	2	2.65	5.30
422.58	5/8" Flat Washer	GST	2	3.05	6.10
335.58	5/8" UNC Stover Locknut	GST	8	0.67	5.36
Hours		GST	4	1.15	4.60
	Drivers side mirror head missing screw in bottom, installed new screw, had to shorten screw so it does not bottom out, tightened other screw.	GST	0.25	110.00	27.50
Hours	Air leak on brake application, applied brakes with	GST	3	110.00	
	root pedal, lound leak coming out of RH rear abe	usi	3	110.00	330.00
	modulator valve, Remove RH valve off of center valve, bolts seized, got them moving and worked				
	them back and forth to avoid breaking got old holte				
	out, clearled corrosion off of center valve ran tan				
	down holes on center valve to clean up mount threads for side valve, swap fittings over, found				
	customer had gotten LH valve instead of RH ran to				
	town and swapped out valve, installed valve, hook up air lines, test for leaks, no leaks at valve, now leak on #3 RH brake pot, check and clear abs codes in computer.				
Parts	Customer supplied ABS modulator valve	GST	1	0.00	0.00
074.516.31	2 5/16" x 3.5" UNC Hex Bolt	GST	1	0.60	0.00
422.516	5/16 Flat Washer	GST	2	0.50	0.60 0.30
444.516	5/16" Lock Washer	GST	1	0.10	0.10
074.516	5/16" Gr8 Hex Nut	GST	1	0.15	0.15
553.59001	Large Zip Ties	GST	3	0.40	1.20
553.55040		GST	2	0.25	0.50
Hours	Inspect air leak on #3 RH brake pot, only leaks above 80 psi application, leaking out diaphragm and clamp on service side of pot, clamped rod, aired up spring side to take pressure off of service side,	GST	0.50	110.00	55.00
	removed clamp, removed back half of brake pot.				
	cleaned diaphragm and pot, installed and made sure stayed in place as clamp was put on and tightened,				
	aired right up and made hard brake application, no more leaks on brake application				
Hours	Clevis Jam nut loose #3 RH brake pot, tightened, pots all new, checked all others, made sure good	GST	0.25	110.00	27.50
	and tight.				

Hours	Poor head of the Dill				
	Rear bracket for RH rear fender broken, cleaned up and v notched crack, protected air bag with old mud	GST	1	110.00	110.00
F0F 0000	flap, welded bracket, painted				
585.6336	3 inch 36 Grit Resin Fibre Surface Prep Disc	GST	1	4.50	4.50
Hours	Clip and washer missing for RH hood spring, no washers at rad on hood springs, installed washers at rad and washer and clip at hood	GST	0.25	110.00	27.50
Parts	Customer supplied clips	GST	1	0.00	0.00
422.58	5/8" Flat Washer	GST	3	0.67	2.01
Hours	Install LH hood latch on hood	GST	0.25	110.00	27.50
Parts	Customer supplied latch	GST	1	0.00	133763
Hours	Install stroke indicators on all 6 brake pot push rods.	GST	0.25	110.00	0.00
Parts	Customer supplied pushrod indicators	GST	1	0.00	27.50
Hours	Install Peterbilt mud flaps onto back of hood fenders, bolts all broken or seized, come in from backside between brace for flap and fender, brace is riveted into fender, not enough room to put in new bolts, drilled out brace and put pop nuts in it, drilled mud flaps and installed with new short stainless bolts	GST	1.50	110.00	0.00 165.00
Parts	Customer supplied mud flaps	GST	1	0.00	0.00
47350	1/4-20 Rivet Nut 27-165 Grip Range	GST	10	1.10	11.00
H18.8C14.1 FW18.8C14	W. W. Cramicos Offici Dolf	GST	10	0.28	2.80
LW18.8C14	The state of the s	GST	10	0.06	0.60
412.14.114	The state of the s	GST	10	0.10	1.00
Hours	William Street S	GST	10	0.20	2.00
Tiouis	ABS light came on, scanned for codes, LH front sensor open, found sensor wire had caught steer shaft, ripped wire apart and wrapped up on steer shaft, patched wire, heat shrink over patch, tied up so it wont catch, re adjusted brake hose so it wont hit steer shaft, or hood, turned tires all the way both ways while monitoring to be sure.	GST	1	110.00	110.00
555.5161	Pink Heat Shrink Butt Connector 22-18 Ga	GST	2	1.15	2.30
553.55040		GST	5	0.25	1.25
775.014	1/4" Black Heat Shrink Tube	GST	1	2.00	2.00
Hours	Discharge hose off of air compressor is wrong kind of hose, already starting to melt from heat, needs proper steel braid air compressor hose, removed old hose and installed proper hose, clamped to bracket on frame so it won't run steer shaft, clamped oil pressure line to bracket also.	GST	0.50	110.00	55.00
Parts	Customer supplied compressor discharge hose	GST	1	0.00	0.00
76-6332	1/2" Rubber Tube Clamp	GST	1	1.80	1.80
76-6334	3/4" Rubber Tube Clamp	GST	1	2.20	2.20
074.12.1	1/2" x 1" UNC Gr8 Hex Bolt	GST	1	0.43	0.43
074.14 410.014	1/4" Gr8 Hex Nut	GST	1	0.16	0.16
444.14	1/4" Flat Washer 1/4" Lock Washer	GST	2	0.12	0.24
444.14	I/T LUCK WASHER	GST	1	0.10	0.10

Hours	Cruise stopped working, scanned and found clutch switch not working, checked at switch under cab and found one wire in one plug pulled out of place, shorter than other wire, cut wires to same length, wires on new pins, re used plug, plugged in, all good.	GST	0.50	110.00	
557.14150	Male OEM Terminal 20-18Ga	GST	2	1.10	
557.14152	Green OEM Cable Plug 20-18Ga	GST	2	1.07	
Hours	Customer wants to change rear fenders, removed old stainless half fenders, removed all brackets off of frame, will plug holes with bolts once new fenders figured out and installed.	GST	1	110.00	
Hours	Inspect bunk and engine webasto heaters not working, power not hooked up to either heater. -Bunk webasto, found power and ground wires tucked up into bunk crossmember, pulled wires out, jumped power and ground to them, tried to run webasto, wouldn't fire, no intake or exhaust hose hooked up, intake hose tied to wires, blew air through intake and then back through exhaust, tried to fire again, still no fire, fed air into intake while trying to fire, got webasto to start, ran for a few hours to try and clean out, turned on next morning, fired no problem, ran for a couple hours, works very well, extended wires to reach battery box, put fuse on power side and hooked up wires, tied up wires, put intake hose back on and clamped on, installed hood used exhaust pipe and clamped on. -Engine webasto, found power and ground wires, jumped power to them, no power at timer, checked fuses at webasto, all good, checked plugs on top, one not plugged in good, removed and found all corroded in plug, one pin on circuit board corroded off, installed hood used circuit board, set up with good used harness and timer, ran wires to fuel pump, jumped power and ground to it, webasto fired right up, ran great and started heating coolant, left good used circuit board in place, removed old wiring harness from truck, installed brand new old style webasto wiring harness, ran wires to fuel pump, batteries, and into dash to timer, had to take dash and kick panels apart, tied wiring in place and hooked up, webasto not mounted, mounted with good used mounting clamp, had to run new line from filter to pump to reach mounting location. Note: need some screws for kick panels, was missing most of them Note: Webasto coolant lines are hooked up backwards, would be fighting engine water pump if both ran at same time, other coolant hoses need attention, 1 inch hose to rad is ran wrong and kinked over at rad, one hose is almost rubbing exhaust flex pipe, recommend adjusting fittings, will fix all at same time.	GST	10	110.00	

55.00

2.20 2.14 110.00

1,100.00

Parts	Customer supplied one fuse holder for bunk w	vebasto GST	1	0.00	0.00
Parts	2 (8) 2 (8) 7				
1 22 25	Webasto parts -New old style webasto wiring harness -good used engine webasto circuit board (can new, have to replace webasto) -good used fuel pump mount clamp -good used intake hose -good used exhaust hose -3 ft webasto fuel line -1 new webasto rubber fuel connector line -2 new webasto fuel line clamps	GST o't buy	1	500.00	500.00
47350	1/4-20 Rivet Nut 27-165 Grip Range	GST	1	1.10	1.10
074.14.1	1/4" x 1" UNC Gr8 Hex Bolt	GST	1	0.25	0.25
410.014	1/4" Flat Washer	GST	1	0.12	0.12
444.14	1/4" Lock Washer	GST	1	0.10	0.10
PHS-8	#8 Hose Clamp	GST	2	2.40	4.80
555.5162	Blue Heat Shrink Butt Connector 16-14 Ga	GST	4	1.50	6.00
555.5164	Yellow Heat Shrink Butt Connector 12-10 Ga	GST	2	1.55	3.10
555.5161	Pink Heat Shrink Butt Connector 22-18 Ga	GST	2	1.15	2.30
555.9174	Yellow Heat Shrink Butt Connector w/8mm Ri Terminal 12-10 Ga	ing GST	4	2.95	11.80
82-5502	2 Wire Coated Wire /ft	GST	6	0.75	4.50
555.90522	Blue Heat Shrink w/ 1/4" Female Spade Cont	nector GST	3	2.65	7.95
731.0201	20 Amp Mini Fuse	GST	1	0.75	0.75
074.516	5/16" Gr8 Hex Nut	GST	1	0.15	0.15
422.516	5/16 Flat Washer	GST	1	0.15	0.15
553.55040	Regular Zip Ties	GST	52	0.25	13.00
553.5900 1	Large Zip Ties	GST	12	0.40	4.80
		BTOTAL			5,207.25
		ST @ 5%			260.49
	TO	TAL			5,467.74

BALANCE DUE

\$5,467.74

1 - 6-5



Lethbridge 1001 41 ST. NORTH LETHBRIDGE, AB T1H 6J3 P:(403) 327-7611

BODYSHOP 5783 80TH AVE SE CALGARY, AB T2C4S6 (825) 257-5782

BILL TO
TORLEY'S UNLIMITED SALES - 12440
89 CANYONCREST POINT WEST/ILLA BILL
TETHBRIDGE, AB TIK 0B4

2000 Stelevit 379 Largue
W63" Michael

DELIVER TO TORLEY'S UNLIMITED SALES - 12440 89 CANYONCREST POINT WEST LETHBRIDGE AB T1K 0B4

PARTS INVOICE: X103024589:01

ESTIMATE: E103006979

DATE INVOICE	POSTED TIME	SHIP VIA	SALESPERSON	VIN	SALE TYPE	TERMS	PO#
2022-07-13	3:00:04PM	DELIVERY	3505		PRET	CASH	

QTY SHP	QTY B/O	ITEM	DESCRIPTION	BIN	UNIT PRICE	EXTD PRICE
3		103D/DDE 23509744	STUD BOLT	CAB16	16.20	48.60
12		103D/DDE 08929357	BOLT	C7	10.02	120.24
1		FRT	FREIGHT		25.00	25.00
3		103D/DDE 23539193	GASKET	W2A	11.91	35.73
		VIN; 06R0684626				30.70
1		103D/DDE 23513509	SEALANT GSKT	C7	30.76	30.76
1		103D/DDE 23533687	BOLT	CAB16	12.58	12.58
1		103D/DDE 05100532	PLATE	C7	16.63	16.63
12		103D/DDE 08929795	BOLT	C7	2.61	31.32
1		103D/DDE 23539104	GASKET	W2E	77.04	77.04
		TAKKEN			7.10.	

NEW WEST FREIGHTLINER

SALE

\$417.79 RRN 001348009 Card Type Acct # *******3327 Exp Date **/**
A0000000031010

++++++++++++++++++++++++ 001 APPROVED-THANK YOU ++++++++++++++++++++ Retain this copy for your records Customer copy



PARTS INVOICE: X103024589:01

ESTIMATE: E103006979

DATE INVOICE	POSTED TIME	SHIP VIA	SALESPERSON	VIN	SALE TYPE	TERMS	PO #
2022-07-13	3:00:04PM	DELIVERY	3505		PRET	CASH	

PICKED BY:	VERIFIED BY:
------------	--------------

Parts Invoice Disclaimer

No exchanges, credits or warranty claims without providing the original invoice at the time of the return. All special-order items will have a minimum 15% restocking charge and all-in stock items may be subject to a restocking charge. All returns are subject to an inspection to confirm it is in a scilable condition and in original packaging. Parts that have been installed, programmed or used for any testing purposes are not returnable. Cores must be returned in original packaging and are subject to the supplier's core acceptance guidelines. Cores must be returned within 90 days of original purchase date. Warranty replacements are to be paid in full, a credit will be issued upon an approved claim from the vendor. Electrical items and freight are non-returnable.

SUB-TOTAL	\$ 372.90
TAX	\$ 19.89
PREPAY	\$ 0.00
FREIGHT	\$ 25.00
TOTAL.	\$ 417.79

Please Remit Payment To; New West Freightliner Inc. 5925 79 Ave SE Calgary, AB T2C 5K3 GST#: 100731173



Tell Us How We Did!



Truck-Trailer Parts and Service www.fleetbrake.com

4005 9 Avenue North Lethbridge, AB T1H 6H6

PH: (403)327-2626 FAX: (403)327-0233 parts4@fleetbrake.com Invoice: 04P60138

Date / Time: 2/28/2023 12:06:54PM

Parts Order: 60138 Customer: 00104 Branch: FBP04 Invoice Total: \$ 347.73 *** Credit Card ***

Bill To: CASH CUSTOMER 4005 9 AVE N LETHBRIDGE, AB T1H 6H6

Moderin Blue
2000 Peterbett 379 hongruse W/63" medrise sleeper
Ship To:TORLEY'S UNLIMITED SALES
403-588-4309

Customer P/O

Invoiced By: varneson

Delivery Method: Customer Pickup

Territory: 1

Part / Misc Description / Ref Number 4006110210 Ext U/M MOD VALVE KIT Quantity Price Price S-100 BRAKE MATE FOR 5/8 PUSHROD EA \$324.57 \$324.57 EA 6 \$1.10 \$6.60

TNOOWY

8 8

GST/HST Number:

101819472

Detail Tax Info:

GST

\$16.56 Total: \$16.56

> Invoice Subtotal: **Total Tax:**

Invoice Total:

\$331.17 \$16.56 \$347.73

Payment Method: Credit Card

Payment Terms: COD

Due Date: 03/01/2023

Remit To: -

Fleet Brake Parts & Service - Lethbridge 7843 54th STREET SE

CALGARY, AB T2C 4R7

Any warranties on the product sold hereby are those made by the manufacturer. Payment is Net 30 Days. Service Charge of 2% per month will be charged for all overdue accounts. No good accepted for credit unless approved by a Fleet Brake representative. No returns on special order parts. A restocking charge of

Payment Guaranteed by,	
Signature:	_



Lethbridge 1001 41 ST. NORTH LETHBRIDGE, AB T1H 6J3 P:(403) 327-7611

BODYSHOP 5783 80TH AVE SE CALGARY, AB T2C4S6 (825) 257-5782

BILL TO

TORLEY'S UNLIMITED SALES - 12440 89 CANYONCREST POINT WEST LETHBRIDGE, AB T1K 0B4

P:

SIGNATURE X

DELIVER TO

TORLEY'S UNLIMITED SALES - 12440 89 CANYONCREST POINT WEST

Due 2000 Peterbett 379 hongrosse W/63 4 midrise sleeper

PARTS INVOICE: X103034820:01

DATE INVOICE	POSTED TIME	SHIP VIA	SALESPERSON	VIN	SALE TYPE	TERMS	PO#
2/9/2023	5:53:00PM	DELIVERY	3504		PRET	CASH	

QTY SHP	QTY B/O	ITEM .	DESCRIPTION	BIN	UNIT PRICE	EXTD PRICE
1		103D/A06-26631-000	SOLENOID VALVE-AIR/ELEC	C11	132.60	132.60

NEW WEST FREIGHTLINER 1001/41st St NORTH TH6J3 LETHBANGE AB 2149040901	SALE	17:53:53 HF Card Type VI	RRN 001528011	\$139.23	\$139.23	APPROVED-THANK YOU	y for your Is copy	
NEW WEST FR 1,000-478T ST NC TETHERNOGE 2149040 QB214904	o,	02-09-2023 Acct # ********5434 Exp Date **/** C 6000000031010 VISA CREDIT	Trace # 100011 Inv. # 34820 Auth # 006170	Sale	TOTAL	######################################	Retain this copy records Customer c	

No exchanges, credits or warranty claims without providing the original invoice at unc minimum 15% restocking charge and all-in stock items may be subject to a restocking charge. All returns are subject to a in a sellable condition and in original packaging. Parts that have been installed, programmed or used for any testing purposes are not returnable. Cores must be returned in original packaging and are subject to the supplier's core acceptance guidelines. Cores must be returned within 90 days of original purchase date. Warranty replacements are to be paid in full, a credit will be issued upon an approved claim from the vendor. Electrical items and freight are non-returnable.

SUB-TOTAL \$ 132.60 TAX \$ 6.63 PREPAY \$ 0.00 **FREIGHT** \$ 0.00 TOTAL \$ 139.23

Please Remit Payment To: New West Freightliner Inc. 5925 79 Ave SE Calgary, AB T2C 5K3 GST#: 100731173



nto a draw for a \$100.00 Parts or Service credit



Truck-Trailer Parts and Service www.fleetbrake.com

4005 9 Avenue North Lethbridge, AB T1H 6H6

PH: (403)327-2626 FAX: (403)327-0233 parts4@fleetbrake.com

Blue 2000 Pc

Invoice: 04P59164

Date / Time: 2/15/2023 1:03:17PM

Parts Order: 59164 Customer: 00104 Branch: FBP04 Invoice Total: \$ 282.90 *** Credit Card ***

Page 1 of 1

Bill To: CASH CUSTOMER 4005 9 AVE N LETHBRIDGE, AB T1H 6H6 Ship To: TORLEY'S UNLIMITED SALES GET PHONE NUMBER. LOCAL, AB

Delivery Method: Customer Pickup

Territory: 1 Ext Price Price Quantity U/M Description / Ref Number Part / Misc \$188.83 \$188.83 EA AIR BAG 1R12-568 \$80.60 \$80.60 1 FA CRIMPED ASSEMBLY HT10C48FS10FS10

Invoiced By: varneson

+ 1 from span 188,83

SALE

Customer P/O:

00000018

AMOUNT

8

GST

\$13.47 \$13.47 Total:

\$269.43 Invoice Subtotal: \$13.47 **Total Tax:** Invoice Total: \$282.90

Payment Method: Payment Terms: Credit Card COD

Due Date: 02/16/2023

Remit To: -

Fleet Brake Parts & Service - Lethbridge 7843 54th STREET SE CALGARY, AB T2C 4R7

Any warranties on the product sold hereby are those made by the manufacturer. Payment is Net 30 Days. Service Charge of 2% per month will be charged for all overdue accounts. No good accepted for credit unless approved by a Fleet Brake representative. No returns on special order parts. A restocking charge of 15% or greater applies to all returned goods.

Payment Guaranteed b	y,	
0'	0.00	



Truck-Trailer
Parts and Service
www.fleetbrake.com

4005 9 Avenue North Lethbridge, AB T1H 6H6

PH: (403)327-2626

FAX: (403)327-0233

parts4@fleetbrake.com

Invoice: 04P60569

Date / Time: 3/4/2023 10:28:12AM

Parts Order: 60569 Customer: 00104

Branch: FBP04
Invoice Total: (\$340.80)

*** Credit Card ***

Page 1 of 1

Madien, Blue

2000 Petay but 379 horgane W/6311 Midnise sleeper
Ship To:TORLEY'S UNLIMITE

Bill To: CASH CUSTOMER 4005 9 AVE N LETHBRIDGE, AB T1H 6H6

Customer P/O:M/C CREDIT

588-4309 LETH, AB

Delivery Method: Customer Pickup

 Part / Misc
 Description / Ref Number
 U/M
 Quantity
 Price
 Ext

 4006110210
 MOD VALVE KIT
 EA
 -1
 \$324.57
 \$-324.57

Invoiced By: whoeksema

GST/HST Number: 101819472 Detail Tax Info:

GST

\$(16.23) Total: \$(16.23)

Invoice Subtotal: \$(324.57)

Total Tax: \$(16.23)

Invoice Total: \$(340.80)

Payment Method; Payment Terms:
Credit Card COD
Remit To:

Fleet Brake Parts & Service - Lethbridge 7843 54th STREET SE

7843 54th STREET SE CALGARY, AB T2C 4R7

Any warranties on the product sold hereby are those made by the manufacturer. Payment is Net 30 Days. Service Charge of 2% per month will be charged for all overdue accounts. No good accepted for credit unless approved by a Fleet Brake representative. No returns on special order parts. A restocking charge of 15% or greater applies to all returned goods.

Due Date:

03/05/2023

Payment Guaranteed	by,
Cianatura	

CALGARY PETERBILT LTD.

Phone: (403) 235-2550 · Fax: (403) 235-1322

PETERBILT RED DEER

PETERBILT MEDICINE HAT

Phone: (403) 342-5100 · Fax (403) 342-5153 Phone: (403) 526-4460 · Fax: (403) 525-5299



PETERBILT LETHBRIDGE

4110 - 18th Avenue North Lethbridge, AB. TIH 6N7

Tel: 403-328-0500

Fax: 403-328-0225 Toll-Free: 1-888-777-3112

\$ 0	TORLI		COUN UNLI	T NO	D SA	OR 2 OR 03 LES CE		INVOICE DA	ATE AR Udd	23 wn	INVOID NUMB	H 379	936L PAGE 1 OF 1 hurgnose i	unit# w/63 ⁴ muluīosl
LETHBRIDG AVENUE 1	AB. T1H 6N7 8-0600	MF0 MC		R -FG	Proximity **/**	\$39.42	APPROVED	DESCRIPT LAP-FE		сору	LPRK	NET 37.54	LETHBRIDGE AMOUNT 37.54	ALBT ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 20% RE-STOCK CHARGE ON ALL RETURNED PARTS. Thank Your Jou Jou Jou Jou Jou Jou Jou
PE [†] EŘBILT 440 18TH	LETHBRIDGE 403-3	S \	Batch #: 135	#: 314 CODE:	Trace: 30 MASTERCARD ********4022	AMOUNT	APP	Mastercard AID: A0000000041010 TVR: 00 00 00 80	THANK Y	CUSTOMER	XTOTAL		37.54 0.00 1.88 \$39.42	Your Business!

PETERBILT LETHBRIDGE 4110 18TH AVENUE NE LE HBRIDGT AB. TIH 6N. 403-328-0600

:RBILT LTD. ax: (403) 235-1322

DATE SHIPPED

:18:13

50

21 FEB 23

ETERBILT MEDICINE HAT

'hone: (403) 526-4460 · Fax: (403) 525-5299



PETERBILT LETHBRIDGE

4110 - 18th Avenue North Lethbridge, AB. TIH 6N7 Tel: 403-328-0500 Fax: 403-328-0225

Toll-Free: 1-888-777-3112

LETHBRIDGE ALBT

351.96 6.42 30.82 67.61 105.00 15.00 25.00

AMOUNT

SALE

Batcl #: 127

02/21/23

Trace: 25 MASTERCARD

TSI: E8 00

**********4022

REF#: 00000025

15:17:40

TED SALES LTD NT PLACE T1K 0B4

INVOICE DATE

TERMS

SEAL-TRIM BUL RING-RETAININ HOOK-HOOD HOL SEAL-DOOR SEC SEAL-DOOR SEC

CHARGE

CASH

21 FEB

2C3 DR5F V17A 1D5 1D5

CUST

INVOICE NUMBER 314194L

F.O.B.

NET

175.98 3.21 30.82 67.61 105.00 15.00 25.00

UNIT#

NO. 910803 Kongroe W/634 P MIBRIE PUNK Ó

AMOUNT \$631.90 **APPROVED** Mastercard AID: A000000041010 TVR: 00 00 00 80 00

+ 194L APPR CODE: 02219Z

THANK YOU / MERCI

CUSTOMER COPY equired on Core returns to receive

rvice. Call our details!!

PARTS SUBLET FREIGHT 601.81 0.00

Thank You For Your Business

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS.

SALES TAX 30.09 TOTAL

GST NO. R100731918

Cat Electronic Technician 2015A v1.0 **Trip Segment - Fleet**

4/20/2023 2:48 PM

Comments: Modern Blue Peterbult 379 Longrase W/634 midises lapor

Torleys 2000 Pete

3406E Truck (2ws39907)	
Parameter	Value
Vehicle ID	527711D
Engine Serial Number	2ws39907
ECM Serial Number	31190348KA
	2707085-00
Personality Module Part Number	MAY05
Personality Module Release Date	41
Personality Module Code	4/20/2023 3:13:38 AM
ECM Date/Time	7/20/2023 3:23:35 1 11

Description	Value	Unit
Time	33391:51	hours
Driving Time	21993:21	hours
Distance	2125181.0	Miles
Fuel	356028.8	gal
Overall Fuel Economy	5.97	MPG
Driving Fuel Economy	6.12	MPG
Idle Time	11398:30	hours
Idle Fuel	8496.9	gal
% Idle Time	34	%
PTO Time	0:00	hours
PTO Fuel	0.0	gal
% PTO Time	0	%
Avg Load Factor	34	%
Avg Vehicle Speed	63.6	mph
Avg Driving Speed	96.6	mph
Max Vehicle Speed	100	mph
Max Engine Speed	2878	rpm
Start Time	0:00	hours

file:///C:/ProgramData/Caterpillar/Electronic%20Technician/temp/STPLReport3.HTM

End Time	33391:50	hours
Start Odometer	0.0	Miles
End Odometer	2125180.9	Miles

Cat Electronic Technician 2015A v1.0 Configuration

4/20/2023 2:49 PM

Comments: Medium Blue Feterbilt 379 hargnue w/63 "michine plager

Torleys 2000 Pete

3406E Truck (2ws39907)	
Parameter	Value
Vehicle ID	527711D
Engine Serial Number	2ws39907
ECM Serial Number	31190348KA
Personality Module Part Number	2707085-00
Personality Module Release Date	MAY05
Personality Module Code	41
ECM Date/Time	4/20/2023 3:14:41 AM

Description	Value	П
Selected Engine Rating		
Rating Number	1	1
Rating Type	Standard	
Multi-Torque Ratio	Unavailable	0
Advertised Power	550 hp	
Governed Speed	2 100 rpm	
Rated Peak Torque	1850 lb-ft @ 1200 rpm	
Top Engine Speed Range	1600 - 2120 rpm	
Test Spec	0K1014-00	
Test Spec with BrakeSaver		_
ECM Identification Parameters		_ _
Vehicle ID	52 7711D	
Engine Serial Number	2ws39907	
ECM Serial Number	31190348KA	
Personality Module Part Number	2707085-00	
Personality Module Release Date	MAY05	
Security Access Parameters		
Total Tattletale	96	

file:///C:/ProgramData/Caterpillar/Electronic%20Technician/temp/STPLReport4.HTM

ast Tool to change Customer Parameters	ET000911	
ast Tool to change System Parameters	ET000911	
CM Wireless Communications Enable	No	0
/ehicle Speed Parameters		
/ehicle Speed Calibration	29390 P/mile	3
Vehicle Speed Cal (J1939-Trans)	Unavailable	
Vehicle Speed Cal (J1939-ABS)	Unavailable	
Vehicle Speed Limit	81 mph	5
VSL Protection	2099 rpm	3
Tachometer Calibration	113.0 PPR	0
Soft Vehicle Speed Limit	No	0
Two Speed Axle - Low Speed Range Axle Ratio	Unavailable	
Nominal Axle Ratio - High Speed Range Axle Ratio	Unavailable	
Cruise Control Parameters	Origination	\dashv
Low Cruise Control Speed Set Limit	20 mph	3
High Cruise Control Speed Set Limit	78 mph	5
Engine Retarder Mode	Latch	3
Engine Retarder Minimum VSL Type	Hard Limit	0
Engine Retarder Minimum Vehicle Speed	0 mph	0
Auto Retarder in Cruise (0 = Off)	2 mph	4
Auto Retarder in Cruise Increment	0 mph	5
Cruise/Idle/PTO Switch Configuration	Set/Accel-Res/Decel	0
SoftCruise Control	No	1
Adaptive Cruise Control Enable	Disabled	0
Idle Parameters (Old PTO)		
Idle Vehicle Speed Limit	1 mph	
Idle RPM Limit	1500 rpm	
Idle/PTO RPM Ramp Rate	150 rpm/s	
Idle/PTO Bump RPM	100 rpm	
Dedicated PTO Parameters		
PTO Configuration	Off	
PTO Top Engine Limit	Unavailable	
PTO Engine RPM Set Speed (0 = Off)	Unavailable	
PTO Engine RPM Set Speed A (0 = Off)	Unavailable	
PTO Engine RPM Set Speed B (0 = Off)	Unavailable	
PTO to Set Speed	Unavailable	
Maximum PTO Enable Speed	Unavailable	
PTO Cab Controls RPM Limit	Unavailable	

file: ///C: / Program Data / Caterpillar / Electronic % 20 Technician / temp / STPL Report 4. HTM

O Kickout Vehicle Speed Limit	Unavailable	
ax PTO Vehicle Speed	Unavailable	
orque Limit	Unavailable	
TO Shutdown Time (0 = Off)	Unavailable	
TO Shutdown Timer Maximum RPM	Unavailable	
TO Activates Cooling Fan	Unavailable	
ingine/Gear Parameters		
ower Gears Engine RPM Limit	2120 rpm	0
ower Gears Turn Off Speed	3 mph	0
Intermediate Gears Engine RPM Limit	2120 rpm	0
Intermediate Gears Turn Off Speed	5 mph	0
Gear Down Protection RPM Limit	2120 rpm	0
Gear Down Protection Turn On Speed	127 mph	0
Top Engine Limit	2120 rpm	0
Top Engine Limit with Droop	No	0
Low Idle Engine RPM	700 rpm	1
Transmission Style	Manual Option 1	0
Eaton Top 2 Override with Cruise Switch	Unavailable	
Top Gear Ratio	0.730	1
Top Gear Minus One Ratio	0.000	0
Top Gear Minus Two Ratio	0.000	0
Governor Type	Full Range	0
Timer Parameters		
Idle Shutdown Time (0 = Off)	0 min	0
Idle Shutdown Timer Maximum RPM	2120 rpm	0
Allow Idle Shutdown Override	Yes	0
Minimum Idle Shutdown Outside Temperature	Not Installed	
Maximum Idle Shutdown Outside Temperature	Not Installed	
A/C Switch Fan On-Time (0 = Off)	1 sec	3
Fan with Engine Retarder in High Mode	No	0
Engine Retarder Delay	0.0 sec	0
Smart Idle Parameters		
Battery Monitor and Engine Control Voltage	0.0 Volts	
Engine Monitoring Parameters		
Engine Monitoring Mode	Warning	
Engine Monitoring Lamps	Warning Lamp	
Coolant Level Sensor	No	
Maintenance Parameters		

file:///C:/ProgramData/Caterpillar/Electronic%20Technician/temp/STPLReport4.HTM

aintenance Indicator Mode	Off	0
M1 Interval	0 Miles	0
ngine Oil Capacity	40 quarts	0
rip Parameters		
Fuel Correction Factor	0 %	0
Dash - Change Fuel Correction Factor	No	0
Dash - PM1 Reset	No	0
Dash - Fleet Trip Reset	No	0
Dash - State Selection	Yes	0
Theft Deterrent System Control	No	0
Theft Deterrent Password	***	15 1
Quick Stop Rate	10 mph/s	3
Vehicle Activity Report Parameters		
Minimum Idle Time (0 = Off)	0 min	0
Driver Reward		
Driver Reward Enable	Enabled	0
Input Selections		
Fan Override Switch	J1/P1:46	3
Ignore Brake/Clutch Switch	Unavailable	
Torque Limit Switch	Unavailable	
Diagnostic Enable Switch	None	0
PTO On/Off Switch	Unavailable	
Remote PTO Set Switch	Unavailable	
Remote PTO Resume Switch	Unavailable	
PTO Engine RPM Set Speed Input A	Unavailable	
PTO Engine RPM Set Speed Input B	Unavailable	0
Starting Aid On/Off Switch	None	0
Two Speed Axle Switch	None None	2
Cruise Control On/Off Switch	J1/P1:59	
Cruise Control Set/Resume/Accel/Decel Switch)1/P1:35 & 44	ir
Cruise Control Pause Switch	None	
Clutch Pedal Position Switch	J1/P1:22 J1/P1:23 & 40	
Retarder Off/Low/Med/High Switch		
Service Brake Pedal Position Switch #1	J1/P1:45 J1/P1:66	
Accelerator Pedal Position	J1/P1:32 & 33	
Vehicle Speed Input	J1/F1.32 & 33	
Output Selections	None	
Engine Running Output	NOTE	

file:///C:/ProgramData/Caterpillar/Electronic%20Technician/temp/STPLReport4.HTM

4/20/2023

Engine Shutdown Output	None	0
Auxiliary Brake	None	0
Starting Aid Output	None	0
Fan Control Type	On-Off	1
PTO Active Output	Unavailable	
Passwords		
Customer Password #1	*****	
Customer Password #2	*****	_
Data Link Parameters	_	
Powertrain Data Link	J1922 & J1939	3
System Settings		
Personality Module Code	41	2
FLS	4	3
FTS	0	3



RUCK CENTRES

LETHBRIDGE

41109 Ave N Lethbridge, AB

LETHBRIDGE

403-317-2450

1-888-345-3036

T1H6L9

www.dunloptrucks.com

MV# 0

BE BILLED OUT YET

Invoice: 0202S218041.02

Date / Hour: 3/17/2023 4:51:37PM

Repair Order: 218041 Customer: 00100

Branch: 2

Total Invoice: \$ 2,869.42

COD

Page 2 of 3

Bill To:

1284194 ALBERTA LTD.

89 CANYONCREST POINT WEST

LETHBRIDGE, AB T1K 0B4

Ship To: 1284194 ALBERTA LTD.

89 CANYONCREST POINT WEST

LETHBRIDGE, AB T1K 0B4

Office Phone: 403-588-4309

Work: 403-588-4309

Customer P/O:

Open Date: 02/10/2023

Completion Date: 03/09/2023

Department: Bodyshop

Salesperson:

U/M

Task 4 Subtotals

Add User: rainscough

95-100002.01 Salvage Body Inspection Task: 4

Complaint: Body portion of salvage inspection.

Correction: 2/13/2023 2:28:42 PM 1449 1. Inspected truck. Fails for following reasons.

8.1- Missing clip and washer that holds hood spring to hood.

- Missing hood catch.

- Missing rear mudflaps on hood. 8.6 - Cab mounts worn out.

- Bolts missing in crossmember.

8.8 - Left and right door seals worn out and need replacing.

8.18 - Driver side mirror head missing screw.

8.21 - Rigth rear quarter fender bracket broken.

Description / Ref Number Supp. Part

Quantity Parts: \$248.93 Labor

Department: Service

Task 4 Subtotals

\$248.93

Price

Extended

\$0.00

Price

47-100016.01 CVIP Reinspection

Complaint: REINSPECTION Correction: 3/9/2023 10:49:05 AM 1305 Filled out salvage inspection on efacility. Printed copy and signed.

Description / Ref Number Part Task 5 Subtotals

Quantity Parts:

Extended Price Price \$0.00

\$200.00

\$200.00

\$178.29

Labor Task 5 Subtotals

Customer Tax ID:

104593520

GST/HST Number: 898710827RT0001

Detail Tax Info:

Alberta GST #

\$136.64 \$136.64 Total

Total Labor: Total SHOP SUPPLIES: \$2,302.22 \$252.27

Invoice Subtotal: **Total Tax:**

Total Parts:

\$2,732.78 \$136.64

Total Invoice:

\$2,869.42

Payment Method ***COD****

DUE ON RECEIPT - INTEREST4/15/2023 @ 2% PER MO. THEREAFTER

Daid Man 1/200



TRUCK CENTRES

LETHBRIDGE

LETHBRIDGE

403-317-2450

1-888-345-3036

41109 Ave N Lethbridge, AB

www.dunloptrucks.com

MV# 0

T1H6L9

COD Page 1 of 3

Invoice: 0202S218041.02

Date / Hour: 3/17/2023 4:51:37PM

Repair Order: 218041 Customer: 00100

Branch: 2

Total Invoice: \$ 2,869.42

Bill To:

1284194 ALBERTA LTD.

89 CANYONCREST POINT WEST LETHBRIDGE, AB T1K 0B4

Ship To: 1284194 ALBERTA LTD.

89 CANYONCREST POINT WEST LETHBRIDGE, AB T1K 0B4 Office Phone: 403-588-4309

Department: Service

Work: 403-588-4309

Customer P/O:

Open Date: 02/10/2023

Salesperson:

Completion Date: 03/09/2023

Add User: rainscough

Model Year: 2000

Make/Model: Peterbilt 379

Type: Heavy Truck

Unit Number: 1

VIN: 1XP5DB9XOYN549426

Meter: 81478 Kilometers

94-100001.01 Salvage CVIP Task: 1

Complaint: Mechanical portion of salvage inspection.

Correction: 2/11/2023 5:26:48 PM 1330 meassured tire preassure and depth, helped calvin meassure brake stroke, lifted front of truck up and set on jack stands

2/11/2023 5:27:12 PM 1305 Brought truck into shop and started salvage inspection.

2/13/2023 9:18:45 AM 1305 Performed mechanical portion of salvage inspection on truck. Noted findings on paper copy and filled

2/13/2023 9:20:12 AM 1333 Started by putting the truck on jack stands once that was done i removed all the wheels and brake drums for inspection. I then helped messure brake componants, once this was done I put the wheels back on except for the front rear axle incase the customer wants us to replace the failed air bags, the wheels were NOT torqued and the brake were NOT adjusted yet 2/13/2023 3:22:25 PM 1305 Completed filling out inspection on efacility, failed truck, printed 2 copies.

2/14/2023 9:46:48 AM 1305 Reinstalled #2 axle wheels. Aired up truck, adjusted brakes, lift axles, and removed stands. Set on floor and torqued wheels to 470ft/lbs. Installed torque tag in cab.

2/14/2023 9:54:38 AM 1330 put on 2nd axle wheels and torqued and oiled all wheels to 475, adjusted all brakes correctly, set truck down, wrote as retorque tag, parked truck outside

Supp. Part Description / Ref Number

UM

Task 1 Subtotals

Task 2 Subtotals

Quantity Parts: Labor: Price Price \$0.00 \$1,066.64

Extended

Task 1 Subtotals

\$1,066.64

Extended

Extended

Price

Price

95-100001.01 Salvage Frame Inspection

Task: Complaint: Set up and gauge frame as part of salvage inspection. FRAME INSPECTED AND REPAIRED ON INVOICE 215644

Supp. Part Description / Ref Number

Quantity

11/8/

Department: Service

Price Price Quantity UM \$0.00 Parts: \$0.00 Labor: \$0.00 Task 2 Subtotals

Department: Service

93-100001.01 Salvage Alignment Task:

Complaint: Wheel alignment, set ride height as part of salvage inspection.

Correction: 2/25/2023 3:58:25 PM 1324 check tire pressures ride height and components for wear or damage, mount and calibrate sensors, measure angles, adjust scrub, caster, total toe, and straighten steering weel, still need to change u-bolts, as can't be reused.

2/27/2023 9:44:12 AM 1336 - removed old u-bolts


- installed new u-bolts

- torqued u-bolts to 350Ft/Lbs

	n : i / Def Number	UNIVI	~~~	41 111114 - 11	
Supp. Part	Description / Ref Number		1.0	\$3.81	\$3.81
AV SPRGDN34	3/4 DEEP NUT		1.0	27/2/2015/201	34465567
AV SPRODITOR	OU EL AT MACHED		8.0	\$3.20	\$25.60
AV SPRGFW34	3/4 FLAT WASHER			\$37.22	\$148.88
	3/4 U-BOLT		4.0	Ψ31.ZZ	\$140.00
SPRGUB3422	J . • -	Task 3 Subtotals	Parts:		\$178.29
		idon o dans	Labor.		\$786.65
			Task 3 Subtotals		\$964.94

^{**} See Last Page for Invoice Total





1-888-345-3036

LETHBRIDGE

41109 Ave N Lethbridge, AB T1H6L9

www.dunloptrucks.com

MV# 0

Bill To:

1284194 ALBERTA LTD.

LETHBRIDGE

89 CANYONCREST POINT WEST LETHBRIDGE, AB T1K 0B4

Ship To: 1284194 ALBERTA LTD.

89 CANYONCREST POINT WEST LETHBRIDGE, AB T1K 0B4 Office Phone: 403-588-4309

Work: 403-588-4309

Customer P/O:

Add User, rainscough

Open Date: 02/10/2023

Completion Date: 03/09/2023

Invoice: 0202S218041.02

Date / Hour: 3/17/2023 4:51:37PM

Repair Order: 218041 Customer: 00100

Branch: 2

Total Invoice: \$ 2,869.42

COD

Page 3 of 3

Salesperson:

TERMS: DUE ON RECEIPT, INTEREST AT 2% PER MONTH(24% ANNUM) CHARGED ON OVERDUE ACCOUNTS.

NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 15% RE-STOCK CHARGE ON ALL RETURNED PARTS.

DISCLAIMER OF WARRANTIES: ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY THE MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED. INCLUDING ANY IMPLIED WARRANTY OR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND ROCKY MOUNTAIN DIESEL, LTD. NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE SAID PRODUCTS.

NOTE: ANY DISCREPANCY REGARDING REPAIRS, MUST BE REPORTED WITHIN 30 DAYS OF THE SAME, FOR ANY CONSIDERATION. CUSTOMER MUST PRESENT A COPY OF THE ORIGINAL REPAIR ORDER INVOICE

	DATE:
Signature:	





80083100002108912

CERTIFICATE NUMBER

Salvage Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Typ	e:	Truck			Seating	Capa	city	:					
GVW:					Brake Type:				Air				
Owner Nam	e:	1284194	Alberta	LTD									
Address: 89 Canyoncrest Point West													
City:	Let	hbridge		Pro	vince: AB					Posta	l Code:	T1K	0B4
Telephone	Nun	ber:	(403) 588	8-4309									
Vehicle Ide	ntifi	cation Nu	mber:	1	XP5DB9>	KOYN5	4942	26					
Make:		Peterbilt				41	Mod	del:	Conven	tional	-		1 12
Year:		2000				Unit Nun			mber:		124		
Odometer:		81518 KM		Licence	e Plate Nu	Plate Number:			: E86212			e: -	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Salvage Vehicle.

Structural Facility Name:	Facility Number:						
Dunlop Western Star Truck Centre Ltd.	13094						
Structural Technician Name:	Technician Number:						
Bryce Schrage	B8076						
Structural Technician Signature	Inspection Date 2023/03/09						
Mechanical Facility Name:	Facility Number:						
Dunlop Western Star Truck Centre Ltd.	13094						
Mechanical Technician Name:	Technician Number:						
Calvin Holthe	C7656						
Mechanical Technician Signature Cal Hoh	Inspection Date 2023/03/09						

NOTICE TO VEHICLE OWNER

- This inspection certificate expires after 14 days from the Inspection date. After 14 days, a complete re-inspection of the vehicle is required.
- 2. The original of this Certificate must be presented to an Alberta Registry Agent within 14 days; however, there is no requirement to register the vehicle when the certificate is presented.





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Typ	e:	Truck			Seating							
GVW:					Brake Type:							
Owner Nan	ne:	128419	4 Alberta LT	D								
Address: 89 Canyoncrest Point West												
City:	Let	hbridge		Prov	vince:	vince: AB Postal Co					T1K)B4
Telephone	Num	ber:	(403) 588-4	1309								
Vehicle Ide	entific	cation Nu	mber:	1	1XP5DB9X0YN549426							
Make:		Peterbilt					Model:	Conver	ntional			
Year:	3	2000	140		Unit Number: 124				124			
Odometer:		81518 KN	л <u> </u> [icence	e Plate Number: E8			E86212			e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	_ 1 3 + 2 = 2	Facility Number:				
Dunlop Western Star Truck Centre L	.td.	13094				
Inspection Technician Name:		Technician Number:				
Calvin Holthe		C7656				
Inspection Technician Signature:		Coh Hoh				
Inspection Date:	2023/03/09	,,				



The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

icle Inf			n participation	_			Δ	X	0	Y	N	5	4	9	4	2	(
1	X	F)	5	D	В	9	X	U	1							
Init Nur	mber	1		Year			Ma	ke			Mod					ometer	
712		-		000			Peter	bilt			Conve	ntional			81	,518	
12	24					gistered	Owner	r'e Name							Plate	Number	-
															E86	212	
						1284194	Albert	a LID				Postal	Codo		Pho	one Nun	ber
					Addres							T1K((403) 588-4	309
			89	Canyo	ncrest	Point V	Vest					1 11.55					
Dru	m Brake	es:	A-Ful	l Inspec	ction with	h Drum R	emoved		Disc	Brakes:							
						LEFT		FF	RONT		RIGH	<u> </u>					
				Г		15.035	in		s/Rotors		15.03	35 in		92	psi		
		95	_			0.62	in	Linin	gs/Pads		0.5			19/32 i			
		13/32	in			1 1/2	in	Push l	Rod Trave	el	11	/2 in					
95	psi	92	psi	Γ.		16.515	in		s/Rotors		16.54 0.8			95	psi	92 ps	i)
17/32	· ·	15/32	· 1			0.80	in		gs/Pads	-	17/			17/32 i	in	19/32 in	
				_		1 3/4	in	Pusn	Rod Trave								
_				Г		16.510	in	Drum	s/Rotors		16.53	30 in		92 ,		90 ps	1
50) psi	95	psi	1		0.79	in	Linin	gs/Pads		0.8			15/32 i		15/32 in	
19/32	2 in	16/32	in	_		1 7/16	in	Push F	Rod Trave	<u> </u>	13	3/8 in		15/52)
2				_			in	Deue	ns/Rotors			in					\
	psi		psi	-			in		ngs/Pads		-	in		'	psi Y	psi	
	in		in	-			in		Rod Trave	al		in		<u> </u>	in	in)
									- ID - A			in	_				
	psi		psi	-			in in		s/Rotors gs/Pads	.===		— in		p	si 🏻	psi	
	in		in				. ''' in		Rod Trave			— in		1	n 🗼	in	
_		_	\neg	_													
			$\overline{}$			_	in	Drum	s/Rotors			_ in			osi	psi)
	psi		psi _				in	Linin	gs/Pads	-		in			n	— ir	
\subseteq	in	'	in	L <u>-</u>			in	Push F	Rod Trave	el		in					
				Park I	Brake Lii	ning L	eft n/	a in	Right	<u>n/a</u> in	Trans	n/a	in				
						ue Check				ft lbs O	513015		t lbs				
						10.00	Se	ection 1		Train			(ma.)		apre de la	E	
	l ib		mpon					PFN	Commence of the Commence of th	naine Ct		Compone	ent			P	F
. Accelera			tie Act	uator				1			art Safety tion Indica					1	

	l n	-	NA	Component	P	FA
Component	P	9.4	All and the second	The state of the s	1	
.3. Emission Control Systems and Devices .4. Drive Shaft	1		-	1.10. Engine or Accessory Drive Belt 1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System	/	7
1.5. Clutch and Clutch Pedal 1.6. Engine/Transmission Mount	1			1.12. Gasoline or Diesel Fuel System 1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*	4	-

NOTES:

· · · · · · · · · · · · · · · · · · ·	-	APPEN	ND	IX "A"		INVA
Component	P			Component	P	FNA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System		4	/	A.3. Liquefied Natural Gas (LNG) Fuel System		
A.2. Compressed Natural Gas (CNG) Fuel System		V				

NOTES:

	Secti	on	2 - S	uspension		
Component	P	F	NA	Component	P	F NA
2.1. Suspension & Frame Attachments	/	glomato.	Section 1991	2.5. Air Suspension	1	
2.2. Axle Attaching & Tracking Components	1			2.6. Self-Steer and Controlled-Steer Axle	1	
2.3. Axle & Axle Assembly	1			2.7. Shock Absorber/Strut Assembly	1	_
2.4. Spring & Spring Attachment	1					

NOTES:

2.5: Axle#2 both air bags showing cords. (Replaced)

Section 3H - Hydraulic Brakes									
Component	P	F	NA	Component	P	F	NA		
3H.1. Hydraulic System Components			1	3H.13. Disc Brake System Components			1		
3H.2. Brake Pedal/Actuator			1	3H.14. Mechanical Parking Brake			1		
3H.3. Vacuum Assist (Boost) System			1	3H.15. Spring-Applied Air-Released Parking Brake			1		
3H.4. Hydraulic Assist (Boost) System			1	3H.16, Spring-Applied Hydraulic-Released Parking Brake			1		
3H.5, Air Assist (Boost) System			1	3H.17. Anti-Lock Brake System (ABS)			1		
3H.6. Air-Over-Hydraulic Brake System			1	3H.18. Stability Control System			1		
3H.11. Brake System Indicator Lamps			1	3H.19. Brake Performance			1		
3H.12. Drum Brake System Components			1						

NOTES:

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.1. Air Compressor	1			3A.13. Air System Components	1			
3A.2. Air Supply System	1			3A.14. Brake Chamber	1			
3A.4. Air Tank	1			3A.15. Drum Brake System Components	1			
3A.5. Air Tank Check Valves	1			3A.16. S-Cam Drum Brake System	1			
3A.6. Brake Pedal/Actuator	1			3A.17. Brake Shoe Travel (Wedge Brakes)			1	
3A.7. Treadle Valve and Trailer Hand Valve	1			3A.18. Disc Brake System Components			1	
3A.8. Brake Valves & Controls	1			3A.19. Anti-Lock Brake System (ABS)	1			
3A.9. Proportioning, Inversion or Modulation Valve	1			3A.21. Stability Control System			1	
3A.10. Towing Vehicle (Tractor) Protection System	1			3A.23. Brake Performance			1	
3A.11. Parking Brake & Emergency Application	1							

1	-
/ .	
100	٧Э.
.0	Lo.

3A.13: Audible air leak when service brakes applied. (Repaired) 3A.16: No stroke indicators on push rods. (Installed)

3A.16: NO Suorie	Section 4 - Steering											
Component	P	F	NA	Component	P	F	NA					
4.1. Steering Control and Linkage	1			4.4. Kingpin	1							
4.1. Steering Control and Electric) 4.2. Power Steering System (Hydraulic and Electric)	1			4.5. Self-Steer and Controlled-Steer Axle	~							
4.3. Steering Operation (Active Steer Axle)	1											

NOTES:

Sec	P	F	N/				
Component	P	F	NA		1	-	
	1	0.000,000		5.8. Heater & Windshield Defroster			\vdash
5.1. Fire Extinguisher 5.2. Hazard Warning Kit	1	9		5.9. Fuel-Burning Auxiliary Heater			1
	1			5.10. Chain/"Headache" Rack		1	1
5.3. Hom 5.5. Speedometer	1			5.11. Auxiliary Controls and Devices			1
5.6. Odometer	1			5.12. Auxiliary Drive Controls			
5.7. Windshield Wiper/Washer	1				·		

NOTES:

5.2: No hazard warning kit. (Installed)

	56	CUOII	0 -	- Lamps	P	F	N/
	P	FN	IA	Component	-		20000
Component		PACION DO		6.4. Instrument Panel Lamps	1		
6.1. Required Lamps	1			6.5. Headlamp Aim	-		
6.2. Reflex Reflector 6.3. Retro-Reflective Marking		17, 1					

NOTES:

·····································	Section 7	-El	ectrical Sys	stem	Section 1	E NA
Component	P	FN	IA	Component	P	
Property and the second	1		7.3. Traile	r Cord (output to towed vehicle)		
7.1. Wiring 7.2. Battery	1	\perp				

NOTES:

Section 8 - Body										
Component	P	F	NA	Component	P	Ę.	NA			
State of the state	1			8.12. Bumper	V	_	-			
8.1. Hood or Engine Enclosure			1	8.13. Windshield	V		-			
8.2. Tilt Cab	1		-	8.14. Side Windows	✓		-			
8.3. Air-Suspended Cab	/			8.15. Rear Window			1			
8.4. Cab and Passenger-Vehicle Body			1	8.16. Interior Sun Visor	1					
8.5. Cargo Body	1		~	8.17. Exterior Windshield Sun Visor	1					
8.6. Frame, Rails & Mounts	-		-	8.18. Rear-View Mirror	1					
8.7. Unitized Body Elements	V		-		1					
8.8. Cab or Cargo Door	✓			8.19. Seat	/		+			
8.9. Cargo Tank or Vessel			1	8.20. Seat Belt/Occupant Restraint		_	+			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	~			8.21. Fender/Mud Flap	~					
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			1	8.24. Aerodynamic Device & Attachment			_			

Missing clip and washer for hood spring. (Installed) 8.1: Missing rear mud flaps on hood. (Installed)

8.6: Bolts missing in crossmember after rear of cab. (Installed)

8.18: Left side mirror head missing screw. (Installed)

8.1: Missing hood latch on left side. (Installed)

8.6: Cab mounts are worn out. (Replaced)

8.8: Left and right front door seals worn. (Replaced)

8.21: Right rear fender mounting bracket broken. (Repaired)

Component	P	F	NA	Component	l D	F	N
9.1. Tire Tread Depth	/	-	A STATE	9.7. Wheel/Rim (Applies to all wheel types)	P	F	
3.2. Tire Tread Condition	1			9.8. Multi-Piece Wheel/Rim	1		+
3.3. Tire Sidewall & Manufacturer Markings	1			9.9. Spoke Wheel/Demountable Rim System	1		
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	1		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	1		
9.6. Wheel Bearing	1						

NOTES:

9.2: Axle#3 left side tire was 50psi, adjusted to 95psi.

Section 10 - Couplers and Hitches									
Component	P	F	NA	Component	P	F	NA		
10.1. Hitch Assembly, Structure & Attaching Components	1	1170160		10.5. Roll-Coupling Hitch			1		
10.2. Secondary Attachment (Safety Chain or Cable)			1	10.6. Automated Coupling Device			1		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			1	10.7. Fifth Wheel Coupler	1				
10.4. Ball Type Hitch			1	10.8. Oscillating Fifth Wheel Coupler			1		

NOTES:

Section 12 - Structural Integrity									
Component	P	F	NA	Component	P	F NA			
12.1. Documentation	1	'		12.5. Frame	1				
12.2. Vehicle Identification Number	1	'		12.6. Roof	1				
12.3. Body - General	1			12.7. Pillars	1				
12.4. Structural Dimensions - ***Must be attached***	1			12.8. Floor	✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #5108915) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection(Mechanical) 2023/03/09	Technician Number (Mechanical) C7656	Facility Number (Mechanical) 13094	Signature #
Date of Inspection(Structural) 2023/03/09	Technician Number (Structural) B8076	Facility Number (Structural) 13094	Signature

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2023/03/09

Customer Signature