



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00658WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 6,175

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cooling - Radiator Repair: Blow rads out	1		CA\$ 0.00

Repair Story: Tyson Waldner - 04/26/2025: Blow rads out, Air filter, and put New Fuel Cap on old one the Vent was Broke

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00658WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00605WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 6,143

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	General - Site Service Call: -DRIVE TO COLUMBIA ICE FIELDS FROM RTRC SHOP AND REMOVE BLADE FROM UNIT. -(UNIT BLADE QUICK CONNECT FITTING NEEDS TO BE REPLACED.)	12		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00605WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00548WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007Welding ONLY

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	General - Custom Fabrication / Build: repaired cracks	2.5		CA\$ 0.00
Repair Story: Trey Albers - 04/02/2025: welded and fixed crack				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00548WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00540WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 6,069

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Dozer Blade Repair / Weld: Remove blade	3		CA\$ 0.00

Repair Story: Cory Bell - 04/03/2025: Removed blade. Trunion hardware and shims are in the cab in a bag.

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00540WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00527WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 6,068

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Two-Way Radio Repair: -install grommet and silicone antenna on wire going into cab -remove and replace float face oring and ripper hose that was leaking. -grease entire unit. -found unit has some cracks in the blade (sent matt a picture.) -remount brigade system that was falling off. -checked all fluids (all were good) -hard mount 2 way radio antenna on unit.	6		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00527WO

Closing Date

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00485WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 6,066

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: -Remove steering hydraulic motor. -reseal steering motor and adaptor. -reinstall steering motor. -reinstall floor and belly pans. -install track shovel holder. -Check all fluids on unit. -Top off right hand side final drive. -Tried to hook up diagnostic computer but computer keeps crashing.	18.5		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00485WO

Closing Date

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00481WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 123

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - 500 Hour Service: Complete full 500HR Service.	7.5		CA\$ 0.00
Repair Story: Cory Bell - 03/25/2025: complete inspection on unit. complete 500 hour service. Remove floor mat and floor panels, as well as belly pans. identify where oil leak was coming from and review schematics and order parts with cary.				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00481WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Diagnose and Advise - General Inspection / Walkaround: Complete full inspection on unit Blade control lever goes to full stroke of the cylinders when dozing periodically, once this happens, the lever won't work at all, after moving the lever around to all positions, it finally starts working again.	9.5		CA\$ 0.00
Repair Story: Cory Bell - 03/27/2025: remove ripper shanks and place them oil a pallet behind machine. assist David with completing steering motor repair. complete inspection repairs. install belly pans and floor.				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00426WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 6,030

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	General - Site Service Call: -DRIVE TO ROCKY FARMS FROM RTRC SHOP TO CHECK OUT AFTERTREATMENT CODES ON UNIT.	1.5		CA\$ 0.00

Repair Story:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Aftertreatment - DPF Forced Regen: -HOOK UP DIAGNOSTIC COMPUTER AND DELETE CODES. (ARD AIR PRESSURE LOW) -3 FORCED REGENS WITH COMPUTER TILL DPF SOOT LEVEL REACHED 0%. -RAN UNIT FOR A WHILE AND CODES DID NOT RETURN.	3.5		CA\$ 0.00

Repair Story:

Parts:



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00426WO

Closing Date

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00313WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007Welding ONLY

Manufacturer: CAT

Year: 2015

Hours: -1

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tracks - Track Pad Replace (Rubber): corks	11		CA\$ 0.00
Repair Story: Trey Albers - 02/23/2025: welded corks on				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00313WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00234WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 5,801

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Ripper Tooth Replace: -REMOVE AND REPLACE RIPPER SHANK. -REMOVE AND INSTALL NEW RIPPER TOOTH.	1.5		CA\$ 0.00
Repair Story:				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00234WO

Closing Date