



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023860

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 863,796

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cab - Seat Replace: replace seat	1.5		CA\$ 0.00
Repair Story: replace drivers seat				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Electrical - Switch Replace: replace worn dash switches	3		CA\$ 0.00
Repair Story: replace 5 air switches and 2 electrical switches				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	General - Other (Specify in Detail): Put 6 cage in glove box			CA\$ 0.00
Repair Story:				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023860

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Suspension - Shock Absorber Replace: Replace shocks on axle 1,2,3			CA\$ 0.00
Repair Story:				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Engine - Belt Replace: replace ACC. belt			CA\$ 0.00
Repair Story:				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Brakes - Brake Chamber Replace: Installed break pot plug on axle 4	0.25		CA\$ 0.00
Repair Story: installed cage bolt plug				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	: install stroke ind. on axle 1	0.25		CA\$ 0.00
Repair Story: Installed stroke ind.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
8	Electrical - Marker / Clearance Light Replace: change left center maker light	0.5		CA\$ 0.00
Repair Story: removed light and found light and plug were bad, installed new pig tail and light				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
9	Tires - Tire Rotation: Rotate Tires on axle 3 and 4	1.75		CA\$ 0.00
Repair Story: take off and put back on then torque.				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023860

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
10	Diagnose and Advise - Coolant Leak: Fix coolant leaks	3		CA\$ 0.00
Repair Story: pressure test cooling system no major leaks found. let truck sit over night as leaks show more when cold. Drained coolant and removed over sized pipe, measured ends and ordered new hose, installed new hose with new clamps refilled and tested for leaks				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
11	Engine - Oil and Filter Service: Drop oil and replace with 5w-40	0.5		CA\$ 0.00
Repair Story: Dried old oil and filled with 5w-40				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
12	Electrical - Battery Terminal Service: Service batteries	1		CA\$ 0.00
Repair Story: Cleaned battery terminals and cables sprayed with battery protector				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
13	Diagnose and Advise - General Inspection / Walkaround: Inspection	1		CA\$ 0.00
Repair Story: did inspection				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
14	Electrical - Wiper Blade Replace: Change wiper blades	0.25		CA\$ 0.00
Repair Story: changed blades				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023860

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
15	: replace reflective tape	1		CA\$ 0.00
Repair Story: replace box gate reflective tape				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
16	General - Custom Fabrication / Build: Repair weld brackets on end gate	4		CA\$ 0.00
Repair Story:				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 2,689.81

Work Order Total after GST: CA\$ 2,824.30



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023856

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Repair (Plug / Patch): air up tires	0.75		CA\$ 0.00
Repair Story: fill all 10 tires				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023856

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023728

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 861,891

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Diagnose and repair coolant leak.	3.5		CA\$ 0.00

Repair Story: pressure test confirm where coolant is leaking, several clamps leaking, drain coolant, take hoses and clamps off, replace new clamps, check other clamps and tight as required, vacuum system put coolant back in, pressure test, held pressure for 45 minutes, wash engine bay off,

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023728

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023696

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Engine - Oil and Filter Service: oil and filter change	1.75	CA\$ 100.00	CA\$ 175.00
Repair Story: start and warm engine move to shop, drain oil and change filter.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Tires - Tire Replace: replace steering tires	3.5	CA\$ 100.00	CA\$ 350.00
Repair Story: Removed front tires and installed new ones also replace valve stems				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Drivetrain - Clutch Replace (Manual): adjust clutch	2	CA\$ 100.00	CA\$ 200.00
Repair Story: Clutch brake was worn out so I replaced it, was a once piece clutch brake had to one piece out				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023696

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Electrical - Fuse / Relay Replace: repair tarp motor stahls out	1	CA\$ 100.00	CA\$ 100.00
Repair Story: check circuitry for tarp motor found after a few seconds of use circuit breaker trips. replace circuit breaker with mega fuse test tarp all functions works good				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Brakes - Brake Line Replace - Hydraulic: front right brake hose kinking	0.25	CA\$ 100.00	CA\$ 25.00
Repair Story: take off hose untwist it and put back on.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Cooling - Radiator Repair: a/c condenser falling off only 1 bolt holding	2	CA\$ 100.00	CA\$ 200.00
Repair Story: reinstall AC condenser to the radiator. replaced some hardware with new rubber washers				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	Cab - Mirror Replace: repair driver side convex mirror heat	0.25	CA\$ 100.00	CA\$ 25.00
Repair Story: cut electrical and take off old mirror. bolt new mirror on, and hook up new electrical				

Parts:

Labour Billed:CA\$ 1,075.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 2,290.00

Work Order Total after GST: CA\$ 2,404.50



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023696

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023666

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Repair (Plug / Patch): repair tire, right rear inside	3.5		CA\$ 0.00

Repair Story: travel back to shop after hours, bring truck in and check for low tire. remove and found a nail in it. swap out tire, torque wheel nuts.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Tires - Tire Repair (Plug / Patch): Repaired tire	1		CA\$ 0.00

Repair Story: removed tire from rim, installed a plug and patch and reinstalled on the rim, install wheel on truck and torqued to spec

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023666

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023480

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: COOLANT LEAK	1		CA\$ 0.00
Repair Story: TOP SILICONE HOSE FROM THERMOSTAT TO STEEL PIPE HAD PIN HOLE IN IT, DRAIN COOLANT, REMOVE HOSE, INSTALL NEW ONE TOP WITH COOLANT, CHECK FOR LEAKS NOT LEAKING SEND TO WORK, SILICONE HOSE PART # (P) FO4-6006				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: Annual scheduled service.	2		CA\$ 0.00
Repair Story: change oil, fuel, grease				

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023480

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023479

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: COOLANT LEAK	1		CA\$ 0.00

Repair Story: DRAIN COOLANT REMOVE TOP RAD HOSE FROM THERMOSTAT TO STEEL PIPE
INSTALL NEW HOSE TOP UP WITH 1 JUG OF COOLANT AND SEND BACK TO WORK
PART # F04-6006

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023479

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023447

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	General - Equipment Cleaning / Detail: Equipment cleaning / detail.	1		CA\$ 0.00

Repair Story: CLEAN BOX OUT

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Tires - Tire Repair (Plug / Patch): TIRE REPAIR	1		CA\$ 0.00

Repair Story:

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

WO-2023447

Closing Date