



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00315WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 27,153

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,144,735

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Body - Tool Box Repair: replace chain hanger	1		CA\$ 0.00

Repair Story: Evan Williams - 02/24/2026: removed old broken hanger. marked and made holes in new. installed.

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00315WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00258WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit:	1511	Serial Number:	1NPWX4TX1DD187441
Manufacturer:	Peterbilt	Model:	Conventional
Year:	2013		
Hours:	27,089	KM's:	1,141,877

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: change unit numbers	0.5		CA\$ 0.00
Repair Story: Evan Williams - 02/14/2026: removed old numbers cleaned. installed new				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	HVAC - Auxiliary Heater Service (Webasto / Espar): repair webasto	0.5		CA\$ 0.00
Repair Story: Evan Williams - 02/14/2026: found timer was set as air top, changed settings. works as should.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Body - Tool Box Repair: repair chain hanger	0.5		CA\$ 0.00
Repair Story: Evan Williams - 02/14/2026: lifted box to change hanger. upon inspection found old hanger went the other way, need different one.				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00258WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Diagnose and Advise - General Inspection / Walkaround: check over truck	1.25		CA\$ 0.00

Repair Story: Scott Dancy - 02/17/2026: bring truck into shop, check lights all good, still needs more checking over.

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	M11-390L CHAIN HANGER	1	\$252.07

Parts Total for Line: \$252.07

Labour Billed:CA\$ 0.00

Parts Total: \$252.07

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 252.07

Work Order Total after GST: CA\$ 264.67



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00072WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 27,040

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,139,502

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Engine - Cylinder Head Gasket Replace: Diag. pushing coolant out of surge tank	3.75		CA\$ 0.00

Repair Story: Adam Kohler - 01/15/2026: Helped Evan with Diag.

Evan Williams - 01/15/2026: boosted truck brought inside. drained coolant and plugged off turbo. filled and tested. still pressuring. drained coolant and capped compressor as well. filled. still pressurizing. need to look into engine.



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00072WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Engine - Cylinder Head Replace: Change head	47		CA\$ 0.00

Repair Story: Adam Kohler - 01/15/2026: Helped with tare down, removed accories from right side and front
 Evan Williams - 01/15/2026: removed rad, stripped rh side of engine and front. times and removed all valve train.
 removed injectors and head bolts. lifted head. found crack in #5
 Adam Kohler - 01/19/2026: Cleaning the deck and measuring protrusion
 Scott Dancy - 01/26/2026: install head gskt, torque head to 300 ft lb.
 Adam Kohler - 01/26/2026: Cleaned block surface again and set head, torqued down to 300 ft/lbs will retorque in morning
 Adam Kohler - 01/27/2026: Finished torquing the head, installed cam, install rockers, installed gear train and set timing, resealed and installed Injectors
 Adam Kohler - 01/28/2026: Set timing, spun engine twice, started on left side got fuel system on, reconnected coolant lines to air compressor, installed thermostat housing, and exhaust manifold, removed egr cooler, went to install kit but need to make modifactions
 Adam Kohler - 01/29/2026: Finished installing everything on left side, installed rad hooked up everything, Had to do a bunch of rerouting of coolant lines, deleted ERG cooler,
 Adam Kohler - 01/30/2026: Installed turbo, finished running coolant, filled pressure tested
 Adam Kohler - 02/02/2026: Finished installing air intake and tried to fire up, took a lot to prime fuel system, checked oil and topped up, went with Chris for test drive.
 Adam Kohler - 02/03/2026: Has VGT codes, worked with Evan checked over the wiring and hooked up computer and recalibrated Actuator, retorqued wheels when it got back and installed nut covers

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Wiring Harness Repair: Fix driver side window only working while door is closed	7		CA\$ 0.00

Repair Story: Adam Kohler - 01/16/2026: Pulled door panel and dash, found wires at door hinge broken, have to make new harness
 Adam Kohler - 01/19/2026: Made new harness and tested, pulled off passenger side as well reconnected window motor and retested, everything works



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00072WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	HVAC - Auxiliary Heater Service (Webasto / Espar): Install new wabasto	8.5		CA\$ 0.00

Repair Story: Adam Kohler - 01/20/2026: Removed old, cut out wires and fuel lines, installed new in passenger side box, ran air and exhaust, installed fuel pump and fuel lines, ran wiring and installed button start and display, need to install head before running water lines

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Frame - Deck Floor Repair: Fix broken pie ce of wood on gravel dump	2.75		CA\$ 0.00

Repair Story: Porter Dyer - 01/20/2026: Removed old wood. Found new piece out in the yard. Cut to right length. Found some paint and painted it.
Porter Dyer - 01/21/2026: Installed bored on truck.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Body - Tail Gate Repair: Welding	1.5		CA\$ 0.00

Repair Story: J. P. Allemand - 01/27/2026: fix cracks on tailgate

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	Steering - King Pin Replace: change kingpins.	19.5		CA\$ 0.00

Repair Story: Scott Dancy - 01/30/2026: removed king pin dr side almost got pass side out and pin moved a bit then stopped.

Scott Dancy - 02/02/2026: remove pass side king pin. very tight. install bushings and sized pass side.

Scott Dancy - 02/02/2026: install bushings and sized dr side. install kingpins both sides shimmed up installed both drums and tires. also put dust covers on.



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00072WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
8	Cab - Window Replace - Windshield: Replace both wind shields	2		CA\$ 0.00

Repair Story: Adam Kohler - 02/02/2026: Prepped and installed both windshields, had to do driver side 2 times as seal ripped on first attempt

Parts:

Line: 0

SKU:	Part Name:	Quantity Used:	Total:
		1	\$14,058.47
		1	\$891.42

Parts Total for Line: \$14949.89

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
J22-1010	POWER STEERING RES CAP	1	\$25.78
SC2010D	EXPANSION TANK CAP	1	\$46.94
AF4195	Air filter	2	\$192.96

Parts Total for Line: \$265.68

Line: 2

SKU:	Part Name:	Quantity Used:	Total:
	HEAD GASKET KIT 4376104CUM	1	\$2,050
	EXH MANIFOLD BOLTS 4965698	12	\$149.52
	EXH GASKETS	1	\$35.46
	EXH GASKET 5486657	8	\$250
	FITTING FOR EGR DELETE	1	\$24.88
	EX PRESSURE SENSOR	1	\$267.43
2866636	Gaskets	1	\$22.85

Parts Total for Line: \$2800.14

Line: 4

SKU:	Part Name:	Quantity Used:	Total:
	HEATER WEBASTO ENGINE WEB5013920A	1	\$1,252.07



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00072WO

Closing Date

5013445A	Webasto on/off switch	1	\$28.48
----------	-----------------------	---	---------

Parts Total for Line: \$1280.55

Line: 7

SKU:	Part Name:	Quantity Used:	Total:
	KINGPIN CAPS 971370ETN	4	\$110.72

Parts Total for Line: \$110.72

Labour Billed: CA\$ 0.00

Parts Total: \$19,406.98

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 19,406.98

Work Order Total after GST: CA\$ 20,377.33



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02314WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit:	1511	Serial Number:	1NPWX4TX1DD187441
Manufacturer:	Peterbilt	Model:	Conventional
Year:	2013		
Hours:	26,983	KM's:	1,136,590

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Tail Light Replace: Repair lights as needed	1.5		CA\$ 0.00

Repair Story: Adam Kohler - 01/04/2026: front bumper left light, found multiple corroded wires, spliced and tested, changed pig tail works tapped up and retested, changed bullet light on visor

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Cab - Mirror Replace: Change broken convex mirror	0.5		CA\$ 0.00

Repair Story: Adam Kohler - 01/04/2026: removed old installed new wired in for heat

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Intake - Turbocharger Replace: repair no power, smoking.	4		CA\$ 0.00

Repair Story: Evan Williams - 01/07/2026: removed exhaust elbow turbine good. removed vgt actuator. veins not going full sweep. drained coolant and removed turbo. took apart no good. installed used turbo, calibrated vgt actuator. hooked up all piping and filled with coolant. tested. has small leak but works.



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02314WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Electrical - Wiper Blade Replace: replace wipers	0.5		CA\$ 0.00

Repair Story: Evan Williams - 01/07/2026: removed and changed wipers. cleaned spray nozzles.

Parts:

Line: 4

SKU:	Part Name:	Quantity Used:	Total:
W612-1	NOZZLE WASHER- PETERBILT	2	\$6.2

Parts Total for Line: \$6.20

Labour Billed:CA\$ 0.00

Parts Total: \$6.2

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 6.20

Work Order Total after GST: CA\$ 6.51



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02230WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,898

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 113,487

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Brakes - Service Brake Adjustment: adjust all brakes	0.5		CA\$ 0.00
Repair Story: Cory Thorburn - 12/14/2025: air up truck adjust all brakes				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Drivetrain - Differential Service / Fluid Change: reseal diff lock	0.5		CA\$ 0.00
Repair Story: Cory Thorburn - 12/14/2025: reseal diff lock				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Washer Pump Replace: check windshield sprayer	0.5		CA\$ 0.00
Repair Story: Cory Thorburn - 12/14/2025: adjust windshield washer sprayer				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02230WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Tires - Tire Repair (Plug / Patch): repair flat tire	1		CA\$ 0.00

Repair Story: Cory Thorburn - 12/15/2025: repair #3 right out side tire

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	WASHER NOZZLE W612-1	2	\$6.2
	FRT SLACK ADJUSTER K044332BXW	1	\$251.53

Parts Total for Line: \$257.73

Labour Billed: CA\$ 0.00

Parts Total: \$257.73

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 257.73

Work Order Total after GST: CA\$ 270.62

The Following Wheels were removed. It is YOUR responsibility to ensure a re-torque is completed within 250km

Axle 3 Right Removed



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02127WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,765

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,126,652

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: service and inspect	2		CA\$ 0.00
Repair Story: Evan Williams - 11/29/2025: completed service and inspection				

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
LF14000NN	Lube filter	1	\$54.63
FF5825NN	Fuel filter	1	\$74.12
FS20075	Fuel filter	1	\$37.71
5W40ROTELLA BULK	5W40 ROTELLA	52	\$354.12

Parts Total for Line: \$520.58

Labour Billed:CA\$ 0.00

Parts Total: \$520.58

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 520.58

Work Order Total after GST: CA\$ 546.61



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02127WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02082WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,720

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,124,882

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Drivetrain - Differential Service / Fluid Change: repair leaking pdl and diff locks	2		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02082WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01957WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,559

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: mid life	1		CA\$ 0.00
Repair Story: Evan Williams - 11/02/2025: completed mid life and inspection				

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
LF14000NN	Lube filter	1	\$54.63
5W40ROTELLA BULK	5W40 ROTELLA	5	\$39.8

Parts Total for Line: \$94.43

Labour Billed:CA\$ 0.00

Parts Total: \$94.43

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 94.43

Work Order Total after GST: CA\$ 99.15



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01957WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01889WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,478

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - Air Leak (Truck Air System): Fix air leaks	2.75		CA\$ 0.00

Repair Story: Porter Dyer - 10/23/2025: Diagnosed air leaks. Replaced parking valve due. Noticed other air leak coming from the parking brake sensor. Patched line and ordered new sensor.
Porter Dyer - 10/24/2025: Installed air parking valve sensor in truck to fix false alert.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	HVAC - Cabin Air Filter Replace: Cab filter clean out.	1		CA\$ 0.00

Repair Story: Porter Dyer - 10/23/2025: cabin air filter was so dirty i had to blow the heater core clean. Once clean i replaced the air filter and blew out the cab.

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	park brake pressure switch	1	\$62.59

Parts Total for Line: \$62.59



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01889WO

Closing Date

Labour Billed: CA\$ 0.00

Parts Total: \$62.59

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 62.59

Work Order Total after GST: CA\$ 65.72



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01736WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,299

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cooling - Fan Hub Replace: -fan hub	1		CA\$ 0.00
Repair Story: Lance MacElheren - 09/28/2025: -help Evan install fan hub				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: service	2		CA\$ 0.00
Repair Story: Evan Williams - 10/02/2025: drained oil. changed oil and fuel filters. file with oil.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Cooling - Thermostat Replace: thermostat	2		CA\$ 0.00
Repair Story: Evan Williams - 10/02/2025: drained coolant. removed housing. removed and changed thermostat and seal. installed. filled iwth coolant let run outside. Got up to temp.				

Parts:

Labour Billed:CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01736WO

Closing Date

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00