



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01200WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,581

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: service and inspect	1		CA\$ 0.00
Repair Story: Evan Williams - 07/12/2025: change oil filter top up oil and inspected				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	HVAC - Blower Motor Replace: Blower fan replaced by evan			CA\$ 0.00
Repair Story:				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01200WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01118WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,491

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,055,935

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Alternator Replace: Change alternator	2.25		CA\$ 0.00

Repair Story: Adam Kohler - 07/03/2025: aired up truck and brought to shop

Scott Dancy - 07/03/2025: r/r alt. cleaned battery posts and cables., also cleaned cables on the alt.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Body - Hood Latch / Hinge Repair: change rotten rubber hood latch			CA\$ 0.00

Repair Story:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Tail Light Replace: fix lights as needed	1.75		CA\$ 0.00

Repair Story: Scott Dancy - 07/03/2025: replace cab light, rear light on trio. repair wiring on rear marker.



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01118WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Drivetrain - Driveshaft Replace: check driveline.	0.5		CA\$ 0.00
Repair Story: Scott Dancy - 07/03/2025: check drive lines.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Suspension - Equalizer Beam Service: r/r rear diff top torque arm.	1.5		CA\$ 0.00
Repair Story: Scott Dancy - 07/03/2025: installed rear diff torque arm.				

Parts:

Line: 3

SKU:	Part Name:	Quantity Used:	Total:
FLTCM25003A	LIGHT 2.5" AMBER CLEARANCE	1	\$7.84

Parts Total for Line: \$7.84

Line: 4

SKU:	Part Name:	Quantity Used:	Total:
TMRN844	TORQUE ARM- UPPER DIFF	1	\$123.64

Parts Total for Line: \$123.64

Labour Billed: CA\$ 0.00

Parts Total: \$131.48

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 131.48

Work Order Total after GST: CA\$ 138.05



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01118WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01054WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,432

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,053,066

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - CVIP / DOT Inspection: CVIP INSPECTION wheels on	2		CA\$ 0.00

Repair Story: Adam Kohler - 06/23/2025: Brought truck in and made WO
Evan Williams - 06/23/2025: completed cvip inspection

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Electrical - Power Window Motor Replace: diag and fix right window not working	2		CA\$ 0.00

Repair Story: Evan Williams - 06/23/2025: checked for power at fuse. traced back to window switch had power and worked as should. removed door panel and checked for power. had power. jumped 12v and window worked. greased sliders and tried with switch window works.



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01054WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Brakes - ABS Sensor Replace: Diag. ABS Light	2		CA\$ 0.00

Repair Story: Evan Williams - 06/23/2025: Hooked up computer. found code for right rear #3 voltage. checked sensor ohms was good. checked power. none. traced and could not find issue. tested voltage and had voltage. found wire corroded in connector. spliced in ne wend and tested. no codes.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Lube - Full Greasing: Grease Unit			CA\$ 0.00

Repair Story:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Electrical - Tail Light Replace: fix lights as required	1.5		CA\$ 0.00

Repair Story: Evan Williams - 06/23/2025: removed burned out lights. wired in new and tested. works as should.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Cab - Window Replace - Windshield: Change right wind shield	2		CA\$ 0.00

Repair Story: Adam Kohler - 07/01/2025: removed windshield and cleaned broken glass prepped surfaces and installed new

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	: check and repair a/c is not working	2.5		CA\$ 0.00

Repair Story: Evan Williams - 06/23/2025: checked system for pressure, none. ran vacume and pressure tesed found leak at shreader valve. replaced. pressur etesed. found leak at condenser O-ring. replaced. no leaks. charged system, works as should.

Parts:

Line: 4



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01054WO

Closing Date

SKU:	Part Name:	Quantity Used:	Total:
FLTCM25003R	LIGHT 2.5" RED CLEARANCE	2	\$19.58
49333	LIGHT AMBER PENNY	1	\$11.18

Parts Total for Line: \$30.76

Labour Billed:CA\$ 0.00

Parts Total: \$30.76

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 30.76

Work Order Total after GST: CA\$ 32.30



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00931WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,295

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,043,159

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: service	1.5		CA\$ 0.00

Repair Story: Evan Williams - 06/08/2025: Drained oil. changed oil and fuel filters. filed with il. ran and checked level.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Diagnose and Advise - Loss of Power: diag. low power issue	1.5		CA\$ 0.00

Repair Story:

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
LF14000NN	Lube filter	1	\$50.96
FF5825NN	Fuel filter	1	\$68.88
FS20075	Fuel filter	1	\$35.59
5W40bulk	5W40 bulk oil	48	\$322.08

Parts Total for Line: \$477.51



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00931WO

Closing Date

Labour Billed: CA\$ 0.00

Parts Total: \$477.51

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 477.51

Work Order Total after GST: CA\$ 501.39



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00894WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit:	1511	Serial Number:	1NPWX4TX1DD187441
Manufacturer:	Peterbilt	Model:	Conventional
Year:	2013		
Hours:	25,252	KM's:	1,040,972

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Fuse / Relay Replace: diag. and fix radio	1		CA\$ 0.00
Repair Story: Adam Kohler - 06/03/2025: brought truck to shop and found blown fuse installed new fuse				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Electrical - Switch Replace: check into starter not always working	1		CA\$ 0.00
Repair Story: Adam Kohler - 06/03/2025: checked wiring, had loose connections on switch, internals of switch were also loose changed switch				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Tires - Tire Replace: repair axle 3 right inner tire	2		CA\$ 0.00
Repair Story: Adam Kohler - 06/03/2025: removed tire found nail right beside patch, and patch had lifted, got 2 new tires and replaced both on axle 2 right, torqued to spec				

Parts:



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00894WO

Closing Date

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00822WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,135

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,033,064

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Solenoid Valve Replace: box raises in neutral and comes down very slow	2		CA\$ 0.00

Repair Story: Adam Kohler - 05/22/2025: Tested for air by pass in switch, no bypass checked shuttle not returning fully, had to remove pump to take shuttle housing off, cleaned it and resealed tested and reinstalled, tested again, works

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00822WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00811WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,112

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,031,258

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Brakes - Slack Adjuster Replace: Slacks, Dryer	9.5		CA\$ 0.00

Repair Story: Tyson Waldner - 05/19/2025: Change Air Dryer, change all Slack adjusters on Drives had to pull 3 wheels and S Cams to get Adjusters off, Found a couple air leaks repaired them while i was there

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00811WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00760WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,071

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,028,326

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Service / PM - Rental Out Inspection: quick inspection	0.5		CA\$ 0.00

Repair Story: Jeff Franklin - 05/10/2025: complete a quick inspection

found axle 3 right inner tire flat

license plate light out

HVAC not working properly, mixer not changing

air conditioner needs charged or repaired

axle 1 right hub oil seemed low, inspected for leaks but was dry, topped up and cleaned breather hole in plug

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: mid service filter change	0.5		CA\$ 0.00

Repair Story: Jeff Franklin - 05/10/2025: removed oil filter and installed new filter, topped up engine oil

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Tires - Tire Repair (Plug / Patch): axle 3 right inner tire flat repair	1		CA\$ 0.00

Repair Story: Jeff Franklin - 05/10/2025: remove wheels axle 3 right, air up inner tire and found leak, remove tire and do flat repair, install tire, install wheels, torque, tag, mark and pics

Parts:



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00760WO

Closing Date

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00730WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,023

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,025,005

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Fuse / Relay Replace: Fix intermittent radio	1		CA\$ 0.00

Repair Story: Adam Kohler - 05/06/2025: Found someone had used a tap a fuse, tap a fuse was on hot side of the fuse. and was making poor contact, found switched power behind gauges and ran wire to it. working now

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00730WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00700WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,992

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,023,077

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Drivetrain - Driveshaft Replace: replace drive shaft	5		CA\$ 0.00
Repair Story: Cory Thorburn - 05/01/2025: remove drive shaft off 1517, install drive shaft on 1511 torque to spec, adjust all brakes Jeff Franklin - 05/03/2025: remove old driveshaft between axle 2 and 3, had to use heat and bolt extractors to remove rounded bolts, clean and install new driveshaft, torque to spec				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Body - Bumper Replace / Repair: install new moose bumper	6		CA\$ 0.00
Repair Story: Jeff Franklin - 05/03/2025: use 1520 to remove old bumper off unit and install new moose bumper, test for marker, blinker and ground both sides, make wiring harness and splice into truck harness to hook up bumper lights, test and works				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Tires - Tire Replace: Replace tires on axle 1	1		CA\$ 0.00
Repair Story:				

Parts:



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00700WO

Closing Date

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00