



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00082WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,347

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 994,942

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Drivetrain - Driveshaft Replace: Diag. major air leak	2		CA\$ 0.00

Repair Story: Adam Kohler - 01/24/2025: Found axle 4 left brake lines were rubbing on drive shaft, removed and got new ones made, reinstalled and tested seems good to go
Cory Thorburn - 01/24/2025: replace air lines on #4 left

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00082WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00065WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,333

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 994,329

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Suspension - Air Bag / Air Spring Replace: Change blown airbag axle 4 left	1.5		CA\$ 0.00

Repair Story: Cory Thorburn - 01/22/2025: remove #4 left air bag, install new air bag

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: Change fuel filters	1.5		CA\$ 0.00

Repair Story: Cory Thorburn - 01/22/2025: replace fuel filters let run for a bit, park in line up

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00065WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00030WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,248

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 991,751

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cooling - Fan Hub Replace: Rebuild leaking fan hub	2.5		CA\$ 0.00

Repair Story: Jeff Franklin - 01/11/2025: remove air to air, remove fan belt, remove tensioner, remove alternator, remove both rad supports, remove fan, remove fan hub, change out the pill and install new fan hub, reassemble

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Aftertreatment - DEF Tank Repair: Fix tire chains, remove DEF Tank, Change leaking air line	8.5		CA\$ 0.00

Repair Story: Jeff Franklin - 01/11/2025: put safety gear back in truck, go through tire chains, had to fix all the tire chains as they were all missing pieces and or broken, hung 2 triples and a steering chain on unit for use
Cory Thorburn - 01/11/2025: remove DEF tank, test fit tool box, make new air line from compressor to air dryer



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00030WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Intake - Turbocharger Replace: Replace turbo	9		CA\$ 0.00
Repair Story: Jeff Franklin - 01/10/2025: drain coolant, drain engine oil, suck out AC, condenser has a hole as it only had a bit in it, remove air to air and steam out as it was full of oil, remove all turbo lines and wiring, clean area, change over some fittings to new turbo, prime turbo, remove and install new mount studs, changed all o-rings and seals and gaskets, installed new turbo, reassemble all piping and install turbo lines and wiring Jeff Franklin - 01/11/2025: take for test drive and dump load off truck in yard, pull back in shop to double check for leaks				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Engine - Valve Adjustment: valve set	2		CA\$ 0.00
Repair Story: Jeff Franklin - 01/10/2025: remove cross over pipe, remove valve cove, clean all surface area and vacuum out rocks around edge of cover, set valves , install valve cover, install cross over pipe, threads were stripped for 1 bolt so had to drill out and install Heli coil				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	: Service Unit	2		CA\$ 0.00
Repair Story: Jeff Franklin - 01/10/2025: change out oil filter, change fuel filter, change fuel/water sep. filter, check lights Jeff Franklin - 01/11/2025: finish off service and top up coolant				

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00030WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00007WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,241

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 991,554

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Drivetrain - Clutch Adjustment: check over unit	3		CA\$ 0.00

Repair Story: Cory Thorburn - 01/02/2025: check over unit, adjust clutch, move block heater plug

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00007WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02595WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit:	1511	Serial Number:	1NPWX4TX1DD187441
Manufacturer:	Peterbilt	Model:	Conventional
Year:	2013		
Hours:	24,093	KM's:	984,297

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Body - Hood Repair: replace broken hood cable	0.5		CA\$ 0.00
Repair Story: Cory Thorburn - 12/04/2024: replaced right broken hood cable				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	HVAC - Defrost Repair: hvac not working	13.5		CA\$ 0.00
Repair Story: Cory Thorburn - 12/04/2024: pull dash apart replaced heater controls, pull dash apart to check drum, drum was stuck, pull motor off to replace found drum was broken, rotate drum to defrost put dash back together Jeff Franklin - 12/07/2024: remove dash panels, remove heat pipes Jeff Franklin - 12/09/2024: finish removing housing for hvac, remove cylinder, install new cylinder and test, found new part to be catching on housing, remove again and modify part, install and test, bolt housing together, install heater fan, install heater piping, install dash panels, install floor and kick panels, test all again				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	: replace leaking wheel seal	3		CA\$ 0.00
Repair Story: Cory Thorburn - 12/05/2024: remove #4 left wheels, drum, hub, shoes, clean all parts install new wheel seal, replace shoes, install hub, clean drum, install drum and wheels torque to spec, adjust all brakes				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02595WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Software - Diagnostic Scan: Scan for engine codes	0.5		CA\$ 0.00
Repair Story: Adam Kohler - 12/10/2024: AK- scanned codes got 1898, 2387				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Electrical - Switch Replace: mirror selector switch broken	0.5		CA\$ 0.00
Repair Story: Jeff Franklin - 12/09/2024: remove left side mirror selector cluster, remove switch and replace, install cluster and test				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Fuel - Throttle Body Service: throttle pedal sticking	1		CA\$ 0.00
Repair Story: Jeff Franklin - 12/09/2024: remove pin and bushings on foot throttle, clean up corrosion and install new pin and bushings				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	HVAC - AC Compressor Replace: AC pump broken	1		CA\$ 0.00
Repair Story: Jeff Franklin - 12/09/2024: drain AC system, remove AC lines, remove AC compressor, change seals, install new compressor, install lines, tie up lines, remove fan belt, install new accessories belt, install fan belt, recharge AC system, valve was faulty and would not charge				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
8	Drivetrain - Clutch Adjustment: clutch needs adjusted	0.5		CA\$ 0.00
Repair Story: Jeff Franklin - 12/09/2024: help with clutch adjustment				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02595WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
9	Electrical - Two-Way Radio Repair: 2-way radio not turning on	0.5		CA\$ 0.00
Repair Story: Jeff Franklin - 12/09/2024: 2-way not turning on, check all fuses, pull kick panel off and found power wire not connected to the add-a-fuse, when connected, seemed loose, crimped down and reconnected, tested and all works good				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02552WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	HVAC - Auxiliary Heater Service (Webasto / Espar): boost	1		CA\$ 0.00
Repair Story: boost webasto was left of for days				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02552WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02521WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Solenoid Valve Replace: BOX WOULD NOT COME DOWN	1		CA\$ 0.00

Repair Story: PUMP SHUTTLE VALVE FROZE THAW OUT AND CLEAR ICE AWAY

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02521WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02505WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,993

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 979,522

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Wheel Replace: #2 axle left outer tire and rim damaged driver caught edge of scale at settler landfill	1.5		CA\$ 0.00
Repair Story: remove #2 axle left outer wheel due to being damaged, install good used rim and tire, torque, tag, mark and pics				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02505WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02440WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,815

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 971,457

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: 971,457km			CA\$ 0.00
Repair Story:				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Diagnose and Advise - Coolant Leak: coolant leak	2		CA\$ 0.00
Repair Story: pressure test coolant system find leak and repair				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02440WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02408WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,815

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 971,452

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: service and inspection	2		CA\$ 0.00

Repair Story: change oil, change oil filter, change fuel filter, change fuel/water separator filter, inspect unit, top up fluids, check lights and grease

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Tires - Tire Replace: #1 left tire has cords showing through on inside edge	4		CA\$ 0.00

Repair Story: did a live change #1 left tire, remove and install good used tire

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02408WO

Closing Date