



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02362WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - General Inspection / Walkaround: -Do checks on unit and make sure unit has fire extinguisher, first aid kit, and spill kit. -Unit had broken hood latch. -Remove hood latch and put it on cary's desk.	1		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02362WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02356WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,709

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 966,808

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Brakes - Brake Chamber Replace: drive to stettler land fill, block off brake pot drive back to shop	1.75		CA\$ 0.00

Repair Story: drive to stettler land fill, plug air line for #4 right brake pot, drive back to shop

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Brakes - Brake Chamber Replace: #4 right brake chamber no good	0.5		CA\$ 0.00

Repair Story: remove #4 right brake pot, cut new rod to length and install new pot, adjust brakes

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02356WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02320WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,621

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 963,717

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: check and repair wabasto	2.5		CA\$ 0.00

Repair Story: Checked both bunk and engine wabasto's engine not working, checked fuse was blow, replaced and still blowing, check other truck and this one has 15 am other trucks has 20, working now, removed controler at Jasons request and wired up to switch and tested working now

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02320WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02249WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,556

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 960,423

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Find and fix coolant leak	2		CA\$ 0.00

Repair Story: Found leak at lower rad hose, changed clamps and checked all the rest of the clamps at loose, tightened and refilled coolant and pressure tested for 10 mins no pressure loss

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02249WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02220WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Fuse / Relay Replace: clearance lights not working	2.5		CA\$ 0.00

Repair Story: separate wagon and truck, replace blown fuse and test lights, both seem good, checked female plug end on back of truck and found it to be corroded, pull apart and replace plug end, test everything together and works

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02220WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02067WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,366

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 952,555

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - Park Brake Issue: Check right front for brakes sticking on	2		CA\$ 0.00

Repair Story: removed wheel and drum found brake is staying on, checked outside bearing, looks good reinstalled and set, filled hub with oil, found wrong return spring. reinstalled everything and ordered parts

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	HVAC - Cabin Air Filter Replace: clean cab filter	1		CA\$ 0.00

Repair Story: wash cab filter blow out evaporator

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Cab - Window Replace - Windshield: both windshields broken	7		CA\$ 0.00

Repair Story: cut around both windshields removing inner rubber, try removing windshield, found it to be glued in, kicked both windows out, cleaned up glass and scraped glue off frame, install windshields right and left



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02067WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Body - Tarp Repair: tarp ripped	2		CA\$ 0.00

Repair Story: cut off ripped tarp, reattach tarp at front of box and cut off bad portion and remount at rear of box will need a new tarp ordered as this will not last too long

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Brakes - Brake Shoe / Pad Replace: #1 axle brakes sticking	3		CA\$ 0.00

Repair Story: remove wheels, remove drum, found s-cam to be hanging up on springs both sides, modify and replace brake shoes, install drums, install wheels, adjust brakes and test, works great, torque, tag, mark and pics

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Body - Tail Gate Repair: left and right tailgate latches worn out	4		CA\$ 0.00

Repair Story: remove latches, install new latches and test, rebuild latch arms to size needed, install and test, readjust and tighten

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	Engine - Belt Tensioner Replace: belt squealing	1.5		CA\$ 0.00

Repair Story: remove belt and tensioner, install new tensioner and belt

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
8	Air System - Air Line Repair: slow air build up	3		CA\$ 0.00

Repair Story: remove compressor line and hook up shop air, test, compressor seems good and build up was still slow, pulled lines off tanks and air dryer and tested, doesn't seem to have any blockage anywhere but does have 5 tanks in use instead of 3 so its justifiable



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02067WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
9	: Unit needed parts			CA\$ 0.00
Repair Story: Purchased from Glover				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01991WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,305

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 948,528

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: complete service	3		CA\$ 0.00
Repair Story: complete service				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01812WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,140

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 938,524

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Battery Replace: batteries dead	2		CA\$ 0.00

Repair Story: bring unit in, test batteries, 1 battery found shorting internally, pull all 4, clean battery box, install 4 new batteries, clean all connections and replace wire that was burnt from shorting out, apply protection spray

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01812WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01755WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Two-Way Radio Repair: 2 way radio not working	2.5		CA\$ 0.00
Repair Story: check fuses, follow wires found wire unplugged, put to key power				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01755WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01701WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Air System - Air Dryer Cartridge Replace: slow air build up and noisy fan belt	4.5		CA\$ 0.00

Repair Story: remove and replace fan belt and tensioner, install new air dryer pigtail, install new air dryer filter, install new water separator pig tail, air up truck and quad, inspect for leaks

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Air System - Air Line Repair: leaky airlines on lower firewall air manifold	4		CA\$ 0.00

Repair Story: remove fuse panel and other lines in the way, label and remove all air lines on outer firewall, remove lower panels inside cab, label and remove all air lines, trim ends and reinstall into new manifold, put cab interior back together and reinstall outer airlines, install fuse panel and tie up lines

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Frame - Crossmember Replace: cracked front cross member	13.5		CA\$ 0.00

Repair Story: remove airline and wiring harness mounts off cross member, cut all huck bolts with grinder and air chiesel, remove cross member and install new cross member, install new harness and airline brackets



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01701WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Tires - Tire Replace: worn out tires #2 and 3 axle	2		CA\$ 0.00
Repair Story: pull wheels, remove tires, install new tires, install wheels, torque, tag, mark and pics				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	: Unit needed a new belt			CA\$ 0.00
Repair Story: Purchased from Glover				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	: Unit needed a filter			CA\$ 0.00
Repair Story: Purchased from Glover				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	: Unit required a new harness			CA\$ 0.00
Repair Story: Purchased from Glover				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
8	: Unit needed parts			CA\$ 0.00
Repair Story: Purchased from Peterbilt				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01701WO

Closing Date