



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01633WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 23,043

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 933,552

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: complete service	4		CA\$ 0.00
Repair Story: change engine oil and filter replace fuel filters, look over unit, grease				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01583WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Unit needed parts			CA\$ 0.00
Repair Story: Purchased from Fountain Tire				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01528WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 22,974

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 930,377

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Wheel Replace: Change front left rim because of crack	1.5		CA\$ 0.00
Repair Story: removed wheel and took off tire, took tire off spare, installed old tire on new rim				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Brakes - Slack Adjuster Replace: change front slack adjuster	2		CA\$ 0.00
Repair Story: removed old slacks installed new				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Brakes - Brake Shoe / Pad Replace: change front drums and shoes	3		CA\$ 0.00
Repair Story: Removed front brake parts installed new				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01528WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	: Change front left leaking wheel seal	2.5		CA\$ 0.00
Repair Story: removed hub and leaking wheel seal cleaned area, installed new seal, reinstalled hub				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Drivetrain - Clutch Adjustment: Adjust clutch	0.5		CA\$ 0.00
Repair Story: Adjusted clutch				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	: Unit required parts.			CA\$ 0.00
Repair Story: Purchased from Peterbilt.				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01196WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 22,710

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 914,280

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Drivetrain - Clutch Replace (Manual): Change Worn Clutch	30.5		CA\$ 0.00

Repair Story: AK_Removed shifter and air lines, cooler lines, mounts, drive shaft and exhaust, removed transmission and clutch, changed input shaft, cross shafts and bushings
install clutch, install transmission, hook up lines, cut new flex pipe for exhaust, install driveshaft, install pump, install transmission cooler, fix airlines, wire wheel exhaust ends before installing exhaust, install new gasket on bottom bello pipe, hook up cooler lines. CT adjust clutch linkage and clutch

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Body - Body Panel Repair: Body panel repair.	3.5		CA\$ 0.00

Repair Story: Repaired cracks on door of box

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	: replace reflective tape on tailgate, tighten DEF cover	0.75		CA\$ 0.00

Repair Story: remove old reflective tape on tailgate install new tape. replace bolt in DEF cover



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01196WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Drivetrain - U-Joint Replace: remove wheels for cvip	3		CA\$ 0.00

Repair Story: jack up #4 axle put on stands remove wheels. remove drive shaft from #3 axle to #4 axle replace both ujoints. install drive shaft with all new bolts check brakes put wheels back on. remove wheels on #3,#2,#1 axles check brakes. #1 axle drums and linings are worn out.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Suspension - Air Bag / Air Spring Replace: replace both air bags on #2 axle	1.75		CA\$ 0.00

Repair Story: replace air bags on #2 axle had to make a new fitting for driver side bag

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
6	Suspension - Equalizer Beam Service: replace transvers arm	0.75		CA\$ 0.00

Repair Story: replace #4 axle transvers arm

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
7	Cab - Mirror Replace: replace passenger side mirror	0.5		CA\$ 0.00

Repair Story: replace passenger side mirror. tighten mirror mount

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
8	Brakes - Brake Shoe / Pad Replace: torque wheels	2.25		CA\$ 0.00

Repair Story: install #1 axle brakes install tires torque all wheels to 500 ft lbs set brakes



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01196WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
9	Brakes - Service Brake Adjustment: double check everything	0.75		CA\$ 0.00
Repair Story: air up truck and trailer check for air leaks check brake adjustment				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
10	Electrical - Sensor Replace - Generic: reverse sensor not working	1		CA\$ 0.00
Repair Story: pull truck in shop, remove floor, pull sensor and replace, test sensor, put floor back and take to line up				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
11	: Unit required parts,			CA\$ 0.00
Repair Story: Purchased from Glover.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
12	: Unit required parts.			CA\$ 0.00
Repair Story: Purchased from On Track.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
13	: Unit required parts			CA\$ 0.00
Repair Story: Purchased from Glover				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
14	Service / PM - CVIP / DOT Inspection: sublet cvi			CA\$ 0.00
Repair Story:				

Parts:



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01196WO

Closing Date

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01153WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 911,386

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Repair (Plug / Patch): flat tire #4 right outer	0.5		CA\$ 0.00
Repair Story: air up tire, find leak, pull wheel, remove tire, plug hole, install tire, install wheel, torque, tag, mark and pics				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Tires - Tire Replace: worn tires	2.5		CA\$ 0.00
Repair Story: take good tires from #4 and #2, match up and install on #2, remove and install 4 new tires onto #4 axle, air up #3 right outer, find leak, remove tire and install plug, remount tire, torque, tag, mark and pics				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01153WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01081WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 22,553

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 905,080

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Completed service	2		CA\$ 0.00
Repair Story: Change oil, oil filter, fuel filters and water seperator, completed inspection, and greased				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-01032WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Unit required a clutch Kit			CA\$ 0.00
Repair Story: Purchased from Diamond				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 219.76

Work Order Total after GST: CA\$ 230.75



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00943WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Body - Body Panel Repair: repaired box guide	5		CA\$ 0.00
Repair Story: same				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00943WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00808WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 892,317

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Replace: Change out damaged tire, right axle 3 inner	0.5		CA\$ 0.00
Repair Story: found tire on rim and swapped it out and torqued to spec				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00808WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00754WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Brakes - Service Brake Adjustment: PULLING HARD RIGHT WHEN BRAKING	0.5		CA\$ 0.00

Repair Story: READJUST FRONT RIGHT BRAKE
SEEM TO BE DRAGING AND NOT RELEASING AS QUICK

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-00754WO

Closing Date