

 <p>Canada's Tournament Capital</p>	<p>City of Kamloops Inspection: 21588 FLEET_Decommission Inspection Parent Work Order <u>4090091</u></p>
--	--

Inspection Summary

Object Inspected	FLEETEQUIPMENT 3332
Location	81328
Status	Overall Pass
Inspected By	LLOYD, BRANDON
Date	4/6/2023 11:11:49 AM
Summary	Dent on left front door, dent on left side rear fender, surface rust on both rear fenders and left passenger door. Rips/tears in drivers seat and centre console. Owners manual and service manual. 2 job boxes and a headache rack.
Repairs Made	
Recommendations	

Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	WHITE	
Colour - Interior	BLACK GREY	
Wheel Drive	4x4	
Body Style	4 Door	
Engine Size	4.8L V8	
Damage Declaration over \$2,000		
Estimated Damage Amount		
Body Condition	Fair	
Body Damage	Yes	
Mechanical	Unknown	
Transmission Operable	Yes	
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Chipped	
Jack Assembly	Yes	

Spare Tire	Yes	
Check all Vehicle Options that apply	Block Heater	
Check all Vehicle Options that apply	Air Bag	
Check all Vehicle Options that apply	Air Conditioning	
Check all Vehicle Options that apply	Tilt Steering	
Check all Vehicle Options that apply	Alarm System	
Check all Vehicle Options that apply	Delay Wipers	
Check all Vehicle Options that apply	Power Door Locks	
Check all Vehicle Options that apply	AM/FM Radio	
Check all Vehicle Options that apply	CD Player	
Hours or Odometer (Blank if N/A)	147888	

Add Signature and Date Fields Here?

Work Order Details

<p>Assigned To: Supervisor:</p> <p>Work Status: WORK IN PROGRESS</p> <p>Scheduled Start: 4/3/2023 12:00:07 PM Scheduled Finish: 4/3/2023 12:00:07 PM</p>	<p>Location: 81328</p> <p>[Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name: Account: 7401Receiving Account (IPTs): Asset Details:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">FLEETEQUIPMENT</th> </tr> <tr> <th style="text-align: left;">Name</th> <th style="text-align: left;">Value</th> </tr> </thead> <tbody> <tr> <td>OBJECTID</td> <td>65</td> </tr> <tr> <td>ASSETID</td> <td>3332</td> </tr> <tr> <td>UNITNO</td> <td>81328</td> </tr> <tr> <td>MAKE</td> <td>CHEVROLET</td> </tr> <tr> <td>MODEL</td> <td>SILVERADO</td> </tr> <tr> <td>MODELYEAR</td> <td>2007</td> </tr> <tr> <td>VIN</td> <td>2GCEK19CX71588054</td> </tr> <tr> <td>DESCRIPTION</td> <td>2007 CHEV FS 1/2T EXT 4X4</td> </tr> </tbody> </table>	FLEETEQUIPMENT		Name	Value	OBJECTID	65	ASSETID	3332	UNITNO	81328	MAKE	CHEVROLET	MODEL	SILVERADO	MODELYEAR	2007	VIN	2GCEK19CX71588054	DESCRIPTION	2007 CHEV FS 1/2T EXT 4X4
FLEETEQUIPMENT																					
Name	Value																				
OBJECTID	65																				
ASSETID	3332																				
UNITNO	81328																				
MAKE	CHEVROLET																				
MODEL	SILVERADO																				
MODELYEAR	2007																				
VIN	2GCEK19CX71588054																				
DESCRIPTION	2007 CHEV FS 1/2T EXT 4X4																				

EQUIPMENTTYPE	LIGHT DUTY TRUCK/VAN
FUELTYPE	GASOLINE
METERTYPE	KILOMETERS
FLEETSTATUS	OUT OF SERVICE (SALE PENDING)
NSCCCLASSIFICATION	NON NSC
LINKEDUNITNO	
AXELCOUNT	
LICENSEPLATE	BD7487
GVW	
LICENSEDGVW	5000
ACQUIREDATE	3/6/2007 12:00:00 AM
ACQUIRECOST	18500
DEPARTMENT	CIVIC OPERATIONS
DIVISION	PARKS & CIVIC FACILITIES
SUBDIVISION	NATURAL RESOURCES
LOCATION	81328
ADDRESS	
WARRANTYDATE	
WARRANTYODOMETERHRS	
WARRANTYNOTES	
CONDITION	6
CONDITIONDATE	
CONDITIONCOMMENT	REPLACEMENT ON ORDER - BL
SECURELINK	
DOCUMENTATIONLINK	
ODOMETER	
HOURSMETER	
AGE	15
USEFULLIFE	0
REMAININGLIFE	-5
DISPOSALDATE	
DISPOSALVALUE	
DEPRECIATIONLIFE	10
REPLACEMENTYEAR	0
CURRENTREPLACEMENTCOST	40000