



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01282WO

Closing Date Jul 23, 2026

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 1

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	New Unit Rig Up: Hook loader up	10.5		CA\$ 0.00

Repair Story: Punch #1 (Line 1) - 07/08/2026: went to hook loader up and found tractor was dead, boost and get running went to hook loader up and found a broken pin for Main lift arm notified Dylan and he ordered new park tractor in line up and start looking into why we have dead batteries when Master is off, found the cause is likely a bad master Switch Punch #2 (Line 1) - 07/09/2026: build a pin so I could hook the loader up install pin Hooke loader up bring to wash bay and wash loader and tractor off the correct pin came in and install correct pin Punch #3 (Line 1) - 07/13/2026: Dig out Blade, unhook Loader Attempt to Hook Blade up Need parts, Derig tractor Punch #4 (Line 1) - 07/21/2026: Hook Blade up Change Hyd Block and get working

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
	#8 MOFS X 1/2" MNPT STRAIGHT	4	\$16.84
	POPPET STYLE COUPLER TIP	4	\$36.52
	BALL TYPE COUPLER QAC-08-08NPTF	1	\$18.23
	PIN	1	\$286.51

Parts Total for Line: \$358.10



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-01282WO

Closing Date Jul 23, 2026

Labour Billed: CA\$ 0.00

Parts Total: \$358.1

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 358.10

Work Order Total after GST: CA\$ 376.01