



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00910WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 0

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Cylinder Replace: - grapple cylinders were sent away for rebuild -install rebuilt grapple cylinders on unit	2.5		CA\$ 0.00
Repair Story: David Bergen - 05/19/2026: -grapple cylinders were sent away for rebuild -install rebuilt grapple cylinders on unit				

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
	1-1/8" COLD ROLL ROD	3	\$59.07
	1" COLD ROLL ROD	3	\$28.05
LF3462	Lube filter	1	\$9.54
FF5226	FILTER FUEL	1	\$9.65
5W40ROTELLA BULK	5W40 ROTELLA	5	\$39.8

Parts Total for Line: \$146.11

Labour Billed:CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00910WO

Closing Date

Parts Total: \$146.11

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 146.11

Work Order Total after GST: CA\$ 153.42



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00866WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 0

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's: 0

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Quick Tach / Coupler Repair: check over unit	3.5		CA\$ 0.00

Repair Story: Cory Thorburn - 05/18/2026: check over unit, grease, get washed, hook up to wobbles
Tyson Waldner - 05/19/2026: Install Grapple on Loader Grind down pin to fit got loader to move Grapple over, Did not have pin for Left Cylinder Matty said its in the tractor

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00866WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00835WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Cylinder Replace: - REPAIR GRAPPLE CYLINDER	0		CA\$ 0.00

Repair Story:

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
	7500 bucket grapple cylinder repair	1	\$1,331.12

Parts Total for Line: \$1331.12

Labour Billed:CA\$ 0.00

Parts Total: \$1,331.12

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 1,331.12

Work Order Total after GST: CA\$ 1,397.68



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00835WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00660WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 6,221

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - General Inspection / Walkaround: Pre Job inspection	3		CA\$ 0.00

Repair Story: Tyson Waldner - 04/20/2026: Boost get Started,
Hook up Disc, Bring to wash bay
Do Pre Job inspection
Change 4 grease zerks on Disc grease complete unit check all fluids
Tyson Waldner - 04/21/2026: Pull Grapple Cyl apartand give to Dylan forrebuild

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00660WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00453WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 6,231

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Charging System Test: -check machine for discharging batteries	3		CA\$ 0.00
Repair Story: Lance MacElheren - 03/12/2026: -boost and start machine -check charging system -trace ground wires that bypass master switch to see what might be drawing on batteries				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00453WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00334WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: -START UNIT -CHECKOVER -PUT LOADER ARMS ON	2		CA\$ 0.00

Repair Story: David Bergen - 02/26/2026: -remove and replace battery on unit

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2026-00334WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02279WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 6,215

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - No Start: get tractor running	3		CA\$ 0.00

Repair Story: Evan Williams - 12/26/2025: set up genset with charger and heater. got running. brought into shop. tired to get front pto to work

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-02279WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01855WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 0

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cab - Door Latch / Handle Repair: door	11.5		CA\$ 0.00
Repair Story: Tyson Waldner - 10/14/2025: try and Adjust door again seem to get it Adjusted a bit better and go through Power harrow attachment and Disc attachment Evan Williams - 10/25/2025: removed what was left of LH driver door. cleaned out glass from cab Evan Williams - 10/25/2025: started mounting new hinges on new glass Evan Williams - 10/26/2025: re shaped door handle to mount to glass. installed seal and latch. installed door and adjusted. cleaned out all glass. Tyson Waldner - 10/26/2025: re shaped door handle to mount to glass. installed seal and latch. installed door used Crane to hold door and adjusted. cleaned out all glass.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Software - Forced DPF Regen Initiate: boost	2		CA\$ 0.00
Repair Story: Tyson Waldner - 10/29/2025: Boost machine (Master Switch was left on) got running and found had Exhaust filter code, had to do a parked Regen as the Auto Regen was Disabled, did park Regen and set the system to auto Regen				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01855WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Battery Cable Replace: shorted Battery	4		CA\$ 0.00

Repair Story: Tyson Waldner - 11/13/2025: travel to site found Negative Battery post clam melted, cut Clamp off, Crimp new one on, check battery, start tractor, check alternator test tractor function all seems good travel back to shop

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
		2	\$239.84
		2	\$390.38
		4	\$108.4
		8	\$145.2
		2	\$671.18
		2	\$1,685.78
		2	\$234.48
		4	\$48.04
		6	\$10.38
		8	\$22.24
		8	\$400
		1	\$155.33

Parts Total for Line: \$4111.25

Labour Billed: CA\$ 0.00

Parts Total: \$4,111.25

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 4,111.25

Work Order Total after GST: CA\$ 4,316.81



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01855WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01724WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 6,064

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - 3-Point Hitch Repair: 3pt hitch air seat switch	5		CA\$ 0.00

Repair Story: Tyson Waldner - 10/01/2025: looked at why pins and retainers keep breaking on 3pt hitch found that attachment pins have excessive movement went to Schnell and Barrie and got 2 Bushings to bring 3pt hitch arms from 1-1/2" bore to 1-1/4" bore. Had to turn Bushings down to proper size Tractor was Metric and Bushings were SAE use Lathe to turn down and then press bushings into Bore Flapper wheel I.D. to Accommodate Pins, Build Spacers to tighten up area between pin and Attachment, put all together Check with Dylan and Matt Build 4 more Spacers and send 2 new pins, 4 Spacers and a bunch of Lynch pins along install new seat ride height switch test and works properly



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01724WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Cab - Mirror Replace: Door not closing properly Mirror wiggly	2		CA\$ 0.00

Repair Story: Tyson Waldner - 10/06/2025: Install spacers on the mirror, seemed to tighten up a fair bit. If the problem persists will need to order new plastic mounting piece.

Door closes hard.

Tried adjusting striker, seemed to help a bit.

No adjustment on hinges.

Just the way John Deeres are.

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	55339 BUSHING 1 1/4 X 1 1/2 X 1 1/2	4	\$38

Parts Total for Line: \$38.00

Labour Billed: CA\$ 0.00

Parts Total: \$38

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 38.00

Work Order Total after GST: CA\$ 39.90



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01693WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 6,237

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cab - Seat Replace: -seat	1		CA\$ 0.00

Repair Story: Lance MacElheren - 09/21/2025: -check seat for not airing up

-**air line to armrest switch broken off switch, need new switch

-plug off air line so seat will air up

-order parts

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	34M7266 insert	5	\$13.2

Parts Total for Line: \$13.20

Labour Billed:CA\$ 0.00

Parts Total: \$13.2

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 13.20

Work Order Total after GST: CA\$ 13.86



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01693WO

Closing Date