



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01557WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 6,004

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cab - Mirror Replace: Inspection	5		CA\$ 0.00

Repair Story: Tyson Waldner - 09/08/2025: Completed inspection
Tyson Waldner - 09/09/2025: Driver side mirror loose
Tried to make shims to put in there, I could not find anything small enough.
Spoke with Dylan, he will speak with John Deere to get correct parts

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	RE225257 Air ride seat switch	1	\$145.71

Parts Total for Line: \$145.71

Labour Billed:CA\$ 0.00

Parts Total: \$145.71

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 145.71

Work Order Total after GST: CA\$ 153.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01557WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01471WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 5,993

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Battery Replace: - check machine for not starting	6.5		CA\$ 0.00
Repair Story: Lance MacElheren - 08/24/2025: -pick up battery at Glover -travel to site at Opal -change battery -check charging system OK -travel back to shop				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01471WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01203WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 5,957

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Service and inspect	5.5		CA\$ 0.00

Repair Story: Adam Kohler - 07/14/2025: Made wo
Scott Dancy - 07/14/2025: service unit.
Tyson Waldner - 07/14/2025: Build Spacers for 3pt Hitch

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01203WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00859WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 5,833

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - Pre-Trip Defect: inspection	4.5		CA\$ 0.00

Repair Story: Jeff Franklin - 05/28/2025: check over unit before sending to site, remove broken slow moving vehicle sign and replace, checked lights, left rear signal and brake lights not working, remove light assembly and change both bulbs and tested, install unit numbers, top up hydraulic oil, pull rad screens and blow out, blow out rads, remove and replace air filter, fill washer fluid and test, check hivac controls, tightened loose bolts on wheel weights, serpentine belt no good, remove fan, fan hub and shroud to access and work new belt around hydraulic front drive to bottom pully, install belt, install fan, fan hub and adjust shroud to fit and tighten, blow off excess dirt before starting

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00859WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00744WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 5,800

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Lube - Full Greasing: Tractor and Attachments	4		CA\$ 0.00

Repair Story: Tyson Waldner - 05/05/2025: look at attachments Grease and check over and check Tractor over hook up power harrows and test and move Disk, tractor and Power Harrows to Wash Bay
Tyson Waldner - 05/08/2025: un hook power Harrow and hook up Disk and Bring to wash bay

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Body - Body Panel Repair: 20LB Extinguisher	1		CA\$ 0.00

Repair Story: Tyson Waldner - 05/14/2025: look at where to Mount a 20LB Extinguisher Got Carry over to find a suitable spot to mount it and it was decided to put an updated5 LB updated back in

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00744WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00646WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 5,800

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Gauge Cluster Replace: install new Cluster	2.5		CA\$ 0.00

Repair Story: Tyson Waldner - 04/23/2025: installed new Cluster but would not go into gear and made a phone call and found that the new cluster needs to be programed to Tractor lined up with Matty to get done
Tyson Waldner - 04/24/2025: Go with contractor and install new Cluster Program

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00646WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00568WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500
Manufacturer: Deere
Year: 2013
Hours: 123

Serial Number: 1RW6170RLDD006326
Model: 6170R
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Frame - Battery Box Replace: Repair master switch lo cation and wiring.	7.5		CA\$ 0.00

Repair Story: Cory Bell - 04/09/2025: Removed passenger side ladder to access battery box.

Disconnect and remove e master switch.

Find location to install master.

find some angle iron and cut to size and drill holes for mounting.

Cory Bell - 04/10/2025: Complete master switch and bracket install.

Install grapple attachment. heated up and bent one ear straight for the grapple cylinder mounting pin.

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00568WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00086WO

Closing Date

Account:

,

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Repair (Plug / Patch): Repair flat tire and wheel weight fell off	9		CA\$ 0.00

Repair Story: Jason Cordel - 01/24/2025: null

Jason Cordel - 01/25/2025: Go to unit Saturday loaded tire on 1504. Jessie brought this truck. Remount the weight onto hub. Lift tractor some more and install tire . Once mobile

Moved tractor back to laydown. Dropped Jessie at his truck again then went back to lay down. Check over tractor and found weight on right side wheel was almost falling off too. Secure it . Return to shop

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Hydraulics - Fitting Replace: repair hydraulic leak at quick connect	2.83		CA\$ 0.00

Repair Story: Cory Thorburn - 01/27/2025: travel from shop to site, replace bad oring on quick connect, test for leaks, no leaks, clean up oil, travel from site to shop

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00086WO

Closing Date

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00080WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Bucket Replace: remove grapple	4		CA\$ 0.00

Repair Story: Cory Thorburn - 01/23/2025: travel from shop to sit

Cory Thorburn - 01/23/2025: remove grapple

Cory Thorburn - 01/23/2025: travel from sit to shop

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Hydraulics - Hose Replace - Single: fix oil leak, grease unit	3		CA\$ 0.00

Repair Story: Cory Thorburn - 01/29/2025: hyd hose at front left corner of motor blew off, install hose with new clamp, top up hyd oil, grease unit,

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00080WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00079WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Bucket Replace: Remove grapple	4		CA\$ 0.00

Repair Story: Cory Thorburn - 01/23/2025: travel from shop to site

Cory Thorburn - 01/23/2025: remove grapple put on back of truck

Cory Thorburn - 01/23/2025: travel from sit to shop

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00079WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00066WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours: 5,682

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Battery Replace: replace battery, install disconnect switch , install battery blanket	4		CA\$ 0.00

Repair Story: Jason Cordel - 01/22/2025: null

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00066WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00035WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - 3-Point Hitch Repair: service call to Augustin pit	2.5		CA\$ 0.00

Repair Story: Jeff Franklin - 01/13/2025: take 1520 to Augustin pit to help Matt lift snow blade back on mount, 3 point hitch ended up breaking the weld so disconnected and waited for another unit to arrive with trailer to hoist onto deck and help chain down, head back to shop

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00035WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02666WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500Welding ONLY

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Dozer Blade Repair / Weld: blade mount	7		CA\$ 0.00
Repair Story: Trey Albers - 12/20/2024: modified blade monting plate				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Attachment - Dozer Blade Repair / Weld: Dozer blade weld repair.	4		CA\$ 0.00
Repair Story: Trey Albers - 12/21/2024: mounted blade to tractor				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02666WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02205WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 7500

Manufacturer: Deere

Year: 2013

Hours:

Serial Number: 1RW6170RLDD006326

Model: 6170R

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: install unit numbers	0.5		CA\$ 0.00
Repair Story: clean area, install unit numbers on both sides of loader arms				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00