



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00244WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Fluid Service / Filter Change: -Fill unit with hydraulic oil -Grease unit -Fix oring on ripper	4		CA\$ 0.00

Repair Story:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	General - Site Service Call: -Drive to rocky farms from RTRC shop	1.5		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00244WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00258WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 5,801

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Ripper Tooth Replace: -Remove and replace ripper tooth-Remove and replace broken oring on ripper -Drive back to RTRC shop	3.5		CA\$ 0.00
Repair Story:				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	General - Site Service Call: Travel back to shop.	1.5		CA\$ 0.00
Repair Story:				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00258WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00150WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Ripper Tooth Replace: -Drive to Rocky farms to do prestarts and lubing. -Remove and replace ripper teeth. -Onsite mechanic for the day. -Drive back to RTRC shop.	14		CA\$ 0.00
Repair Story:				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00150WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00153WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Attachment - Ripper Frame Repair: -Remove and replace ripper guard. -Drive back to RTRC shop.	6		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00153WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00111WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - Hydraulic Leak: Hyd Hoses on machine	0.5		CA\$ 0.00

Repair Story: Tyson Waldner - 01/25/2025: look over hoses on machine touch base with Carrie and get her part number for hoses that are likely next to go

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00111WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00078WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Hose Replace - Single: repair leaking hose on ripper	4		CA\$ 0.00

Repair Story: Jason Cordel - 01/24/2025: null

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00078WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02689WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours:

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Two-Way Radio Repair: -Hardwire in 2way radio (programable) -Fuel unit. -Check all fluids (truck swivel oil low) -Hook up diagnostic computer and clear all codes.	4.5		CA\$ 0.00

Repair Story: David Bergen - 12/27/2024: -Hardwire in 2way radio (programable)

-Fuel unit.

-Check all fluids (truck swivel oil low)

-Hook up diagnostic computer and clear all codes.

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02689WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02678WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 3007

Manufacturer: CAT

Year: 2015

Hours: 5,557

Serial Number: CAT00D8THFMC00329

Model: D8T

KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cab - Seat Replace: Flip Ripper Shanks, and Seat Sensor not working	6		CA\$ 0.00
Repair Story: Tyson Waldner - 12/23/2024: Flip Shanks Tyson Waldner - 12/23/2024: Chase wiring in seat Sensor find Broken Wire and repair				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2024-02678WO

Closing Date