



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01708WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,274

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,103,215

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Air System - Air Line Fitting Replace: Fix air to fan	0.5		CA\$ 0.00
Repair Story: Adam Kohler - 09/29/2025: Removed Broken quick connect, installed nut and furl.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Intake - Turbocharger Replace: Fix Turbo Gasket leak	2.25		CA\$ 0.00
Repair Story: Adam Kohler - 09/29/2025: Removed turbo, installed new gasket and reinstalled turbo				

Parts:

Line: 2

SKU:	Part Name:	Quantity Used:	Total:
	T STAT	1	\$124.56
	GASKET	1	\$16.08
	SEAL 186780	1	\$31.74
	GASKET 3682673	1	\$43.67

Parts Total for Line: \$216.05

Line: 3

SKU:	Part Name:	Quantity Used:	Total:
------	------------	----------------	--------



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01708WO

Closing Date

BELT	1	\$180.99
PULLEY CRANK	1	\$292.99

Parts Total for Line: \$473.98

Line: 4

SKU:	Part Name:	Quantity Used:	Total:
LF14000NN	Lube filter	1	\$54.63
5W40ROTELLA BULK	5W40 ROTELLA	52	\$387.4
FF5825NN	Fuel filter	1	\$74.12
FS20075	Fuel filter	1	\$35.79

Parts Total for Line: \$551.94

Labour Billed:CA\$ 0.00

Parts Total: \$1,241.97

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 1,241.97

Work Order Total after GST: CA\$ 1,304.07



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01704WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,266

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Cooling - Fan Hub Replace: replace fan hub	2		CA\$ 0.00

Repair Story: Evan Williams - 09/28/2025: removed fan belt and tensioner, removed hub. installed new. still squealing. alternator pully little play?

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	HVAC - Auxiliary Heater Service (Webasto / Espar): check webasto, block heater	1		CA\$ 0.00

Repair Story: Evan Williams - 09/28/2025: checked block heater good. tried to get webasto to start, couldn't get to fire.

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01704WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01668WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,228

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,101,543

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Axle 2 left axle gasket leaking	1.5		CA\$ 0.00
Repair Story: Adam Kohler - 09/24/2025: Removed axle, cleaned surfaces installed new gasket, checked diff lvl				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01639WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,181

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,098,915

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Suspension - Cab Air Bag Replace: Replace cab air bags	1.5		CA\$ 0.00

Repair Story:

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01639WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01640WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit:	1511	Serial Number:	1NPWX4TX1DD187441
Manufacturer:	Peterbilt	Model:	Conventional
Year:	2013		
Hours:	26,187	KM's:	1,099,197

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Engine - Belt Replace: Diag and fix belt squealing and truck heating up	1.5		CA\$ 0.00

Repair Story: Adam Kohler - 09/20/2025: Found that belt was very hard and rad was plugged up, tried to blow out, its to packed up brought to wash bay and washed out as best as I could, belts ordered

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Engine - Belt Replace: Change both engine belts	1		CA\$ 0.00

Repair Story: Adam Kohler - 09/21/2025: Started truck, aired up and brought to shop, changed both belts

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Electrical - Power Window Motor Replace: Close passenger side window	1.75		CA\$ 0.00

Repair Story: Adam Kohler - 09/21/2025: Rolled window down to back up won't go back up, checked fuse its good, tried to just at switch won't move, pulled door apart to check plug, have constant power on one side and nothing on either side when pushing down, jumped motor with external battery to close and put back together will need further diag



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01640WO

Closing Date

Parts:

Line:

SKU:	Part Name:	Quantity Used:	Total:
	as70360 air bag	2	\$137.98
	PL1369-4ATEC FITTING	2	\$23.98

Parts Total for Line: \$161.96

Labour Billed:CA\$ 0.00

Parts Total: \$161.96

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 161.96

Work Order Total after GST: CA\$ 170.06



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01543WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 26,060

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Switch Replace: fix driver window	0.5		CA\$ 0.00

Repair Story: Evan Williams - 09/06/2025: found window switch was no good. jumped wires to role up and removed switch.

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: service			CA\$ 0.00

Repair Story:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Tires - Tire Replace: replace #4 axle tires			CA\$ 0.00

Repair Story:

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
	LH WINDOW SWITCH	1	\$60.99



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01543WO

Closing Date

Parts Total for Line: \$60.99

Line: 2

SKU:	Part Name:	Quantity Used:	Total:
LF14000NN	Lube filter	1	\$54.63
5W40ROTELLA BULK	5W40 ROTELLA	8	\$59.6

Parts Total for Line: \$114.23

Labour Billed:CA\$ 0.00

Parts Total: \$175.22

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 175.22

Work Order Total after GST: CA\$ 183.98



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01489WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,993

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Steering - King Pin Replace: check front end, replace tires	2.5		CA\$ 0.00
Repair Story: Evan Williams - 08/30/2025: Jacked up front end. found king pins worn, need replaced. removed front tires swapped over new rubber				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	: level 2 inspection	1.5		CA\$ 0.00
Repair Story: Evan Williams - 08/31/2025: Completed level 2 inspection				

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
	300305 KING PINS	1	\$319.43

Parts Total for Line: \$319.43

Labour Billed:CA\$ 0.00

Parts Total: \$319.43

Consumables: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01489WO

Closing Date

Work Order Total before GST : CA\$ 319.43

Work Order Total after GST: CA\$ 335.40



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01441WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,900

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 107,600

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Diagnose and Advise - Coolant Leak: coolant leak	2		CA\$ 0.00
Repair Story: Cory Thorburn - 08/22/2025: travel from shop to unit, fix coolant leak, travel to shop				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Intake - Turbocharger Replace: exhaust leak	11		CA\$ 0.00
Repair Story: Cory Thorburn - 08/23/2025: checked exhaust leak found all of exhaust is loose/ broken and leaking Cory Thorburn - 08/24/2025: remove turbo to replace mounting gasket, found turbo and manifold are cracked, pick up new parts at ontrack, remove broken manifold bolts, install new manifold and turbo,				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Body - Tarp Replace: replace tarp	2.5		CA\$ 0.00
Repair Story: Cory Thorburn - 08/24/2025: replaced tarp				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01441WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Exhaust - Exhaust Pipe Replace: Fix exhaust at stacks	3.75		CA\$ 0.00
Repair Story: Adam Kohler - 08/26/2025: removed exhaust clamps, cut left size to fit Adam Kohler - 08/26/2025: removed other side clamps and cut out pipe, cut flex pipe to fit, struggled to get pipe to fit, finally got it				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
5	Intake - Turbocharger Replace: Diag. loud turbo	5.5		CA\$ 0.00
Repair Story: Adam Kohler - 08/26/2025: Confirmed its whistling, removed intake and exhaust off turbo, no change, noticed broken manifold bolts, Called dispatch made sure I could take it out of service and brought into shop, drained coolant and removed turbo and manifolds, extracted broken bolts Cory Thorburn - 08/26/2025: install manifold and turbo				

Parts:

Line: 2

SKU:	Part Name:	Quantity Used:	Total:
	FTP61055	1	\$6,585
	MCBISX009	1	\$295.92
	2880215	1	\$36.98
	2880214	1	\$24.12
	3682940	1	\$15.83
	M-368271	4	\$49.24

Parts Total for Line: \$7007.09

Line: 4

SKU:	Part Name:	Quantity Used:	Total:
	TURBO GASKET	1	\$25.48
	SPACER	1	\$19.79
	EXHAUST MANIFOLD GASKETS	4	\$125.92
	EXH MAN BOLTS	12	\$155.88
	EX GASKET 3682940CUM	2	\$73.98

Parts Total for Line: \$401.05

Line: 5



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01441WO

Closing Date

SKU:	Part Name:	Quantity Used:	Total:
X007785	SealClamp	4	\$75.44

Parts Total for Line: \$75.44

Labour Billed:CA\$ 0.00

Parts Total: \$7,483.58

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 7,483.58

Work Order Total after GST: CA\$ 7,857.76



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01349WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,833

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,076,604

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: Service and inspect lvl 2	3		CA\$ 0.00

Repair Story: Adam Kohler - 08/07/2025: Made WO

Cory Thorburn - 08/07/2025: change oil and oil

Evan Williams - 08/09/2025: changed both fuel filters. completed inspection.

Parts:

Line: 1

SKU:	Part Name:	Quantity Used:	Total:
LF14000NN	Lube filter	1	\$54.51
5W40bulk	5W40 bulk oil	44	\$295.24

Parts Total for Line: \$349.75

Labour Billed: CA\$ 0.00

Parts Total: \$349.75

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 349.75

Work Order Total after GST: CA\$ 367.24



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01349WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01278WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 25,727

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,069,737

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Engine - Belt Replace: replace engine fan vbelt and tensioner,	0.5		CA\$ 0.00
Repair Story: Jason Cordel - 07/27/2025: remove old fan belt and tensioner, get new and install.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Body - Hood Repair: replace left hood strap	0.5		CA\$ 0.00
Repair Story: Jason Cordel - 07/27/2025: remove hood strap find correct one and instal lit.				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Tires - Tire Replace: replace all axle 2 tires,	1.5		CA\$ 0.00
Repair Story: Jason Cordel - 07/27/2025: remove all axle 2 tires, and replace with new tires, remount and torque wheel nuts,				



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-01278WO

Closing Date

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
4	Diagnose and Advise - General Inspection / Walkaround: quick check	0.5		CA\$ 0.00

Repair Story: Jason Cordel - 07/27/2025: perfrom quick check,

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00