



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00611WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,849

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,014,105

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Hydraulics - Hose Replace - Single: Blown HYD line on Pup	4		CA\$ 0.00

Repair Story: Tyson Waldner - 04/14/2025: Top truck with oil, travel to site, repair trailer, top with oil 150L Verify Fix travel back to shop

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Electrical - Tail Light Replace: light out and Air leaks	4.5		CA\$ 0.00

Repair Story: Tyson Waldner - 04/13/2025: Repair Lights as needed found a couple Substantial Air leaks and repair as needed

Parts:

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00611WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00572WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,818

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	: complete service	4		CA\$ 0.00

Repair Story: Cory Thorburn - 04/08/2025: drain engine oil replace filter, fill with oil, wash off fuel filters, replace both fuel filters, check over truck, replace #3 right brake pot, tighten #4 right brake pot

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00572WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00472WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,718

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,006,885

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Trailer Plug / 7-Pin Receptacle Replace: Trailer Right Signal light out	3		CA\$ 0.00
Repair Story: Tyson Waldner - 03/24/2025: right signal out on Trailer check trailer plug not working on truck side check fuses with test light good check Junction box under Box connections are clean and had no power coming there check junction under cab no power there either pulled fuses again and replaced and worked after that put all back together				

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Electrical - Marker / Clearance Light Replace: marker lights	0.5		CA\$ 0.00
Repair Story: Tyson Waldner - 03/24/2025: did Quick check and found Marker out replace				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00472WO

Closing Date

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00356WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,587

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,002,342

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Brakes - S-Cam / Cam Shaft Service: REPLACE BROKEN S-CAM TUBE AXLE 4 LEFT	5.5		CA\$ 0.00

Repair Story: Jason Cordel - 03/08/2025: null

Jason Cordel - 03/08/2025: null

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00356WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00310WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,748

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,002,326

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Air System - Air Line Repair: air leak	1.5		CA\$ 0.00

Repair Story: Jeff Franklin - 03/01/2025: check for air leaks, found an air line rubbed through on back of transmission, remove and replace line, check for leaks, push connect fitting not sealing, cut out and install compression style fitting, check for leaks, diff lock valve seems to be leaking, will need to order new valve

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Body - Body Panel Repair: replace broken side boards	1.5		CA\$ 0.00

Repair Story: Jeff Franklin - 03/01/2025: remove broken side boards, cut and install new boards

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
3	Tires - Tire Replace: replace worn out steer tires	2		CA\$ 0.00

Repair Story: Jeff Franklin - 03/01/2025: remove wheels, remove tires axle 1 right and left, install new tires, torque, tag, mark and pics

Parts:



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00310WO

Closing Date

Labour Billed: CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00276WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,583

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,002,325

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Replace: Change worn tires axle 4	2		CA\$ 0.00
Repair Story: Adam Kohler - 02/26/2025: R and R axle 4 tires, and torqued to spec				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00276WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00272WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,581

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 1,002,323

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Tires - Tire Replace: Change damaged front right tire	1		CA\$ 0.00
Repair Story: Adam Kohler - 02/25/2025: Removed wheel change tire, inflated and torqued to spec				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00272WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00165WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours:

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's:

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Tail Light Replace: repair wiring at rear of truck for lights and trailer cords,	11.5		CA\$ 0.00
Repair Story: Jason Cordel - 02/15/2025: null Jason Cordel - 02/16/2025: null				

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00165WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00145WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,450

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 998,961

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Electrical - Tail Light Replace: fix lights and end gate wiring	1.5		CA\$ 0.00

Repair Story: Cory Thorburn - 02/06/2025: fix broken wires for tail lights and end gate under box in junction box

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00145WO

Closing Date



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00132WO

Closing Date

Account:

Road to Rail Construction Group Inc

RR1 Site 5 Box 9

Camrose,AB Canada T4V 2M9

Customer PO:

Unit: 1511
Manufacturer: Peterbilt
Year: 2013
Hours: 24,413

Serial Number: 1NPWX4TX1DD187441
Model: Conventional
KM's: 997,666

Repair Line Items:

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
1	Air System - Hand / Trailer Valve Replace: divertor valve froze up	1		CA\$ 0.00

Repair Story: Jeff Franklin - 02/03/2025: use torch to heat divertor valve, work switch and free up, lift box, clean and lube slider, drain air in 2527 and alcohol blast

Line Number:	Repair Description:	Tech Hours:	Rate:	Labour Charged:
2	Intake - Turbocharger Replace: replace turbo	7		CA\$ 0.00

Repair Story: Cory Thorburn - 02/04/2025: make new block off plate for cross over pipe
Cory Thorburn - 02/04/2025: install turbo speed sensor, let run take oil sample top up oil
Jeff Franklin - 02/04/2025: help offload unit into shop, drain coolant, remove all pipes and wiring, remove turbo, remove exhaust pipes, clean up and weld all the holes where the turbine hit, change over fitting to new turbo, prime turbo and install, torque to spec, install lines, hoses and wiring, fill with coolant, install exhaust

Parts:

Labour Billed:CA\$ 0.00

Parts Total: \$

Consumables: CA\$ 0.00



Road to Rail Construction Group Inc.

RR1 Site 5 Box 9

Camrose, AB Canada T4V 2M9

2025-00132WO

Closing Date

Work Order Total before GST : CA\$ 0.00

Work Order Total after GST: CA\$ 0.00