

Finning (Canada), a division of Finning International Inc.

118 MACDONALD CRESCENT
FORT MCMURRAY, AB T9H 4B2
(780) 743-2218
(780) 791-0584 FAX

Date 18/04/23
Invoice Number 962385011
Invoice Total \$5,308.67
Payment Terms NET 60 DAYS

PAYER CA-0048404
SURERUS PIPELINE INC
10912 91 AVENUE
FORT ST JOHN BC V1J 6G9

Due Date 17/06/23
Currency CANADIAN DOLLAR
Customer Tax Exemption No.
Customer Reference No. 2016955
Order Date 21/02/23
Order Number 0060874682
Finning Contact ASHLEY TUCKER 780 713 4273
Customer Contact AARON WURZ 780 974 4154
Customer Commitment Date 03/04/23
Actual Completion Date 03/04/23



CUSTOMER LOCATION CA-0048404
SURERUS PIPELINE INC
C/O 118 MACDONALD CRES
FORT MCMURRAY AB T9H 4B2

Make CAT
Model 336E
Serial Number FJH00310
Unit Number EX209-FJH00310
Meter Reading H 9592.00
(21/02/23)

Line No.	Qty	Item No.	Description	U/M	Sales Price
10		336E 336E	DPF TRBLSHOOT IN FIELD		
		Customer Reference No.	REGEN LOCK OUT		
		UNIT EX209			
		COMPLAINT: CUSTOMER ADVISED UNIT IS DOWN FOR REGEN LOCK OUT			
		SUSPECTS OPERATOR IGNORED WARNING			
		CAUSE: ICE IN AIR TO AIR COOLER			
		FEB 22 2023			
		PSR			
		ACTIVE CODES SOOT LEVEL HIGH			

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This Service Invoice is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms

Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty

Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations. The Terms and Conditions of this Service Invoice, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.



SERVICE INVOICE

Page: 2 (3)

Finning (Canada), a division of Finning International Inc.

118 MACDONALD CRESCENT
FORT MCMURRAY, AB T9H 4B2
(780) 743-2218
(780) 791-0584 FAX

Date 18/04/23
Invoice Number 962385011
Invoice Total \$5,308.67
Payment Terms NET 60 DAYS

Due Date 17/06/23

CUSTOMER NUMBER CA-0048404

Line No.	Qty	Item No.	Description	U/M	Sales Price
			TRIED TO DO A REGEN IT FAILED LOW AIR PRESSURE INSPECTED INTAKE HOSES, ALL LOOK OK BOOST PRESSURE READS ZERO HOOK UP GUAGE, IT READS BETWEEN 1 PSI AND 14 PSI DEPENDING ON RPM SENSOR NOT WORKING CORRECTLY REMOVED SENSOR AND INSPECTED, TRIED TO CLEAN OUT SENSOR CUSTOMER PICKING UP PARTS FROM TOWN INSTALLED NEW SENSOR SAME RESULTS REMOVED SENSOR RUN MACHINE SENSOR PORT HAS A VACUUM SUSPECT ICE IN AIR TO AIR COOLER BLOCKING OFF INTAKE WHEN RUNNING NOT ENOUGH AIR FLOW GUAGE SHOWED PRESSURE BECUASE OF LOCATION AND SIZE OF PORT OUT OF TIME CUSTOMER WILL PUT HEAT ON MACHINE OVER NIGHT FEB 23 2023 REMOVED GUARD FROM UNDER RAD REMOVED AIR TO AIR OUTLET PIPE, LOTS OF WATER CAME OUT RUN MACHINE WITH PIPE OFF TO BLOW OUT WATER INSTALLED HOSE AND GUARD RUN MACHINE NOW BOOST PRESSURE READS BETWEEN 1 AND 8 PSI DEPENDING ON RPM DID A MANUAL REGEN , IT WAS SUCCESFUL DID A SECOND ONE BECAUSE IT WAS OUT 120% PLUGGED SECOND BURN SUCCESFUL REPLACED ARD HEAD SPARK PLUG BECAUSE IT HAS 1 HIT FOR BAD PLUG LEFT NEW MANIFOLD PRESSURE SENSOR IN MACHINE BECAUSE OF		

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001



SERVICE INVOICE

Page: 3 (3)

Finning (Canada), a division of Finning International Inc.

118 MACDONALD CRESCENT
FORT MCMURRAY, AB T9H 4B2
(780) 743-2218
(780) 791-0584 FAX

Date 18/04/23
Invoice Number 962385011
Invoice Total \$5,308.67
Payment Terms NET 60 DAYS

Due Date 17/06/23

CUSTOMER NUMBER CA-0048404

Line No.	Qty	Item No.	Description	U/M	Sales Price
AMOUNT OF WATER IN THE INTAKE SYSTEM PACKED UP					
COMPLICATION: LOCATION MACHINE ON HIGHWAY 63 WAIT AT SAND TIGER LODGE COLD -35'C					
	1.00	3203061	SENSOR GP	PC	407.27
	1.00	2953099	PLUG-SPARK	PC	18.03
	1.00	2287101	SEAL-O-RING	PC	10.58
	11.00	108F-035- -ACZ-001	JOURNEYMAN FIELD	EA	3,080.00
	5.50	108F-035- -ACZ-001	JOURNEYMAN TRAVEL	EA	1,540.00
Labor					4,620.00
Material					435.88
Service Total					5,055.88
Order total					5,055.88
GST					252.79
Invoice Total					\$5,308.67

Thank you for your business.



PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This Service Invoice is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms

Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty

Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations. The Terms and Conditions of this Service Invoice, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.



SERVICE INVOICE

Page: 1 (3)

Finning (Canada), a division of Finning International Inc.

10910 - 170 STREET
EDMONTON, AB T5S 1H6
(780) 483-1122
(780) 443-7995 FAX

Date 27/04/23
Invoice Number 962390359
Invoice Total \$8,225.62
Payment Terms NET 60 DAYS

PAYER CA-0048404
SURERUS PIPELINE INC
10912 91 AVENUE
FORT ST JOHN BC V1J 6G9

Due Date 26/06/23
Currency CANADIAN DOLLAR
Customer Tax Exemption No.
Customer Reference No. PO# 2016895
Order Date 10/04/23
Order Number 0060883971
Finning Contact TOM KUZIO / STEPHANIE PRICE
Customer Contact JARET SURERUS 780-231-0744
Customer Commitment Date 00/00/00
Actual Completion Date 27/04/23



CUSTOMER LOCATION CA-0048404
SURERUS PIPELINE INC
10912 91 AVENUE
FORT ST JOHN BC V1J 6G9

Make CAT
Model 336E
Serial Number FJH00310
Unit Number EX209-FJH00310
Meter Reading H 9750.00
(10/04/23)

Line No.	Qty	Item No.	Description	U/M	Sales Price
----------	-----	----------	-------------	-----	-------------

10		336E	CLN EMISN MOD TRBLSHOOT IN		
		336E	FIELD		

Customer Reference No. PO# 2016895

WORK ORDER: 2236590

COMPLAINT:

-AFTERTREATMENT IS LOCKED OUT DUE TO HIGH SOOT LOAD NEEDS
MANUAL REGEN AND POSSIBLE TROUBLESHOOT THE HIGH SOOT LOAD

-SMU: 9756 HRS

CAUSE:

-FOULED DPF FILTER 160% SOOT LOADED

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This Service Invoice is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms

Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty

Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations. The Terms and Conditions of this Service Invoice, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.



SERVICE INVOICE

Page: 2 (3)

Finning (Canada), a division of Finning International Inc.

10910 - 170 STREET
EDMONTON, AB T5S 1H6
(780) 483-1122
(780) 443-7995 FAX

Date 27/04/23
Invoice Number 962390359
Invoice Total \$8,225.62
Payment Terms NET 60 DAYS

Due Date 26/06/23

CUSTOMER NUMBER CA-0048404

Line No.	Qty	Item No.	Description	U/M	Sales Price
----------	-----	----------	-------------	-----	-------------

CORRECTION:
APRIL 17 2023
-TRAVEL TO SITE
-LOCKED OUT THE MACHINE
-VERIFIED THE CUSTOMERS COMPLAINT
-HOOKED UP COMPUTER AND DOWNLOADED PSR
-ACTIVE 991 CODE DPF LOCKED OUT
-RESET CODE WITH FACTORY PASSCODES
-RAN MACHINE AND HEARD BOOST LEAK (TIGHTENED ALL CLAMPS
FOUND NO OBVIOUS SIGNS OF BOOST LEAK)
-BOOST MACHINE (GOOD)
-BLOCKED THE RADIATOR
-RAN MACHINE UP TO 104 'C
-PERFORMED A MANUAL REGEN SUCCESSFUL
-JARET SAID TO GO AHEAD WITH THE DPF REPLACEMENT
-ORDERED PARTS
-TRAVEL FROM SITE

APRIL 19 2023
-TRAVEL TO SITE
-LOCKED OUT THE MACHINE
-REMOVED FAULTY DPF
-INSTALLED NEW DPF FOLLOWING KENR8149-08
-PERFORMED ASH SERVICE
-PERFORMED ASH SERVICE RESET
-PERFORMED A MANUAL REGEN
-TESTED THE MACHINE AND CONFIRMED THE REPAIR
-DOWNLOADED PSR
-TRAVEL FROM SITE

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

Finning (Canada), a division of Finning International Inc.

10910 - 170 STREET
EDMONTON, AB T5S 1H6
(780) 483-1122
(780) 443-7995 FAX

Date 27/04/23
Invoice Number 962390359
Invoice Total \$8,225.62
Payment Terms NET 60 DAYS

Due Date 26/06/23

CUSTOMER NUMBER CA-0048404

Line No.	Qty	Item No.	Description	U/M	Sales Price
COMPLICATION: -NONE					
	1.00	20R8028	KIT-FILTER	PC	5,201.80
		20R8028			
	1.00	CORECHGCATMCO	CORE CHARGE CAT MCO		3,790.84
	7.25	108D-035- -ACZ-001	JOURNEYMAN FIELD	EA	1,580.50
		336E			
	2.50	108D-035- -ACZ-001	JOURNEYMAN TRAVEL	EA	562.00
		336E			
	1.00-	20R8028	KIT-FILTER	PC	-3,790.84
		EN122365900002			
Labor					2,142.50
Material					5,201.80
Service Total					7,344.30
Order total					7,344.30
GST					367.22
PST					514.10
Invoice Total					\$8,225.62

Thank you for your business.



PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This **Service Invoice** is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms

Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty

Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

The Terms and Conditions of this **Service Invoice**, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.



Owner:	Surcus
Inspected By:	Dayton Foster
Start Date:	Aug 27, 2024
Hrs / Km:	10680 HRS

[illegible]

Signature

Date Completed



9312 - 109th street - fort St. John, BC
V1J 6G9

ENTERED

2

Mob / Demob Inspection Repair Report

Owner:	Surerus
Inspected By:	Tony Bexte
Start Date:	Nov 3 12 3
Hrs / KM:	10289

UNIT #	Ex 209	MAKE	CAT	MODEL	336E	SERIAL #	
--------	--------	------	-----	-------	------	----------	--

JOB #		MOB ☐	DEMOB ☒	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	10288	ML
-------	--	------------------------------	---	--	----------------------	-------	----

SAFETY	CHECKED	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	☒	
2. SEAT BELTS / ANCHORS	☒	☒	
3. BACKUP ALARM / HORN	☒	☒	
4. HANDRAILS / STEPS / GUARDS	☒	☒	
5. SPILL KIT / FIRST AID KIT		☒	
6. INSPECTION DECALS / LIFT CHARTS / CERTS		☒	
7. TRACK SHOVEL / POLASKI		☒	
8. LOG BOOK - FILL IN		☒	

CAB / ELECTRICAL	CHECKED	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☐	☒	
10. ROPS / FOPS / DECALS	☒	☒	
11. DOOR LATCHES / HANDLES	☒	☐	
12. SEAT CUSHIONS / FRAME	☒	☒	
13. BATTERIES - LEVELS & POSTS	☒	☐	
14. CHARGING SYSTEM / BELTS	☒	☐	
15. GAUGES - TACH, SPEED, HOUR METER, ETC.		☒	
16. WARNING LIGHTS / ALARMS		☒	
17. HEATER / AIR CONDITIONING / VENTILATION		☐	
18. 2 WAY RADIO / AM & FM RADIO		☒	
19. HEAD / SIGNAL / TAIL / DOME LIGHTS		☐	
20. POSITIVE AIR SHUT OFF		☐	

ATTACHMENTS	INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT #	☐	☐	
22. DIGGING BUCKET UNIT #	☐		
23. BLADE / RIPPER / WINCH		☐	
24. CABLE LENGTH:			BOOMLINE _____ FT LOADLINE _____ FT


MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	
26. LEAKS / RUNNING TEST	☒	
27. ENGINE / RADIATOR	☒	
28. HARD BAR BEARINGS	☒	
29. HARD NOSE BUSHINGS	☒	
30. UNDERCARRIAGE	☒	
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
☐	Light on cab not working	Marc MAZ
☐	Needs wiper blade ✓	
☐	Bucket cylinder steel tube mount isolators coming out	
☐	Front window raised latch missing bolts / loose	
☐	Outer cab filter access door damaged	
☐	Look at aux hyd fitting on RH and stick	
☐	Engine appears to not reach operating temp / Possible thermostats	
☐	Check positive air shut off / two switches	
☐	- take EGR cooler out & sent to get tested &	
☐	cleaned, Replaced coolant Reservoir	
☐	- Replaced L.H Idler	
☐	- Replaced Both pressure lines to travel motors / L.H, R.H	
☐	- Replaced L.H Idler	

SIGNATURE

DATE COMPLETE

Feb 28



Owner:	Sunerus
Inspected By	Tristan Saychuk
Start Date:	Nov 14, 2022
Hrs / KM:	9085 hr

[illegible]

SIGNATURE

DATE COMPLETE Nov 15, 2022