

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 1

Maint Code	Work Performed	Date Maint Performed	Reading
0155	<u>Western Star Bunk White Freigh</u>		
250HR	250 Hour Service	Feb 25/17	60216.00
		Dec 01/17	60216.00
		Apr 01/19	0.00
		Apr 17/20	32163.00
		Mar 10/22	0.00
AIR	Air System	Nov 23/17	0.00
AIRB	Air Bag	Nov 20/17	0.00
BRAKES	Repair	Nov 17/17	0.00
		Jan 15/21	0.00
EOIL	Engine Oil	Oct 08/16	25185.00
		Aug 21/20	25185.00
		Jul 07/22	25185.00
GRE	Grease	Mar 22/21	0.00
LIT	Lights	Apr 29/21	0.00
MISC	Misc. Maintenance & Repair	May 24/16	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		
	-new cord side dump switch to back		
	-new cord truck to trailer		
	-fix solenoid for tarp		
	Jun 1/16 - Gilles Services		
	-2 broken bolt fan belt ??? , 1 out		
	-start ??? part o remove rad		
	Jun 2/16 - Gilles Services		
	-take hood rad out		
	-drill bolt, remove it		
	-new bolt, install tensioners		
	-rad on		
	-start hook up hose, mount, top rod air to air hose		
	-rad hose		
	Jun 3/16 - Gilles Services		
	-hook up all hose, wiring		
	-hood back on		
	-hook up light		
	-put clamps hold hardware		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-antifreeze

Jun 18/16

-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

-remove and replace turbo
-installed new gaskets and O-rings
-installed new 90DEG rubber intake elbow with new clamps
-run up unit to check for leaks - all good
-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

-repair RH low beam
-repair wires, bulb, L rear tail light out, plug, tridem
gravel trailer identification light out
-resecure RH marker light
-replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out
-reset circuit breakers
-cut free trailer cord to not pull so hard and tie up
freely
-set tambone brakes
-found tight
-trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
out
-found AC compressor seized and belt blew apart damaged
main belt
-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

-service and check over
-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 3

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	May 25/16	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- make ??? side dump
- short in cable
- need new cable & plug in female 4 plug
- put light bottom cable

May 25/16 - Gilles Services

- new cord side dump switch to back
- new cord truck to trailer
- fix solenoid for tarp

Jun 1/16 - Gilles Services

- 2 broken bolt fan belt ??? , 1 out
- start ??? part o remove rad

Jun 2/16 - Gilles Services

- take hood rad out
- drill bolt, remove it
- new bolt, install tensioners
- rad on
- start hook up hose, mount, top rod air to air hose
- rad hose

Jun 3/16 - Gilles Services

- hook up all hose, wiring
- hood back on
- hook up light
- put clamps hold hardware
- antifreeze

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 5

Maint Code	Work Performed	Date Maint Performed	Reading
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 6

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- change trailer plug on end dump
- change male & female hydraulic couplers
- check hydraulic oil
- test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

- change oil and filter
- replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

- repaired coolant leak on upper radiator hose
- replaced boost pipe hose
- checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

- pull unit to start running

Apr 23/25 Tire North INV#272051733

- tire change over

MISC	Misc. Maintenance & Repair	Jun 01/16	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services

- no light on trailer
- short hardness
- make ??? side dump
- short in cable
- need new cable & plug in female 4 plug
- put light bottom cable

May 25/16 - Gilles Services

- new cord side dump switch to back
- new cord truck to trailer
- fix solenoid for tarp

Jun 1/16 - Gilles Services

- 2 broken bolt fan belt ??? , 1 out
- start ??? part o remove rad

Jun 2/16 - Gilles Services

- take hood rad out
- drill bolt, remove it
- new bolt, install tensioners
- rad on
- start hook up hose, mount, top rod air to air hose

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-rad hose		
	Jun 3/16 - Gilles Services		
	-hook up all hose, wiring		
	-hood back on		
	-hook up light		
	-put clamps hold hardware		
	-antifreeze		
	Jun 18/16		
	-hole in oil pan		
	-cleanup, silicone & JB welding		
	-fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998		
	-remove and replace turbo		
	-installed new gaskets and O-rings		
	-installed new 90DEG rubber intake elbow with new clamps		
	-run up unit to check for leaks - all good		
	-charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926		
	-repair RH low beam		
	-repair wires, bulb, L rear tail light out, plug, tridem		
	gravel trailer identification light out		
	-resecure RH marker light		
	-replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066		
	-remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082		
	-check lights out		
	-reset circuit breakers		
	-cut free trailer cord to not pull so hard and tie up		
	freely		
	-set tambone brakes		
	-found tight		
	-trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088		
	-service call to km44 pit bolt came off and coolant drained		
	out		
	-found AC compressor seized and belt blew apart damaged		
	main belt		
	-everything else was good		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 8

Maint Code	Work Performed	Date Maint Performed	Reading
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129 -repaired coolant leak on upper radiator hose -replaced boost pipe hose -checked ECR cooler		
	Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165 -pull unit to start running		
	Apr 23/25 Tire North INV#272051733 -tire change over		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 9

Maint Code	Work Performed	Date Maint Performed	Reading
MISC	Misc. Maintenance & Repair May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC	Jun 02/16	60216.00

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts
- replace MAP sensor
- replaced Vpod

Jun 19/24 - Gilles Services

- start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- replace oil can and valve cover gaskets
- replace coolant hose for EGR
- replace air bag LH rear
- replace U-joint
- replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

- change trailer plug on end dump
- change male & female hydraulic couplers
- check hydraulic oil
- test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

- change oil and filter
- replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

- repaired coolant leak on upper radiator hose
- replaced boost pipe hose
- checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

- pull unit to start running

Apr 23/25 Tire North INV#272051733

- tire change over

MISC	Misc. Maintenance & Repair	Jun 03/16	60216.00
------	----------------------------	-----------	----------

May 24/16 - Gilles Services

- no light on trailer
- short hardness
- make ??? side dump
- short in cable
- need new cable & plug in female 4 plug
- put light bottom cable

May 25/16 - Gilles Services

- new cord side dump switch to back
- new cord truck to trailer
- fix solenoid for tarp

Jun 1/16 - Gilles Services

- 2 broken bolt fan belt ??? , 1 out
- start ??? part o remove rad

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 2/16 - Gilles Services

- take hood rad out
- drill bolt, remove it
- new bolt, install tensioners
- rad on
- start hook up hose, mount, top rod air to air hose
- rad hose

Jun 3/16 - Gilles Services

- hook up all hose, wiring
- hood back on
- hook up light
- put clamps hold hardware
- antifreeze

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up
- freely
- set tambone brakes
- found tight
- trailer has no flats

Maint Code	Work Performed	Date Maint Performed	Reading
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129 -repaired coolant leak on upper radiator hose -replaced boost pipe hose -checked ECR cooler		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 14

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jun 18/16	60216.00
------	----------------------------	-----------	----------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16
-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jul 08/16	60216.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		

Maint Code	Work Performed	Date Maint Performed	Reading
	-new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp		
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint
Code

Work Performed

Date Maint
Performed

Reading

-reset circuit breakers
 -cut free trailer cord to not pull so hard and tie up
 freely
 -set tambone brakes
 -found tight
 -trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088
 -service call to km44 pit bolt came off and coolant drained
 out
 -found AC compressor seized and belt blew apart damaged
 main belt
 -everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289
 -service and check over
 -repair left side wiring to headlights
 -change broken high beam
 -low beam dim check connection
 -change fan stat not enough air flow going through it -
 good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
 -charge batteries
 -R&R ECM
 -found broken air intake temp sensor - replace with used
 engine parts
 -replace MAP sensor
 -replaced Vpod

Jun 19/24 - Gilles Services
 -start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
 -replace oil can and valve cover gaskets
 -replace coolant hose for EGR
 -replace air bag LH rear
 -replace U-joint
 -replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
 -change trailer plug on end dump
 -change male & female hydraulic couplers
 -check hydraulic oil
 -test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 19

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Aug 05/16	60216.00
------	----------------------------	-----------	----------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-put clamps hold hardware
-antifreeze

Jun 18/16

-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

-remove and replace turbo
-installed new gaskets and O-rings
-installed new 90DEG rubber intake elbow with new clamps
-run up unit to check for leaks - all good
-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

-repair RH low beam
-repair wires, bulb, L rear tail light out, plug, tridem
gravel trailer identification light out
-resecure RH marker light
-replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out
-reset circuit breakers
-cut free trailer cord to not pull so hard and tie up
freely
-set tambone brakes
-found tight
-trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
out
-found AC compressor seized and belt blew apart damaged
main belt
-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

-service and check over
-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 21

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Aug 12/16	60216.00
	May 24/16 - Gilles Services		
	-no light on trailer		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- short hardness
- make ??? side dump
- short in cable
- need new cable & plug in female 4 plug
- put light bottom cable

May 25/16 - Gilles Services

- new cord side dump switch to back
- new cord truck to trailer
- fix solenoid for tarp

Jun 1/16 - Gilles Services

- 2 broken bolt fan belt ??? , 1 out
- start ??? part o remove rad

Jun 2/16 - Gilles Services

- take hood rad out
- drill bolt, remove it
- new bolt, install tensioners
- rad on
- start hook up hose, mount, top rod air to air hose
- rad hose

Jun 3/16 - Gilles Services

- hook up all hose, wiring
- hood back on
- hook up light
- put clamps hold hardware
- antifreeze

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light

Maint Code	Work Performed	Date Maint Performed	Reading
	-replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066		
	-remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082		
	-check lights out		
	-reset circuit breakers		
	-cut free trailer cord to not pull so hard and tie up freely		
	-set tambone brakes		
	-found tight		
	-trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088		
	-service call to km44 pit bolt came off and coolant drained out		
	-found AC compressor seized and belt blew apart damaged main belt		
	-everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289		
	-service and check over		
	-repair left side wiring to headlights		
	-change broken high beam		
	-low beam dim check connection		
	-change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339		
	-charge batteries		
	-R&R ECM		
	-found broken air intake temp sensor - replace with used engine parts		
	-replace MAP sensor		
	-replaced Vpod		
	Jun 19/24 - Gilles Services		
	-start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256		
	-replace oil can and valve cover gaskets		
	-replace coolant hose for EGR		
	-replace air bag LH rear		
	-replace U-joint		
	-replace input yoke & sealant		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 24

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Aug 15/16	60216.00
------	----------------------------	-----------	----------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 26

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129 -repaired coolant leak on upper radiator hose -replaced boost pipe hose -checked ECR cooler		
	Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165 -pull unit to start running		
	Apr 23/25 Tire North INV#272051733 -tire change over		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 27

Maint Code	Work Performed	Date Maint Performed	Reading
MISC	Misc. Maintenance & Repair May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good	Jun 07/17	27605.00

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts
- replace MAP sensor
- replaced Vpod

Jun 19/24 - Gilles Services

- start check over

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Mar 27/18	27605.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		
	-new cord side dump switch to back		
	-new cord truck to trailer		
	-fix solenoid for tarp		
	Jun 1/16 - Gilles Services		
	-2 broken bolt fan belt ??? , 1 out		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-start ??? part o remove rad		
	Jun 2/16 - Gilles Services		
	-take hood rad out		
	-drill bolt, remove it		
	-new bolt, install tensioners		
	-rad on		
	-start hook up hose, mount, top rod air to air hose		
	-rad hose		
	Jun 3/16 - Gilles Services		
	-hook up all hose, wiring		
	-hood back on		
	-hook up light		
	-put clamps hold hardware		
	-antifreeze		
	Jun 18/16		
	-hole in oil pan		
	-cleanup, silicone & JB welding		
	-fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998		
	-remove and replace turbo		
	-installed new gaskets and O-rings		
	-installed new 90DEG rubber intake elbow with new clamps		
	-run up unit to check for leaks - all good		
	-charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926		
	-repair RH low beam		
	-repair wires, bulb, L rear tail light out, plug, tridem		
	gravel trailer identification light out		
	-resecure RH marker light		
	-replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066		
	-remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082		
	-check lights out		
	-reset circuit breakers		
	-cut free trailer cord to not pull so hard and tie up		
	freely		
	-set tambone brakes		
	-found tight		
	-trailer has no flats		

Maint Code	Work Performed	Date Maint Performed	Reading
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129 -repaired coolant leak on upper radiator hose -replaced boost pipe hose		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 32

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Oct 15/18	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16
-hole in oil pan
-cleanup, silicone & JB welding

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up
freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained
out
- found AC compressor seized and belt blew apart damaged
main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 34

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Aug 05/20	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		

Maint Code	Work Performed	Date Maint Performed	Reading
	May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp		
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint
Code

Work Performed

Date Maint
Performed

Reading

-check lights out
 -reset circuit breakers
 -cut free trailer cord to not pull so hard and tie up
 freely
 -set tambone brakes
 -found tight
 -trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088
 -service call to km44 pit bolt came off and coolant drained
 out
 -found AC compressor seized and belt blew apart damaged
 main belt
 -everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289
 -service and check over
 -repair left side wiring to headlights
 -change broken high beam
 -low beam dim check connection
 -change fan stat not enough air flow going through it -
 good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
 -charge batteries
 -R&R ECM
 -found broken air intake temp sensor - replace with used
 engine parts
 -replace MAP sensor
 -replaced Vpod

Jun 19/24 - Gilles Services
 -start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
 -replace oil can and valve cover gaskets
 -replace coolant hose for EGR
 -replace air bag LH rear
 -replace U-joint
 -replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
 -change trailer plug on end dump
 -change male & female hydraulic couplers
 -check hydraulic oil
 -test Hydraulic & test TRIP switch

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 37

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Aug 21/20	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16

-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

-remove and replace turbo
-installed new gaskets and O-rings
-installed new 90DEG rubber intake elbow with new clamps
-run up unit to check for leaks - all good
-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

-repair RH low beam
-repair wires, bulb, L rear tail light out, plug, tridem
gravel trailer identification light out
-resecure RH marker light
-replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out
-reset circuit breakers
-cut free trailer cord to not pull so hard and tie up
freely
-set tambone brakes
-found tight
-trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
out
-found AC compressor seized and belt blew apart damaged
main belt
-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

-service and check over
-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts
- replace MAP sensor
- replaced Vpod

Jun 19/24 - Gilles Services

- start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

- replace oil can and valve cover gaskets
- replace coolant hose for EGR
- replace air bag LH rear
- replace U-joint
- replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

- change trailer plug on end dump
- change male & female hydraulic couplers
- check hydraulic oil
- test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

- change oil and filter
- replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

- repaired coolant leak on upper radiator hose
- replaced boost pipe hose
- checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

- pull unit to start running

Apr 23/25 Tire North INV#272051733

- tire change over

MISC	Misc. Maintenance & Repair	Aug 21/20	0.00
	May 24/16 - Gilles Services		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable		
	May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp		
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out		

Maint Code	Work Performed	Date Maint Performed	Reading
	-resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Mar 10/21	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		
	-new cord side dump switch to back		
	-new cord truck to trailer		
	-fix solenoid for tarp		
	Jun 1/16 - Gilles Services		
	-2 broken bolt fan belt ??? , 1 out		
	-start ??? part o remove rad		
	Jun 2/16 - Gilles Services		
	-take hood rad out		
	-drill bolt, remove it		
	-new bolt, install tensioners		

Maint Code	Work Performed	Date Maint Performed	Reading
	-rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts
- replace MAP sensor
- replaced Vpod

Jun 19/24 - Gilles Services

- start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

- replace oil can and valve cover gaskets
- replace coolant hose for EGR
- replace air bag LH rear
- replace U-joint
- replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

- change trailer plug on end dump
- change male & female hydraulic couplers
- check hydraulic oil
- test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

- change oil and filter
- replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

- repaired coolant leak on upper radiator hose
- replaced boost pipe hose
- checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

- pull unit to start running

Apr 23/25 Tire North INV#272051733

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-tire change over

MISC	Misc. Maintenance & Repair	Mar 18/21	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services

-no light on trailer

-short hardness

-make ??? side dump

-short in cable

-need new cable & plug in female 4 plug

-put light bottom cable

May 25/16 - Gilles Services

-new cord side dump switch to back

-new cord truck to trailer

-fix solenoid for tarp

Jun 1/16 - Gilles Services

-2 broken bolt fan belt ??? , 1 out

-start ??? part o remove rad

Jun 2/16 - Gilles Services

-take hood rad out

-drill bolt, remove it

-new bolt, install tensioners

-rad on

-start hook up hose, mount, top rod air to air hose

-rad hose

Jun 3/16 - Gilles Services

-hook up all hose, wiring

-hood back on

-hook up light

-put clamps hold hardware

-antifreeze

Jun 18/16

-hole in oil pan

-cleanup, silicone & JB welding

-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

-remove and replace turbo

-installed new gaskets and O-rings

-installed new 90DEG rubber intake elbow with new clamps

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-run up unit to check for leaks - all good
-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

-repair RH low beam
-repair wires, bulb, L rear tail light out, plug, tridem
gravel trailer identification light out
-resecure RH marker light
-replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out
-reset circuit breakers
-cut free trailer cord to not pull so hard and tie up
freely
-set tambone brakes
-found tight
-trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
out
-found AC compressor seized and belt blew apart damaged
main belt
-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

-service and check over
-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used
engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services

-start check over

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 47

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	May 20/21	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 48

Maint Code	Work Performed	Date Maint Performed	Reading
	-2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight		

Maint Code	Work Performed	Date Maint Performed	Reading
	-trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088		
	-service call to km44 pit bolt came off and coolant drained out		
	-found AC compressor seized and belt blew apart damaged main belt		
	-everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289		
	-service and check over		
	-repair left side wiring to headlights		
	-change broken high beam		
	-low beam dim check connection		
	-change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339		
	-charge batteries		
	-R&R ECM		
	-found broken air intake temp sensor - replace with used engine parts		
	-replace MAP sensor		
	-replaced Vpod		
	Jun 19/24 - Gilles Services		
	-start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256		
	-replace oil can and valve cover gaskets		
	-replace coolant hose for EGR		
	-replace air bag LH rear		
	-replace U-joint		
	-replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658		
	-change trailer plug on end dump		
	-change male & female hydraulic couplers		
	-check hydraulic oil		
	-test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757		
	-change oil and filter		
	-replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129		
	-repaired coolant leak on upper radiator hose		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 50

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	May 24/21	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16
-hole in oil pan

Maint Code	Work Performed	Date Maint Performed	Reading
	-cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM		

Maint Code	Work Performed	Date Maint Performed	Reading
	-found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod Jun 19/24 - Gilles Services -start check over Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129 -repaired coolant leak on upper radiator hose -replaced boost pipe hose -checked ECR cooler Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165 -pull unit to start running Apr 23/25 Tire North INV#272051733 -tire change over		

MISC	Misc. Maintenance & Repair May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable	Aug 03/21	0.00
------	--	-----------	------

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

May 25/16 - Gilles Services

- new cord side dump switch to back
- new cord truck to trailer
- fix solenoid for tarp

Jun 1/16 - Gilles Services

- 2 broken bolt fan belt ??? , 1 out
- start ??? part o remove rad

Jun 2/16 - Gilles Services

- take hood rad out
- drill bolt, remove it
- new bolt, install tensioners
- rad on
- start hook up hose, mount, top rod air to air hose
- rad hose

Jun 3/16 - Gilles Services

- hook up all hose, wiring
- hood back on
- hook up light
- put clamps hold hardware
- antifreeze

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint
Code

Work Performed

Date Maint
Performed

Reading

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out

-reset circuit breakers

-cut free trailer cord to not pull so hard and tie up
freely

-set tambone brakes

-found tight

-trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
out-found AC compressor seized and belt blew apart damaged
main belt

-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

-service and check over

-repair left side wiring to headlights

-change broken high beam

-low beam dim check connection

-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

-charge batteries

-R&R ECM

-found broken air intake temp sensor - replace with used
engine parts

-replace MAP sensor

-replaced Vpod

Jun 19/24 - Gilles Services

-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

-replace oil can and valve cover gaskets

-replace coolant hose for EGR

-replace air bag LH rear

-replace U-joint

-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

-change trailer plug on end dump

-change male & female hydraulic couplers

-check hydraulic oil

-test Hydraulic & test TRIP switch

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 55

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Oct 08/21	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		
	-new cord side dump switch to back		
	-new cord truck to trailer		
	-fix solenoid for tarp		
	Jun 1/16 - Gilles Services		
	-2 broken bolt fan belt ??? , 1 out		
	-start ??? part o remove rad		
	Jun 2/16 - Gilles Services		
	-take hood rad out		
	-drill bolt, remove it		
	-new bolt, install tensioners		
	-rad on		
	-start hook up hose, mount, top rod air to air hose		
	-rad hose		
	Jun 3/16 - Gilles Services		
	-hook up all hose, wiring		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- hood back on
- hook up light
- put clamps hold hardware
- antifreeze

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up
- freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained
- out
- found AC compressor seized and belt blew apart damaged
- main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 57

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used
engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Nov 08/21	0.00
------	----------------------------	-----------	------

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable		
	May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp		
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem		

Maint Code	Work Performed	Date Maint Performed	Reading
	gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

-pull unit to start running

Apr 23/25 Tire North INV#272051733

-tire change over

MISC	Misc. Maintenance & Repair	Nov 09/21	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services

-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services

-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services

-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services

-take hood rad out
-drill bolt, remove it

Maint Code	Work Performed	Date Maint Performed	Reading
	-new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

main belt
-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289
-service and check over
-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used
engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 63

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Mar 13/22	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16
-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998
-remove and replace turbo
-installed new gaskets and O-rings

Maint Code	Work Performed	Date Maint Performed	Reading
	-installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 65

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

-replace oil can and valve cover gaskets

-replace coolant hose for EGR

-replace air bag LH rear

-replace U-joint

-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

-change trailer plug on end dump

-change male & female hydraulic couplers

-check hydraulic oil

-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

-change oil and filter

-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

-repaired coolant leak on upper radiator hose

-replaced boost pipe hose

-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

-pull unit to start running

Apr 23/25 Tire North INV#272051733

-tire change over

MISC	Misc. Maintenance & Repair	Mar 21/22	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services

-no light on trailer

-short hardness

-make ??? side dump

-short in cable

-need new cable & plug in female 4 plug

-put light bottom cable

May 25/16 - Gilles Services

-new cord side dump switch to back

-new cord truck to trailer

-fix solenoid for tarp

Maint Code	Work Performed	Date Maint Performed	Reading
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes		

Maint Code	Work Performed	Date Maint Performed	Reading
	-found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Mar 28/22	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-R&R ECM
-found broken air intake temp sensor - replace with used engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jun 27/22	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-put light bottom cable

May 25/16 - Gilles Services

- new cord side dump switch to back
- new cord truck to trailer
- fix solenoid for tarp

Jun 1/16 - Gilles Services

- 2 broken bolt fan belt ??? , 1 out
- start ??? part o remove rad

Jun 2/16 - Gilles Services

- take hood rad out
- drill bolt, remove it
- new bolt, install tensioners
- rad on
- start hook up hose, mount, top rod air to air hose
- rad hose

Jun 3/16 - Gilles Services

- hook up all hose, wiring
- hood back on
- hook up light
- put clamps hold hardware
- antifreeze

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Maint Code	Work Performed	Date Maint Performed	Reading
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

-change oil and filter

-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

-repaired coolant leak on upper radiator hose

-replaced boost pipe hose

-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

-pull unit to start running

Apr 23/25 Tire North INV#272051733

-tire change over

MISC	Misc. Maintenance & Repair	Jul 18/22	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services

-no light on trailer

-short hardness

-make ??? side dump

-short in cable

-need new cable & plug in female 4 plug

-put light bottom cable

May 25/16 - Gilles Services

-new cord side dump switch to back

-new cord truck to trailer

-fix solenoid for tarp

Jun 1/16 - Gilles Services

-2 broken bolt fan belt ??? , 1 out

-start ??? part o remove rad

Jun 2/16 - Gilles Services

-take hood rad out

-drill bolt, remove it

-new bolt, install tensioners

-rad on

-start hook up hose, mount, top rod air to air hose

-rad hose

Jun 3/16 - Gilles Services

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-hook up all hose, wiring
 -hood back on
 -hook up light
 -put clamps hold hardware
 -antifreeze

Jun 18/16

-hole in oil pan
 -cleanup, silicone & JB welding
 -fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

-remove and replace turbo
 -installed new gaskets and O-rings
 -installed new 90DEG rubber intake elbow with new clamps
 -run up unit to check for leaks - all good
 -charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

-repair RH low beam
 -repair wires, bulb, L rear tail light out, plug, tridem
 gravel trailer identification light out
 -resecure RH marker light
 -replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out
 -reset circuit breakers
 -cut free trailer cord to not pull so hard and tie up
 freely
 -set tambone brakes
 -found tight
 -trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
 out
 -found AC compressor seized and belt blew apart damaged
 main belt
 -everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

-service and check over
 -repair left side wiring to headlights

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used
engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services

-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

-pull unit to start running

Apr 23/25 Tire North INV#272051733

-tire change over

Maint Code	Work Performed	Date Maint Performed	Reading
MISC	Misc. Maintenance & Repair May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam	Jul 26/23	0.00

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 78

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jul 31/23	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-found AC compressor seized and belt blew apart damaged
main belt
-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289
-service and check over
-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used
engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 81

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Sep 15/23	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16
-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998
-remove and replace turbo

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts
- replace MAP sensor
- replaced Vpod

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Sep 20/23	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		
	-new cord side dump switch to back		
	-new cord truck to trailer		
	-fix solenoid for tarp		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Jun 18/16
-hole in oil pan
-cleanup, silicone & JB welding
-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998
-remove and replace turbo
-installed new gaskets and O-rings
-installed new 90DEG rubber intake elbow with new clamps
-run up unit to check for leaks - all good
-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926
-repair RH low beam
-repair wires, bulb, L rear tail light out, plug, tridem
gravel trailer identification light out
-resecure RH marker light
-replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066
-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082
-check lights out
-reset circuit breakers
-cut free trailer cord to not pull so hard and tie up
freely

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 86

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Oct 24/23	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 88

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Nov 02/23	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		

Maint Code	Work Performed	Date Maint Performed	Reading
	-need new cable & plug in female 4 plug -put light bottom cable		
	May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp		
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066		

Maint Code	Work Performed	Date Maint Performed	Reading
	-remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082		
	-check lights out		
	-reset circuit breakers		
	-cut free trailer cord to not pull so hard and tie up freely		
	-set tambone brakes		
	-found tight		
	-trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088		
	-service call to km44 pit bolt came off and coolant drained out		
	-found AC compressor seized and belt blew apart damaged main belt		
	-everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289		
	-service and check over		
	-repair left side wiring to headlights		
	-change broken high beam		
	-low beam dim check connection		
	-change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339		
	-charge batteries		
	-R&R ECM		
	-found broken air intake temp sensor - replace with used engine parts		
	-replace MAP sensor		
	-replaced Vpod		
	Jun 19/24 - Gilles Services		
	-start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256		
	-replace oil can and valve cover gaskets		
	-replace coolant hose for EGR		
	-replace air bag LH rear		
	-replace U-joint		
	-replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658		
	-change trailer plug on end dump		
	-change male & female hydraulic couplers		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jun 19/24	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Maint Code	Work Performed	Date Maint Performed	Reading
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-repair left side wiring to headlights
-change broken high beam
-low beam dim check connection
-change fan stat not enough air flow going through it -
good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339
-charge batteries
-R&R ECM
-found broken air intake temp sensor - replace with used
engine parts
-replace MAP sensor
-replaced Vpod

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 94

Maint Code	Work Performed	Date Maint Performed	Reading
MISC	Misc. Maintenance & Repair May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump -short in cable -need new cable & plug in female 4 plug -put light bottom cable May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926	Aug 13/24	0.00

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jan 17/25	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

out

- found AC compressor seized and belt blew apart damaged main belt

- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over

- repair left side wiring to headlights

- change broken high beam

- low beam dim check connection

- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries

- R&R ECM

- found broken air intake temp sensor - replace with used engine parts

- replace MAP sensor

- replaced Vpod

Jun 19/24 - Gilles Services

- start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

- replace oil can and valve cover gaskets

- replace coolant hose for EGR

- replace air bag LH rear

- replace U-joint

- replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

- change trailer plug on end dump

- change male & female hydraulic couplers

- check hydraulic oil

- test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

- change oil and filter

- replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

- repaired coolant leak on upper radiator hose

- replaced boost pipe hose

- checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 99

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-pull unit to start running

Apr 23/25 Tire North INV#272051733

-tire change over

MISC	Misc. Maintenance & Repair	Jan 17/25	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services

-no light on trailer

-short hardness

-make ??? side dump

-short in cable

-need new cable & plug in female 4 plug

-put light bottom cable

May 25/16 - Gilles Services

-new cord side dump switch to back

-new cord truck to trailer

-fix solenoid for tarp

Jun 1/16 - Gilles Services

-2 broken bolt fan belt ??? , 1 out

-start ??? part o remove rad

Jun 2/16 - Gilles Services

-take hood rad out

-drill bolt, remove it

-new bolt, install tensioners

-rad on

-start hook up hose, mount, top rod air to air hose

-rad hose

Jun 3/16 - Gilles Services

-hook up all hose, wiring

-hood back on

-hook up light

-put clamps hold hardware

-antifreeze

Jun 18/16

-hole in oil pan

-cleanup, silicone & JB welding

-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem
- gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up
- freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained
- out
- found AC compressor seized and belt blew apart damaged
- main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it -
- good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used
- engine parts
- replace MAP sensor
- replaced Vpod

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 101

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 19/24 - Gilles Services
-start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256
-replace oil can and valve cover gaskets
-replace coolant hose for EGR
-replace air bag LH rear
-replace U-joint
-replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658
-change trailer plug on end dump
-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Jan 23/25	0.00
	May 24/16 - Gilles Services		
	-no light on trailer		
	-short hardness		
	-make ??? side dump		
	-short in cable		
	-need new cable & plug in female 4 plug		
	-put light bottom cable		
	May 25/16 - Gilles Services		
	-new cord side dump switch to back		
	-new cord truck to trailer		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-fix solenoid for tarp		
	Jun 1/16 - Gilles Services		
	-2 broken bolt fan belt ??? , 1 out		
	-start ??? part o remove rad		
	Jun 2/16 - Gilles Services		
	-take hood rad out		
	-drill bolt, remove it		
	-new bolt, install tensioners		
	-rad on		
	-start hook up hose, mount, top rod air to air hose		
	-rad hose		
	Jun 3/16 - Gilles Services		
	-hook up all hose, wiring		
	-hood back on		
	-hook up light		
	-put clamps hold hardware		
	-antifreeze		
	Jun 18/16		
	-hole in oil pan		
	-cleanup, silicone & JB welding		
	-fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998		
	-remove and replace turbo		
	-installed new gaskets and O-rings		
	-installed new 90DEG rubber intake elbow with new clamps		
	-run up unit to check for leaks - all good		
	-charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926		
	-repair RH low beam		
	-repair wires, bulb, L rear tail light out, plug, tridem		
	gravel trailer identification light out		
	-resecure RH marker light		
	-replaced beacon		
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066		
	-remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082		
	-check lights out		
	-reset circuit breakers		
	-cut free trailer cord to not pull so hard and tie up		

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Apr 03/25	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Jun 3/16 - Gilles Services
-hook up all hose, wiring
-hood back on
-hook up light
-put clamps hold hardware
-antifreeze

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 18/16

- hole in oil pan
- cleanup, silicone & JB welding
- fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

- remove and replace turbo
- installed new gaskets and O-rings
- installed new 90DEG rubber intake elbow with new clamps
- run up unit to check for leaks - all good
- charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

- repair RH low beam
- repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out
- resecure RH marker light
- replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

- remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

- check lights out
- reset circuit breakers
- cut free trailer cord to not pull so hard and tie up freely
- set tambone brakes
- found tight
- trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

- service call to km44 pit bolt came off and coolant drained out
- found AC compressor seized and belt blew apart damaged main belt
- everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump -change male & female hydraulic couplers -check hydraulic oil -test Hydraulic & test TRIP switch		
	Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757 -change oil and filter -replace power steering leak loose fitting on pump		
	Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129 -repaired coolant leak on upper radiator hose -replaced boost pipe hose -checked ECR cooler		
	Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165 -pull unit to start running		
	Apr 23/25 Tire North INV#272051733 -tire change over		
MISC	Misc. Maintenance & Repair May 24/16 - Gilles Services -no light on trailer -short hardness -make ??? side dump	Apr 08/25	0.00

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
	-short in cable -need new cable & plug in female 4 plug -put light bottom cable		
	May 25/16 - Gilles Services -new cord side dump switch to back -new cord truck to trailer -fix solenoid for tarp		
	Jun 1/16 - Gilles Services -2 broken bolt fan belt ??? , 1 out -start ??? part o remove rad		
	Jun 2/16 - Gilles Services -take hood rad out -drill bolt, remove it -new bolt, install tensioners -rad on -start hook up hose, mount, top rod air to air hose -rad hose		
	Jun 3/16 - Gilles Services -hook up all hose, wiring -hood back on -hook up light -put clamps hold hardware -antifreeze		
	Jun 18/16 -hole in oil pan -cleanup, silicone & JB welding -fix pipe 5" exhaust		
	Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998 -remove and replace turbo -installed new gaskets and O-rings -installed new 90DEG rubber intake elbow with new clamps -run up unit to check for leaks - all good -charged AC		
	Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926 -repair RH low beam -repair wires, bulb, L rear tail light out, plug, tridem gravel trailer identification light out -resecure RH marker light -replaced beacon		

Maint Code	Work Performed	Date Maint Performed	Reading
	Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066 -remove and replace hydraulic line		
	Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082 -check lights out -reset circuit breakers -cut free trailer cord to not pull so hard and tie up freely -set tambone brakes -found tight -trailer has no flats		
	Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088 -service call to km44 pit bolt came off and coolant drained out -found AC compressor seized and belt blew apart damaged main belt -everything else was good		
	Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289 -service and check over -repair left side wiring to headlights -change broken high beam -low beam dim check connection -change fan stat not enough air flow going through it - good now		
	Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339 -charge batteries -R&R ECM -found broken air intake temp sensor - replace with used engine parts -replace MAP sensor -replaced Vpod		
	Jun 19/24 - Gilles Services -start check over		
	Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256 -replace oil can and valve cover gaskets -replace coolant hose for EGR -replace air bag LH rear -replace U-joint -replace input yoke & sealant		
	Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658 -change trailer plug on end dump		

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

-change male & female hydraulic couplers
-check hydraulic oil
-test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757
-change oil and filter
-replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129
-repaired coolant leak on upper radiator hose
-replaced boost pipe hose
-checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165
-pull unit to start running

Apr 23/25 Tire North INV#272051733
-tire change over

MISC	Misc. Maintenance & Repair	Apr 23/25	0.00
------	----------------------------	-----------	------

May 24/16 - Gilles Services
-no light on trailer
-short hardness
-make ??? side dump
-short in cable
-need new cable & plug in female 4 plug
-put light bottom cable

May 25/16 - Gilles Services
-new cord side dump switch to back
-new cord truck to trailer
-fix solenoid for tarp

Jun 1/16 - Gilles Services
-2 broken bolt fan belt ??? , 1 out
-start ??? part o remove rad

Jun 2/16 - Gilles Services
-take hood rad out
-drill bolt, remove it
-new bolt, install tensioners
-rad on
-start hook up hose, mount, top rod air to air hose
-rad hose

Maintenance Report

Maintenance Period : Jan 01/10 - Oct 15/26

Sort By : Equipment Code

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

Jun 3/16 - Gilles Services

-hook up all hose, wiring

-hood back on

-hook up light

-put clamps hold hardware

-antifreeze

Jun 18/16

-hole in oil pan

-cleanup, silicone & JB welding

-fix pipe 5" exhaust

Jul 3/23 - Blue Diamond Enterprises Ltd INV#27998

-remove and replace turbo

-installed new gaskets and O-rings

-installed new 90DEG rubber intake elbow with new clamps

-run up unit to check for leaks - all good

-charged AC

Jul 26/23 - Blue Diamond Enterprises Ltd INV#27926

-repair RH low beam

-repair wires, bulb, L rear tail light out, plug, tridem
gravel trailer identification light out

-resecure RH marker light

-replaced beacon

Sept 15/23 - Blue Diamond Enterprises Ltd INV#28066

-remove and replace hydraulic line

Sep 20/23 - Blue Diamond Enterprises Ltd INV#28082

-check lights out

-reset circuit breakers

-cut free trailer cord to not pull so hard and tie up
freely

-set tambone brakes

-found tight

-trailer has no flats

Sept 28/23 - Blue Diamond Enterprises Ltd INV#28088

-service call to km44 pit bolt came off and coolant drained
out-found AC compressor seized and belt blew apart damaged
main belt

-everything else was good

Oct 24/23 - Blue Diamond Enterprises Ltd INV#28289

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

- service and check over
- repair left side wiring to headlights
- change broken high beam
- low beam dim check connection
- change fan stat not enough air flow going through it - good now

Nov 2/23 - Blue Diamond Enterprises Ltd INV#28339

- charge batteries
- R&R ECM
- found broken air intake temp sensor - replace with used engine parts
- replace MAP sensor
- replaced Vpod

Jun 19/24 - Gilles Services

- start check over

Aug 13/24 - Blue Diamond Enterprises Ltd INV#29256

- replace oil can and valve cover gaskets
- replace coolant hose for EGR
- replace air bag LH rear
- replace U-joint
- replace input yoke & sealant

Jan 17/25 - Blue Diamond Enterprises Ltd INV#29658

- change trailer plug on end dump
- change male & female hydraulic couplers
- check hydraulic oil
- test Hydraulic & test TRIP switch

Jan 23/25 - Blue Diamond Enterprises Ltd INV#29757

- change oil and filter
- replace power steering leak loose fitting on pump

Apr 3/25 - Blue Diamond Enterprises Ltd INV#30129

- repaired coolant leak on upper radiator hose
- replaced boost pipe hose
- checked ECR cooler

Apr 14/25 - Blue Diamond Enterprises Ltd INV#30165

- pull unit to start running

Apr 23/25 Tire North INV#272051733

- tire change over

01 - 851791 NWT Ltd.
Maintenance Report
Maintenance Period : Jan 01/10 - Oct 15/26
Sort By : Equipment Code

Pg 112

Maint Code	Work Performed	Date Maint Performed	Reading
---------------	----------------	-------------------------	---------

==== End of Report ====