

Kelvin's Car Care Ltd.

Site 416, Box 2, Comp 3, RR3
 Drayton Valley, AB. T7A 2A3

Phone: 780-542-2056 Fax: 780-542-2061

INVOICE

37807

GST #86843 1487

INVOICE

Printed Date: 07/26/2022 Work Completed: 07/26/2022

Mackinaw, Katelyn

Box 13
 Buck Lake, Ab T0C0T0
 Home 780-682-0009 Katelyn
 Cellular 587-377-7309 Katelyn

2009 Dodge - Journey SXT - 3.5L, V6 (214CI) VIN(V)
 Lic # : CHT-9846 Odometer In : 188132

VIN # : 3D4GH57V5 9T566633

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
lateral link - toe control link CMS25175	2.00	0.00	n/c	Replace rear lower rearward lateral arm, rear toe control link. Replace rear lower inner control arm bushings, rear upper control arm and rear lower forward control arm bushings and rear lower rearward control arm bushings Most Parts supplied. Used Torch on many seized Components 10.7 hours spent Wheel alignment Had to heat up 3 bolts to remove Inspect rims and buff as necessary. Mount tires on rims, computer spin balance and install on vehicle. Torque lug nuts to manufacturer's specifications.	6.00	690.00
Control am bushing - rear lower inner K201368	2.00	0.00	n/c			
Knuckle bushing - rear lower forward K201354	2.00	0.00	n/c			
Knuckle bushing - rear lower rearward K201383	2.00	0.00	n/c			
Control arm - rear upper CMS25174	2.00	0.00	n/c			
lateral link - rear lower rearward CMS251247	2.00	0.00	n/c			
Special Camber Bolts 35088486AA	1.00	37.27	37.27			
Camber Washers 6508488AA	1.00	12.83	12.83			
Nut 6508487AA	1.00	9.86	9.86			
Hercules Terra Trac Cross V 225/55R19 Size: 2255519 98064	2.00	262.50	525.00			
Tire recycling fee	2.00	4.00	8.00			
suspension nuts 6104711AA	2.00	13.63	27.26			
Shop Supplies			20.00			

Email Address: kelvin@kelvinscarcare.ca