

CUSTOMER #: 2724

279328

DENHAM CHRYSLER

Lloydminster

ROYAL WELL SERVICING LTD

INVOICE

ENION LUNDBERG

5103 65 STREET

LLOYDMINSTER, AB T9V 2E4

HOME: 780-808-2333 CONT: 780-205-0121

BUS: 780-205-0121 CELL:

PAGE 1

2302-50 Avenue Lloydminster, AB T9V 2W7
Phone: (780) 875-5337 Fax: (780) 872-5050
Toll Free: (800) 561-5337
www.denhamchryslerjeep.com

SERVICE ADVISOR: 7367 CRYSTAL GARNER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
WHITE	17	DODGE R1500 CREW 4WD	1C6RR7LM2HS879917		203636/203697	T9917

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30DEC17 DE			17:00 03JUL24	1	154.00	CASH	17JUL24

R.O. OPENED READY OPTIONS: DLR:C8580

17:28 29APR24 09:45 17JUL24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A	DIAGNOSE	CEL.	SERVICE	THROTTLE	MESSAGE		
	900	DIAGNOSE	THROTTLE	MESSAGE	ON.	PERFORM	PCM
		UPDATE					
		5439	CP			693.00	693.00
	1	68148329AB	RAIL-FUEL		408.00	408.00	408.00
	800	REPLACED	BATTERY				
		5439	CP			92.40	92.40
	1	BA49F900AA	BATTERY-STORAGE		249.00	249.00	249.00
	SUBL	SUBLET	RE-TUNE	AFTER	RECALLS	PERFORMED	
		IPS					(N/C)
PARTS:	657.00	LABOR:	785.40	OTHER:	0.00	TOTAL LINE A:	1442.40

203636
 Diagnose throttle message on
 P0088
 Fuel rail pressure too high has update available in pcm for this
 code
 Had to perform update to latest software
 Test drive after update and DTC returned.
 Performed recalls.
 P0191 fuel rail pressure performance active code
 Diagnose as per service info
 Check fuel condition ok
 Perform fuel delivery flow test multiple times
 Has 3 litres of combined flow with 3- 15 second tests
 Disconnect rail pressure sensor and recheck codes p0193 fuel rail
 pressure sensor high
 Needs new sensor.
 Needs new battery will not take charge - keeps going dead
 Replace fuel rail pressure sensor - test drive fuel pressure code
 did not come back on at this time
 Set code P2D2F cold start turbo under boost
 Need to replace battery before further diag
 replace battery
 erase codes and test drive

CHRYSLER
Jeep
DODGE
SERVICE

"Your Pride... is Our Passion"

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

GST# R121738660

CUSTOMER COPY

CUSTOMER #: 2724

279328

DENHAM CHRYSLER

Lloydminster

2302-50 Avenue Lloydminster, AB T9V 2W7
Phone: (780) 875-5337 Fax: (780) 872-5050
Toll Free: (800) 561-5337
www.denhamchryslerjeep.com

ROYAL WELL SERVICING LTD

INVOICE

103 65 STREET
LOYDMINSTER, AB T9V 2E4
PHONE: 780-808-2333 CONT: 780-205-0121
FAX: 780-205-0121 CELL:

PAGE 2

SERVICE ADVISOR: 7367 CRYSTAL GARNER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	KILOMETRES IN/ OUT	TAG
WHITE	17	DODGE R1500 CREW 4WD	1C6RR7LM2HS879917		203636/203697	T9917
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
07DEC17 DD			17:00 03JUL24	1	154.00	CASH
R.O. OPENED	READY	OPTIONS: DLR:C8580				INV. DATE
07:28 29APR24	09:45 17JUL24					17JUL24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1				reset codes			

3 66A 2014-2019 DS 2014-2020 WK LOSS OF CRANK
CAUSE: RECALL
1866A181 Safety Recall 66A - Loss of Crank
Position - Inspect Inspect PCM Software
Level (0 - Low Skilled)

5439 W40
FC: 1B PART#: COUNT:
CLAIM TYPE: S
AUTH CODE:

0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00 (N/C)

PARTS: 203636
Inspect pcm software level
is up too date no further action required

C WB1 DIESEL EGR COOLER RECALL
CAUSE: VB1 RECALL
25VB1182 Safety Recall VB1 - Diesel EGR Cooler -
Replace Inspect Fault Codes, and Replace EGR
Cooler (2 - Skilled)

5439 W40
1 CSNDVB12AA BUSHING
1 CSNDVB11AA COOLER-EGR VALVE
FC: 1B
PART#: CSNDVB11AA
COUNT: 1
CLAIM TYPE: S
AUTH CODE:

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	



SERVICE

"Your Pride... is Our Passion"

CUSTOMER COPY

GST# R121738660

INVOICE NUMBER	435306B
Subtotal	
GST	
PST	
AMOUNT DUE	

279328

DENHAM CHRYSLER

Lloydminster

INVOICE

2302-50 Avenue Lloydminster, AB T9V 2W7
Phone: (780) 875-5337 Fax: (780) 872-5050
Toll Free: (800) 561-5337
www.denhamchryslerjeep.com

ICING LTD

AB T9V 2E4
333 CONT:780-205-0121
121 CELL:

PAGE 3

SERVICE ADVISOR: 7367 CRYSTAL GARNER

MAKE/MODEL		VIN		LICENSE	KILOMETRES IN/ OUT	TAG
DODGE R1500 CREW 4WD		1C6RR7LM2HS879917			203636/203697	T9917
D. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
		17:00 03JUL24	1	154.00	CASH	17JUL24
READY		OPTIONS: DLR:C8580				
24	09:45	17JUL24				

TECH TYPE HOURS	LIST	NET	TOTAL
0.00 LABOR:	0.00 OTHER:	0.00	TOTAL LINE C: 0.00

perform recall wb1 replace EGR cooler

4-2019 DS, 2012-2014 LX, 2011-2021

6 HPFP

6182 Safety Recall Z46 - 3.0L Diesel High Pressure Fuel Pump - Test and Replace
Replace High Pressure Fuel Pump, Fuel Tubes, and Fuel Filter (2 - Skilled)

5439 W40

- 1 CSSMZ461AA PUMP-FUEL INJECTION (N/C)
- 1 CSFP01A1AA MANUAL (N/C)
- 1 CSSMZ46EAA TUBE-FUEL INJECTOR SUPPLY (N/C)
- 1 CSSMZ462AA \$FILTER KI-FUEL WATER SEPARATOR (N/C)

FC: 1B CHRYSLER



DODGE

PART#: CSSMZ461AA

COUNT: 1

CLAIM TYPE: S

AUTH CODE:

0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

536

perform recall z46
replace fuel injection pump and fuel filter

VEHICLE WILL BE STAYING UNTILL ALL RECALLS ARE COMPLETED. VERIFY VEHICLE IS NOT DELETED,

2300 INFO

5439 CP

0.00 0.00

0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	



SERVICE

"Your Pride... is Our Passion"

GST# R121738660

CUSTOMER COPY