

Saskatoon- HQ

304323 Township Road 350 Saskatoon, SK (306) 955-1350

Lloydminster 15 Horizon Drive Llovdminster, SK (306) 955-1350

Moose Jaw Highway 1 West Moose Jaw, SK (306) 955-1350

Ship To: IN STORE PICKUP

Invoice To: INTERNAL USE-SASKATOON

304323 TWP RD 350 SASKATOON SK S7K 3J

| Branch | | | | | |
|------------|----------|----------|-------|--------|--------|
| SASKATOON | | *REPF | *TNI | | |
| Date | Time | | | | Page |
| 11/07/24 | 23: | 01:11 | (B) | | 01 |
| Account No | Phone No |) | | Inv N | 10 |
| INT01 | | | | W0(| 044301 |
| Ship Via | | Purchase | Order | | |
| | | | | | |
| Tax ID No | | | | | |
| | | | | | |
| | | | Sale | sperso | n |
| | | | | BR1 | / 000 |

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

001070

2020 SUPREME 1500T 1500TR

X 215TR0090

2.74 HRS

SEGMENT# 1 C CSMI NA 10/15/24 10/15/24

Inspect mixer for needed repairs

CORRECTION:

Pulled unit into shop. Knives require replacement on all three screws, kicker plates as well. Front.screw need a cap as well. Tested all hydraulics, ok. No oil leaks on axles. Recommend gearbox and planetary and hub oil change. Front steady bearing has play, recommend replacement. No scales on unit. Right rear axle outer rim damaged, holding air. PTO shield intact but damaged. Rear door open indicator stiff but functional. Converter movent bearing worn. Scale screen harness ends corroded./

Front door closes on its own when disconnected. Rear screw cap also needs replacing.

> 411.00 LABOR

12300001

SEGMENT TOTAL ==>

411.00

SEGMENT# 2 C CSMI NA 10/15/24 10/15/24

20.09 HRS

Approved Repairs

CORRECTION:

Drained and filled all three gearboxes. Drained planetaries x3. Drained and filled all four wheels hubs. Installed new scale head and addition display. Removed and replaced front driveshaft steady bearing, reinstalled PTO, still needs one bolt. Filled front and center planetaries.

Filled rear planetary. Install new knives (5 on each screw)

Installed rear kicker plate.

Installed center and front kicker plate.

Removed front and rear screw cap, cleaned center out and

CONTINUED ON PAGE 02

Received By



Saskatoon- HQ

304323 Township Road 350 Saskatoon, SK (306) 955-1350

Lloydminster 15 Horizon Drive Lloydminster, SK (306) 955-1350

Moose Jaw Highway 1 West Moose Jaw, SK (306) 955-1350

Ship To: IN STORE PICKUP

Invoice To: INTERNAL USE-SASKATOON

304323 TWP RD 350 SASKATOON SK S7K 3J

| Branch | | | | | |
|------------|----------|----------|-------|--------|--------|
| SASKATOON | | | | | |
| Date | Time | | | | Page |
| 11/07/24 | 23: | 01:11 | (B) | | 02 |
| Account No | Phone No | | | Inv N | lo |
| INT01 | | | | W0(| 044301 |
| Ship Via | | Purchase | Order | | |
| | | | | | |
| Tax ID No | | | | | |
| | | | | | |
| | | | Sales | sperso | n |
| | | | | BR1 | / 000 |

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

001070 2020 SUPREME 1500T X 215TR0090

1500TR

installed new caps.

Removed end panel and conveyor hoses to remove conveyor.

Removed conveyor wheels and installed four new wheels.

Reinstalled conveyor panels and hoses. Greased unit.

Removed PTO bolts and installed 2 new bolts.

ADDITIONAL DESCRIPTION:

- replace the steady bearing
- replace conveyor bearings
- change oils gearboxes and hubs
- install a used scale head
- install used extra display
- install a new auger cap
- install new knives and hardware

| THE CATT HOW IN | ni veb diid ildi dwale | | | |
|-----------------|---------------------------------------|--------|---------------|--------|
| AUX18CAP | | 2 | 313.40 | 626.80 |
| | AUX18CAP - AUGER: KIT, CAP, 18" OD, | | | |
| | W/BOLT | | | |
| AUX503 | | 3 | 63.24 | 189.72 |
| | AUGER: KICKER PLT, 16" | | | |
| BPX002 | | 3 | 73.17 | 219.51 |
| | SUPREME BPX002 BACKING PLATE | | | |
| BRGUCP309D1 | | 1 | 90.21 | 90.21 |
| | SUPREME BRGUCP309D1 - BEARING PTO ST | 'EAD | | |
| | Y BRG 45MM | | | |
| BRG8984YY | | 4 | 11.62 | 46.48 |
| | SUPREME BRG8984YY - BEARING RADIAL BA | LL | | |
| | SINGLE 203KRR3 | | | |
| BT3/8X3/4FHNCKS | | 15 | 1.10 | 16.50 |
| | BT3/8X3/4FHNCSK - KNIFE SMALL FLATHEA | D B | | |
| | OLT | | | |
| CBT5/8X2 | | 45 | 5.45 | 245.25 |
| | | CONTIN | UED ON PAGE (| 03 |
| | | | | |

| X | | |
|---|-------------|--|
| | Received By | |



Saskatoon- HQ

304323 Township Road 350 Saskatoon, SK (306) 955-1350 Lloydminster 15 Horizon Drive Lloydminster, SK (306) 955-1350 Moose Jaw Highway 1 West Moose Jaw, SK (306) 955-1350

Ship To: IN STORE PICKUP

Invoice To: INTERNAL USE-SASKATOON

304323 TWP RD 350 SASKATOON SK S7K 3J

| Branch | | | | | |
|------------|----------|----------------|-------|--------|--------|
| SASKATOON | | | | | |
| Date | Time | | | | Page |
| 11/07/24 | 23: | 01:11 | (B) | | 03 |
| Account No | Phone No | | | Inv N | lo |
| INT01 | | | | W0(| 044301 |
| Ship Via | | Purchase Order | | | |
| | | | | | |
| Tax ID No | | | | | |
| | | | | | |
| | | | Sales | sperso | n |
| | | | | BR1 | / 000 |

SERVICE INVOICE

| STK#/FLEET# | | HRS PIN/EI | N WA | RRANTY DATE | HRS |
|---------------|------------|-----------------------|-------------|-------------|----------|
| 001070 20 | 20 SUPREME | 1500T X 215TR0 | 090 | | |
| 1 | L500TR | | | | |
| | SUPREME | CBT5/8X2-1/2NC8 - KNI | FE BOLT | | |
| DIGI361026*US | SED* | USED TMR3610 | 1 | 3000.00 | 3000.00 |
| DIGI407227*US | SED* | USED RD2500V | 1 | 1000.00 | 1000.00 |
| LKNUT5/8NCP | | | 45 | 1.25 | 56.25 |
| | LKNUT5/8 | BNCP - KNIFE LOCKNUT | | | |
| SCX208 | | | 1 | 523.68 | 523.68 |
| | SUPREME | SCX208 - SCALE: KIT, | WEIGHT REPE | | |
| | ATER ARM | M, (30 PCS) | | | |
| SUBLETP | | Bolts/LNuts | 1 | 6.00 | 6.00 |
| SUP17X | | | 15 | 156.06 | 2340.90 |
| | STANDARI | O KNIFE, SERRATED | | | |
| | | | | PARTS | 8355.30 |
| | | | | LABOR | 3013.50 |
| | | | | SUBLET | 6.00 |
| | 420202 | 201 | SEGME | NT TOTAL==> | 11374.80 |
| | | | | | |

***** WORK ORDER TOTALS ******
INTERNAL CUSTOMER

PARTS 8355.30
LABOR 3424.50
SUBLET 6.00
INTERNAL TOTAL 11785.80

| (| |
|----------|--|
| | |