

|                                                                                                                                                                                                                     |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|------------------------|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| Yearly Scheduled Maintenance Spread Sheet - Unit 28 - Mechanical has warranty to 240,000 KM or July-31-21 with \$0 deductible & has prepaid FMPP to 150,000 or July-31-22 with \$0 deductible / Keyless Entry 64604 |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Vehicle Description 2015, Ford F-150 4X4, White - VIN - 1FTEX1E82FFB72915 - Plate: L76255 continuous                                                                                                                |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| OIL CHANGES DONE EVERY 8,000 - 10000 KMS                                                                                                                                                                            |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Next oil change due @ 230,000 kms                                                                                                                                                                                   |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Scheduled Maintenance as per Manufacturer                                                                                                                                                                           |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Repairs                                                                                                                                                                                                             |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Repair Description                                                                                                                                                                                                  | Repaired Date | Repair By (Mechanic, Shop, Dealer) | Km's at time of Repair | Cost (No GST) | Comments                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |  |  |
| Vehicle decals for unit 28, 8 hrs installation, 5 lb fire extinguisher w/vehicle bracket, environmental charge                                                                                                      | Apr-27-17     | Helmig                             | NR                     | \$ 1,605.02   | see invoice 84008 - this invoice has 2 units decaled total \$3138.04                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |  |  |
| mud flaps                                                                                                                                                                                                           | May-9-17      | Griffiths Motors                   | NR                     | \$ 236.50     | invoice #180753 has Unit #19 \$285.00 + Unit #28 \$236.85 mud flaps front & rear = 547.58                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |  |  |
| Install D board rack, radio, roof light and rear bar light ASSY                                                                                                                                                     | Oct-13-17     | D.A.M. Mechanics                   | 40488                  | \$ 3,565.00   | made mounts for rack ASSY, made mount for roof light ASSY and antenna, weld to rack, made and welded plates to bottom of rack to rise up and use for mounting system, make mounting for light controllers and radio, route wiring into cab for lights and radio, seal off areas, tie up all wiring                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |  |  |
| 14 GA arctic cable, ATC fuse holder                                                                                                                                                                                 | Jun-28-17     | Parts - NAPA                       | NR                     | \$ 24.71      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Maintenance service, oil chg., oil filter, air filter, multi point inspection, rotate tires                                                                                                                         | Jul-28-17     | Quick Lane                         | 44879                  | \$ -          | warranty work - *retorque tires @ 44,959 KM                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |  |  |
| Windshield                                                                                                                                                                                                          | Oct-12-17     | Trade Winds Glass                  | NR                     | \$ 325.00     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Oil, oil filter, replace air filter, multi point inspection - replace battery                                                                                                                                       | Oct-13-17     | Quick Lane                         | 53926                  | \$ 257.09     | warranty work for oil change - battery failed at 397CCA - recommended spec is 680 CCA - cost is for battery                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |  |  |
| Maintenance service, oil change, oil filter, pollen filter, 2 wipers, air filter, multi point inspection, rotate tires, rear brake pads, replaced both slide pins                                                   | Jan-9-18      | Quick Lane                         | 61279                  | \$ -          | warranty work - upon inspection during service tech noted that rear brakes @ 2-3MM, road test verified, requires replacement, replaced rear pads, tech notes that rear slide pins seized both sides, replaced slide pins, rotate complete- retorque tires in 100 KM                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |  |  |
| Jan-30 as per Dale Lewis went to Cascade and it was too busy to get a quote for damage                                                                                                                              |               |                                    |                        |               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Oil, oil filter, replace air filter, multi point inspection - rotate tires                                                                                                                                          | Mar-1-18      | Quick Lane                         | 70248                  | \$ -          | warranty work - Rotated tires – retorque in 100 KM / 70248 KM + 100 KM = 70348 KM                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |  |  |
| Oil, oil filter                                                                                                                                                                                                     | Mar-28-18     | Wessons Automotive - Fox Creek     | 73185                  | \$ 80.00      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Recall 17S33, doors will not open or close, replace block heater and core, misc electrical message stating not in ready mode, glass repairs driver window will not go up and down                                   | Apr-16-18     | Griffiths Motors                   | 70383                  | \$ 49.95      | Parts for TSB were ordered, but have no ETA on parts arrival due to parts shortage, recommend using A/C with heat for the time being to warm vehicle, replaced heater core ASSY heater operation all functions work and heat output is good and hot, *unit has one my key programmed and one administrator key, if keys are used at different times this message is displayed, no problem just a message indicating what key is being used, in order to erase my key settings both original keys will have to be present for a erase and re program procedure, printed off my key information for customer, glass repair driver window switch pack signal stuck hi, possible dirt or snow may have caused the switch to stick at one point, switch is functioning normally and code does not reset |  |  |
| Air Filter                                                                                                                                                                                                          | May-10-18     | NAPA - Fox Creek                   | NR                     | \$ 22.39      | no signature                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |  |  |
| Oil, oil filter, air filter                                                                                                                                                                                         | May-31-18     | Wessons Automotive - Fox Creek     | 81127                  | \$ 130.23     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| replaced external water pump, anti freeze                                                                                                                                                                           | Jun-4-18      | Quick Lane                         | 81455                  | \$ -          | warranty - please note coolant leak was verified-water pump replaced-"tech notes that "Green Coolant" present throughout cooling system....as per Ford spec Motor craft "Orange Coolant" is required                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |  |  |
| Right rear tire repair                                                                                                                                                                                              | Jul-4-18      | Cory's Engine Repair - Fox Creek   | 86384                  | \$ 62.40      | all tires are torqued to spec and ***must be retorqued after 80 KM***                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |  |  |
| Right rear tire, rear pads, slide pin kits                                                                                                                                                                          | Jul-23-18     | Wessons Automotive - Fox Creek     | 87822                  | \$ 619.16     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Completed engine scan for engine light, cleaned vent hose, fuel inlet message checked                                                                                                                               | Oct-2-18      | Quick Lane                         | 100752                 | \$ 144.30     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Brake rotor rear, brake pads rear                                                                                                                                                                                   | Oct-2-18      | Parts- Napa                        | NR                     | \$ 214.42     | Invoice# 810-335925                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |  |  |
| Fix back brakes rotors, right side new pads,brake plungers needed fixing                                                                                                                                            | Oct-03-18     | McStrong Shop                      | 100762                 | \$ -          | Greg Completed                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |  |  |
| Washer, bolt, hose asy, hose asy                                                                                                                                                                                    | Oct-16-18     | Griffiths Motors                   |                        | \$ 27.48      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| Housing, brake kit                                                                                                                                                                                                  | Oct-16-18     | Griffiths Motors                   |                        | \$ 313.85     |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |

|                                                                                                                                                                               |           |                                |        |             |                        |  |  |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------------------------|--------|-------------|------------------------|--|--|
| Kit brake                                                                                                                                                                     | Oct-16-18 | Griffiths Motors               | NR     | \$ 15.53    |                        |  |  |
| Brake Pads- Rear                                                                                                                                                              | Oct-16-18 | Parts- Napa                    | NR     | \$ 79.98    | Invoice#810-339333     |  |  |
| Core deposit, housing, bolt & washer                                                                                                                                          | Oct-17-18 | Griffiths Motors               | NR     | \$ 325.80   |                        |  |  |
| Core return, bolt                                                                                                                                                             | Oct-17-18 | Griffiths Motors               |        | -\$ 60.52   |                        |  |  |
| Back brakes, caliper new, clear engine code                                                                                                                                   | Oct-17-18 | McStrong Shop                  | 10206  | \$ -        | Greg Completed         |  |  |
| Oil changed                                                                                                                                                                   | Oct-23-18 | McStrong Shop                  | 102308 | \$ -        | Greg Completed         |  |  |
| Hose assembly                                                                                                                                                                 | Oct-24-18 | Griffiths Motors               | NR     | \$ 39.62    | Inv # 190323           |  |  |
| Complete engine scan for check engine light on dash, inspected under vehicle to find canister pigtail broken vehicle requires canister pigtail                                | Oct-24-18 | Quick Lane                     | 102318 | \$ -        |                        |  |  |
| Check GRS & brakes, back brakes needed bleeding,                                                                                                                              | Oct-31-18 | McStrong Shop                  | 110306 | \$ -        | Greg Completed         |  |  |
| <b>Note: Door latch freezing concerns only book in for repair if unit has freezing latch problems repair through Oct-31-28</b>                                                | Nov-5-18  | Ford Motors Company            | NR     | \$ -        | Service Recall # 18N03 |  |  |
| GPS Not Working- Cut white wire as told by Titan- will call to see if fixed                                                                                                   | Dec-26-18 | McStrong Shop                  | 105333 | \$ -        |                        |  |  |
| <b>RECALL- 18S45 ENGINE BLOCK HEATER WIRE ASSEMBLY- WATER INTRUSION OR CORROSION &amp; 18N03 DOOR LATCH FREEZING CONCERNS</b>                                                 |           |                                |        |             |                        |  |  |
| Tire Repair                                                                                                                                                                   | Feb-11-19 | Wessons Automotive - Fox Creek | 109537 | \$ 35.00    |                        |  |  |
| Oil Change- Needs water pump**on order                                                                                                                                        | Feb-14-19 | Wessons Automotive - Fox Creek | 110241 | \$ 85.00    |                        |  |  |
| Water pump, Coolant                                                                                                                                                           | Feb-21-19 | Wessons Automotive - Fox Creek | 112261 | \$ 567.00   |                        |  |  |
| O Ring, Rad Cap, Coolant, Diagnose Wobble(Mud in rear wheels) upper rad hose                                                                                                  | Mar-14-19 | Wessons Automotive - Fox Creek | 114094 | \$ 638.18   |                        |  |  |
| Oil Change                                                                                                                                                                    | Mar-22-19 | McStrong Shop                  | 115000 | \$ -        | Greg Completed         |  |  |
| Replace plugs and intake gasket, repair bead leak back rear tire                                                                                                              | Mar-27-19 | Quick Lane                     | 114250 | \$ 75.75    |                        |  |  |
| Change Spark Plugs, Air Filter Replaced                                                                                                                                       | Mar-28-19 | Quick Lane                     | 114250 | \$ 247.53   |                        |  |  |
| Installed new Battery                                                                                                                                                         | Mar-29-19 | McStrong Shop                  | 115000 | \$ -        | Greg Completed         |  |  |
| Flat Repair                                                                                                                                                                   | Mar-27-19 | Quick Lane                     | 114250 | \$ 75.75    |                        |  |  |
| Tow, Rear shaft, Y pipe right, cross member, insulator, studs/nuts, 02 sensors, used tire                                                                                     | Apr-17-19 | Wessons Automotive - Fox Creek | 115431 | \$ 4,040.84 |                        |  |  |
| <b>RECALL-ENGINE BLOCK HEATER WIRE ASSEMBLY - WATER INTRUSION OR CORROSION/ DOOR LATCH FREEZING CONCERNS/ DOOR LATCH FREEZING CONCERNS</b>                                    |           |                                |        |             |                        |  |  |
| Replace Fuse, Replace Battery, Repair block heater assembly                                                                                                                   | May-14-19 | Griffiths Motors               | 115899 | \$ 437.52   |                        |  |  |
| Supply and install windshield                                                                                                                                                 | Jul-2-19  | Tradewinds Glass               | NR     | \$ 330.75   |                        |  |  |
| LT265/70T17 TOYO M55 3PMS 121Q 10E RBL- Wheel Balance                                                                                                                         | Jul-2-19  | OK TIRE                        | 115980 | \$ 1,490.24 |                        |  |  |
| Skid Plate, front rad protector- Checked for active leaks, lubed doors, hinges and pivot points, rechecked oil level and topped up all fluids                                 | Jul-4-19  | McStrong Shop                  | 115995 | \$ -        | Cam Completed          |  |  |
| <b>RECALL- 19G01- UPGRADED BLOCK HEATER CORD IS NOW AVAILABLE- IF PREVIOUSLY BROUGHT IN FOR SERVICES UNDER 18S45 OR19S11, PLEASE DO SO AGAIN TO RECEIVE THE UPGRADED CORD</b> |           |                                |        |             |                        |  |  |
| Oil change and air filter                                                                                                                                                     | Oct-19-19 | Lube City                      | 122730 | \$ 106.97   |                        |  |  |
| Full service oil change, new air filter                                                                                                                                       | Apr-23-20 | Lube City                      | 131462 | \$ 108.97   |                        |  |  |
| RECALL 18N03R- Door Latch Freezing Complete                                                                                                                                   | May-19-20 | Griffiths Motors               | 132739 | \$ -        |                        |  |  |
| All Fluid changed (oil, transfer case, and diffs). New rear rotors, calipers, saddles and brakes installed                                                                    | May-26-20 | McStrong Shop                  | 132800 |             | Cam Completed          |  |  |
| Replace 4 Cam Phasers, timing chain and tensioner, reassembled crank timing sprocket and idler, 4 Wheel alignment                                                             | May-27-20 | Windsor Ford - Grande Prairie  | 133287 | \$ 202.44   |                        |  |  |
| Replaced faulty purge valve on intake on evap system.                                                                                                                         | Aug-5-20  | Windsor Ford - Grande Prairie  | 137755 | \$ 409.83   |                        |  |  |
| Oil change, change air filter.                                                                                                                                                | Sept-4-20 | Lube City                      | 140659 | \$ 76.89    |                        |  |  |
| Oil change, air filter change                                                                                                                                                 | Feb-13-21 | Lube City                      | 148776 | \$ 113.72   |                        |  |  |
| GPS installation                                                                                                                                                              | May-20-21 | McStrong Shop                  | 154543 |             | Mike completed.        |  |  |
| McStrong Inspection - pilot board has inop lighting/needs weld repair, LR plate light inop, RR door dent                                                                      | May-21-21 | McStrong Shop                  | 154543 |             | Mike completed.        |  |  |
| Repaired 3 of 5 lights on pilot board- waiting for parts. Added 2L washer Fluid                                                                                               | May-21-21 | McStrong Shop                  | 154543 |             | Mike completed.        |  |  |
| Oil Change, inspection completed                                                                                                                                              | 15-Jun-21 | Lube City                      | 156442 | \$ 79.97    |                        |  |  |

|                                                                                                                                                                                                                                               |           |                               |        |             |                         |  |  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------|--------|-------------|-------------------------|--|--|
| Inspect unit for brake pulsation, check engine light on, leak in evap system. Referred to dealership for futher diagnosis                                                                                                                     | 12-Jul-21 | Quick Lane                    | 157969 | \$ 277.50   | Quick Lane              |  |  |
| Replace Evap purge solenoid, evap cannister and cleaned out Evap vent tube. Erased codes and road tested good. Complete general inspection, replaced wiper blades. Cabin air filter may be due next service. All other systems & fluids good. | 16-Jul-21 | Griffiths Motors              | 157979 | \$ 213.18   | Griffiths Ford          |  |  |
| Full service oil change                                                                                                                                                                                                                       | 3-Oct-21  | Jiffy Lube (Grande Prairie)   | 166000 | \$ 83.54    | Jiffy Lube (Gr Prairie) |  |  |
| full service oil change                                                                                                                                                                                                                       | 24-Jan-22 | Jiffy Lube (Grande Prairie)   | 170545 | \$ 101.09   | Jiffy Lube (Gr Prairie) |  |  |
| Change oil & filter, replace bulb, replace cabin air filter, replace all lugnuts                                                                                                                                                              | 18-Feb-22 | Windsor Ford - Grande Prairie | 176947 | \$ 238.64   | Windsor Ford completed  |  |  |
| Change oil & filter                                                                                                                                                                                                                           | 6-Jun-22  | McStrong Shop                 | 184812 | \$ -        | Ricky Completed         |  |  |
| JL3Z-2B712-A Motor 3b                                                                                                                                                                                                                         | 8-Jun-22  | Griffiths Motors              | 185017 | \$ 371.42   | parts only              |  |  |
| replace both headlights with new LED bulbs                                                                                                                                                                                                    | 5-Jul-22  | McStrong Shop                 | 186689 | \$ -        | Cam Completed           |  |  |
| head light (H11)                                                                                                                                                                                                                              | 5-Jul-22  | Griffiths Motors              | 186689 | \$ 129.95   | parts only              |  |  |
| change oil & oil filter, change engine air filter & cabin air filter. Install buggy whip                                                                                                                                                      | 6-Sep-22  | McStrong Shop                 | 191314 | \$ -        | Cam Completed           |  |  |
| <a href="#">fan stuck on high. Evacuated AC &amp; recharged. Fans working normally</a>                                                                                                                                                        | 5-Oct-22  | Quick Lane                    | 194562 | \$ 456.30   | Quick Lane              |  |  |
| <a href="#">Supply and install windshield</a>                                                                                                                                                                                                 | Jan-27-23 | Tradewinds Glass              | 196857 | \$ 310.00   | Tradewinds Completed    |  |  |
| <a href="#">install new headlights(both sides)</a>                                                                                                                                                                                            | Jan-30-23 | McStrong Shop                 | 196859 | \$ -        | Cam Completed           |  |  |
| <a href="#">new headlights</a>                                                                                                                                                                                                                | 30-Jan-23 | Napa                          | 196859 | \$ 264.66   | parts only              |  |  |
| replace passenger side headlight, change oil, oil filter & replace engine air filter                                                                                                                                                          | Feb-14-23 | McStrong Shop                 | 199201 | \$ -        | Cam Completed           |  |  |
| <a href="#">replace passenger side low beam</a>                                                                                                                                                                                               | Apr-21-23 | McStrong Shop                 | 202326 | \$ -        | Cam Completed           |  |  |
| <a href="#">wire a sor</a>                                                                                                                                                                                                                    | Apr-22-23 | Griffiths Motors              | 202326 | \$ 48.41    | Griffiths Ford          |  |  |
| <a href="#">compressor discharged, recover .81kg of refrigerant, replaced TXV and filled with .88kg</a>                                                                                                                                       | May-18-23 | Griffiths Motors              | 206303 | \$ 511.47   | Griffiths Ford          |  |  |
| <a href="#">change oil/oil filter, replace cabin air filter, replace engine air filter, recharge freon, replace passenger headlight pig tail</a>                                                                                              | May-19-23 | McStrong Shop                 | 206320 | \$ -        | Cam Completed           |  |  |
| <a href="#">replace wipers, change oil/oil filter, replace engine air filter, replace D sign, rear right beacon and rear right flasher, grease pilot board hinge &amp; rams, wash entire unit, undercarriage &amp; engine bay</a>             | Jul-31-23 | McStrong Shop                 | 214169 | \$ -        | Cam Completed           |  |  |
| <a href="#">WHEEL ALIGNMENT, REPLACED UPPER AND LOWER TIE RODS, REPLACE BALL JOINT, TIRE MOUNT AND BALANCE (4), REPLACE REAR BRAKE PADS,</a>                                                                                                  | Dec-15-23 | Quick Lane                    | 219387 | \$ 3,839.65 | Quick Lane Completed    |  |  |
| Change oil/oil filter, replace engine air filter, replace cabin air filter                                                                                                                                                                    | Aug-16-24 | McStrong Shop                 | 221963 | \$ -        | Cam Completed           |  |  |
| legend battery                                                                                                                                                                                                                                | Aug-21-24 | Napa                          | 222262 | \$ 195.95   | parts only              |  |  |
| replaced 4 TPMS, TPMS Sensor                                                                                                                                                                                                                  | May-15-25 | Quick Lane                    | 223392 | \$ 476.64   | Quick Lane Completed    |  |  |

\*\*\*RECALL An intermittent signal loss from the Transmission Range Sensor (TRS) is causing an unexpected downshift to a lower gear, which can cause rear wheels to slide or lock up momentarily. PCM update is require

|  |
|--|
|  |
|  |

[illegible]



[illegible]

[illegible]