

**WEBB'S MACHINERY LTD.**

4503 - 48th Street
LAMONT, AB T0B 2R0
Tel: 780-895-2189 Fax: 780-895-2174
GST # 858106172RT0001

**Estimate: E11035L****Date: 07/26/2024**

FOLLY FARMS LTD
C/O LES & JODI SPEERS
24331 TWP RD 552
STURGEON COUNTY, AB T8T 1P5

Year		Make/Model		Serial Number		
		2012 NH CR8090		YCG115547		
Stock No	PO	Misc Information	Tag	Customer	Telephone	
8182-2L				08682	780-710-8682	

Cond	OpCode	T	Description	Quantity	List	Net	Total
------	--------	---	-------------	----------	------	-----	-------

Type: **COMBINE** RO Open Date: **07/18/24** Meter In: **2332**

001 **GENERAL**

F - TOP REAR SHIELD RIVNUT BROKEN OUT OF SHIELD AND SHIELD LOOSE
(1.0 HR)

CLAB	L CUSTOMER LABOUR						172.00
	P 86976968 INSERT	1.00		4.22			4.22
Subtotal charges this section							176.22

002 **ELECTRICAL**

F - TOP FRONT WORK LIGHT HOUSING HAS WATER IN HOUSING (6.0 HRS) —
- TOP RH CAB BULBS NOT WORKING (1.0 HRS IF BULBS ONLY)
- LEFT FRONT BEACON AND REAR BEACON LIGHTS NOT ROTATING (1.3 HRS)
- LEFT REAR TAIL LIGHTS NOT WORKING (0.5 HR IF BULBS ONLY)
- LEFT REAR WORK LIGHT BURNT OUT (0.3 HR)
- BOTH REAR SIGNAL LIGHTS NOT WORKING (0.6 HR IF BULBS ONLY)
NOTE : **** REPLACED FUSE FOR HAZARD LIGHTS AS FRONT SIGNALS
DID NOT FUNCTION ****

CLAB	L CUSTOMER LABOUR						1668.40
	P 84607387 LAMP	1.00		188.12			188.12
	P 894 BULB	2.00		14.01			28.02
	P 87050694 BEACON	2.00		164.75			329.50
	P 1157 1157 BULB	1.00		0.92			0.92
Subtotal charges this section							2214.96

003 **FEEDER**

F - REPLACE FEEDER DRIVE CHAIN (0.7 HR)
- UPPER FEEDER REVERSER DRIVE BELT TENSIONER HARDWARE TENSION
INCORRECT (0.7 HR)
- ANTIWRAP SHIELDS MISSING/ REMOVED
- STONE DOOR DAMAGED AND HOLE IN DOOR (2.0 HRS)
- REMOVE FEEDER HOUSE AND DSP DSP FRAME BOLT MISSING AND LOWER
BOLT LOOSE ON DSP (7.0 HRS)
- REPLACE DSP WEAR BARS (2.0 HRS)
- REPAIR/ STRAIGHTEN LHS BELT SHIELDS BENT CONTACTING AND
WEARING BELTS FOR FEEDER DRIVE (2.0 HRS)

CLAB	L CUSTOMER LABOUR						2476.80
	P 47626191 KIT	1.00		5000.00			5000.00
	P 80-1R #80 CHAIN	7.00		36.66			256.62
	P 80-1RCONN 80 CONN	1.00		6.49			6.49
	P 84482723 STRIP PRO	3.00		245.13			735.39
	P 84482718 STRIP PRO	3.00		76.60			229.80

**WEBB'S MACHINERY LTD.**

4503 - 48th Street
LAMONT, AB T0B 2R0
Tel: 780-895-2189 Fax: 780-895-2174
GST # 858106172RT0001

**Estimate: E11035L****Date: 07/26/2024**

FOLLY FARMS LTD
C/O LES & JODI SPEERS
24331 TWP RD 552
STURGEON COUNTY, AB T8T 1P5

Year		Make/Model		Serial Number		
		2012 NH CR8090		YCG115547		
Stock No	PO	Misc Information	Tag	Customer	Telephone	
8182-2L				08682	780-710-8682	

Cond	OpCode	T	Description	Quantity	List	Net	Total	
			P 210049 BEARING B	1.00		100.15	100.15	
			P 87315599 V-BELT	1.00		95.32	95.32	
			Subtotal charges this section					8590.31
006			RESIDUE					
			F - *** CHOPPER DRIVE COUPLER SPLINES WORN *** (1.3 HRS)					
			- REPLACE CHOPPER DRIVE BELT; CRACKED (0.70 HRS)					
			- CHOPPER HOUSING CRACKED WITH HOLES (5.0 HRS)					
			- FLIP CHOPPER KNIVES REPLACE FLAILS AS NEEDED (3.5 HRS)					
			- REPLACE RH CHOPPER BEARING; NOT TAKING GREASE (2.0 HRS)					
			- STRAW DOOR HINGE LHS WORN IN HOUSING; WELD IN SUPPORT WASHER (2.0 HRS)					
	CLAB		L CUSTOMER LABOUR				2494.00	
			P 87396382 COUPLING	1.00		232.30	232.30	
			P 87557181 BELT TRAN	1.00		488.52	488.52	
			P 84287666 HOUSING	1.00		3187.82	3187.82	
			P 87338613 BEARING AS	1.00		188.23	188.23	
			Subtotal charges this section					6590.87
007			GRAIN STORAGE					
			F - INSTALL GRAIN TANK DOOR LATCH BOLT; REAR COVER MISSING (0.3 HRS)					
			- SILICONE AROUND BUBBLE UP TUBE SEAL (0.6 HRS)					
	CLAB		L CUSTOMER LABOUR				154.80	
			Subtotal charges this section					154.80
008			HYDRAULICS					
			F - HYDRAULIC OIL RETURN AT FILLER TUBE SHOWING SIGNS OF LEAKING POSSIBLE CRACK IN TUBE (1.0 HR)					
	CLAB		L CUSTOMER LABOUR				172.00	
			P 84185556 TUBE HYDRA	1.00		159.62	159.62	
			Subtotal charges this section					331.62
009			ENGINE					
			F - REPLACE ROTARY SCREEN BELT CRACKING (1.0 HR)					
			- ROTARY SCREEN SKIRT SEAL PLUGGED MAY NEED REPLACING (3.0 HRS)					
			- LOWER LEFT AIR FILTER HOUSING TAB BROKEN OFF (2.5 HRS)					
			- REMOVE AND CLEAN ASPIRATOR SYSTEM (2.0 HRS)					
	CLAB		L CUSTOMER LABOUR				1462.00	
			P 87664428 V-BELT	1.00		125.29	125.29	
			P 84057430 BRUSH	3.00		210.92	632.76	
			Subtotal charges this section					2220.05
010			GROUND DRIVE					

**WEBB'S MACHINERY LTD.**

4503 - 48th Street
LAMONT, AB T0B 2R0
Tel: 780-895-2189 Fax: 780-895-2174
GST # 858106172RT0001

**Estimate: E11035L****Date: 07/26/2024**

FOLLY FARMS LTD
C/O LES & JODI SPEERS
24331 TWP RD 552
STURGEON COUNTY, AB T8T 1P5

Year		Make/Model		Vehicle Identification		
2012		NH CR8090		YCG115547		
Stock No	PO	License	Tag	Customer	Telephone	
8182-2L				08682	780-710-8682	

Cond	OpCode	T	Description	Quantity	List	Net	Total
------	--------	---	-------------	----------	------	-----	-------

M SHOP MATERIALS**300.00****THANK YOU FOR YOUR BUSINESS****TERMS:**

Account due 10th of month following date of purchase. A service charge of 24 % per annum (2% per month) will be added to over due accounts

20% restocking charge on return or special ordered parts.

All claims and returned goods must be accompanied by this bill.

DESC	TOTALS
LABOR	20683.00
PARTS	22306.25
SUBLET	
MISC	300.00
OTHER	
SUBTOTAL	43289.25
GST	2164.46
PST	
TOTAL	45453.71