

Red Earth Farms TR98 S/N 559756

2023

- Rebuild/update Torque Sensor with TR99 spring
- Rebuild and re-sleeve splined hub in cleaning fan drive sheave.
- Replace shoe drive shaft, bearings & eccentrics
- Overhaul main thresher drive clutch
- Replace fan variator motor
- Replace return elevator housings with good used parts

2026

- Repair electronic stone trap-Replace failed sensor & control box with used parts.
- Replace stone trap switch & harness on feeder house. Open circuit in power supply harness.
- Repair cab door handle/latch
- General inspection and check machine operation. All functions operating normally