

Vancouver • Edmonton • Lloydminster





EDMONTON - WEST 11313 - 170 Street Edmonton, AB T5M 3P5 Phone: 780.413.8800 Fax: 780.413.8808

EDMONTON - SOUTH SIDE 4504 Roper Road NW Edmonton, AB T6B 3T8 Phone: 780.413.9422 Fax: 780.413.9428

R001142696:01
05/07/2020
CASH
10791
125790
777
11940 1776 RT0001

Service Invoice

Bill To:

EXL AGGREGATES & RENTALS 4120 - 41 ST

EXLRENTS@GMAIL.COM

RUSSELL (DRIVER) 780 898 6506 6 AM - 8 PM

LABOR

LABOR

EDMONTON, AB T7A 0B4

Ph: (780)898-0023 Cell: (780)413-8800

EXL AGGREGATES & RENTALS MAIN STORE EDMONTON, AB T5M 3P5

Year: 10 Make: FTL		Make: FTL Model: CA125SLP	
Colour: WHITE	License: U45175	Odometer In 1,189,095	In Service Date: 10/30/2009
Advisor: 1158	Reviewer: 0327	Engine Hr: 0	ESN: 472901S0015764-DETROIT

CUSTOMER CONTACT INFORMATION SR JOB#1 CONTACT BROCK 780 898 0023 6 AM - 9:30 AM CONDITION

JOB#2 EXPRE	S SR EXPRESS ASSESSMENT		14657
CONDITION	WHEN CLIMBING HILL, HEARD A HISS AND STEAM WAS BLOWING ON THE RHS. & OIL PRESSURE LIGHT CAME ON, UNIT SHUT DOWN. DRIVER FOUND A BOLT LO DRIPPING FROM OIL PAN. POSSIBLY PRESSURED UP AND BLEW A GASKET. ALS WHICH MIGHT HAVE DRAINED INTO THE MOTOR.	OSE AND OIL	E
CORRECTION	CHECK ENGINE OIL. ENGINE OIL MILKY AND OVER FULL, COOLANT IN ENGINE O OFF. BROUGHT UNIT INTO SHOP. DRAIN OIL REMOVED SADDLE BRACKET UNDE OIL PAN. REMOVED ENGINE OIL PAN. FOUND #5 CYLINDER LINER DAMAGED, LIN INTAKE THRUST SIDE. NEED TO REPLACE #5 CYLINDER LINER, PISTON, AND CO PERFORM BEARING ROLL IN. REINSTALLED OIL PAN, AND FRAME BRACKET AT MOUNTS. TOWED UNIT OUTSIDE.	R REAR OF ENGINE IER SCORED ON INNECTING ROD.	:
QTY ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE

FIRST TRUCK HEALTH CHECK - FREE INSPECTION JOB#3 HEALTH FIRST TRUCK HEALTH CHECK - FREE INSPECTION CONDITION

JOB#2 EXPRESS ---- PARTS: 0.00 -- LABOR: 846.00 -- TOTAL 846.00





846.00

Bill To: EXL AGGREGATES & RENTALS 4120 - 41 ST EDMONTON, AB T7A 0B4 Owner: EXL AGGREGATES & RENTALS MAIN STORE EDMONTON, AB T5M 3P5

11940 1776 RT0001
777
125790
10791
CASH
05/07/2020
R001142696:01

CORRECTION	FINDINGS		
* ************************************	AIR LEAK AT LEVELING VALVE FDA YOKE LOOSE RDA BOTH SIDE BRAKE POTS BROEKN HOOK MARKER LIGHT DIM WINDSHIELD CRACKED LIC PLATE LIGHT OUT COOLANT LOW ENG OIL OVER FULL		
QTY ITEM		UNIT PRICE	EXTD PRICE
	LABOR		0.00
JOB#3 HEALTH PARTS: 0.00 LABOR: 0.00 TOTAL 0.00			





Bill To: EXL AGGREGATES & RENTALS 4120 - 41 ST EDMONTON, AB T7A 0B4 Owner: EXL AGGREGATES & RENTALS MAIN STORE EDMONTON, AB T5M 3P5

Customer Unit:	777
Unit No.:	125790
Customer No	10791
Terms:	CASH
P.O. No	
Invoice Date	05/07/2020
Invoice No.	R001142696:01

** Should your wheels be removed for any reason, please have them re-torqued after 150 kilometres **

As an Elite Support dealer, we inspect every job for quality of workmanship.

A 15-point Quality Inspection Report is completed by a factory trained technician at the end of your repair.

Your QI report for RO#

R001142696:01

was completed by staff ID #

on

Please Remit Payment to: FIRST TRUCK CENTRE EDMONTON INC 11313 - 170 STREET EDMONTON, AB T5M 3P5

TOTAL	959.36
GST	45.68
SUBTOTAL	913.68
MISC SUPPLIES	67.68
SUBLET	0.00
BODY SHOP SUPPLIES	0.00
LABOR	846.00
PARTS	0.00
MISC CHARGES	0.00

I, the undersigned owner, or duly authorized representative, authorize the repair and service work as detailed on this repair order. Permission is also granted to your employees to operate the vehicle herein described on the streets, highways, or elsewhere for the purpose of testing and/or inspection. It is understood that First Truck Centre Inc. does not assume any responsibility whatsoever to vehicles or contents while in their possession.

****Disclaimer of Warranty****

Any warranties on the products sold hereby are those made by the manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose, and First Truck Centre neither assumes nor authorizes any other person to assume any liability in connection with the sale of the said products.

First Truck Centre shall not be liable for special, indirect or consequential damages, e.g.: down time, loss of revenue, loss of vehicle, towing charges, driver's expenses, loss of perishable cargo, etc.

Failed parts return requests must be made when the unit is checked in.

Please be aware that any aftermarket modifications to OEM components are customer responsibility.

First Truck Centre assumes no responsibility for damage to any aftermarket component as a result of our diagnostics or repairs.

Workmanship is warranted for 90 Days from date of invoice. If a possible warrantable situation arises at a location other than First Truck Centre then First Truck Centre must be contacted to be involved in the repair decision.

I/we hereby acknowledge this invoice and an express garageman's lien thereon to secure full amount of indebtedness.

I/We agree to pay interest at the rate of 2% per month (24% per annum), if the balance due is not paid within the credit terms of First Truck Centre. I/We also agree to pay storage fees of fifty dollars (\$50.00) per day, both before and after judgment plus all costs incurred in the collection of the balance owing, legal fees and disbursements on a solicitor client basis.

Authorized by:	Released by:	
Printed Name:	Date:	Time:

JeID: 5168748 Reprinted 5/07/20 4:31:17PM



Follow us on TWITTER @First_Truck



