	I-RME TABER
Ship to:	DARRELL SRN 007135
o t	
Ē	
S	
Invoice to:	INTERNAL CUSTOMER #10
Ö.	HWY 3 WEST & 864 SECONDAR
oj.	TABER, AB
_ ≥	TABER AB T1G 2E5
-	

17300000

Toll Free: 1-855-763-1427							
Branch	Branch						
TABER		*REPRII	NT*				
Date	Time				Page		
05/11/21	22:0	)3:53 (I	в)		01		
Account No.	Phone N	0.		Refe	rence No.		
INTCUS10	4032	2232333		W42	898		
Ship Via	Purchase Order						
		G.S.T. No.			·		
79759 4660 RT0001					T0001		
Credit Card No.		Sale	spers	on			
			. F	(70			

# **Description of Work and Parts**

PO Box 4300

Fax:

(403) 223-2333 (403) 223-1515

STK#/FLEE	r#	HRS	PIN/EIN	WARRANT	Y DATE	HRS	Fold
126746	COMBINE	1609	/DG222785				
	8230	1206	NO HEADER				
**Here at	Rocky for your pr	otection and o	ours we are	wiping down			
** every ]	piece of equipment	before and a	fter we repa	ir it.			
SEGMENT# :	1 C 00163 NA	05/05/21	05/05/21				
NEEDS NE	W BATTERIES						
COMPLAIN'	Γ <u>:</u>						
NEEDS NE	W BATTERIES						
CAUSE:							
batterie	S						
CORRECTION	<u> NC</u>						
remove co	over from batterie	s					
remove ca	ables from batteri	es					
remove ba	atteries						
install :	new batteries						
install (	cables and cover						
CCMF31GW		GR31 WET	BATT	2	158.33	316.66	
SCRP3		1.5 UNIT	ÇÜRE		27.00	54.00	
SCRP3		1.5 UNIT	CORE	2-	27.00	54.00-	
					PARTS	316.66	
					LABOR	98.60	

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\* INTERNAL -CUSTOMER PARTS 316.66 LABOR 98.60

415.26

DISPOSAL FEE

SEGMENT TOTAL ==>

1.97

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I hereby acknowledge my indebtedness in the amount of \$ amount owing or balance owing as shown hereon.	being the total
(signature) (date)	(signature)	(date)



COMBINE

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

i-rme taber
Darrell Srn 007135

Invoice to:

STK#/FLEET#

126746

INTERNAL CUSTOMER #10 HWY 3 WEST & 864 SECONDAR TABER, AB TABER AB T1G 2E5 PO Box 4300 Hwy 3 & 864 Secondary Taber, AB T1G 2E5

Tel: (403) 223-2333 Fax: (403) 223-1515 Toli Free: 1-855-763-1427

WARRANTY DATE

Branch					
TABER					
Date	Time				Page
05/11/21		03:53 (1	B.)		02
Account No.	Phone No	0.		Refe	rence No.
INTCUS10	4032	2232333		W42898	
Ship Via	Purchase Order				
		G.S.T. No.			
		79759	466	80 R	Γ0001
Credit Card No.			Sale	spers	on
			I	(70	

HRS

INVOICE

Fold - - -

# **Description of Work and Parts**

HRS PIN/EIN

1609 YDG222785

8230	1206 NO HEAI	SHOP SUP	PLIES 8.3	
1997 . 111	entano en la compania de la compania			**; <del>*</del>
	and the second second		e de la companya de	orang sa maga aka mang taga sa sa sa sa sa

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I hereby acknowledge my indebtedness in the amount of \$ being the total amount owing or balance owing as shown hereon.
(signature) (date)	(signature) (date)

	1011 1 Tee. 1-055-705-	1441		
Rocky Mountain Equipment LP o/a Rocky Mountain Equipment  RME  TERNAL CUSTOMER #10  Y 3 WEST & 864 SECONDAR  BER, AB	Branch			
RME TERNAL CUSTOMER #10	TABER		*REPRINT*	
	Date	Time		Page
	08/21/18	20:	02:03 (B)	01
	Account No.		Phone No.	
	INTCUS10	403	2232333	W34731
	Ship Via		Purchase Orde	er
TERNAL CUSTOMER #10	RICHARD BAC	CHO	W34509	
Y 3 WEST & 864 SECONDAR			G.S.T. No.	
BER, AB			79759 46	60 RT0001
ספס אס ייינים מפר	Credit Card No.		Sal	esperson

HRS

4.00 HRS

INVOICE

E36

Fold -- -- --

Ship to:	I-RME
Invoice to: SI	INTERNAL CUSTOMER #10 HWY 3 WEST & 864 SECONDAR TABER, AB TABER AB T1G 2E5

Description	of	Work	and	<b>Parts</b>
-------------	----	------	-----	--------------

STK#/FLEET#	
126746	

COMBINE

8230

HRS PIN/EIN

X YDG222785

1205 NO HEADER

We have expanded our hours to serve you better, Now open Monday - Friday from 7:30am - 5:30pm and Saturday 8am - 12pm

SEGMENT# 1 C 03398 NA

07/10/18 07/10/18

FEEDER FLOOR

COMPLAINT: Feeder floor.

CAUSE:

Feeder floor was worn out.

CORRECTION:

Removed the old feeder floor. Cleaned off the dirt where the floor sits. Installed the new floor held it in place with a floor jack. Put hardware in and tightened hardware.

ADDITIONAL DESCRIPTION:

CLOSED BY KF

AUG 21

67262537

FLOOR

PARTS

895.70

LABOR

2.00 HRS

540.00

17300000

SEGMENT TOTAL ==>

WARRANTY DATE

1435.70

SEGMENT# 2 C 03398 NA

07/10/18 07/10/18

DISCHARGE SPOUT

COMPLAINT:

Discharge spout.

CAUSE:

Somebody hit something with the auger.

CORRECTION:

Removed the damaged spout to replace it. Found a big gash

		being the total
(signature) (date)	(signature)	(date)

ROCKY MOUNTAIN EQUIPMENT
Rocky Mountain Equipment LP o/a R

Rocky Mountain Equipment

	I-RME
Ship to:	
Invoice to:	INTERNAL CUSTOMER #10 HWY 3 WEST & 864 SECONDAR TABER, AB TABER AB T1G 2E5

Branch					
TABER					
Date	Time				Page
08/21/18	20:0	02:03 (1	3)		02
Account No.	Phone No	D.		Refe	rence No.
INTCUS10	4032232333			W34731	
Ship Via		Purchase Order			
RICHARD BACHO	)	W34509			
		G.S.T. No.			_
		79759	466	80 R	Γ0001
Credit Card No.			Sale	spers	on
			7	236	

### **Description of Work and Parts**

STK#/FLEET#

HRS PIN/EIN

X YDG222785

WARRANTY DATE

HRS

Fold - - -

126746 COMBINE 8230 1205 NO HEADER

and dent in the auger near the end. Welded a nut to the dent and tried to pull out the dent it only helped slightly. Decided the only way was to removed the auger and auger tube from the combine. Removed the bolts on the end of the auger. The auger did not want to come apart very easily pried on it hit it with a hammer it would not move.tried to pull it out with the small forklift ended up bending the steady bearing bracket. Put open and shut on

it and let it soak overnight. Still did not want to move. Heated up around the shaft with the torch and used the porta power to push it apart and it finally separated. Pulled the auger out then removed the auger tube. Used the auger tool to straighten out the dent also heated it up and used hammers to bang out the dents. Welded the gash back together on the inside grinded the weld smooth. Cut a patch of steal from a clean grain elevator in the scrap bin. Bent the patch to match the auger tube. Grinded off the paint so the welds would stick. Welded the patch in place grinded the welds smooth. Painted the auger tube. Removed the

steady bearing back in. Put the auger tube back and put the auger back in. Timed the auger and pushed the auger onto the splines. Installed the auger boot. Tested the combine and made sure everything is working properly. Added hytran

steady bearing and heated it up and straightened it. Put

to the main hydraulic tank. . FREIGHT

SHIP-HANDLING 4 OIL1 ENVIRO OIL<30LT 73341722 HYT ULTA 1G 1 84322466 SPOUT 1 M SPRING 84380422 1

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I hereby acknowledge my indebtedness in the amount of \$ being the total amount owing or balance owing as shown hereon.	
(signature) (date)	(signature) (date)	_

I-RME Ship to: nvoice to: INTERNAL CUSTOMER #10 HWY 3 WEST & 864 SECONDAR TABER, AB TABER AB T1G 2E5

INVOICE

PO Box 4300 Hwy 3 & 864 Secondary Taber, AB T1G 2E5 (403) 223-2333

(403) 223-1515 Fax: Toll Free: 1-855-763-1427

Branch				
TABER				· · · <del>- • </del>
Date	Time			Page
08/21/18		02:03 (1	в)	03
Account No.	Phone N	0.		Reference No.
INTCUS10	4032	2232333		W34731
Ship Via		Purchase	Order	
RICHARD BACH	o	W34509		
		G.S.T. No.		
		79759	466	30 RT0001
Credit Card No.			Sale	sperson
			1	36

<b>Description of Work</b>	cand Pa	arts
----------------------------	---------	------

STK#/	FLEET#
12674	6

COMBINE

8230

HRS PIN/EIN

X YDG222785 1205 NO HEADER WARRANTY DATE

SEGMENT TOTAL ==>

HRS

Fold - - -

PARTS

378.00

LABOR

8.00 HRS

270.00 648.00

17300000

07/10/18 07/10/18

CHOPPER BLADE

SEGMENT# 3 C 03398 NA

COMPLAINT:

Chopper blades needed to be replaced.

CAUSE:

Chopper blades were worn out.

CORRECTION:

Removed the old chopper blades. Installed the new chopper

blades and torqued to 230FT-LBS.

FREIGHT

SHIP-HANDLING

1

47677377

4 CHP BLADE KIT

10

1053.69

PARTS LABOR

1080.00

SEGMENT TOTAL==>

2133.69

SEGMENT# 4 C 03398 NA FEEDER STRIPPER BARS

17300000

07/10/18 07/10/18

2.00 HRS

COMPLAINT:

Feeder stripper bars.

stripper bars were worn out from chain rubbing on them.

CORRECTION:

Loosened off the feeder chain. Used a hammer and pry bar to break the old stripper bars out. Used a pry bar to pop the new ones in place.

86638209

STRIP

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I hereby asknowledge my indebtedness in the amount of \$	being the total
(signature) (date)	(signature)	(date)

Γ	I-RME
_	
	INTERNAL CUSTOMER #10
	HWY 3 WEST & 864 SECONDAR
	TABER, AB
	TABER AB T1G 2E5
	· <del></del>
	Description of W

Branch					
TABER					
Date	Time				Page
08/21/18		02:03_(1	в)		04
Account No.	Phone N	٥.		Refe	rence No.
INTCUS10	4032232333		W34731		
Ship Via		Purchase	Order	•	
RICHARD BACH	)	W34509			
		G.S.T. No.			
		79759	466	80 R	T0001
Credit Card No.			Sale	spers	on
			l i	36	

(403) 223-2333 (403) 223-1515

Toll Free: 1-855-763-1427

and Parts

Fax:

#### STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS Fold - - -126746 COMBINE X YDG222785 8230 1205 NO HEADER PARTS 145.20 270.00 LABOR 17300000 SEGMENT TOTAL ==> 415.20 SEGMENT# 5 C 03398 NA 07/10/18 07/10/18 2.00 HRS STRIPPER PLATES COMPLAINT: Stripper plates needed to be replaced. stripper plates were worn out from the feeder chain rubbing on them. CORRECTION: Removed the cover to get at the stripper plates. Removed the old plates and installed the new ones. SHIP-HANDLING 1 FREIGHT 48001318 LH STRIPR PLATE 1 N PLATE <u>1</u> 48001329 84470464 PLATEPARTS 149.73 LABOR 270.00 17300000 SEGMENT TOTAL ==> 419.73

SEGMENT# 6 C 03398 NA

07/10/18 07/17/18

TIGHTEN ALL BELTS AND CHAINS

3.00 HRS

COMPLAINT: Belts and chains needed to be tightened.

Belts and chains were loose from normal wear and tare.

CORRECTION:

Tightened all belts and chains. Lubed all the chains. Took

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I have been a strong and a strong a strong and a strong a strong and a
(signature) (date)	(signature) (date)

Tel: (403) 223-2333 (403) 223-1515 Toll Free: 1-855-763-1427

Branch

TABER

I-RME

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

I .	T - KME		LADER					
l			Date	Tim	е	F	Page	
됩			08/21/18		20:02:03 (E	3) 0	5	
Ship to:			Account No.		ne No.		nce No.	
े रु			INTCUS10		1032232333	W347	31	
<u>-</u>			Ship Via		Purchase 0			
<b>;</b> [	INTERNAL CUSTOMER	±1∩	RICHARD E	BACHO	W34509			
40	HWY 3 WEST & 864 SI		112011212		G.S.T. No.	***************************************		
. <u>ö</u>	TABER, AB	200113111			79759	4660 RT0	0 RT0001	
Invoice	TABER AB T1G 2E5		Credit Card No.			Salespersor	i	
드	110011 110 210					E36		
<u> </u>								
		Description of W	ork and Parts					
		-						
STK#/FLE	ET#	HRS PIN/EIN	WARRANTY I	DATE	HRS		Fold -	
126746	COMBINE	X YDG222785						
	8230	1205 NO HEADER						
out a 1	ink from the unload-	er auger chain and put	in a half					
link. G	reased combine.							
B504982		60H OL LINK	1					
			PA	ARTS	405.00			
			$\mathbf{L} I$	ABOR	405.00			
	17300000		SEGMENT TOTAL	_==>	810.00			
SEGMENT#	7 C 03398 NA	07/10/18 07/10/18						
	ACON BULB	,,		1.00 H	RS			
COMPLAI								
	acon light.							
CAUSE:								
	ulb was burnt out.							
CORRECT								
		new bulb in still woul	dn't turn					
	<del>-</del>	r and found the harnes						
		cover back on. The an						

falling off put it back on with JB weld.

1

SEGMENT TOTAL ==>

BULB

17300000

SEGMENT# 8 C 03398 NA 07/10/18 07/10/18

WIPER BLADE COMPLAINT:

Wiper blade needed to be replaced.

CAUSE:

14151095

wiper blade was damaged and worn out.

CORRECTION:

CONTINUED ON PAGE 06

PARTS

LABOR

.50 HRS

9.10

135.00

144.10

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I hereby acknowledge my indebtedness in the amount of \$ amount owing or balance owing as shown hereon.	being the total
(signature) (date)	(signature)	(date)

I	N	۷	0		CE	
---	---	---	---	--	----	--

ROCKY MOUNTAIN EQUIPMENT
Rocky Mountain Equipment LP of

Г	I-RME
Ship to:	
Invoice to:	INTERNAL CUSTOMER #10 HWY 3 WEST & 864 SECONDAR TABER, AB TABER AB T1G 2E5
<b>-</b> L	

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the emount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by their or fire to machine placed with them for storage, sale, repair or white being tested. Estimates are for labour only, materials additional.

(signature)

Branch	_			
TABER				
Date	Time			Page
08/21/18		02:03	(B)	06
Account No.	Phone N	0.		Reference No.
INTCUS10	4032	223233	3	W34731
Ship Via		Purchas	e Order	
RICHARD BACH	<b></b>	W3450	9	
		G.S.T. N	ο.	
		797	59 466	60 RT0001
Credit Card No.			Sale	sperson

I hereby acknowledge my indebtedness in the amount of \$\_\_ amount owing or balance owing as shown hereon.

(date)

(signature)

# **Description of Work and Parts**

STK#/FLEET#		HRS PIN/EIN	WARRA	NTY DATE	HRS	Fold
126746	COMBINE	X YDG222785				
	8230	1205 NO HEADER				
Removed the blade.	e old wiper blade a	nd installed the new	wiper			
84309098		WIPER, WIN	1 N			
				PARTS	155.68	
				LABOR	67.50	
	17300000		SEGMENT	TOTAL==>	223.18	
SEGMENT# 9 C	C 03398 NA	07/10/18 07/10/18				
BATTERIES				1.00	HRS	
COMPLAINT:						
Replace bat	teries.					
CAUSE:						
Batteries w	were no good.					
CORRECTION:						
Removed the	e old batteries and	installed the new ba	tteries.			
CORE1.5		CORE CHARGE	2			
GX31A		GP31A BATTERY	2			
	A section of the sect		La de la companya de	PARTS	334.70	
				LABOR	135.00	
	17300000		SEGMENT	TOTAL==>	469.70	
SEGMENT#10 C	C 03398 NA	07/10/18 07/10/18				
FEEDER CHAI	IN			4.00	HRS	
COMPLAINT:						
Feeder chai	in.					
CAUSE:	to the second and the	and the second control of the second	despending commences and a second	. The second of	to the control of the	ores (suggestures )
Feeder chai	in was worn out.					
CORRECTION:	<b>:</b>					
Loosened of	- ff the chain. Rotat	ed chain until i had	the			
master link	s at the front. Re	moved the master link	s.			
			CONT	INUED ON PA	AGE 07	

(date)

I-RME

I-RME

I-RME

I - RME

800 INVOICE

PO Box 4300 Hwy 3 & 864 Secondary Taber, AB T1G 2E5 Tel: (403) 223-2333

Fax: (403) 223-1515 Toll Free: 1-855-763-1427

Branch				
TABER				
Date	Time			Page
08/21/18	20:0	02:03 (1	в)	07
Account No.	Phone No	o		Reference No.
INTCUS10	4032	2232333_		W34731
Ship Via		Purchase	Order	•
RICHARD BACHO		W34509		
<del></del>		G.S.T. No.		
		79759	466	80 RT0001
Credit Card No.			Sale	sperson
			l E	E36

HRS

## **Description of Work and Parts**

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

Fold --

126746

COMBINE 8230 X YDG222785

1205 NO HEADER

Removed the feeder face plate. Connected the new chain to the old chain with the master links. Had Zack turn the feeder sprocket while i fed in the new chain. Removed the old chain from the new one and connected with the master links. Re-tensioned the chain. Put the feeder face plate back on. Took the old chain and feeder floor and put in the scrap metal bin. Cleaned up tools.

1329837C2

CLIPS

8

84179639

CHAIN (AGR

1

PARTS 2229.95

LABOR

540.00

17300000

SEGMENT TOTAL==>

2769.95

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

	INTERNAL	CUSTOMER
PARTS	5756.75	
LABOR	3712.50	
SHOP SUPPLIES	335.72	
INTERNAL TOTAL	9804.97	

It hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate
above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms
satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount
of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine
placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.
· · · · · · · · · · · · · · · · · · ·

hereby acknowledge my indebtedness in the amount of \$\_\_ amount owing or balance owing as shown hereon.

eing the total

(date)

(signature)

(signature)