



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Typ	e:	Truck				Seating	д Сар	acity	/ :				
GVW:		16000 k	(g			Brake	Type:		Air				
Owner Name: Eastern Irrigation Distric				trict									
Address: PO Box 128													
City: Brooks			Prov	Province: AB				Posta	al Code:	T1R	1B2		
Telephone	Num	ber:	(403) 36	2-140	00								
Vehicle Ide	ntific	ation Nu	mber:		1FV6JJAB9VH696223								
Make: Freightliner				11		Мо	del: Medium	Medium Conv.					
Year: 1997							Uni	it Number:	610				
Odometer:	12	260786 KI	м	Lic	ence	Plate Nu	mber	per: 16J712 Province			Province	e:	АВ

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:			Facility Number:
Crosstown Truck & Tire (Brooks) Lt	t d.		10838
Inspection Technician Name:			Technician Number:
Michael Wetzstein			B6551
Inspection Technician Signature:		22	ATEL
Inspection Date:	2022/06/02		



The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not

uck											Gro	ss ven		eight re 16000 i	_	ed	
hicle	e Infor	mation													9		
IN	1	F	V	6	J	J	A	В	9	V	Н	6	9	6	2	2	;
	Numbe	er		Year			Ma	ıke			Mode	ı			Ode	ometer	
•	510			1997			Freigh	tliner		1	Medium	Conv.			260	786,	
					Reg	istered	Owne	r's Name							Plate	Number	r
					Eas	tern Irr	igation	District							16.	J712	
				-	ddress						ı	Postal (Code		Ph	one Num	nbe
				P	Box 1	28						T1R1	B2		(403	362-1	40
D	rum Br	akes:	A-Fı	ıll Inspect	ion with [Drum Re	emoved		Disc B	rakes:							
						<u>LEFT</u>		FR	ONT		RIGHT						
		100	psi			81.46	mm	Drums	/Rotors		381.3	g mm		100	psi		
		7	mm			15.02	mm		s/Pads		14.6				mm		
						34	mm	Push R	od Travel		34	4 mm					
	95 psi	70	psi		4	119.35	mm	Drums	/Rotors		419.4	3 mm					
	6 mm		mm			19.06	mm	Lining	s/Pads		18.6	5 mm			psi	95 ps	
						38	mm	Push Ro	od Travel		3	8 mm			mm	16 m	ım
							mm	Drums	/Rotors			mm					
	psi		psi				mm	Lining	s/Pads			mm			psi	ps	si
	mm	<u> </u>	mm				mm	Push Ro	d Travel			mm		_	mm	mr	m
	psi		psi				mm mm		/Rotors			mm			psi	psi	
	mm		mm	_			mm	_	s/Pads od Travel			mm			mm	mm	1
	psi		psi				mm	Drums/				mm				psi	
	mm		mm				mm	Linings				mm			nm		
							mm	Push Ro	d Travel			mm				mm	')
	nel	(psi				mm	Drums/	Rotors			mm			osi)
	psi mm		mm				mm	Linings				mm				psi	
	~						mm	Push Ro	d Travel			mm			nm	mm)

	Sect	lon	1 - P	ower Train			
Component	P	F	NA	Component	P	F	NA
1.1. Accelerator Pedal/Throttle Actuator	✓			1.8. Engine Start Safety Feature	1		
1.2. Exhaust System	✓	-		1.9. Gear Position Indicator	1		
1.3. Emission Control Systems and Devices			1	1.10. Engine or Accessory Drive Belt	1		
1.4. Drive Shaft	~			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			1
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	1		
1.6. Engine/Transmission Mount	~			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			1
1.7. Engine/Shut Down	✓						

NOTES:

APPENDIX "A"											
Component	P	F	NA	Component	Р	F	NA				
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			1	A.3. Liquefied Natural Gas (LNG) Fuel System			1				
A.2. Compressed Natural Gas (CNG) Fuel System			1								

NOTES:

	Sect	on	2 - S	uspension			
Component	Р	F	NA	Component	Р	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	1		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle			1
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES

Right drive air bag top mount is rust jacked and bent, both drive air bags are rubbed to cords, right drive air ride leveling valve is leaking

Replaced both drive air bags, clean and straightened rust jacked top air bag mounts, tightened loose leveling arm on air ride valve

	Section	3H	- Hy	draulic Brakes			
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			1	3H.13. Disc Brake System Components			1
3H.2. Brake Pedal/Actuator			1	3H.14. Mechanical Parking Brake			✓
3H.3. Vacuum Assist (Boost) System			1	3H.15. Spring-Applied Air-Released Parking Brake			✓
3H.4. Hydraulic Assist (Boost) System			1	3H.16. Spring-Applied Hydraulic-Released Parking Brake			✓
3H.5. Air Assist (Boost) System			1	3H.17. Anti-Lock Brake System (ABS)			✓
3H.6. Air-Over-Hydraulic Brake System			1	3H.18. Stability Control System			✓
3H.11. Brake System Indicator Lamps			1	3H.19. Brake Performance			1
3H.12. Drum Brake System Components			1				

NOTES:

	Secti	on	3A -	Air Brakes			
Component	Р	F	NA	Component	Р	F	NA
3A.1. Air Compressor	✓			3A.13. Air System Components	✓		
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓		
3A.4. Air Tank	✓			3A.15. Drum Brake System Components	✓		
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓		
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.7. Treadle Valve and Trailer Hand Valve	1			3A.18. Disc Brake System Components			✓

	1110011	` '	****	TRUCK-TRACTOR			
	Secti	lor	1 3A	- Air Brakes			e propie
Component	P	ı	FN	Component	P	F	NA
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)			1
3A.9. Proportioning, Inversion or Modulation Valve	✓			3A.21, Stability Control System			1
3A.10. Towing Vehicle (Tractor) Protection System			~	3A.23. Brake Performance	~		
3A.11. Parking Brake & Emergency Application	✓						
NOTES:							
Minima to the control of the control		,		- Steering	0	F	NA
Component	P	١	FN		Р	г	147
4.1. Steering Control and Linkage	✓			4.4. Kingpin	4		1
4.2. Power Steering System (Hydraulic and Electric)	✓			4.5. Self-Steer and Controlled-Steer Axle			•
4.3. Steering Operation (Active Steer Axle)	✓						
NOTES:			12	and Auxilian Equipment			
Section				and Auxiliary Equipment Component	Р	F	NA
Component	Р	-	FN	5.8. Heater & Windshield Defroster			
5.1. Fire Extinguisher	✓						1
5.2. Hazard Warning Kit	✓			5.9. Fuel-Burning Auxiliary Heater 5.10. Chain/"Headache" Rack			1
5.3. Hom	✓			5.10. Chain/ Headache Rack 5.11. Auxiliary Controls and Devices			1
	✓			5 11 Auvillary Controls and Devices			/
5.5. Speedometer							~
5.6. Odometer	1			5.12. Auxiliary Drive Controls			•
5.5. Speedometer 5.6. Odometer 5.7. Windshield Wiper/Washer NOTES:	✓ ✓						•
5.6. Odometer 5.7. Windshield Wiper/Washer	✓		ion				
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES:	✓			5.12. Auxiliary Drive Controls 6 - Lamps	P	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component	Se P	ect		5.12. Auxiliary Drive Controls 6 - Lamps	P	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps	Se	ect		5.12. Auxiliary Drive Controls 6 - Lamps Component	P	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector	Se P	ect		5.12. Auxiliary Drive Controls 6. Lamps Component 6.4. Instrument Panel Lamps	P	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps	Se P	ect		5.12. Auxiliary Drive Controls 6. Lamps Component 6.4. Instrument Panel Lamps	P ✓	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking	Se P	F	FN	5.12. Auxiliary Drive Controls 6.4. Instrument Panel Lamps 6.5. Headlamp Aim	P ✓	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES:	Se P /	F 7	- Eld	5.12. Auxiliary Drive Controls 6 Lamps Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim	P		NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component	Se P	F	- Eld	5.12. Auxiliary Drive Controls 6.12. Auxiliary Drive Controls 6.13. Component 6.14. Instrument Panel Lamps 6.15. Headlamp Aim 6.15. Headlamp Aim 6.16. Component	1		
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring	Se P /	F 7	- Eld	5.12. Auxiliary Drive Controls 6 Lamps Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim	1		
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component	Se P /	F 7	- Eld	5.12. Auxiliary Drive Controls 6.12. Auxiliary Drive Controls 6.13. Component 6.14. Instrument Panel Lamps 6.15. Headlamp Aim 6.15. Headlamp Aim 6.16. Component	1		
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery	Se P /	F 7	- Eld	5.12. Auxiliary Drive Controls 6.12. Auxiliary Drive Controls 6.13. Component 6.14. Instrument Panel Lamps 6.15. Headlamp Aim 6.15. Headlamp Aim 6.16. Component	1		
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery	Se P /	F 7	- Eld	5.12. Auxiliary Drive Controls 6.12. Auxiliary Drive Controls 6.13. Component 6.14. Instrument Panel Lamps 6.15. Headlamp Aim 6.15. Headlamp Aim 6.16. Component	1		
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring	Se P /	F 7	- Eld	5.12. Auxiliary Drive Controls 6.12. Auxiliary Drive Controls 6.13. Component 6.14. Instrument Panel Lamps 6.15. Headlamp Aim 6.15. Headlamp Aim 6.16. Component	1		
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery	Section P	F 7	- Eld	5.12. Auxiliary Drive Controls 6.12. Auxiliary Drive Controls 6.13. Component 6.14. Instrument Panel Lamps 6.15. Headlamp Aim 6.15. Headlamp Aim 6.16. Component	1	F	NA
Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES:	Section P	F 7	- Eld	5.12. Auxiliary Drive Controls 6. Lamps 6. Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim 6. Component 7.3. Trailer Cord (output to towed vehicle)	1		NA
Component Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES:	Section P	F F	- Eld	5.12. Auxiliary Drive Controls 6. Lamps 6. Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim 6. Component 7.3. Trailer Cord (output to towed vehicle)	P	F	NA
Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES: Component 8.1. Hood or Engine Enclosure	Section P	F F	- Eld	5.12. Auxiliary Drive Controls 6. Lamps 6. Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim 6.5. Headlamp Aim 7.3. Trailer Cord (output to towed vehicle) 8 - Body Component Component	P	F	NA
Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES: Component 8.1. Hood or Engine Enclosure 8.2. Tilt Cab	Section P	F F	- Eld	5.12. Auxiliary Drive Controls 6. Lamps 6. A. Component 6. 4. Instrument Panel Lamps 6. 5. Headlamp Aim Component 7. 3. Trailer Cord (output to towed vehicle) 8 - Body A. Component 8.12. Bumper	P	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES: Component 8.1. Hood or Engine Enclosure 8.2. Tilt Cab 8.3. Air-Suspended Cab	Section P	F F	- Eld	5.12. Auxiliary Drive Controls 5. Lamps 6. A. Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim Component 7.3. Trailer Cord (output to towed vehicle) 8. Body A. Component 8.12. Bumper 8.13. Windshield 8.14. Side Windows	P	F	
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES: Component 8.1. Hood or Engine Enclosure 8.2. Tilt Cab 8.3. Air-Suspended Cab 8.4. Cab and Passenger-Vehicle Body	Section P	F F	- Eld	5.12. Auxiliary Drive Controls 5. Lamps 6. A. Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim Component 7.3. Trailer Cord (output to towed vehicle) 8. Body Component 8.12. Bumper 8.13. Windshield 8.14. Side Windows 8.15. Rear Window	P	F	NA
5.6. Odometer 5.7. Windshield Wiper/Washer NOTES: Component 6.1. Required Lamps 6.2. Reflex Reflector 6.3. Retro-Reflective Marking NOTES: Component 7.1. Wiring 7.2. Battery NOTES:	Section P	F F	- Eld	5.12. Auxiliary Drive Controls 5. Lamps 6. A. Component 6.4. Instrument Panel Lamps 6.5. Headlamp Aim Component 7.3. Trailer Cord (output to towed vehicle) 8. Body A. Component 8.12. Bumper 8.13. Windshield 8.14. Side Windows	P	F	NA

	S	ect	on 8	- Body			
Component	P	F	NA	Component	P	F	NA
8.8. Cab or Cargo Door	1			8.19. Seat 8.20. Seat Belt/Occupant Restraint			
8.9. Cargo Tank or Vessel 8.10. Body, Device or Equipment Attached or Mounted to the	1		•	8.21. Fender/Mud Flap	1		
Vehicle 8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment			1

NOTES:

Windshield is cracked

Windshield replaced

	Section	Section 9 - Tires and Wheels											
Component	P	F	NA	Component	P	F	NA						
9.1. Tire Tread Depth	1			9.7. Wheel/Rim (Applies to all wheel types)	✓								
9.2. Tire Tread Condition	1			9.8. Multi-Piece Wheel/Rim			1						
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			1						
9.4. Tire Inflation Pressure	1			9.10. Disc Wheel System	✓								
9.5. Wheel Hub	1			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓								
9.6. Wheel Bearing	1												

NOTES:

Left inside drive tire pressure is low

Tire set and rechecked at 95 psi

Se	ction 10	- C	oup	ers and Hitches			
Component	Р	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	1			10.5. Roll-Coupling Hitch			✓
10.2. Secondary Attachment (Safety Chain or Cable)			1	10.6. Automated Coupling Device			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			1	10.7. Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			1	10.8. Oscillating Fifth Wheel Coupler			✓

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #7528033) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2022/06/02	B6551	10838	Ill CASO
Customer Acknowledgment			
and this Record of Inspection (RO	n identifies defects and repairs are r I) may be presented to any Vehicle I failed items noted on this ROI are re	nspection Facility within 10 days of	Date (Year/Month/Day) 2022/06/02
vehicle is not returned for re-inspermust be conducted.	ection within 10 days of the initial da	te of inspection, a new inspection	Customer Signature



EID Service Los

Machine:	Freightline	er FL80
Serial:	1FV6JJAB9	DVH696223
Unit: Date:	Hours:	Repair:
		Istalled new water pump belt. Installed new fan alt belt. Chged out music radio with 1 repaired at Can-tek. Repair broken grease
		zerks on rear ujoint on driveline. Grease unit. Install new piece of flex pipe & band clamps on exhaust just before muffler. Install
		new circuit breakers & relays for tool box & work lights. Remove old cell phone & wiring from unit, remounted 2-way radio so it
Dec/11/12 Mar/08/13	6707	is easier to get at from operators seat. Replace fuse holder for ECM power. Have Newcom weld build a mount for vice. Pick up new vise from Acklands & installed.
IVIAI / 00/ 13		Removed batteries & charged. Cleaned battery box & reinstalled batteries. Clean posts & cables. Build time down strap &
		installed on batteries. Removed alternator & take to Sterns to get tested & it failed purchased new one Inv#. Installed on unit.
Apr/05/13	6863	retry & now it is charging. 165787kms.
July/19/13	6984	Ken installed new starter purchased from Allied dist for \$340.38 inv# 000-171478. At 168542kms. Greased unit. Topped up tire pressures R 105 & F 100. Found eng oil leak at filter housing. Tightened bolts on housing & chged o-
Aug/20/13	7025	rings on fittlings on housing.
		Take unit to General Body & Equip in Calgary & get boss infinity tool air compressor repaired for not going into bypass mode Inv
Sept/30/13	7076	CA07383 for \$1437.50 .
Nov/12/13 Dec/12/13	7120	Installed new thermostat part # 1193075 & gasket. Refill rad with new coolant. Chged RH head light & chk rest of lights.
Feb/28/14		174446kms. Had Crosstown perform c-vip & preform necessary repairs for \$415.50 inv# 33148.
Feb/25/14	7331	Greased unit.
		180369kms. Remove oil pump for used oil recovery. Disassemble suction & outlet manifolds & clean chk balls & seats.
July/31/14 Jan/22/15	7563 7870	Reassemble & reinstall. Build a screen & install in suction line so chk valves do not get jammed with large pieces of debris. 185920kms. Lube door hinges on deck & get tail gate hinges to take grease. Lube truck door hinges.
Feb/04/15	7910	Change rear engine mounts, grease. Repair diff lock switch mount plate.
Jun/10/15	8162	new U- Bolts on rear right. Moved air ride 1.5" to the right
Jun/10/15		Chged Eng oil & filter, air filter, & fuel filter on Welder at 90 hrs.
Sept/01/15	8295	Replaced RH air ride leveling valve & air bag. Installed new height adjusting valve for seat. Have new steering tires installed at Kirks Tire at 194356Kms.
Sept/03/15 Nov/30/15	8456	Installed new headlight on LH side. 196869Kms
Dec/08/15	8489	Installed new weather stripping on both cab doors purchased from New West Trucks. 197322 Kms.
		Installed new drivers side seat purchased from New West Trucks 197739kms. Remove a day later & send back because it was
Dec/15/15	8513	wrong one & reordered again.
Jan/12/16	8536	Lost tail lights. Test circuit until found license plate light wiring shorted to ground. Replace light. Repainted rusted spots arround tail lights.
Jan/12/16 Jan/12/16	8542	Installed new drivers side seat belt assembly. 198221kms
		Built jig to remove welder & pull welder from compartment. Remove battery from welder & recharge & test & tests ok. Reinstall
		battery & reinstall welder in unit. Remove parts pin mount from LH rear compartment. Repair bin mount & reinstall. Aded 2
Jan/18/16 Apr/04/16		mount bolts to top of bin mount to help support it better so it doesn't shake apart again. Had Del equip install the V-Mac Raptair Multifunction diesel drive compressor.
Apr/04/16		Have Newcom Weld build a new mount system for welding cable reels. Installed new system so the reels can be used properly.
Apr/26/16	8784	Pick up new 2/0 cable from BIM & install on reels. Made up a set of booster cable ends for welding cables to work with new V-
		Removed old air compressor from rear of deck. Plugged holes in deck floor & then picked up rubber mat, cut to fit & install. Hans
. (20/45	0704	installed new signal light switch & cover. Installed new switch for high idle & cruise control. Installed new hook for sunvisor
Apr/28/16 May/05/16		above drivers door. Have Newcom Weld build extentions for tool box remote lock bars & install to make closing & opening lock bars.
July/11/16		replace LH air ride valve
Sept/14/16		Have Crack Masters install new windshield.
Nov/30/16		Have Crack Masters repair rock chip in windshield. Greased unit.
Dec/13/16	9017	Installed new batteries purchased from Napa, Cleaned cables & posts.
- 1		Have Newcom Weld build better support brackets for oil dispensing pumps & I installed them. Took the swivel off of the hydraulic hose reel & change O-rings & reinstall. Remove air pressure regulator for oil dispensing pumps. Take apart & clean &
Feb/03/17	- 1	reinstall
Feb/28/17	9155	Remove switch on clutch pedal for cruise & test appears ok. Reinstall. It was loose on pedal.
Mar/24/17	9202	Install new pressure switch for cruise control cut out on brake system. 214940kms
Apr/11/17		install new oil depenser gun on eng oil system for doing services. Take unit to General Body & Equip in Calgary & get boss infinity tool air compressor repaired for not going into bypass mode Inv
May/18/17	9252	CA07383 for \$1437 50
July/18/17	9287	Inatalled new turbo pressure lines from after cooler to intake purchased from North West Trucks.
Sept/22/17		Install new mud flaps on rear of unit
Jan/05/18	0730	new tires on drive 222237 Km
Aug/10/18 Sept/14/18	9730 9750	New waterpump, termostat, rad cap, new coolant New safety valvecut out on air tank to air bags to protect from total air loss in event of air bag failure. 231520km
Dec/14/18	9823	Greased unit. Checked levels all ok.
Mar/23/19	9964	CVIP. Remove steering wheel and turn so is straight when truck goes straight
May/06/19		Have Capital Glass install windshields.
Dec/06/19 Jan/29/20	10158	Repair wiring to compartment lights in service deck as necessary. Replaced 2 rear deck flood lights with LED flood lamps.
Jan/31/20		Have Kal Tire remove balancing beads from steering tires & balance them. Meet a semi on hi-way 36 & drivers door window exploded. Ordered new 1 from Freight liner & had Capital Glass install.
Feb/01/20		Tightened up front fenders & make up rubber washers to install on mount bolt that was pulley through fiber glass fender.
		Meet another oil tanker on hi-way & smashed windsield again. Vacumm glass out of cab & then take to capital glass & have
Apr/02/20		another new windshield installed.

Feb/18/21	May/29/20	Oct/10/19	Dec/14/18	Feb/14/18	May/18/17	Nov/30/16	Feb/19/16	Nov/12/15	Jun/08/15	Feb/04/15	Sep/17/14	Feb/25/14	Aug/20/13	Dec/11/12		Dec 6/10	May 14/10	Nov 23/09	Aug 12/09	Oct 24/08	Date:	Unit:	Machine:	EID Service Log		n	
10606	10360		9823	9530	9252	8985	8627	8414	8162	7910	7608	7331	7025	6707		5800	5500	5222	5018	4812	Hours:	610	Freightliner FL80	98			
	×		×	×		×			×		×	×		×		×				×	Primary Air	FILTERS	FL80				
×	×	×	×	×	×	×	×	×	×	×	×	×	×	×		×	×	×	×	×	Engine Oil		Serial #: 1FV6JJAB9VH696223				
		×	×		×	×					×	×		×		×			×		Inline F Fuel		1FV6JJA				
×		×	×		×	×					×	×		×		×			×		Final Fuel H		B9VH696				
																					Hydraulic S		223				
											×										Power Air Steering Dry						
×														×							Air Cab Dryer Filters						
																×	×	×	×	×	b Engine		Coop	6	4	\$	0
×	×	×	×	×	×	×	×	×	×	×	×		×	 ×		×					e Trans						
											×					×					Diff Hydraulic						
											 ×					×					Steering						
																					Valve Lash		ENGINE				
2	2,		23	22	216	209	200	196	191						_												
255348Km	248686Km		233751km	224407Km	216773km	209117KM	200280km	196218km	191377km																		



Copyright 2014 CDK Global, LLC

New West Freightliner Inc. 5925 79th Ave.S.E. Calgary, Alberta T2C 5K3 Phone: 403-569-4800 Fax: 248-1894 Toll Free: 1-800-925-1631 www.newwesttruck.com

BUSINESS# 100731173

NEW WEST TRUCK CENTRES			
ALL AUTHORIZED RETURNS MUST HAVE INVOICE N	NUMBER AND MAY BE SUBJECT	TO A HANDLING C	HARGE.
DATE ENTERED YOUR ORDER NO. DATE SHIPPED INVOICE 3.0 JAN 2.0 7660.8 3.0 JAN 2.0 3.0	DE DATE JAN 20	1295272C	
S ACCOUNT NO. 26560 L *EASTERN IRRIGATION DISTRICT PO BOX 128 T BROOKS, AB T1R 1B2	16:15	PAGE 1 OF 1	
SHIP VIA SLSM. B/L NO. TERICON	MS AND NET 30 DAYS. 2% PER MONTH OVERDUE ACCOUNTS.	(24% PER ANNUM) CHARG ALGARY , AB	ED ON ALL
ORD SHIP B.O. PART NUMBER DESCR	RIPTION LIST NET	AMOUNT	_
1 1 0 DNC/6807250110 GLASS UNIT#610 DRIVERS SIDE DOT SHOW Row PASSON	MZ27A2 42.69	42.69	ND ACCESSORIES LISTED HEREON INTERTION ON THE UNDERNOTED I HEREBY ACKNOWLEDGE AN I THEREON TO SECURE THE FULL THE INDEBTDNESS. MODEL MODEL SIGNED
ALL PARTS ARE SUBJECT TO A MINIMUM 20% RESTOCKING CHARGE NO RETURNS ON SPECIAL ORDERED PARTS ALL ELECTRICAL NON RETURNABLE INSTALLED PARTS - NO RETURNS	PARTS FREIGHT TAXES	42.69	THE FORTS AND ACCESS ARE FOR INSTALLATION C WEHICLE AND I HEREBY A EXPRESS LIEN THEREON AMOUNT OF THE INDEBTI RECEIVED BY MAKE
	TOTAL	\$42.69	E4204 & 2 2 9

CUSTOMER COPY



KIRK'S TIRE BROOKS LTD. 620 AQUADUCT DRIVE BOX 1769 BROOKS AB T1R 1C5

Phone: (403)362-6647 Fax: (403)362-6680

EASTIR EASTERN IRRIGATION DISTRICT P.O. BOX 128

INVOICE B133475 (Copy)

CONTACT: SHOP --- 3621446--CH**563 26**3-18 Jan 05

BROOKS T1R 1B2

AB

INVOICE TO:

TEL: 403 362-1400

FAX: 403 3626206

YEAR	MAKE		Money				PAG	E : 1
I ATE ME	F/LINER		MODEL				ENGIN	
LATE NO	VIN		0000				LINGIN	
6J712AE	3		ODOMETER		UN	IT NO.	MDITT	-N DV
IME IN	PROMISED	TERMS	222237		610		WRITT	ENBY
:46 AM			GST#		P.C		JB	
	ITEM/DESCRIPTION	NET 30	R866171515				TAG	
4	549100		SIZE	TAX	RETAIL	0/		
4	TOYO M503z Drive On	/Off Road 1	11R22.5 6-H 146/143K	17.00	550.00		NET 550.00	2200.00
4	TIRE RECYCLING FEE H CMT CHANGEOVER MED T	mp.u.c			9.00	0	9.00	36.00
	Payment Method: OnAc				30.00		30.00	120.00
	PLEASE REMEMBER TO AT 100KM'S - IT'S	HAVE YOUR TI YOUR RESPONS	RES RE-TORQUED IBILITY					
						x:		
	200.							
	COPY							
Constitution of the last	WARRING FACE FLOOR	IC MINT APP WATER					DADMO	2000 00
YA.	WARNING LEASE ENSURE LL	STRIBISTED TO	PURLY WITHIN THE FIRST TO	KMS	The state of the state of		PARTS:	2200.00

第二人员	WARRINGL	LEASE ENSUR	E LUG NUTS ARE	RETORIGUED W	ATHUR THE FIRE	FT 100 KM/S	
MICHEL	₩ BFG	odrich	UNIROYAL 		TIRES	Mational	(Tolk)
LETHBRIDGE 403-327-5985	CARDSTON 403-653-4914	TABER 403-223-3441	BROOKS 403-362-6647	REDCLIFF 403-548-3941	CALGARY 403-243-8811	RED DEER 403-347-1004	EDMONTON 780-488-9911
Name:			Signature	:			

shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26 86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS

PARTS:	2200.00	
LABOUR:	120.00	
OTHER:	36.00	
SUB-TOTAL:	2356.00	
GST:	N/C	
PST:	N/C	
TOTAL:	2356.00	



Summit Motors Ltd.



Since '63

Box 1630, 140 15th Ave E. Brooks, AB T1R 1C4 Phone: (403) 501-5687 Fax: (403) 501-5684

Med Hat

DATE: 05-15-18

Taber **⋈** Brooks Ship To:

Branches:

Sold To:

Box 128 EASTERN IRRIG DIST

> PARTS INVOICE# B150528

BROOKS, AB T1R 1B2 Box 128 EASTERN IRRIG DIST Page 1 of 1 Auth:

			Loc	SP	SP	SP	SP	SP
BROOKS, AB T1R 1B2	Customer Acct Number	25014	Part #	20R0586	20R0586#	1193075	4P2684	2W7212
82	ber			WATER	CORE	REGUL	GASKET	GASKE
	Phone Number	362-1400	Description	PUMP		ATOR	7	7
BROOKS, AB T1R 1B2	Salesman	DB	Ord	1				
B T1R 1	390		Ship	1	<u> </u>	·		
32	Ship Via	WILL CALL	B/0 List	582.9		42.2	4.0	30.00
	Customer Purchase Orde	UNIT 610	Unit Price					11 2./4 00 25.00
	chase Order	610	Extension					0 25.00

10-401-56350 MAY 28

ALL OVERDUE ACCOUNTS , TO A LATE CHARGE OF 28 (26.82% PER ANNUM). (26.81% 11:10AM X ARE SUBJECT 2% PER MONTH

X DB 27A1 PARTS NTX

		CUSTOMER	Exaplas	
			DATE:	
136235181				
Please Pay	GST	Sales Tax	Freight	Sub Total
751.47		0.00	25.00	/26.4/

CUSTOMER SIGNATURE:

PRIMACE MODIFY

The personal information received from individuals relating to this termation is collected in accordance with Dealer pulsopic, the collection, use and disclosure is necessary for the purpose of repair, tening, service or other dealing with the Counterer privacy, for the use of any leasure relating, and for providing information about other current and huse products and acresives of the dealer, the manufacturer of new vehicles for which the dealer is franchised, and any privacy for the individual specification and acres of the individual does not to content or wither to withdraw such content, or if the individual wants a copy of the Dealers privacy privacy officer.

BEARING SPECIALISTS AND A WHOLE LOT MORE

BOX 970, 1160 - 2ND ST WEST BROOKS, ALBERTA TIR 0V5



Phone: 403 362-6208 Fax: 403.362.6270

1NVOICE 459669

27-Apr-2017 Page 1 of 1

P.O. # EARL / UNIT 610

Buyer:

Ship Via:

Salesman: Harley

BUMPER TO BUMPERAuto Parts Professionals

Sold to: EASTIRRI EASTERN IRRIGATION DISTRICT

BOX 128

BROOKSALBERTA T1R 1B2

Shipping paid by:

Ship to: SAME

Item	Description	Ordered Sh	nipped	List \$	Unit \$	Extended \$
LIN- 905	METER ELECTRIC LTR	2.00	2.00	1,074.28	690.00	1,380.00
	goods and services tax	1.00	1.00			

10-401-56 330 G MAY 04

Stocked Items	Non- Stocked	Cores	Enviro Charges	Misc Charges	Other Charges	GST	PST	Payments	Document Total	
1,380.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	1,380.00	

REMITTANCE TO LOGAN INDUSTRIES MONDAY - FRIDAY 6:00-5:30PM SATURDAY: 7:00AM-1:00PM AFTER HOURS CALL 403-362-6208

AUTHORIZED SIGNAFUR

SUPPLIES
AUTO
AGRICULTURAL
INDUSTRIAL

GST # 802765297 RT



EASTERN IRRIGATION DISTRICT

KIRK'S TIRE BROOKS LTD. 620 AQUADUCT DRIVE BOX 1769 BROOKS AB T1R 1C5

Phone: (403)362-6647 Fax: (403)362-6680

EASTIR

SEP - 3 2015

INVOICE B115215 (Copy)

CONTACT: SHOP --- 3621446--CH565253-Sep 03 15

P.O. BOX 128

BROOKS

AB

INVOICE TO:

T1R 1B2

TEL: 403 362-1400

FAX: 403 3626206

PAGE: 1

AR	MAKE		MODEL				ENGINE	
	F/LINER							
ATE NO	VIN		ODOMETER			T NO.	WRITTEN	IBY
J712AB			194356		610		ЈВ	
AE IN	PROMISED	TERMS	GST#		P.O		TAG	
01 PM		NET 30	R866171515	5				
	M/DESCRIPTION		SIZE	TAX	RETAIL	%	NET	EXT.PRIC
	3045 FGOODRICH ST230	LRH	11R22.5		483.00		483.00	966.0
TI	TH NVIR. LEVY H. TRUC	CK			9.00	0	9.00	18.0
CM	T CHANGEOVER MED	TRUCK Sep 03	15		30.00		30.00	60.00
Pa	ayment Method: OnA	Account=1044.0	0					
	COPY							
					10-4	01-562	35 PARTS:	
	WASHING PLEASE CHILDRE	LUG HUTS ARE RETOR	este avarias riperzosa	100 KH 8	16			966.0
MICHELIN	BFGoodrich	UNIROYAL E	OYOTIRES	M ational	(COLO	, ,	LABOUR:	60.0
	ARDSTON TABER 3-653-4914 403-223-3441	BROOKS REDO 403-362-6647 403-54	CLIFF CALGARY 8-3941 403-243-8811 4	RED DEER 03-347-1004	EDMONTON 780-488-9911	- 1	\$35 OTHER: SUB-TOTAL:	18.0
al an						9	GST:	N/
hature: With the	above signature I agree to the hereon, or in the amount of an	ne terms below and ack	nowledge indebtedness	for the total a	mount owing a	\$ 5cm	8 PST:	N/

ESTIMATE

BASSANO AUTO BODY (1977) LTD

BOX 420 BASSANO AB TOJ-080

You Bendem We Mendem

PHONE 641-3773 FAX 641-4876

NAME EID (PETE)

ADDRESS CITY BROOKS PROVINCE ALBERTA FILEA PHONE H

PAX# 362 8776 DESCRIPTION

LEFT FRONT FENDER

COMPANY APPRAISER

CLAIM# DATE OF LOSS

SPOT PAINT

8008 SS MAL DATE

email baba@figment.ca VEHICLE INFORMATION

MAKE FREIGHTLINER MODEL BUSINESS CLASS

YEAR 1997 SERIAL# UNIT #610

PAINT CODE ENGINE LICENCE

PAINT SUBLET PARTS LABOUR RAR 2.0 4.0

Add for Clearcoat				0.8
THIS IS AN ESTIMATE		PART9		
	\$15.00	REPAIR MAT	ERIALS	\$60.00
PARTS PRICES ARE SUBJECT TO CHANGE	\$30.00	PAINT MATE	RIALS	\$84.00
* IT DOES NOT COVER ANY UNSEEN DAMAGE	\$62.00	LABOUR	4.0 HOURS	\$248.00
EEEE220241244011111111111111111111111111	\$62.00	PAINT	2.8 HOURS	\$173.60
	\$70.00	FRAME	HOURS	
		SUBLET		
*\$ 1000 OF DAMAGE REQUIRES A POLICE STICKER		HAZARDOUS	WASTE DISPOSAL	\$1.40
* CONTACT YOUR INSURANCE COMPANY		FREIGHT		
* CHOOSE THE REPAIR SHOP OF YOUR CHOICE		WHEEL ALIG	NMENT	
		TOWING AND	STORAGE '	
		SUBTOTAL		\$567 .00
THIS ESTIMATE IS VALID FOR 90 DAYS		GST	5.00%	\$28.35
THIS ESTIMATE IS THE STORES OF STATE		TOTAL		\$595.35
		DEDUCTIBLE	·	
		GRAND TOTA	AL	\$ 5 9 5.35

194-22-2008 13:04 From: 9778535204:07 1/1.9





DAILY FIELD SERVICE REPORT

DATE 1/13/2003

THE CUSTOMES AUTHORICES FINNING INTERNATIONAL INCLUSIONING TO PROTORM THE WORK DESCRIBED ON EACH PAGE OF THIS DAILY FIELD SEXVICE. ACTIVITY REPORT THE WORK IN AN ARCESS TO PAY INTONING ITS CHARGES IN RESPIRATOR THE WORK ON THE THIS MAN AND CONDITIONS ON THE FACE AND ON THE EXPERSE RESIDES. THE CUSTOMER ACCOUNTEDING THE THORNO HEAD ACTIVITY RESPECTABLE OF THE PAGE	AMOUNT OF S REEN LIFT BLANK, THE	IF THE FOREGOING DOLLAR AMOUNT HAS CUSTOMER ACKNOWLENDED THAT ITS INDESTEDNESS	THE GENERAL C	LITY UNDER THE ACREEMENT IS LIMITED. PLEASE READ AND UNDESTAND NORTHONS APPEARING HEREIN AND IN PARTICULAR CLAUSE SOFT HE TEXNI- MA AND CLAUSES OF THE SERVICE WARRANTY POLICY. ON THE REVERSE O SIGNING THIS AGREEMENT.
ACKNOWLEDNEMENT OF INDESTERNESS. FINAL CHARGES FOR THE WORK MAY BE GREATER OF LESSER THAN ESTIMATED AND FINNING DOES. NOT REPRESENT OR GUARANTEE THAT THE ISTIMATED CHARGES WILL BE THE FINAL CHARGES IN RESPECT OF THE WORK.	DATED	CUSTOMER BIONATURE	DATED	CUSTOMER SIGNATURE

	EMPLOYEE NAME	WORK	SEG	CHG CODE	DOC DATE	TIME	1	2	от	VEH	KMS
		ORDER									
~	Tony Clizbe	7704239	11	MEF	1/13	3.5				4303	
5	EMPLOYEE #										
=	2395										
- 3	COST CENTER										
	HZ										

CUSTOMER	
EASTERN IRRIGATION DI	STRICT
ADDRESS	
MODEL.	SERIAL NUMBER
3126	1WM05290
UNIT #	SERVICE METER
	21718
MACHINE LOCATION	PO#
customer shop	

\$0.00 \$0.00
\$0.00
\$ 0.00 \$ 0.00 0
TOTAL EXPENSES \$0.00
RABLE DESCRIPTIVE COMMENTS

DID YOU	YES	NO	TIME	COMMENTS DISTANCE KM5 / NUMBER OF TRIPS
TRAVEL TO JOBS!TE				
035 TROUBLESHOOT				Check oil leak at rear of cylinder head. Engine will need to be washed and ran to locate oil leak. Install wire to ECM to control high idle when air compressor is loaded.
038 DIAGNOSTIC TESTS				Could not get compressor to load without jumping power at relay.
010 R&1 GUARDING				Customer will need to get compressor operating in order to install high idle function. Complete paper work.
010 R&I COMPONENT				Complete paper work.
001 REPAIR COMPONENT				
063 MACHINING / WELDING				
030 TEST AFTER REPAIR				
FAILURE ANALYSIS				
SERVICE REPORT				
OTHER OPERATIONS				



CROSSTOWN TRUCK & TIRE LTD.

639 SUTHERLAND - P. O. BOX 1995 BROOKS, ALBERTA T1R 1C7 PH: (403) 362-6683 - FAX: (403) 362-4545 GST # 10121-2074RT



SERVICE INVOICE

FEB 0 5 2014

EASTERN IRRIGATION DISTRICT PO BOX 128

BROOKS, ALBERTA T1R 1B2

Page
1
Payment Type
CHARGE
Customer Account #

Serial No. 1FV6JJAB9VH696223 Description 1997 FR FL80

Stock No. 610 Fleet No. 610 License 16J712

Job No.	Miles/Hours In	Purchase Order No.	Labor Rates	Invoice Date	R.O. Number
3496	174446			01/28/2014	33148

88

Line Type	e Mech	Repair Description w/ Parts And Labor	Quantity	Unit	Extension
1 C	MW	C COMMERCIAL VEHICLE INSPECTION C CV5120146 F GO THROUGH UNIT & MAKE REPAIR LIST. BRAKE CAM ROTATIONS ON ALL WHEELS. TIGHTEN LOOSE MIRROR BRACKET ON RIGHT SIDE. INSTALL MISSING BOLT ON TOP LEFT OF BUMPER.REPLACE LEFT REAR SUPPLY LINE TO BRAKE POT. TIE UP AND PROTECT FROM RUBBING.ADJUST LEVELING VALVES TO MAKE TRUCK SIT LEVEL. FILL OUT MEASUREMENT SHEET. DO PAPER WORK			
		& STICKER.			
		L LICENSE FEES	0.0		27.00
	L10	L CVIP 33148	3.0		329.67
		P AB RE COUPLER; 1/2 HIDX3/8	2.00	7.79	15.58
		4485-14928C @ 7.79	2 22		
		P AB RE COUPLER; 1/2 HIDX3/8	2.00	7.79	15.58
		4485-14928C @ 7.79			
		P AIR BRAKE HOSE; 3/8 ID	2.00	1.71	3.42
		4485-HAB6CUT @ 1.71	2 22	1 00	
		P AIR BRAKE HOSE; 1/2 ID	2.00	1.92	3.84
		4485-HAB8CUT @ 1.92	1 00	2 52	
		P CLEAR COVER FOR CVIP DECAL 3X4STICKER @ 2.58	1.00	2.58	2.58
		3X4STICKER @ 2.58 Subtotal this section			207 67
		Subtotal this section			397.67
		PLEASE REMEMBER IF YOUR WHEELS WERE OFF FOR ANY REPAIR, GET THE WHEELS RETORQUE AFTER 100 TO 150 KMS.			

Disclaimer of Warranties

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. Any express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You are not responsible for loss or damage to the motor vehicle or its contents due to collision not due to your negligence; or due to fire, theft or other casualty regardless of whether or not such fire, theft or other casualty is due to your negligene; and you and your agents are hereby released from any and all claims for such loss and damage.

UPON BREACH OF FAILURE TO PAY THIS ACCOUNT WHEN DUE THE SELLER MAY DECLARE THIS ACCOUNT TO BE DELIQUENT AND PURCHASER SHALL BE LIABLE FOR ALL COSTS OF COLLECTION INCLUDING A REASONABLE ATTORNEY'S FEE.

RECEIVED BY DATE



CROSSTOWN TRUCK & TIRE LTD.

639 SUTHERLAND - P. O. BOX 1995 BROOKS, ALBERTA T1R 1C7 PH: (403) 362-6683 - FAX: (403) 362-4545 GST # 10121-2074RT



415.50

SERVICE INVOICE

EASTERN IRRIGATION DISTRICT **PO BOX 128**

Purchase Order No.

BROOKS, ALBERTA T1R 1B2

Miles/Hours In

Job No.

Payment Type **CHARGE**

Customer Account # 88

Labor Rates

Serial No.

1FV6JJAB9VH696223 1997 FR FL80

Description 610 Stock No.

610 Fleet No. 16J712 License

> R.O. Number Invoice Date 33148 01/28/2014

3496		4446	Fulchase Order No.	Labor Rates	01/28/2	014	33148	
Line	Туре	Mech	Repair Descri	iption w/ Parts And Labor	Quantity	Uni	t Exte	ension
v tilvys kanadiigidija s vi ske kn na								
en como de mandamenta de m								
				ales tax	0-401-56 0-401-56 10-401-56	330 305 G	, F3 10	41.00 356.67 17.83 415.50 0.00

Disclaimer of Warranties

PLEASE PAY THIS AMOUNT

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. Any express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You are not responsible for loss or damage to the motor vehicle or its contents due to collision not due to your negligence; or due to fire, theft or other casualty regardless of whether or not such fire, theft or other casualty is due to your negligene; and you and your agents are hereby released from any and all claims for such loss and damage.

UPON BREACH OF FAILURE TO PAY THIS ACCOUNT WHEN DUE THE SELLER MAY DECLARE THIS ACCOUNT TO BE DELIQUENT AND PURCHASER SHALL BE LIABLE FOR ALL COSTS OF COLLECTION INCLUDING A REASONABLE ATTORNEY'S FEE

RECEIVED BY DATE CEAS06 EASTERN IRRIGATION DISTRICT P.O. BAG 9 BROOKS, AB TOR 1B2

Sold By: BLN PO #: 42444 Ship By: BRIAN Tax #: 865848	Date 3790	4/21/04	INVOICE		LE 006 92 Open
Tax D Qty Description			*	Price	Amount
COMMENTS NOTE: SUPPLY PARTS AS REQUESTE	ED APRIL 21,	2004			
MISC SALE T FREIGHT CHARGE FROM E	3000				
MISC. PART SALE	3055				29.65
T 1 302601 DIL FILTER T 1 302601 AIR FILTER T 1 302600 COALESCER SPIN	N ON *	* TOTAL N	2	207.59 28.13 250.63 RT SALE	207.59 28.13 2 5 0.63 486.35

** SERVICE IS OUR BUSINESS **

#610

** SUBTOTAL

516.00

** SALES TAX

36.12

Charge Sale X Phone: (403)362-1400

FREIDHT 6092.00	□ □ #				****SUB TOTAL: ****EST/PST TAX -PROV ****GST - R104988332	====	SHOR SUPPLIES	PARTS SUBT	VING AIR RIDE ON SINGLE AXLECTION OF TRUCK. VLY. D	R: 1997 MAKE/MODEL: 96223 KILOMETERS: TO INSTRUCTIONS	Phone: Cell	R/O STATUS: Q QUOTE TERMS: (00) NET 30 DAYS	1100	ASONDER PO ASONDER NO. ASONDER NO.	277	SHIP SHIP
TAL BIANDODINE SALES TAX PLUSE PAY			-	-	 SUPPLIES: 52.00 L: 5092.00 TAX: FROVINCE: A8 0.00 04988332 425.44	\$000.00 1040.00	BIGHAL 52.00			FRIEGHTLINER FL80	Phone:	PRINT JOB TOTALS: Y	04 000/9D		CALGARY AB	FAX 403-362-6206

ESTABLISHED 1924 1-800-663-7800 FAX: 1-403-258-7882

> STANDENS LIMITED P.O. BOX 67, STN. T. 1282 - SBIH AVENUE S.E. CALGARY, ALBERTA T2H 2G7 CANADA (403) 258-7800

> > SUSPENSION, HITCH & DRIVELINE SPECIALISTS SINCE 1924

> > > NO. 391
> > > INVOICE DATE
> > >
> > > 04 - OC
> > > INVOICE NO

PAGE

00016

P.1/1

4.2002-

3:25PM-

-STANDEN'S LIMITED- SERVICE DEPT

CALGARY FREIGHTLINER LTD.

3444 - 44 Avenue, S.E. Calgary, AB T2B 3J9

PH: Parts (403)569-4825 Service (403)569-4835 FAX: (403)248-1894

ESTIMATE SHEET

cus.	TOME	R: ESSTERN PRRIGATION ()	57	COM	PONENT	MODEL:		
	VIN:		SERIAL:					
MC	DDEL:	F180			ARRANG	EMENT:		
CC	ONTAC HONE	T: LLOYD COOK #: 403 362 1446						
		403 362 1400		L	ABOR	PAF	RTS	
REP	REPL	DESCRIPTION	QTY	HRS	COST	COST	TOTAL	TOTAL
		٠٠.				2		

CALGARY FREIGHTLINER LTD.

FREIGHTLINER

3444-44TH AVENUE S.E. CALGARY, ALBERTA T2B 3J9

PHONES: CALGARY: (403) 569-4800/FAX: (403) 248-1894

PARTS ACTION LINE: 569-4825

ALL AUTHORIZED RETURNS MUST HAVE INVOICE NUMBER AND MAY BE SUBJECT TO A HANDLING CHARGE.

		I	
DATE ENTER		INVOICE DATE	INVOICE NUMBER 08518
02 OCT s	02 03 OCT 02 **OUOTE** ACCOUNT NO. 18140	\$ 12:17	PAGE 1 OF 1
0 L D T 0	SHOP S/N 726299; CHNG. SUSP. TO A/RIDE FROM S/N	I P T O	

SHIP VIA SLSM. BIL NO. TERMS	TIONS: OVERDUE ACCOUNTS. CALGARY, AB
CALL 429	TION LIST NET AMOUNT
ORD. SHIP B.O. PART NUMBER 2 2 0 HDR/48411-006 TOROUE 2 2 0 HDR/56805-000 CAP BO' 2 2 0 HDR/50216-000 U-BOLT 4 4 0 HDR/47417-006 U-BOLT 2 2 0 HDR/50973-005 SEAT S. 8 8 0 23-00461-007 NUT 8 8 0 23-09114-005 ROD-CN	DDLE 70.27 47.20 94.40 H. B1 27.86 111.44 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.16 128.78 257.18 25
NEW PARTS & SERVICE FAX # 235-6372 OUR HOURS OF BUSINESS ARE 24HRS. A DAY 7 DAYS A WEEK. WE CLOSE STAT HOLIDAYS. PARTS/TEL 569-4825 SERV/TEL 569-4835	
	CUSTOMER COPY BUSINESS# 100731173

COMMENTS: [DPY OF ESTIMATE TO TOTALS: PTS 4037.84]

CHANGE FROM SPRING

SUSPENSION TO AIR RIDE

PREPARED BY: LARRY FRASER

TOTAL 8075.76