


Vehicle History Report + Lien Check #: 34747355 Report Date: August 3, 2021 | 04:37 PM EST Report Status: Complete Reference: 21HB1015-003



## Vehicle History Report + Lien Check

🔍 Lien Check

No lien records found in Alberta.

### How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

# 실 Accident/Damage

There are no accidents/damage reported on this vehicle.

## Registration

🥑 This vehicle has been registered in the province of **Alberta** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Jul 9		Southside Dodge Chrysler Jeep	Vehicle serviced
		Red Deer, Alberta, Canada	Pre-delivery inspection completed
2015 Jul 30		Service Facility	Vehicle serviced
		Hanna, Alberta, Canada	
2016 May 3	8,781 KM	Jiffy Lube #1031	Vehicle serviced
		Edson, Alberta, Canada	Recommended maintenance performed
			Maintenance inspection completed
			Oil and filter changed
			Air filter replaced
			Air filter checked

### CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount

of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

3C6TR5CTXFG672374

#### CARFAX Canada Vehicle History Reports

DATE	ODOMETER	SOURCE	DETAILS	
2016 Jul 7	17,001 KM	Jiffy Lube #1031	Vehicle serviced	
,	,	Edson, Alberta, Canada	Maintenance inspection completed	
		Euson, Alberta, canada	Air filter replaced	
			Oil and filter changed	
			Air filter checked	
2016 Aug 24	27,003 KM	Jiffy Lube #1031	Vehicle serviced	
5		Edson, Alberta, Canada	Recommended maintenance performed	
		Eason, Alberta, canada	Maintenance inspection completed	
			Oil and filter changed	
			Air filter replaced	
			Air filter checked	
2017 Jun 28	40,752 KM	Jiffy Lube #1031	Vehicle serviced	
		Edson, Alberta, Canada	Maintenance inspection completed	
		,,,,,	Recommended maintenance performed	
			Oil and filter changed	
			Air filter checked	
			Air filter replaced	
2017 Jul 24	46,000 KM	Jiffy Lube #1031	Vehicle serviced	
		Edson, Alberta, Canada	Recommended maintenance performed	
		,,,,,	Maintenance inspection completed	
			Oil and filter changed	
2018 Jun 7	56,852 KM	Jiffy Lube #1031	Vehicle serviced	
		Edson, Alberta, Canada	Maintenance inspection completed	
		,,,,,	Recommended maintenance performed	
			Oil and filter changed	
			Air filter replaced	
			Air filter checked	
2018 Jun 26	62,999 KM	Jiffy Lube #1031	Vehicle serviced	
		Edson, Alberta, Canada	Maintenance inspection completed	
		, _, _,	Air filter replaced	
			Oil and filter changed	
			Air filter checked	
2018 Jul 17	68,999 KM	Jiffy Lube #1031	Vehicle serviced	
		Edson, Alberta, Canada	Recommended maintenance performed	
			Maintenance inspection completed	
			Oil and filter changed	
			Air filter checked	
			Fluids checked	
			Air filter replaced	

## Open Recalls

Recall #: T79 | BRAKE TRANSMISSION SHIFT INTERLOCK Recall Date: 2018 Jan 04

#### **Recall Description**

The Brake Transmission Shift Interlock (BTSI) locking pin may become stuck in the open position. A BTSI locking pin stuck in the open position may allow the transmission to be shifted out of PARK and to or from any gear position without depression of the brake pedal and/or without the key in the ignition, if a key is applicable.

### Remedy

For 2013-2017 model year; Inspect the Brake Transmission Shift Interlock (BTSI) operation and replace if necessary. The Body Control Module (BCM) software will also be updated. For 2009-2012 model year; replace the BTSI, BCM software update not applicable.

#### CARFAX Canada Vehicle History Reports

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit **Ram's website**.

Recall #: U61 | REPROGRAM POWERTRAIN CONTROL MODULE Recall Date: 2018 Jun 26

#### **Recall Description**

The fault handling strategy of the Engine Control Module (ECM) or PCM software in the affected vehicles does not remove positive torque requests from the engine controller if the CAN-C bus stops communicating while the cruise control is requesting positive torque.

#### Remedy

Inspect the software level of the ECM/PCM and, if necessary, perform a software flash on the ECM/PCM of affected vehicles to improve the fault handling so that if the CAN-C bus does stop communicating any active torque requests will be cleared

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.

Recall #: U74 | 2015 - 2017 TAILGATE LATCH Recall Date: 2018 Aug 03

#### **Recall Description**

The tailgate actuator limiter tab within the power lock actuatory control assembly may fracture allowing the lock rod control bracket to overtravel which may pull the lock rods and release the latches, potentially resulting in the tailgate inadvertently falling open at any time

#### Remedy

The remedy for this item will limit the locking actuator travel and not allow the pivot arm from overtraveling and pulling on the locking/unlocking rods

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.

Recall #: V06 | 2013-2018 D TRUCK DRAG LINK Recall Date: 2019 Feb 01

#### **Recall Description**

Some vehicles may have been built with an outboard steering linkage jam nut that could loosen allowing one end of the drag link to separate from the adjuster sleeve.

#### Remedy

Inspect the torque values. If the torque values meet requirement, the nuts will be welded to the adjuster sleeve. If the torque values do not meet requirement, the drag link assembly will be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit **Ram's website**.



This vehicle is not actively declared stolen.

# **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Jul 9		Southside Dodge Chrysler Jeep Red Deer, Alberta, Canada	Service Record	Vehicle serviced
2015 Jul 30		Service Facility Hanna, Alberta, Canada	Service Record	Vehicle serviced
2015 Aug 4		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	First Owner Reported
2015 Aug 4		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Apr 6		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2016 May 3	8,781 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2016 Jul 7	17,001 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2016 Aug 24	27,003 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2017 Apr 25		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jun 28	40,752 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2017 Jul 24	46,000 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2018 Jan 4		RAM	Recall	Manufacturer Recall Issued Recall # T79
2018 Apr 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 7	56,852 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2018 Jun 26	62,999 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2018 Jun 26		RAM	Recall	Manufacturer Recall Issued Recall # U61

#### 8/3/2021

#### CARFAX Canada Vehicle History Reports

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Jul 17	68,999 KM	Jiffy Lube #1031 Edson, Alberta, Canada	Service Record	Vehicle serviced
2018 Aug 3		RAM	Recall	Manufacturer Recall Issued Recall # U74
2019 Feb 1		RAM	Recall	Manufacturer Recall Issued Recall # V06
2019 Apr 25		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Apr 28		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 31		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed



# Questions? We're here to help.

1.866.835.8612 | support.carfax.ca

#### CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner<sup>TM</sup> badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents<sup>IM</sup> badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an asis where-is basis, and CARFAX Canada and its source data providers shall be liable for any losses, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use there decision about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use there decision about the vehicle that is the subject matter of this vehicel history report, ou agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada's Canditons of Use

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.

