

MD OF TABER REPAIRS AND SERVICES REPORT

UNIT: 2-56
YEAR: 1990
MAKE: Fire, Pumper
SERIAL: 46JBAA80LJ003111

<u>DATE</u>	<u>REPAIRS/SERVICES COMPLETED</u>
19-Jan-2022	Rebuild Engine Go Through Unit And Modify/ Repair As Required.
14-Jul-2022	Install Titan Fire System.
10-Mar-2023	Inspection - CVIP