

02114-007



Calgary Head Office
5925 79 AVE. SE
CALGARY, AB T2C 5K3
P: (403) 569-4800

BODYSHOP
6533 79th AVE SE
CALGARY, AB T2C 4S6
P: (825) 257-5782

SERVICE INVOICE: R101037084:01
ESTIMATE: E101002893:01
Tag Number:
License Plate Number:

BILL TO
SFL TRUCKING LTD - 21320
212062 TWP RD 81A
LETHBRIDGE COUNTY AB T1K 8G6
P: (403) 320-7057

DELIVER TO
SFL TRUCKING LTD - 21320
212062 TWP RD 81A
LETHBRIDGE COUNTY AB T1K 8G6
P: (403) 320-7057

Table with invoice details: DATE INVOICE (3/14/2026), SALES TYPE (SRET), ADVISOR (13139), TERMS (NET30), PO # (RC89), YEAR (2021), MAKE (FREIGHTLINER), MODEL (122SD), VIN (3AKJGND11MDMP1211), CUSTOMER UNIT #, ENGINE HOURS (11), IN SERVICE, Component Serial #, ODOMETER (494172)

Sold Operations

JOB #1 WALKIN INFO - NO APPOINTMENT WALKIN

COMPLAINT AUTH - RYAN - 403-320-7057/ 403-795-3246

AUTH - DAREN - 403 635 6902

NO OPEN RECALLS

CAUSE
CORRECTION

Table with 5 columns: QTY, ITEM, DESCRIPTION, UNIT PRICE, EXTD PRICE. Row 1: 0.00 LABOR WALKIN, INFO - No appointment walkin, \$0.00. Summary: Prepay: \$0.00, Parts: \$0.00, Labor: \$0.00, Misc: \$0.00, Sublet: \$0.00, Total: \$0.00

JOB #2 EA EXPRESS ASSESSMENT

COMPLAINT EXPRESS ASSESSMENT

CAUSE
CORRECTION

Table with 5 columns: QTY, ITEM, DESCRIPTION, UNIT PRICE, EXTD PRICE. Row 1: 1.00 LABOR EA, EXPRESS ASSESSMENT / COMPUTER HOOK-UP, \$75.00. Summary: Prepay: \$0.00, Parts: \$0.00, Labor: \$75.00, Misc: \$0.00, Sublet: \$0.00, Total: \$75.00

JOB #3 WA COMPLIMENTARY TRUCK INSPECTION

COMPLAINT COMPLIMENTARY TRUCK INSPECTION

CAUSE
CORRECTION

Table with 5 columns: QTY, ITEM, DESCRIPTION, UNIT PRICE, EXTD PRICE. Row 1: 0.30 LABOR WA, COMPLIMENTARY TRUCK INSPECTION, \$0.00. Summary: Prepay: \$0.00, Parts: \$0.00, Labor: \$0.00, Misc: \$0.00, Sublet: \$0.00, Total: \$0.00



Sold Operations (Cont.)

JOB #4 CMR (TROUBLESHOOT AND ADVISE) **UP TO 2 HRS OF DIAGNOSIS + TAXES AND SHOP SUPPLIES

COMPLAINT TRANSMISSION IS LEAKING A LOT OF OIL. TRANY AND CLUTCH WAS JUST REPLACED ONLY 3-4 HRS ON UNIT SINCE WORK WAS DONE.

CAUSE failed engine flywheel housing

CORRECTION feb 24/26 pressure washed engine and fuel tank trans artea. brake cleaned inside bellhousing. removed fill plug and found trans overfilled by 1l. ran up to temp. could no tverify leak. went around the block. no signs of leaking. road tested unit, lots of oil still leaking out of clutch housing

Removed transmission as per workshop manual, oil covering everything, removed input shaft and bell housing, inspected sealing surfaces, no damage, removed engine flywheel and inspected engine flywheel housing, found a hole in the housing, the oil is actually engine oil, oil has been changed recently so it appears to be transmission oil, diag complete.

during transmission removal noticed most of the fasteners loose and in some case many of them missing and wires and hoses not tied up.

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|------|----------------|---------------------------|------------|------------|
| 2.00 | LABOR CMR | (Troubleshoot and advise) | | 378.00 |
| 1.00 | 101S/922276107 | ENGINE SHAMPOO | 13.21 | 13.21 |
| 8.00 | LABOR CMR | (Troubleshoot and advise) | | 1,512.00 |
| 1.00 | 101D/FUL 14311 | GASKET *D | 2.25 | 2.25 |
| 1.00 | 101S/0150200 | BLUE LOCTITE 10ML | 23.84 | 23.84 |

Prepay: \$0.00 Parts: \$39.30 Labor: \$1,890.00 Misc: \$0.00 Sublet: \$0.00 \$1,929.30

JOB #5 100 INFO ONLY

COMPLAINT please take photos of everything you find - they will be requesting these

CAUSE

CORRECTION

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|------|-----------|-------------|------------|------------|
| 0.00 | LABOR 100 | INFO ONLY | | 0.00 |

Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 \$0.00

JOB #6 DELETED ***Aftertreatment Modification or Delete***** Customer has informed that this unit has an aftertre**

COMPLAINT *****Aftertreatment Modification or Delete***** Customer has informed that this unit has an aftertreatment modification or delete. (INFO ONLY do not punch on this Line)

ABS AND CAL CONTROL ARE UNPLUGED

CAUSE

CORRECTION

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|------|---------------|--|------------|------------|
| 0.00 | LABOR DELETED | *****Aftertreatment Modification or Delete***** Customer | | 0.00 |

Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 \$0.00



Sold Operations (Cont.)

JOB #9 EA-R (EXPRESS ASSESSMENT REPAIR)

COMPLAINT REPLACE REAR FLYWHEEL HOUSING DUE TO HOLE FROM PREVIOUS FAILURE, REPLACE TRANSMISSION BELL HOUSING, VERIFY OPERAITON WITH ROAD TEST.

CAUSE hole in rear structure

CORRECTION removed and replaced rear structure and oil pan as per workshop manual, installed adaptor plate for oil cooler lines, steamed and road tested, no leaks, repair complete.

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-------|------------------------|---------------------------------|------------|------------|
| 12.00 | LABOR EA-R | (Express Assessment Repair) | | 2,268.00 |
| 1.00 | 101D/DDE A0159974946 | OIL SEAL, CRANKSHAFT, REAR | 71.64 | 71.64 |
| 12.00 | 101D/DDE A0029905500 | BOLT - FLYWHEEL TO CRANKSHAFT | 8.60 | 103.20 |
| 8.00 | 101D/23-09438-250 | SCREW-CAP,HEX,7/16-14 X 2.5,GR | 4.21 | 33.68 |
| 4.00 | 101D/23-12891-175 | SCREW-SOCKETHEAD 12PT,1/2-20,1 | 3.69 | 14.76 |
| | C | STOCK | | |
| 1.00 | 101D/DDE A4720154302 | TIMING CASE | 1,309.33 | 1,309.33 |
| | C | CANTON PDC (2-3 BUSINESS DAYS) | | |
| 1.00 | 101D/DDE A0119813525 | PILOT BEARING | 303.15 | 303.15 |
| | C | CALGARY PDC (NEXT BUSINESS DAY) | | |
| 1.00 | 101D/TCX T130158342AB2 | CLAMP-EXHAUST 5 INCH SPHERICAL | 30.08 | 30.08 |
| 1.00 | 101D/TCX AMS013 | GASKET-5 INCH SPHERICAL W/TABS | 22.48 | 22.48 |
| | C | STOCK | | |
| 1.00 | 101D/FUL K3671 | KIT, FORCED LUBE CL HOUSING *D | 707.01 | 707.01 |
| | C | CALGARY PDC (NEXT BUSINESS DAY) | | |
| 2.00 | 101D/FUL 13835 | O - RING *D | 2.44 | 4.88 |
| | C | CALGARY PDC (NEXT BUSINESS DAY) | | |
| 2.00 | 101D/FUL 13653 | O - RING *D | 4.17 | 8.34 |
| | C | STOCK | | |
| 1.00 | 101D/FUL 13834 | O-RING *D | 1.06 | 1.06 |
| 1.00 | 101D/FUL 5568544 | O - RING *D | 2.30 | 2.30 |
| 1.00 | 101D/DDE A4711800209 | KIT, OIL FILTER WITH SEALS | 40.29 | 40.29 |
| 1.00 | 101S/921047461 | 598 ULTRA BLACK 80ML | 13.08 | 13.08 |
| 1.00 | 101D/DDE A4720150480 | MOUNTING GASKET, FLYWHEEL HOUS | 78.53 | 78.53 |
| 1.00 | 101S/0610191 | ANAEROBIC GASKET MAKER. 50ML | 19.98 | 19.98 |
| 1.00 | 101D/FUL 4309447 | GASKET, HOUSING, SHIFT LEVE *D | 14.51 | 14.51 |
| 1.00 | 101D/DDE A0002361880 | GASKET, IDLER 3 COVER PLATE | 13.49 | 13.49 |
| 1.00 | 101D/DDE A4721421380 | GASKET - EXHAUST LINE, TURBOCO | 14.04 | 14.04 |
| 1.00 | 101D/DDE A0019957302 | PIPE CLAMP | 46.15 | 46.15 |
| 2.00 | 101D/DDE N000835012041 | STUD BOLT, STARTING MOTOR | 3.72 | 7.44 |
| 1.00 | 101D/DDE A0029905014 | MOUNTING STUD, STARTING MOTOR | 11.97 | 11.97 |
| 1.00 | 101D/23-13323-002 | STUD-THREAD,DOUBLE END,.312,.4 | 14.32 | 14.32 |
| 1.00 | 101D/FUL K4293 | COOLER LINE ADAPTER PLATE K *D | 100.38 | 100.38 |
| 1.00 | FRT | FREIGHT FOR K4293 | 50.00 | 50.00 |
| 3.00 | 101S/922276107 | ENGINE SHAMPOO | 13.21 | 39.63 |

Prepay: \$0.00 Parts: \$3,025.72 Labor: \$2,268.00 Misc: \$50.00 Sublet: \$0.00 \$5,343.72



Sold Operations (Cont.)

JOB #10 OANDF REPLACE ENGINE OIL AND OIL FILTER(S) - REQUIRED WITH MAJOR ENGINE REPAIR

COMPLAINT REPLACE ENGINE OIL AND OIL FILTER(S) - REQUIRED WITH MAJOR ENGINE REPAIR
 CAUSE oil service
 CORRECTION replaced filter and engine oil, repair complete.

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|-------|----------------------|--------------------------------|------------|------------|
| 0.30 | LABOR CRR | RECOMMENDED SERVICE | | 56.70 |
| 42.00 | 101X/ESO 105420 | OIL, M-DELVAC 1300S 10W-30, *D | 5.40 | 226.80 |
| 42.00 | OIL | GOVERNMENT FEE OIL | 0.06 | 2.52 |
| 1.00 | 101D/DDE A4711800209 | KIT, OIL FILTER WITH SEALS | 40.58 | 40.58 |
| | C | STOCK | | |

Prepay: \$0.00 Parts: \$267.38 Labor: \$56.70 Misc: \$2.52 Sublet: \$0.00 \$326.60

JOB #12 EA-R (EXPRESS ASSESSMENT REPAIR)

COMPLAINT PART ONLY - OIL PAN WIRING HARNESS MOUNTING STUD BROKE OFF PAN DURING REMOVAL NO
 ADDITIONAL LABOUR REQUIRED -
 CAUSE
 CORRECTION

| QTY | ITEM | DESCRIPTION | UNIT PRICE | EXTD PRICE |
|------|----------------------|-----------------------------|------------|------------|
| 0.00 | LABOR EA-R | (Express Assessment Repair) | | 0.00 |
| 1.00 | 101D/DDE A4730104413 | OIL PAN | 833.68 | 833.68 |

Prepay: \$0.00 Parts: \$833.68 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 \$833.68

Sold Operations Totals Prepay: \$0.00 Parts: \$4,166.08 Labor: \$4,289.70 Misc: \$52.52 Sublet: \$0.00 \$8,508.30

Authorization of Repairs & Warranty

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees' permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The dealership is not responsible for damages from freezing due to lack of antifreeze.

I agree that any warranty coverage noted on this statement of account is based solely on New West Truck Centres estimate of warranty coverage and that I remain responsible for any portion of the charges incurred which is shown as being covered by warranty if the warranty coverage is not accepted by the manufacturer and I agree that such rejected amount should be charged to my account and that I will promptly pay such amount.

PRINTED NAME

SIGNATURE

Pre-Work Disclaimer

I agree to receive New West Truck Centres newsletter containing news, updates and promotions regarding New West Truck Centres products. You can withdraw your consent at any time. Please refer to our Privacy Policy or contact us for more details.

X

Emissions Disclaimer

I agree this vehicle emissions system has not been defeated, modified or deleted. New West Truck Centres assumes no responsibility for damage to any aftermarket or modified component as a result of our diagnostics or repairs

Do you authorize New West Truck Centres to undertake any no charge outstanding recalls, field service modifications or campaigns recommended by the manufacturer to the chassis or engine.

X

| | ESTIMATED | BILLED |
|-----------------|-----------|-------------------|
| LABOR | | \$4,289.70 |
| PARTS | | \$4,166.08 |
| MISC | | \$52.52 |
| SUBLET | | \$0.00 |
| DEPOSIT | | \$0.00 |
| SHOP SUPPLIES | | \$442.54 |
| MISC SUPPLIES | | \$0.00 |
| SUBTOTAL | | \$8,950.84 |
| TAX | | \$447.54 |
| TOTAL | | \$9,398.38 |

Please Remit Payment To:

NEW WEST TRUCK CENTRES (AB)
 Inc.
 5925 79 AVENUE SE
 CALGARY, AB T2C 5K3
 GST#: 100731173



GREATWEST KENWORTH LTD



3995 2nd AVENUE N
LETHBRIDGE, AB T1H 0C8
(403) 327-8536

Sold To:

SFL TRUCKING LTD
212062 Twp Rd 81a
Lethbridge, AB T1K 8G6

Ship To:

SFL TRUCKING LTD
212062 Twp Rd 81a
Lethbridge, AB T1K 8G6

PARTS INVOICE NUMBER

PL7109084



Date: 02-17-26

Tax ID:

Authorization #:

REPRINT

Page: 1 of 1

| Customer Acct Number | Phone Number | Salesman | Ship Via | Customer Purchase Order | | | | |
|----------------------|----------------|---------------------------|----------|-------------------------|-----|---------|------------|-----------|
| 15319 | 403 320-7057 | NFF*CBH | PICK UP | JT#89 | | | | |
| Loc | Part # | Description | Ord | Ship | B/O | List | Unit Price | Extension |
| 1F2 | RTL018918BCGL | TRANSMISSION-REMAN RTLO-1 | 1 | 1 | 0 | 5210.68 | 4199.99 | 4199.99 |
| 1F2 | RTL018918BCGL# | CORE | 1 | 1 | 0 | 4800.00 | 4000.00 | 4000.00 |
| | COUPON | PACCAR LOYALTY COUPON | -1 | -1 | 0 | 350.00 | 350.00 | -350.00 |
| | CAPITAL GEAR | REMAN TRANSMISSIONS | | | | | | |
| | WO 19333 | | | | | | | |

THANK YOU! WE APPRECIATE YOUR BUSINESS!
MON-FRI 7:30AM-5:00PM SAT 8:00AM-4:00PM
AFTERHOURS PARTS/SERVICE CALLOUT AVAILABLE
PARTS EMAIL: LETHBRIDGEPARTS@GREATWESTKENWORTH.COM
09:20AM PARTS TAX

Customer Print Name: _____

Customer Signature: _____ Date: _____

REPRINT
GST# R139766661

220

| | |
|------------|---------|
| Sub Total | 7849.99 |
| Freight | 0.00 |
| GST | 392.50 |
| Sales tax | 0.00 |
| Please Pay | 8242.49 |

ALL PARTS RETURNED AFTER 30 DAYS WILL BE SUBJECT TO A MINIMUM 15% RESTOCKING CHARGE. SPECIAL ORDER PARTS ARE ALSO SUBJECT TO A RESTOCKING CHARGE IF AND ONLY IF THEY ARE ACCEPTABLE FOR RETURN. PARTS OLDER THAN 90 DAYS ARE NOT ACCEPTABLE FOR RETURN. NO RETURNS ON ELECTRICAL PARTS.

BALZAC - CALGARY - CLAIRMONT - FOX CREEK - LETHBRIDGE - REDCLIFF - RED DEER