

801 - 11th Ave. East Box 1357 · Kindersley, SK · S0L 1S0

Tel: (306) 463-4700 • Fax: (306) 463-6808 Toll Free: 1-888-819-8090

www.energydodge.com

INVOICE ORIGINAL Work Order #8226 Well-Tec Senergy Services

February 15, 2023 Svc.Adv Yaworski, David Cust.Ph. (403) 223-4244

Tag#

Page 1 of 3 04/13/2023 07:38:41

License #:

Odo. In: 220,988

To: Well-Tec Senergy Services

6006 58th Street

Taber T1G 2B8

AB

Year: 2011 Veh ld: 20349 Unit #:

Make: RAM

Model: 5500 St/Slt/Laramie SLT Colour: Brilliant Black Crystal Pe

Odo. Out: 220.989 V.I.N.#: 3D6WU7CL4BG579211 **Next Service:**

Date In: 02/15/2023 Out:

In Service Date: 05/06/2011 04/13/2023 Cases: 5

Ext. War - - (mo/) - D: \$0.00

Promised Time: 02/15/2023 05:00:00 PM Call When Ready: No

Case: 1 D/R transmission leaking and vehicle wont drive Quantity Description/Correction Price Total 1.00 68086052AB - GASKET PTO \$20.99 \$20.99 \$507.50 \$507.50 Completed by Technician number: GRAE Shop Charges \$16.62 \$16.62 Misc \$16.62 Labour \$507.50 Parts \$20.99 Prepaid Parts Amt: \$0.00 Case Total: \$545.11 Case: 2 Added Operation: remove trans and pto to send for inspection Quantity Description/Correction Price Total \$400.00 \$400.00 Completed by Technician number: GRAE · Shop Charges \$13.10 \$13.10 Misc \$13.10 Labour \$400.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$413.10

Case: 3 Added Operation: REMOVE AND INSTALL TRANSMISSION - Tech Cause: faulty - Tech Comments: replaced trans...tested good

Quantity Description/Correction Price Total 4.00 05189977AD - FLUID- ASRC TRANS \$69.99 \$279.96 1.00 05189966AD - FLUID- ASRC TRANS \$17.99 \$17.99 1L 1.00 462HH450 - AS68RP \$4,000.00 \$4,000.00 \$1,100.00 \$1,100.00

- · Tech Cause: faulty
- Tech Comments: replaced trans...tested good
- · Completed by Technician number: GRAE
- · Enviro Levy-Retail(3)

\$1.52

\$1.52



801 - 11th Ave. East Box 1357 · Kindersley, SK · S0L 1S0 Tel: (306) 463-4700 • Fax: (306) 463-6808 Toll Free: 1-888-819-8090

www.energydodge.com

Enviro Levy-Retail(3)

Freight Charges

· Shop Charges

\$337.70 Labour \$1,100.00

Parts \$4,297.95 Prepaid Parts Amt:

\$0.00

Work Order #8226 Well-Tec Senergy Services February 15, 2023 Svc.Adv Yaworski, David Cust.Ph. (403) 223-4244 Tag#

INVOICE ORIGINAL

Page 2 of 3 04/13/2023 07:38:43

> \$0.15 \$0.15

\$300.00 \$300.00 \$36.03 \$36.03

Case Total: \$5,735.65

Case: 4 Added Operation: carry out trans cooler flush and lines - Tech Cause: due - Tech Comments: carried out trans cooler and line flush....tested good

Quantity Description/Correction

Price \$290.00

Total \$290.00

· Tech Cause: due

Tech Comments: carried out trans cooler and line flush....tested good

 Completed by Technician number: GRAE

Shop Charges

\$9.50

\$9.50

\$9.50 Misc

Misc

Labour \$290.00

Parts \$0.00

Prepaid Parts Amt:

\$0.00

Case Total:

\$299.50

Case: 5 Added Operation: carry out trans reprogram and relearn - Tech Cause: due - Tech Comments: carried out trans reprogram and relearn...all good.....test drove and steering feels stiff and has an intake leak somewhere....shifts good

Quantity Description/Correction

Price

Total

\$145.00

\$145.00

· Tech Cause: due

• Tech Comments: carried out trans reprogram and relearn...all good.....test drove and steering feels stiff and has an intake leak somewhere....shifts good

Completed by Technician number:

GRAE

· Shop Charges

\$4.75

\$4.75

Misc \$4.75

Labour \$145.00

Parts \$0.00

Prepaid Parts Amt: \$0.00

Case Total:

\$149.75

\$0.00



801 - 11th Ave. East Box 1357 • Kindersley, SK • S0L 1S0

Tel: (306) 463-4700 • Fax: (306) 463-6808

Toll Free: 1-888-819-8090 www.energydodge.com

Work Order #8226 Well-Tec Senergy Services February 15, 2023 Svc.Adv Yaworski, David Cust.Ph. (403) 223-4244 Tag#

INVOICE ORIGINAL

Page 3 of 3 04/13/2023 07:38:43

Date	Signature	Payment Type	Total:	\$7,910.87
04/13/2023				
		Ta	x Adjustment:	\$0.00
		G/HST Reg # 859814428RT	PST:	\$410.60
		P/O#:	G/HST:	\$357.16
		Expiry Date:	Sub Total:	\$7,143.11
		Payment Ref:	Misc:	\$380.00
	occasiones described in this work order,		Parts:	\$4,320.61
owing to repairs parts & a	cknowledged for the "Total Charges" being accessories described in this work order.	all or the balance Currency:	Labour:	\$2,442.50



801 - 11th Ave. East Box 1357 · Kindersley, SK · S0L 1S0

Tel: (306) 463-4700 • Fax: (306) 463-6808 Toll Free: 1-888-819-8090

Out:

www.energydodge.com

INVOICE ORIGINAL Work Order #6881

Well-Tec Senergy Services October 12, 2022 Svc.Adv Park, Melanie Cust.Ph. (403) 223-4244

Tag#

Page 1 of 3 10/14/2022 07:42:40

License #:

Odo. In: 201.614

To: Well-Tec Senergy Services

6006 58th Street

Taber T1G 2B8

AB

Year: 2011 Veh ld: 20349 Unit #: Make:

RAM

Date In: 10/12/2022

Model: 5500 St/Slt/Laramie SLT

Colour: Brilliant Black Crystal Pe

V.I.N.#: 3D6WU7CL4BG579211

Odo. Out: 201.615 **Next Service:**

X

In Service Date: 05/06/2011

Cases: 5

10/14/2022 Ext. War - - (mo/) - D: \$0.00

Promised Time: 10/12/2022 05:00:00 PM Call When Ready:

Case: 1 D/R - DRIVERS SIDE CALIPER BLOWN OFF

Quantity Description/Correction

Price

Total

\$87.00 \$87.00 • Tech Cause: checked and found left rear caliper piston popped out..no pad left and damaged rotor right rear is 1mm left on pad and rotor worn and right caliper is sticking...checked front brakes and they need serviced also found both front axle ujoints bady worn

• Tech Comments: replace all listed parts, check engine light and abs light on still-customer declined to look

· Completed by Technician number: GRAE

Shop Charges

Misc \$5.00 Labour \$87.00

Parts \$0.00

Prepaid Parts Amt:

\$0.00

\$5.00 Case Total:

\$5.00 \$92.00

Case: 2 Added Operation: replace rear pads and rotors and wheel seals - Tech Cause: worn - Tech Comments: replaced rear pads and rotors and seals

Quantity Description/Correction 1.00 SX1335 - BRAKE PADS	Price	Total
2.00 710454 - wheel seal	\$277.99 \$97.09	\$277.99 \$194.18
1.00 900359 - REAR BRAKE ROTOR	\$243.99	\$243.99
1.00 68415393AA - ROTOR- BRAKE 3.00 0BF00014AB - FLUID- BRAKE DOT 3	\$336.99	\$336.99
SECOND TECHNOLOGY	\$3.99	\$11.97
 Tech Cause: worn Tech Comments: replaced rear pads and rotors and seals Completed by Technician number: GRAE 	\$725.00	\$725.00
• Shop Charges	\$41.67	\$41.67

\$41.67

Misc \$41.67 Labour \$725.00 Parts \$1,065.12 Prepaid Parts Amt: \$0.00 Case Total: \$1,831.79



801 - 11th Ave. East Box 1357 · Kindersley, SK · S0L 1S0

Tel: (306) 463-4700 • Fax: (306) 463-6808

Toll Free: 1-888-819-8090 www.energydodge.com

INVOICE ORIGINAL Work Order #6881

Well-Tec Senergy Services October 12, 2022 Svc.Adv Park, Melanie Cust.Ph. (403) 223-4244 Tag#

Page 2 of 3 10/14/2022 07:42:40

Case: 3 Added Operation: replace both rear calipers - Tech Cause: worn and seezed - Tech Comments: replaced both

Misc Case:	• T • C GF • S • \$16.67 5 Added @ 2Pl	ech Cause: due and dirty ech Comments: carried of ompleted by Technician AE hop Charges Labour \$290.00 I Operation: SPOKE WIT M - MELANIE	out dully bra number: Parts TH STEVE A	\$46.99	Prepaid Parts Amt: ECLINED ALL OTHER	\$0.00 WORK Q	\$46.99 \$290.00 \$16.67 Case Total: Price	\$46.99 \$290.00 \$16.67 \$353.66
	• T • C GF • S \$16.67	ech Comments: carried of ompleted by Technician RAE hop Charges Labour \$290.00	out dully bra number: Parts	\$46.99			\$290.00 \$16.67 Case Total :	\$46.99 \$290.00 \$16.67 \$353.66
Misc	• T • C GF • S \$16.67	ech Comments: carried of completed by Technician RAE hop Charges Labour \$290.00	out dully bra number: Parts	\$46.99			\$290.00 \$16.67 Case Total :	\$46.99 \$290.00 \$16.67 \$353.66
	• T • C GF • S	ech Comments: carried of completed by Technician RAE hop Charges	out dully bra	ke flu s h			\$290.00	\$46.99 \$290.00
	• T	ech Comments: carried of ompleted by Technician	out dully bra	ke flush				\$46.99
	• T	ech Cause: due and dirty	<i>'</i>					\$46.99
								\$46.99
							04000	
	Quan 1	tity Description/Correction BH383650 - FLEXI	tion HOSE				Price	Total
case.	brake	d Operation: carry out du flush	lly brake flus	sh - Tech (Cause: due and dirty - 1	Fech Com	ments: carried o	ut dully
Case:	, Magazia	Labour \$145.00	Parts	\$370.98	Prepaid Parts Amt:	\$0.00	Case Total:	\$524.31
Misc	\$8.33	S	-	S towards to the Film comme			\$8.33	\$8.33
		ore Return - BBB891775 hop Charges				(\$94.25)	(\$94.25)	
	• Core Charges - BBB8917750B						\$94.25	\$94.25
	Core Return - BBB8917750ACOR						(\$94.25)	\$94.25 (\$94.25)
	Core Charges - BBB8917750A						\$94.25	604.05
	• 1	ech Cause, worn and se ech Comments: replace completed by Technician RAE	d both rear	calipers				
	• Tech Cause: worn and seezed \$1							\$145.00
		1.00 BBB8917750B - CA	LIPER				\$177.99	\$177.99
		1.00 BBB8917750A - CA					Price \$192.99	Total \$192.99
		1 00 BBB80177504 0/						



801 - 11th Ave. East Box 1357 · Kindersley, SK · S0L 1S0

Tel: (306) 463-4700 • Fax: (306) 463-6808 Toll Free: 1-888-819-8090

www.energydodge.com

INVOICE ORIGINAL Work Order #6881

Well-Tec Senergy Services October 12, 2022 Svc.Adv Park, Melanie Cust.Ph. (403) 223-4244

Tag#

Page 3 of 3 10/14/2022 07:42:41

Case: 6 Added Operation: replace left rear caliper flexi hose - Tech Cause: leaking - Tech Comments: replaced left rear faulty leaking flexi hose

Quantity Description/Correction

Price

Total \$145.00 \$145.00

· Tech Cause: leaking

Tech Comments: replaced left rear faulty leaking flexi hose

Completed by Technician number:

GRAE

· Shop Charges

\$8.33

\$8.33

\$8.33

Labour \$145.00

Parts \$0.00

Prepaid Parts Amt: \$0.00

Case Total: \$153.33

\$0.00

Date	Signature	Payment Type	Total:	\$3,280.15
10/14/2022				
in the sail				
		Та	x Adjustment:	\$0.00
		G/HST Reg # 859814428RT	PST:	\$177.31
		P/O#:	G/HST:	\$147.75
)		Expiry Date:	Sub Total:	\$2,955.09
		Payment Ref:	Misc:	\$80.00
			Parts:	\$1,483.09
owing to repairs, parts & a	knowledged for the "Total Charges" being all or the balance ccessories described in this work order.	Currency:	Labour:	\$1,392.00