

The Alberta Superintendent of Insurance has approved this form pursuant to section 803 of the *Insurance Act*.

This report is required only if the vehicle is 12 years or older and must be completed by a Certified Automotive Technician.

Vehicle Owner's Name		Insurance Company	
Insurance Broker			Policy Number
Vehicle Year 2006	Make Dodge	Model Dakota	VIN 1D7HW49N16S637751

This section is to be completed by a Certified Automotive Technician.


Steering	Roadworthy	Reject	Comments
Steering Box/Rack	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Struts/Shocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Front Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Tie Rod Ends	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical System	Roadworthy	Reject	Comments
Head Lamp/Tail Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stop Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Signal Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windshield Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Tires	Roadworthy	Reject	Comments
Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brakes	Roadworthy	Reject	Comments
Front Lining or Drums	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rear Lining or Drums	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Park	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brake Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brake Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
General Conditions	Roadworthy	Reject	Comments
Body Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Muffler/Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Motor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windshield	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Seat Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Is this vehicle roadworthy?  Yes  No      Has the vehicle been altered for speed or performance?  Yes  No

Other Comments

Certified Automotive Technician Statement:

I certify that I have inspected and tested the motor vehicle described above and found it to be in the condition stated above.

Name of Automobile Repair Shop Valley Fleet & Automotive Services		Address 5712 50th Ave	
City Drayton Valley	Province/Territory AB	Postal Code T7A 1J9	Telephone Number 780 621 0061
Certified Automotive Technician's Name Donald Nadeau		Certified Automotive Technician's Certificate Number 009 624106	
Date (yyyy-mm-dd) 2022-10-12		Certified Automotive Technician's Signature 	

# KAL TIRE

October 12, 2022  
4:12:40 PM

Ordered on  
October 11, 2022

Drayton Valley AB T7A 1T1

Workorder # 35706

MAKE & MODEL		FLEET NO.	PHONE	REP	CSH	PO #	TERMS	
2006 Dodge Dakota Quad Sit SLT			780-898-9977	Kortney Hof	KC		Cash	
LICENSE NO.	KM IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOUR	PRD DATE	
	133626	1D7HW48N16S637751.A		4.7L V8 F OHV				
CATALOG	DESCRIPTION		QTY	PARTS	LABOR	DISC	TOTAL	Code
SL	Perform Insurance Inspection		1		109.00		\$109.00	DN
	RIGHT LICENSE PLATE LIGHT OUT , STEERING GEAR LEAKING 3/10 -- REAR PINION SEAL LEAKING 3/10							
	-- REAR STAB LINKS LOOSE							
	SUBTOTAL			.00	109.00		\$109.00	
SL	Replace Front Brake Pads		1		109.00		\$109.00	DN
	14D1084CHF1 - Front Brake Pad		1	118.73			\$118.73	DN-KS
	BOTH CALIPERS WERE STIFF TO PRESS BACK IN							
	SUBTOTAL			118.73	109.00		\$227.73	
SL	Replace Left Rear Wheel Cylinder		1.2		109.00		\$130.80	DN
	RAY WC370177 - cylinder		1	29.16			\$29.16	
	Brake Cleans		1	1.99			\$1.99	DN-KS
	19353127- Brake Fluid		1	7.95			\$7.95	DN-KS
	SUBTOTAL			39.10	130.80		\$169.90	

Welcome, We appreciate your business.

PAID BY

VISA-M/C \$531.96

Parts	\$157.83	Taxable	\$506.63
Labour	\$348.80	Non-Taxable	\$0.00
Freight	\$0.00	Local Tax	\$25.33
Other	\$0.00		
Supplies	\$0.00	<b>TOTAL</b>	<b>\$531.96</b>

Parts and Labor warranties 100% for 90 days or 4000 miles, whichever comes first. This warranty limited to the work on this form only. Vehicle must be returned to our shop at customer's expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Because of the extent of the teardown and inspection, the vehicle may not perform as well as before. No refunds on installed Tires and or Wheels, Special Orders or discontinued items. All returns are subject to 15% handling charge. Any deposits are subject to forfeit if cancelled.

Print Name \_\_\_\_\_

Signature \_\_\_\_\_

Date \_\_\_\_\_

DA Phone:780-542-3443  
 TIN Fax:780-542-1532

# VALLEY FLEET

AB  
 Phone:(780)

Account: 654CASH

GST/HST: 122644537

Year: \_\_\_\_\_  
 Make: \*Loose  
 Model: \_\_\_\_\_  
 Unit: \_\_\_\_\_  
 Lic #: \_\_\_\_\_  
 Prov: \_\_\_\_\_  
 VIN: \_\_\_\_\_  
 Mi/KM: \_\_\_\_\_

Qty	Product Code	Description	Price	Unit	Amount
1	T431883	265/70R16 NOK OUTPOST AT 112T	253.00	PCS	253.00
		Install 1 today rest are coming on rocket			
1	ABLEVY1	ALBERTA TIRE RECYCLING FEE	4.00	EA	4.00
4	LINST	LIGHT TRK TIRE INSTAL & BALANC	20.00	EA	80.00
1	AL4	4 WHEEL ALIGNMENT	126.00	EA	126.00
1	FRGHT	FREIGHT CHARGE	40.00	EA	40.00
3	T431883	265/70R16 NOK OUTPOST AT 112T	253.00	PCS	759.00
		Install 1 today rest are coming on rocket			
3	ABLEVY1	ALBERTA TIRE RECYCLING FEE	4.00	EA	12.00

PRELIMINARY INVOICE FOR PURPOSE OF VEHICLE RELEASE. FINAL INVOICE WILL BE ISSUED.

I AM THE PERSON WHO REQUESTED THAT THE ABOVE WORK BE DONE AND MATERIAL SUPPLIED. OR I AM THE AUTHORIZED AGENT FOR THAT PERSON/COMPANY. I ACKNOWLEDGE INDEBTEDNESS FOR THE AMOUNT OF \$1,337.70 FOR THE WORK DONE AND MATERIALS SUPPLIED.

Agreed Terms: CASH SALE  
 Interest of 16% per Annum Payable on Overdue Accounts.

Subtotal	1,274.00
AB GST/HST	63.70
Total	1,337.70
Down Payment	
<b>Visa</b>	1,205.40
Balance	132.30

IF WE SELL IT... WE GUARANTEE IT! WE WELCOME YOUR COMMENTS! CALL US WEEKDAYS AT 8AM TO 5PM (PACIFIC TIME) AT 1-800-663-9350 OR EMAIL US AT CUSTOMERSERVICE@KALTIRE.COM

Signed X

Release Date: \_\_\_\_\_

\*\*THANK YOU FOR YOUR BUSINESS\*\*

Page: 1  
 Work Order #: 654319591

Printed: Jan 17 2023 10:18  
 Driver:  
 Phone:

OrderConf-2.6.9

[Go to Site \(https://reportshq.com\)](https://reportshq.com)



[PRINT \(\)](#)

[LOAD PDF](#)

[/www.clearvin.com/en/report/download/e7f0ae67d14c110e1de208cd2d1382d997bf2793204e64a3ae566a08fa30fc37?=&pdf&locale=en\)](https://www.clearvin.com/en/report/download/e7f0ae67d14c110e1de208cd2d1382d997bf2793204e64a3ae566a08fa30fc37?=&pdf&locale=en)

## Vehicle History Report for VIN# 1D7HW48N16S637751

Year: **2006**  
Make / Model: **Dodge Dakota**  
Date Generated: **Oct 03 2022**  
Report ID: **8C346DE2**

**J.D. POWER**

### ClearVin Vehicle

?

(<https://www.clearvin.com/en/vehicle-history-rating-review>)

**Rating**

### Report summary

Junk & Salvage Information 0 record(s) found

Insurance Records 0 record(s) found

Ownership History 0 record(s) found

**B**  
GOOD

**A** Title Brand  
**Clean Title**

**A** Past Auctions

**E** Vehicle's Age  
**16 Years**

**A** Liens

A **B** C D E F  
[View Full Vehicle Rating](#)

Title History 0  
record(s)  
found

Odometer  
reading 0  
record(s)  
found

Title Brands 0  
record(s)  
found

Auction Sales 0  
record(s)  
found

Lien & Thief  
Records 0  
record(s)  
found

Recalls 6  
record(s)  
found

## Vehicle Specifications

VIN: **1D7HW48N16S637751**

Year: **2006**

Make: **Dodge**

Model:	<b>Dakota</b>
Trim:	<b>SLT Quad Cab 4WD</b>
Engine:	<b>4.7L V8 SOHC 16V</b>
Style:	<b>CREW CAB PICKUP 4-DR</b>
Made In:	<b>United States of America</b>
Steering Type:	<b>R&amp;P</b>
Anti Brake System:	<b>4-Wheel ABS</b>
Tank Size:	<b>22.00 gallon</b>
Overall Height:	<b>68.60 INCHES</b>
Overall Length:	<b>218.80 INCHES</b>
Overall Width:	<b>71.70 INCHES</b>
Standard Seating:	<b>5</b>
Optional Seating:	<b>6</b>
Highway Mileage:	<b>18 - 20 miles/gallon</b>
City Mileage:	<b>14 - 16 miles/gallon</b>

## **Vehicle Value Information**

SOURCE: J.D.POWER

Retail Value

**UNKNOWN**

Trade in Value

**UNKNOWN**

Rough Trade in Value

**UNKNOWN**

Average Trade in Value

**UNKNOWN**

Loan Value

**UNKNOWN**

MSRP Value

**UNKNOWN**


### **Junk and Salvage Information**

SOURCE: NMVTIS

 Clean Records

### **Insurance Records**

SOURCE: NMVTIS

 Clean Records

### **Title History Information**

SOURCE: NMVTIS

 Clean Records

--

--

## Odometer reading

SOURCE: NVS

Clean Records

## Title Brand Information

SOURCE: NMVTIS

BRAND CATEGORY

Clear ?	<input checked="" type="checkbox"/> No Brand Reported
Flood damage ?	<input checked="" type="checkbox"/> No Brand Reported
Fire damage ?	<input checked="" type="checkbox"/> No Brand Reported
Hail damage ?	<input checked="" type="checkbox"/> No Brand Reported
Salt water damage ?	<input checked="" type="checkbox"/> No Brand Reported
Vandalism ?	<input checked="" type="checkbox"/> No Brand Reported
Kit ?	<input checked="" type="checkbox"/> No Brand Reported
Dismantled ?	<input checked="" type="checkbox"/> No Brand Reported
Junk ?	<input checked="" type="checkbox"/> No Brand Reported
Rebuilt ?	<input checked="" type="checkbox"/> No Brand Reported
Reconstructed ?	<input checked="" type="checkbox"/> No Brand Reported
Salvage ?	<input checked="" type="checkbox"/> No Brand Reported



Test Vehicle ?	<input checked="" type="radio"/> No Brand Reported
Refurbished ?	<input checked="" type="radio"/> No Brand Reported
Collision ?	<input checked="" type="radio"/> No Brand Reported
Reserved ?	<input checked="" type="radio"/> No Brand Reported
Salvage Retention ?	<input checked="" type="radio"/> No Brand Reported
Prior Tax ?	<input checked="" type="radio"/> No Brand Reported
Prior Police ?	<input checked="" type="radio"/> No Brand Reported
Original Tax ?	<input checked="" type="radio"/> No Brand Reported
Original Police ?	<input checked="" type="radio"/> No Brand Reported
Remanufactured ?	<input checked="" type="radio"/> No Brand Reported
Gray Market ?	<input checked="" type="radio"/> No Brand Reported
Warranty Return ?	<input checked="" type="radio"/> No Brand Reported
Antique ?	<input checked="" type="radio"/> No Brand Reported
Classic ?	<input checked="" type="radio"/> No Brand Reported
Agricultural Vehicle ?	<input checked="" type="radio"/> No Brand Reported
Logging Vehicle ?	<input checked="" type="radio"/> No Brand Reported
Street Rod ?	<input checked="" type="radio"/> No Brand Reported

"Vehicle Contains Reissued VIN" ?	<input checked="" type="radio"/> No Brand Reported
Replica ?	<input checked="" type="radio"/> No Brand Reported
Totaled ?	<input checked="" type="radio"/> No Brand Reported
Owner Retained ?	<input checked="" type="radio"/> No Brand Reported
Bond Posted ?	<input checked="" type="radio"/> No Brand Reported
Memorandum Copy ?	<input checked="" type="radio"/> No Brand Reported
Parts Only ?	<input checked="" type="radio"/> No Brand Reported
Recovered Theft ?	<input checked="" type="radio"/> No Brand Reported
Undisclosed Lien ?	<input checked="" type="radio"/> No Brand Reported
"Prior Owner Retained" ?	<input checked="" type="radio"/> No Brand Reported
"Vehicle Non-conformity Uncorrected" ?	<input checked="" type="radio"/> No Brand Reported
"Vehicle Non-conformity Corrected" ?	<input checked="" type="radio"/> No Brand Reported
"Vehicle Safety Defect Uncorrected" ?	<input checked="" type="radio"/> No Brand Reported
"Vehicle Safety Defect Corrected" ?	<input checked="" type="radio"/> No Brand Reported
"VIN replaced by a new state assigned VIN" ?	<input checked="" type="radio"/> No Brand Reported
Gray Market ?	<input checked="" type="radio"/> No Brand Reported
Gray Market ?	<input checked="" type="radio"/> No Brand Reported

Manufacturer Buy ?	<input checked="" type="checkbox"/> No Brand Reported
Former Rental ?	<input checked="" type="checkbox"/> No Brand Reported
Salvage--Stolen ?	<input checked="" type="checkbox"/> No Brand Reported
"Salvage--Reasons Other Than Damage or Stolen" ?	<input checked="" type="checkbox"/> No Brand Reported
Disclosed Damage ?	<input checked="" type="checkbox"/> No Brand Reported
Prior Non- ?	<input checked="" type="checkbox"/> No Brand Reported
Export only vehicle ?	<input checked="" type="checkbox"/> No Brand Reported
Crushed ?	<input checked="" type="checkbox"/> No Brand Reported
Hazardous substance ?	<input checked="" type="checkbox"/> No Brand Reported
Actual ?	<input checked="" type="checkbox"/> No Brand Reported
Not Actual ?	<input checked="" type="checkbox"/> No Brand Reported
Not Actual ?	<input checked="" type="checkbox"/> No Brand Reported
"Exempt from Odometer Disclosure" ?	<input checked="" type="checkbox"/> No Brand Reported
"Exceeds Mechanical Limits" ?	<input checked="" type="checkbox"/> No Brand Reported
"Odometer may be Altered" ?	<input checked="" type="checkbox"/> No Brand Reported
Odometer Replaced ?	<input checked="" type="checkbox"/> No Brand Reported
"Reading at Time of Renewal" ?	<input checked="" type="checkbox"/> No Brand Reported

"Odometer Discrepancy" ?  No Brand Reported

Call Title Division ?  No Brand Reported

"Rectify Previous Exceeds Mechanical Limits Brand" ?  No Brand Reported

Pending Junk ?  No Brand Reported

Junk Automobile - ?  No Brand Reported

## Lien / Impound / Thief Records

SOURCE: NVS

No Lien, Impound or Export Records Found

## Detailed History

Clean Records

## Recalls

SOURCE: NHTSA

**Report** Feb 08 2006

**Receipt Date:**

**Recall No** 06V038000

**Component(s):** SERVICE BRAKES, HYDRAULIC:ANTILOCK/TRACTION

CONTROL/ELECTRONIC LIMITED SLIP:CONTROL  
UNIT/MODULE

SUMMARY

ON CERTAIN PICKUP TRUCKS EQUIPPED WITH FOUR-WHEEL ANTILOCK BRAKE SYSTEMS (ABS), THE ABS ELECTRONIC CONTROL UNIT (ECU) MAY CAUSE A LOSS OF FRONT TO REAR BRAKE BALANCE, AND THE REAR BRAKES COULD LOCK UP PREMATURELY DURING CERTAIN BRAKING CONDITIONS.

CONSEQUENCE

THIS COULD RESULT IN A LOSS OF VEHICLE CONTROL AND CAUSE A CRASH WITHOUT WARNING.

REMEDY

DEALERS WILL REPLACE THE ABS ECU. THE RECALL IS EXPECTED TO BEGIN DURING THE WEEK OF JULY 17, 2006. OWNERS MAY CONTACT DAIMLERCHRYSLER AT 1-800-853-1403.

NOTES

DAIMLERCHRYSLER RECALL NO. F05. (MITSUBISHI RECALL NO. SR-06-003). CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

<b>Report Receipt Date:</b>	Feb 08 2006
<b>Recall No</b>	06V039000
<b>Component(s):</b>	VISIBILITY:WINDSHIELD WIPER/WASHER:SWITCH/WIRING

## SUMMARY

ON CERTAIN PICKUP TRUCKS AND SPORT UTILITY VEHICLES, A STATIC ELECTRICITY SPARK BETWEEN THE OPERATOR AND THE VEHICLE CAN CAUSE THE TURN SIGNAL, HEADLAMPS OR WINDSHIELD WIPERS TO MALFUNCTION WITHOUT WARNING.

## CONSEQUENCE

THIS CAN IMPAIR THE DRIVER'S VISION AND RESULT IN A CRASH.

## REMEDY

DEALERS WILL RE-FLASH THE INSTRUMENT CLUSTER. THE RECALL BEGAN ON MARCH 6, 2006. OWNERS MAY CONTACT DAIMLERCHRYSLER AT 1-800-853-1403.

## NOTES

DAIMLERCHRYSLER RECALL NO. F08. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

<b>Report Receipt Date:</b>	Apr 06 2009
<b>Recall No</b>	09E012000
<b>Component(s):</b>	EXTERIOR LIGHTING

## SUMMARY

SABERSPORT IS RECALLING 16,270 COMBINATION CORNER AND BUMPER LAMP ASSEMBLIES OF VARIOUS PART NUMBERS SOLD FOR USE AS AFTERMARKET EQUIPMENT FOR VARIOUS PASSENGER VEHICLES. THESE HEADLAMPS FAIL TO CONFORM TO THE REQUIREMENTS OF

FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 108, "LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT." THESE LAMPS DO NOT CONTAIN THE REQUIRED AMBER SIDE REFLECTORS.

#### CONSEQUENCE

DECREASED LIGHTING VISIBILITY MAY RESULT IN A VEHICLE CRASH.

#### REMEDY

SABERSPORT WILL NOTIFY OWNERS AND OFFER A FULL REFUND FOR THE NONCOMPLIANT COMBINATION LAMPS. THE SAFETY RECALL BEGAN ON MAY 11, 2009. OWNERS MAY CONTACT SABERSPORT AT 1-909-598-7589.

#### NOTES

THIS RECALL ONLY PERTAINS TO AFTERMARKET REPLACEMENT EQUIPMENT AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON VEHICLES PRODUCED BY THE VEHICLE MANUFACTURER. IN ORDER TO DETERMINE IF YOUR AFTERMARKET LAMP ASSEMBLY IS AFFECTED BY THIS NONCOMPLIANCE, PLEASE REVIEW THE LIST OF MODEL NUMBERS PROVIDED TO US BY SABERSPORT. THE LIST CAN BE FOUND UNDER "DOCUMENT SEARCH" LOCATED AT THE BOTTOM OF YOUR SCREEN. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) ([HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov)).

**Report Receipt Date:** Dec 15 2014

**Recall No** 14V795000

**Component(s):** ELECTRICAL SYSTEM:IGNITION:SWITCH

## SUMMARY

Chrysler Group LLC (Chrysler) is recalling certain model year 2006-2007 Dodge Ram 1500, 2500, 3500, Dakota, and 2006 Mitsubishi Raider vehicles manufactured July 1, 2005, to July 31, 2006 with manual transmissions. The return springs in the clutch ignition interlock switch may break.

## CONSEQUENCE

Broken springs can result in a no-start condition, or cause unintended movement when the ignition is cranked, increasing the risk of a vehicle crash.

## REMEDY

Chrysler will notify owners, and dealers will replace the clutch ignition interlock switch, free of charge. The recall began on March 27, 2015. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is P80.

## NOTES

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

<b>Report Receipt Date:</b>	May 26 2015
<b>Recall No</b>	15V313000
<b>Component(s):</b>	AIR BAGS:FRONTAL:DRIVER SIDE:INFLATOR MODULE

## SUMMARY



Chrysler (FCA US LLC) is recalling certain model year 2005-2009 Dodge Ram 2500, 2004-2008 Dodge Ram 1500 and Durango, 2006-2009 Dodge Ram 3500, 2008-2010 Dodge Ram 4500 and 5500, 2007-2008 Chrysler Aspen, 2005-2010 Chrysler 300, 300C, 300S, and SRT8, 2006-2010 Dodge Charger, 2005-2008 Magnum, 2005-2011 Dodge Dakota, and 2006-2009 Mitsubishi Raider vehicles. The affected vehicles are equipped with a dual-stage driver frontal air bag that may be susceptible to moisture intrusion which, over time, could cause the inflator to rupture.

#### CONSEQUENCE

In the event of a crash necessitating deployment of the driver's frontal air bag, the inflator could rupture with metal fragments striking the driver or other occupants resulting in serious injury or death.

#### REMEDY

Chrysler will notify the affected Chrysler and Dodge owners and Mitsubishi will notify the affected Raider owners. Dealers will replace the driver's frontal air bag inflator, free of charge. The recall began for Chrysler on June 8, 2015. The recall for Mitsubishi started on June 24, 2015. Chrysler and Dodge owners may contact Chrysler customer service at 1-800-853-1403. Mitsubishi owners may call 1-888-648-7820.

Chrysler's number for this recall is R25. Note: This recall supersedes recall 14V817 in its entirety. Vehicles that have had their driver side frontal air bag replaced previously need to have their air bag replaced under this recall as well.

#### NOTES

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

**Report Receipt**

May 23 2016

**Date:**

**Recall No** 16V352000

**Component(s):** AIR BAGS:FRONTAL:PASSENGER SIDE:INFLATOR  
MODULE

#### SUMMARY

Chrysler (FCA US LLC) expanded the affected population to include 73,712 2005-2009 RAM 2500 trucks produced at the St. Louis North Assembly Plant. With this change, Chrysler is recalling certain model year 2004-2008 RAM 1500, 2005-2009 RAM 2500, 2006-2009 RAM 3500, 2007-2010 RAM 3500 Cab Chassis, 2008-2010 RAM 4500 and 5500 Cab Chassis, 2004-2009 Dodge Durango, 2007-2009 Chrysler Aspen, 2007-2012 Jeep Wrangler, 2008-2012 Dodge Challenger, 2005-2008 Dodge Magnum, 2005-2012 Chrysler 300, 2006-2012 Dodge Charger, 2005-2011 Dodge Dakota, and 2006-2009 Mitsubishi Raider vehicles originally sold, or ever registered, in AL, CA, FL, GA, HI, LA, MS, SC, TX, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands, or "Zone A." Additionally, unless included in "Zone A" above, Chrysler is also recalling 2004-2008 RAM 1500, 2005-2009 RAM 2500, 2006-2009 RAM 3500, 2007-2009 RAM 3500 Cab Chassis, 2008-2009 RAM 4500 and 5500 Cab Chassis, 2004-2009 Dodge Durango, 2007-2009 Chrysler Aspen, 2007-2009 Jeep Wrangler, 2008-2009 Dodge Challenger, 2005-2008 Dodge Magnum, 2005-2009 Chrysler 300, 2006-2009 Dodge Charger, 2005-2009 Dodge Dakota and 2006-2009 Mitsubishi Raider vehicles originally sold, or ever registered, in AZ, AR, DE, Washington D.C., IL, IN, KS, KY, MD, MO, NE, NV, NJ, NM, NC, OH, OK, PA, TN, VA, and WV, or "Zone B." Lastly, unless included in "Zone A" or "Zone B" above, Chrysler is recalling certain 2005-2008 RAM 2500, 2006-2008 RAM 3500, 2007-2008 RAM 3500 Cab Chassis, 2008 RAM 4500 and 5500 Cab Chassis, 2004-2008 Dodge Durango, 2007-2008 Chrysler Aspen, 2007-2008 Jeep Wrangler, 2008 Dodge Challenger, 2005-2008 Dodge Magnum, 2005-2008 Chrysler 300, 2006-2008 Dodge Charger, 2005-2008 Dodge Dakota, and 2006-2008 Mitsubishi Raider vehicles originally sold, or registered, in AK, CO, CT, ID, IA, ME, MA, MI, MN, MT, NH, NY, ND, OR, RI, SD, UT, VT, WA, WI, and WY.

## CONSEQUENCE

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules, and used as original equipment or replacement equipment. These inflators may rupture due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling. An inflator rupture may result in metal fragments striking the vehicle occupants resulting in serious injury or death.


## REMEDY

Chrysler will notify the Chrysler, Dodge, Jeep and RAM owners. Mitsubishi owners will be notified by their company. Dealers will replace the passenger frontal air bag inflator, free of charge. The recall began on March 27, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is S43. Note: This recall supersedes recall 14V-7700.

## NOTES

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

## **NMVTIS Consumer Access Product Disclaimer**



The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMVTIS is intended to serve as a reliable source of title and brand ([https://vehiclehistory.bja.ojp.gov/nmvtis\\_glossary](https://vehiclehistory.bja.ojp.gov/nmvtis_glossary)) history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because some states ([https://vehiclehistory.bja.ojp.gov/nmvtis\\_states](https://vehiclehistory.bja.ojp.gov/nmvtis_states)) are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, consumers are **strongly encouraged to also obtain an independent vehicle inspection** to ensure the vehicle does not have hidden damage. The Approved NMVTIS Data Providers ([https://vehiclehistory.bja.ojp.gov/nmvtis\\_vehiclehistory](https://vehiclehistory.bja.ojp.gov/nmvtis_vehiclehistory)) (look for the NMVTIS logo) can include vehicle condition data from sources other than NMVTIS.

NMVTIS data **INCLUDES** (as available by those entities required to report to the System):

- Information from participating ([https://vehiclehistory.bja.ojp.gov/nmvtis\\_states](https://vehiclehistory.bja.ojp.gov/nmvtis_states)) state motor vehicle titling agencies.
- Information on automobiles, buses, trucks, motorcycles, recreational

vehicles, motor homes, and tractors. NMVTIS may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time.

- Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.
- Most recent odometer reading in the state's title record.
- Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.
- Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Consumers are advised to visit [vehiclehistory.bja.ojp.gov](https://vehiclehistory.bja.ojp.gov) (<https://vehiclehistory.bja.ojp.gov>) for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies.

VEHICLE MAKE: Dodge  
MODEL OR SERIES: Dakota  
VEHICLE STYLE: Truck  
YEAR: 2006  
VEHICLE ACCESS CODE (VAC): 08337-9974  
BODY COLOR: M. Grey  
FUEL: Gas  
VEHICLE IDENTIFICATION NUMBER (VIN): 1D7HW48N16S637751  
VEHICLE STATUS: active  
SPECIAL CONDITIONS:

**SECTION 1**

LICENCE PLATE NO. CMS8149	CLASS 3	LICENCED MASS kg	VEHICLE STATUS active
EXPIRY DATE (Y/M/D) 2024/03/31	TYPE OF OPERATION Passenger		
REGISTRATION NUMBER R289854408	IF LEASED VEHICLE, LEASING COMPANY NAME AND MVID		

MOTOR HOME SUPERSTRUCTURE / SECONDARY PARTS DESCRIPTION  
MAKE: MODEL OR SERIES:

NAME & ADDRESS OF REGISTRANT(S)  
TYPE: INDIVIDUAL  
CLIENTS MVID: 0902-91717

LICENCE PLATE NO. CMS8149	CLASS 3
EXPIRY DATE (Y/M/D) 2024/03/31	

BARTEK BRYN RYELIN  
RR 1 SITE 436 BOX 2 COMP 2  
DRAYTON VALLEY AB T7A 2A1



This Certificate to be signed on the back by the registrant(s) and presented on demand of a Peace Officer.

REGISTRY AGENT: 0218-34338  
VALIDATED: 2023/03/24

ISSUED 2023/03/24  
MAXIMUM SERVICE AMOUNT

\$\*\*\*\*\*93.00