

Address: White Lake Colony

...rd, AB

Vehicle VIN: #1  
YMG 244749

Date work Begins April 3/23

Odometer 8461683 hrs

Section II

Complaint: Field ready inspection

Complaint and Labor Instructions

Labour Hours Date:

Labour Instructions: Completed full inspection + run machine  
Repair list below; Ran all machine functions.  
\* All functions worked at time of inspection.

Section III

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price	Total Labour Hours	
					Section IV	Outside Repairs
			SHOP SUPPLIES			
1			Change Air, Hydraulic and oil filters. Crank case breather should be changed. Clean out plugged cab air filter housing. Shorten both unloading auger chains. Tighten clean grain chain. Install new chopper blades. Fix hanging stationary knives. Small Hyd leak on 3015 float pressure gauge. RH signal light not working on 3016. Processor cover missing. Rear straw chute bolts loose. RAS blade end rubbers worn out.			

Section IV

Complaint:

Vendor's Name:

Invoice #:

FPO#:

Price

Parts

Labour

Tax

Total

Work Order Totals

Total Shop Labour Cost (Sect. II)

Total Parts & Supplies Cost (Sect. III)

Total Outside Repairs Cost (Sect. IV)

Grand Total

Work Completed by: Bf DH  
Signature

Picked up by: \_\_\_\_\_  
Signature

April 3/23 # \_\_\_\_\_

Date Work Completed \_\_\_\_\_

Work Order #: \_\_\_\_\_

Total Parts & Supplies Cost