

Date in Shop

Harvesting 940-886-6434 119 12st N Nobleford, AB

Section I

Customer: *White Lake Colony*
Address:

Vehicle VIN: #2
YMG244760

Date work Begins *April 3/23*

Odometer *826/633 hrs*

Section II

Complaint: *Field Ready Inspection*

Complaint and Labor Instructions

Labour Hours Date:

Labour Instructions: *Completed full inspection + run machine
Repair 1st below. Ran all machine functions.
* All functions worked at time of inspection.*

Section III

Parts and Supplies

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price	Total Labour Hours
			Change air, hydraulic and oil filters	SHOP SUPPLIES	
			Crank case breather should be changed. Clean out cab air filter housing. Install new chopper blades. Fix hanging stationary knives. Both unloading chains need a link removed.		
			Clean grain chain loose. Flat tire on 3016. Auger finger cover missing on 3016 + Broken fingers. Shaker frame rollers not adjusted close enough to frame. Straw chute RH panel bent. RAS blade tip rubbers worn out. Hyd oil low.		
			<i>Pto oil low.</i>		
				Total Parts & Supplies Cost	

Section IV

Complaint: _____

Vendor's Name: _____

Invoice #: _____ FPO#: _____

Price: _____ Outside Repairs: _____

Parts: _____ Labour: _____ Tax: _____ Total: _____

Work Order Totals

Total Shop Labour Cost (Sect. II) _____

Total Parts & Supplies Cost (Sect. III) _____

Total Outside Repairs Cost (Sect. IV) _____

Grand Total _____

Work Completed by: *B/DH* Signature _____ Picked up by: _____ Signature _____

Date Work Completed *April 3/23* # _____ Work Order #: _____