

Date in Shop

...harvesting 940-886-6434 119 12st N Nobleford, AB

Section I

Customer: *Whitelake Colony*
Address:

Vehicle VIN: #1
333655-18
Date work Begins *April 5/23*

Odometer *N/A*

Section II

Complaint: *Inspection*

Complaint and Labor Instructions

Labour Hours Date:

Labour Instructions: *Completed inspection, list below:*

Section III

Parts and Supplies

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price
			SHOP SUPPLIES	
			- Adjust all chains + belts. Feeder house lock bent.	
			Both RH light brackets + lights broke. Replace missing	
			auger fingers. Set tire pressures. Rubber seal on LA25 adapter	
			coming out of hold down, loosen + reinstall. RH outside skid	
			shoe worn out. Straighten reel end fingers (lodged crop fingers)	
			grease Grease unit.	
			* Sickle bar worn out	
			* Guards worn.	

Total Labour Hours		Price
Section IV	Outside Repairs	
Complaint:	Parts	
	Labour	
Vendor's Name:	Tax	
Invoice #:	FPO#:	Total
Work Order Totals		
Total Shop Labour Cost (Sect. II)		
Total Parts & Supplies Cost (Sect. III)		
Total Outside Repairs Cost (Sect. IV)		
Grand Total		
Work Completed by:	Picked up by:	
<i>B. J. D. H.</i>		
Signature	Signature	
<i>April 5/23</i>	#	
Date Work Completed	Work Order #:	

Total Parts & Supplies Cost