

## Inspection Summary

FLEETEQUIPMENT 0
81307
Unit has job boxes and tommy gate.

## Observations / Results

Inspected	Acceptable?	Comments
Colour - Exterior	White	
Colour - Interior	Grey	
Wheel Drive	2x4	
Body Style	2 Door	
Engine Size		
Damage	No	
Declaration over		
\$2,000		
Estimated		
Damage Amount		
Body Condition	Fair	
Body Damage	No	
Mechanical	Poor	
Transmission	Yes	
Operable		
Interior	Fair	
Interior Dirty	Yes	
Tires	Fair	
Windshield	Chipped	
Jack Assembly	Yes	
Spare Tire		
Check all Vehicle		
Options that		
apply		

Hours or		155444	
Odometer	(Blank		
if N/A)			

Add Signature and Date Fields Here?

## Work Order Details

Assigned To:SINCLAIR, TAYLOR	Location:
Supervisor:	81307
Work Status: WORK IN PROGRESS	[Instructions: [WOInstructions]Accomplishment Units to be recorded as Requested By: Project Name:
Scheduled Start: 4/19/2024	Account: 7401Receiving Account (IPTs): Asset
9:45:05 AM	Details:
Scheduled Finish: 4/19/2024	
9:45:05 AM	