



TRANS·WEST
AUTOMOTIVE APPRAISERS (ALBERTA) LTD.

PHONE: (780) 453 – 5624 PO Box 25558, Edmonton, Alberta T5T 7E7 Fax: (780) 454-9757

info@transwestappr.com

Date: June 2, 2019

Appraised By: Brian Acheson

Owner(s):

Address:

Phone: Res:

Cell:

Bus:

e-mail:

Insurance Company / Agent:

N/A

VEHICLE SPECIFICATIONS

Manufacture Date 11/1987

Year: 1988

Make: Ford

Model: Bronco – Eddie Bauer

Body Style: 2 Door – Utility - 4X4

Serial Number: 1MEU15N3JLA27192

License Plate: 1-133 (Alberta)

Odometer: 286,320 km.

Mileage since restoration:

Remarks: This vehicle has fresh paint along with new tires and alloy wheels. The owner is still working on the interior. The suspension and mechanical have all been redone. The paint work is excellent as the black finish would show any flaws. The vehicle is very well done..

BODY

Body Manufacture:	Ford Motor Company
Body Style:	Two Door – Utility – Very Good Condition
Body Material:	Factory – Steel – Very Good Condition
Body Modifications:	N/A
Front Bumper:	Factory – Chrome – Steel – New – Very Good Condition
Front Valance:	Factory – Straight – Painted – Very Good Condition
Grille:	Factory – Plastic – No Cracks
Hood:	Factory – Steel – Rust Free – Good Condition
Headlamps and Parklamps:	Aero – Clean – No Cracks – Very Good Condition
Left Front Fender:	Factory – Steel – Rust Free – Very Good Condition
Right Front Fender:	Factory – Steel – Rust Free – Very Good Condition
Left Inner Fender:	Factory – Steel – Rust Free – Very Good Condition
Right Inner Fender:	Factory – Steel – Rust Free – Very Good Condition
Left Front Air Deflector:	Factory – Very Good Condition
Right Front Air Deflector:	Factory – Very Good Condition
Left Front Door:	Factory – Steel – Rust Free – Very Good Condition
Right Front Door:	Factory – Steel – Rust Free – Very Good Condition
Left Rear Door:	N/A

Right Rear Door:	N/A
Left Rocker Panel:	Factory – Steel – Rust Free – Very Good Condition
Right Rocker Panel:	Factory – Steel – Rust Free – Very Good Condition
Left Rear Fender:	N/A
Right Rear Fender:	N/A
Right Rear Box Panel:	Factory – Steel – Rust Free – Very Good Condition
Left Rear Box Panel:	Factory – Steel – Rust Free – Very Good Condition
Roof:	Factory – Steel – Rust Free – Rear Fiberglas - Very Good Condition
Rear Gate:	Factory – Steel – Rust Free –Straight - Very Good Condition
Rear Taillights:	Factory – Good Color – No Cracks – Good Condition
Rear Bumper:	New – Chrome – Step – Steel - Straight
Rear Valance:	Factory – Painted – Good Condition
Body Shell:	Rust Free – Clean - Straight
Front Box Panel:	N/A
Tailgate:	Half Gate – Half Glass – Straight – Works Well
Box Floor:	Rust Free – Straight – Good Condition
Left Running Board:	Pipe Style – Good Condition
Right Running Board:	Pipe Style – Good Condition
Exterior Trim:	Eddie Bauer Package – Complete & Intact

Emblems: Factory – Eddie Bauer Package – Good Condition

Filler Door: Side Fill – Painted – Good Condition

Fuel Tank: Underslung – Clean – Good Condition

Rear Wheel Tubs: Stock – Rust Free – Very Good Condition

Underbody: Clean

Bodywork Done By: Owner – Precision Autobody in Whitecourt

Paint Color and Type: Black – Base / Clear – Excellent Condition

Painted By: Owner – Precision Autobody in Whitecourt

Graphic and Murals: N/A

Pin striping: N/A

Comments: This vehicle has fresh paint and the bodywork is excellent. The black shows the flaws very easily – but the body is good and straight. The vehicle is well done. The owner has put mud flaps on the front and rear to protect the paint.

INTERIOR

Upholstery By:	Ford Motor Company
Material and Color:	Red – Cloth & Vinyl – Good Condition
Carpet:	Factory – Red – Cloth
Front Seats:	Factory – Bucket – Red – Very Good Condition
Left Door Panel:	Factory – Cloth & Vinyl – Good Condition
Right Door Panel:	Factory – Cloth & Vinyl – Good Condition
Left Rear Panel:	Factory – Cloth & Vinyl – Good Condition
Right Rear Panel:	Factory – Cloth & Vinyl – Good Condition
Headliner:	Factory – Cloth – Good Condition
Sun Visors:	Factory – Cloth – Good Condition
Dashboard:	Factory - No Holes – No Cracks – Good Condition
Dash Trim:	Eddie Bauer Package
Interior Trim:	Complete – could use some cleanup
Rear Cab Panel:	N/A
Gauges and Inserts:	Factory – Works Well – Very Good Condition
Steering Wheel:	Factory – Controls in Wheel – No Cracks
Steering Column:	Tilt – Good Condition
Rear View Mirror:	Factory – Day & Night

Exterior Mirror:	Left & Right Sides – Stainless – Good Condition
Seat Belts:	Factory – Three Point – Good Condition
Stereo and Speakers:	Factory – Dual Speakers
Air Conditioning:	Factory – Works Well – Good Air
Heater:	Factory – Works Well – Good Heat
Cruise Control:	Factory – Works Well
Clock Accessories:	N/A
Rear Defroster:	N/A
Antenna:	Factory – Good Condition
Door Locks:	Power – Good Condition
Trunk:	N/A
Keyless Entry:	N/A
Wiring:	Factory – Good Condition
Windshield:	Glass – No Rock Damage – Good Condition
Left Front Door Glass:	Factory – Light Tint – No Chips – Good Condition
Right Front Door Glass:	Factory – Light Tint – No Chips – Good Condition
Left Rear Door Glass:	Factory – Light Tint – No Chips – Good Condition
Right Rear Door Glass:	Factory – Light Tint – No Chips – Good Condition
Rear Window:	Deep Tint – No Cracks – No Scratches

Window Seals and Felts: Good Condition

Door and/or Body Weather-Strips: Factory – Good Condition

Comments: The interior needs some minor work to bring it back to top condition .

CHASSIS

Frame / Manufacturer: Ford Motor Company

Wheel Base: 104 inch Wheel Base

Modifications: N/A

Paint Color and Type: Black – Good Condition

Undercoated: N/A

Front Suspension: 4X4 – Independent – New Shocks – Very Good Condition

Rear Suspension: Leaf Springs - New Shocks

Rear Differential: Ford 9” – No Leaks or Noise

Front Brakes: Disc – New – Very Good Condition

Rear Brakes: Drum – New -- Very Good Condition

Master Cylinder and Booster: Dual Master – c//w Power Booster

Steering Box: Power Steering – No Leeks - Good Condition

Front Wheel / Make / Size: 15” Alloy -- Excellent Condiition

Rear Wheels / Make / Size: 15” Alloy -- Excellent Condiition

Front Tires / Make / Size: M&S – 35 x 12.50 R15LT – Bog Foot XT - New

Rear Tires / Make / Size: M&S – 35 x 12.50 R15LT – Bog Foot XT - New

Comments: The owner has gone through the suspension and now it is in excellent condition.

ENGINE

Make:	Ford – V-8 – Runs Great
Displacement:	5.0 – V-8 – Very Good Condition
Modifications:	N/A
Rebuilt By:	N/A
Cylinder Heads:	Cast Iron – Good Condition
Valve Covers:	Factory - Aluminum - Good Condition
Intake Manifold:	Factory - Aluminum - Good Condition
Air Cleaner:	Factory – EFi - Good Condition
Exhaust Manifold:	Factory – Cast Iron
Exhaust Pipes and Mufflers:	Dual - Very good Condition
Ignition and Distributor:	Electronic Fuel Injection – Very Good Condition
Wiring Harness:	No Cracks – Very Good Condition
Engine Belts & Hoses:	New – Very Good Condition
Radiator:	Factory – No Leaks - Good Condition
Battery and Cables:	New Battery & Cables
Engine Compartment:	Correct – Could use a good cleaning

TRANSMISSION

Year and Make: 1988 Ford Bronco

Model: Automatic

Modifications: N/A

Rebuilt By: Unknown

Converter: Very Good Condition

Shifter: Factory – Works Well

Console: Factory - Clean

Transmission Cooler: Factory – No Leaks



Driveshaft Manufacture: Factory – Front & Rear – Good Condition

Universal Joints: New


Transfer Case: Rebuilt – Very Good Condition




Comments: The transmission fluid is clean with good color.













Car Pricing | Change Make | Change Year & Model | Change ZIP | Price with Options | Values

1988 Ford Bronco Prices and Values

2 Door Utility 4X4

Values

	Original MSRP	Low Retail	Average Retail	High Retail
Base Price	\$15,397	\$2,375	\$4,725	\$7,675
Options (Add)				
Total Price	\$15,397	\$2,375	\$4,725	\$7,675

Research another car

US FUNDS
 - *FRESH PAINT*
 - *8001E & 8052A* *50015*
 - *FULL LEAD.*
VALUE \$14,900 ea
in Canada
fun

Value Type Definitions

Original MSRP

Manufacturer Suggested Retail Price

Low Retail Value

This vehicle would be in mechanically functional condition, needing only minor reconditioning. The exterior paint, trim and interior would show normal wear, needing only minor reconditioning. May also be a deteriorated restoration or a very poor amateur restoration. Most usable 'as-is'. This column does **not** represent a 'parts car' or a non-running vehicle.

Note: Some of the vehicles in this publication could be considered 'Daily Drivers' and are not valued as a classic vehicle. When determining a value for a daily driver, it is recommended that the subscriber use the low retail value.

Average Retail Value

This vehicle would be in good condition overall. It could be an older restoration or a well-maintained original vehicle. Completely operable. The exterior paint, trim and mechanics are presentable and serviceable inside and out. A "20-footer".

High Retail Value

This vehicle would be in excellent condition overall. It could be a completely restored or an extremely well-maintained original vehicle showing very minimal wear. The exterior paint, trim and mechanics are not in need of reconditioning. The interior would be in excellent condition. Some vehicles may be considered "matching numbers" vehicles.

Note: This column does **not** represent a "100 Point" or "# 1" vehicle*.

* A "100 Point" or "# 1" vehicle is not driven. It would generally be in a museum or transported in an enclosed trailer to concours judging and car shows. This type of car would be stored in a climate regulated facility.

APPRAISAL ESTIMATE

Vehicle: 1988 Ford Bronco Eddie Bauer Utility 4 X 4

Serial Number: 1FMEU15N3JLA27192

For the purpose of Insuring the Vehicle the following information is relevant. To the best of our knowledge and ability we state the estimate value of this vehicle is:

\$ 14,900.00 in Canadian Funds

The estimate is based on a combination of current market values throughout North America and the individual merits of the vehicle. It also takes into consideration the cost to replace the vehicle should a total loss occur.

The estimate assumes that the vehicle remains in its current condition. The collector vehicle market has gone through value cycles and changes so it is advisable to have it re-evaluated periodically (3 years) to reflect the changing market and the condition of the vehicle.

Dated: June 2, 2019

We certify that Trans West Auto Appraisers, an Alberta Registered Company, has no interest in the vehicle whatsoever.

Vehicle Condition Rating: Scale of 1 to 6

1 – Excellent **2 – Fine** 3 – Very Good 4 – Good 5 – Restorable 6 – Parts Car

Overall Condition rating of this vehicle is: **2 – Fine**

Appraiser Signature:

Trans West Automotive Appraisers is the oldest licensed appraisal firm in Alberta. We have been in business for over 35 years.

The staff at **Trans West Automotive Appraisals** are all certified. Within our staff we have members holding Provincial and Inter-Provincial mechanical licenses as well as certificates in brake and steering. We have appraisers with a vast amount of experience. In addition we have appraisers that specialize in heavy equipment, farm equipment and recreational vehicles.

We are an **Alberta Registered Company** that has an office that has been in the business for over 35 years. **Trans West Appraisers** holds a **valid Business License**.

Members of our staff have built and own specialized vehicles.

Staff also keep current with I-Car courses and attending automotive conferences and shows to keep up with current changes in vehicles.

Trans West Automotive Appraisers

- Provincial and Inter-Provincial Licenses
- Brake and Steering specialists
- I-Car Courses
- Attends SEMA yearly
- Attends Barrett Jackson
- Appraisal courses at S.A.I.T.
- Taught Insurance courses
- Hosts full Car Show yearly

Trans West Automotive completes appraisals for

- Insurance Companies
- Museums
- Auctions
- Charities / i.e. Hope Mission
- City of Edmonton
- Estates / Court Settle Values / Disputes

We have an extensive amount of resources to assist in determining values on all types of vehicles such as NADA Guide, Old Car Guide, Gold Book, Red Book and Resource Library.