


SIEVE ANALYSIS REPORT

TEST NO. SA23

PROJECT CONKLIN PROJECT PROJECT NO. PP LOCATION Conklin, AB



Reporting of these test results constitutes a testing service only. Engineering interpretation or evaluation of test results is provided only on written request.