



Automobile Insurance Motor Vehicle Inspection Report

This report is for insurance underwriting purposes only.

The Alberta Superintendent of Insurance has approved this form pursuant to section 803 of the *Insurance Act*.

This report is required only if the vehicle is 12 years or older and must be completed by a Certified Automotive Technician.

Vehicle Owner's Name		Insurance Company	
Insurance Broker			Policy Number
Vehicle Year 2013	Make Ford F150	Model	VIN 1FTVW1ET3DKE63841

This section is to be completed by a Certified Automotive Technician.

Steering	Roadworthy	Reject	Comments
Steering Box/Rack	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Struts/Shocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Front Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Tie Rod Ends	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Electrical System	Roadworthy	Reject	Comments
Head Lamp/Tail Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Stop Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Signal Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windshield Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Tires	Roadworthy	Reject	Comments
Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brakes	Roadworthy	Reject	Comments
Front Lining or Drums	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Rear Lining or Drums	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Park	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brake Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brake Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
General Conditions	Roadworthy	Reject	Comments
Body Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Muffler/Exhaust	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Motor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Windshield	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Seat Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Is this vehicle roadworthy? Yes No Has the vehicle been altered for speed or performance? Yes No

Other Comments

Certified Automotive Technician Statement:

I certify that I have inspected and tested the motor vehicle described above and found it to be in the condition stated above.

Name of Automobile Repair Shop LV3 Mechanical		Address 718 9th Street	
City Fort Macleod	Province/Territory AB	Postal Code T0L 0Z0	Telephone Number 403 330 9460
Certified Automotive Technician's Name Lyndon Van Buren		Certified Automotive Technician's Certificate Number 105862A	
Date (yyyy-mm-dd) May 1 2026		Certified Automotive Technician's Signature 	

TOM & GERRY'S SERVICE

3617 9 AVE N
 LETHBRIDGE, AB. T1H 6G8
 Phone: (403)-328-7959 | Fax: (403)-327-2466
 www.tomandgerryservice.ca | service@tomandgerryservice.ca
 ** READY TO SERVE YOU AND YOUR CAR **

Invoice # 079384
 Original Est # 124083

Invoice

Balance Due: \$507.57

	2013 Ford - F-150 - XLT	Work Complete:	03-25-2026
	3.5L, V6 (213CI) VIN(T)	Service Advisor:	
Cellular:	VIN: 1FTVW1ET3 DKE63841	Customer ID:	18982
	Odometer: In 219,169	Printed Date:	04-06-2026
		License Plate:	AB

Type	Description	Part #	Qty	Sale	Total
PRE-PURCHASE INSPECTION					\$136.45

Labor	PERFORM PRE-PURCHASE INSPECTION PERFORMED PRE PURCHASE INSPECTION VEHICLE HAD TO BE BOOSTED TO GET IT INTO SHOP ENGINE HAS NOTICEABLE RATTLE TO IT, *DID NOT ROAD TEST DUE TO RATTLE* CHECK ENGINE LIGHT IS ON WINDSHIELD IS CRACKED BOTH LICENSE LIGHT/HOLDERS MISSING BOTH FOG LIGHT ASSY MISSING RECOMMEND NEW AIR FILTER ✓ ENGINE OIL LEVEL LOW ✓ TURBO OIL LINE LEAKING ON PASSENGER SIDE REAR CV JOINT ON FRONT DRIVE SHAFT WORN OUT ✓ FRONT BRAKES 2MM ✓ RIGHT LOWER BALL JOINT HAS MINOR PLAY * BATTERY FAILS LOAD TEST REAR SEATS ARE FOLDED UP AND WILL NOT RELEASE, CAN NOT CHECK REAR SEAT BELTS FRONT SWAY BAR BUSHINGS WORN OUT AND HAVE SPACERS ✓ THAT ARE WORN OUT REAR VIEW MIRROR IS MISSING			\$129.95
-------	---	--	--	----------

Parts: \$0.00 Labor: \$129.95 Tax: \$6.50 Total: \$136.45

DRIVEBAILITY					\$73.50
---------------------	--	--	--	--	----------------

Labor	CHECK FOR ENGINE LIGHT IS ON SCANNED FOR CODES P0016, CRANK SHAFT POSITION- CAM SHAFT POSITION CORRELATION BANK 1 SENSOR A P01217, ENGINE COOLANT OVERTEMP CONDITION ENGINE OVER SPEED CONDITION P0299, TURBO UNDER BOOST CONDITION P06B8, INTERNAL CONTROL MODULE NON-VOLATILE RANDOM ACCESS MEMORY ERROR P1285, CYLINDER HAD OVER TEMP CONDITION P1299, CYLINDER HEAD OVER TEMP PROTECTION ACTIVE SUSPECT TIMING CHAIN AND WATER PUMP FAILURE, RECOMMEND FORD DEALER FOR REPLACEMENT OF TIMING CHAIN AND PUMP			\$70.00
-------	--	--	--	---------

Parts: \$0.00 Labor: \$70.00 Tax: \$3.50 Total: \$73.50

BATTERY					\$283.45
----------------	--	--	--	--	-----------------

Labor	BATTERY - Remove & Replace - [Includes: Test.]			\$70.00
Part	BATTERY CCA 850 40 MO WARR PERS USE,18 MO COMM USE	MS65-1100	1.00	\$199.95

Parts: \$199.95 Labor: \$70.00 Tax: \$13.50 Total: \$283.45

Type	Description	Part #	Qty	Sale	Total
MIRROR AND SEAT					\$0.00
Labor	REPLACE REAR VIEW MIRROR AND FOLD DOWN REAR SEAT WINDSHIELD GLASS IS BROKEN AT MIRROR MOUNT- RECOMMEND GLASS SHOP FOR THIS REPAIR				\$0.00
	REAR SEAT HAS BEEN FOLDED DOWN- LATCH CABLES ARE PARTIALLY BROKEN BUT CAN BE USED TO FOLD SEAT				

Parts: \$0.00 Labor: \$0.00 Tax: \$0.00 Total: \$0.00

Order					\$14.18
Misc	Shop Supplies				\$13.50
Total:	\$14.18	Tax:	\$0.68		

G.S.T 135664472RT0001

I HEREBY ACKNOWLEDGE MY INDEBTNESS IN THE AMOUNT AS STATED ON INVOICE. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 DAYS PARTS AND LABOR . Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor	\$269.95
Parts	\$199.95
Shop Supplies	\$13.50
Subtotal	\$483.40
Taxes	\$24.17
Order Total:	\$507.57

Signature _____ Date _____ Time _____

	REQUIRES IMMEDIATE ATTENTION		
	MAY NEED FUTURE ATTENTION		CHECKED AND OKAY
LOAD TEST			
Engine Idle Quality	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Performance/Smooth Acceleration	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Engine Noise High/Low Speeds	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Transmission/Transaxle Noise	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Automatic Transmission Shift Points/Slippage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shift Interlock (Operation)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Axle Gear Noise/Vibration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Manual Transmission (Gear Change/Operation/No Grinding)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Clutch Operation (Smooth Engagement/Slippage/Chatter)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steering/Rack And Pinion/Steering Linkage Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steering Wheel Free Play/Centre	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brakes/Abs Effectiveness/Operation/Noise/No Pulling Or Pulsating) Note: Abs Can Pulsate Under Hard Braking	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cruise Control Operation (Including Resume)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gauge/Speedometer/Tachometer/Odometer/Oil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Body/Suspension (Performance/Noise/Rough Road Test)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR/EXTERIOR			
Head Lights, Tail Lights, Turn Signals, Brake Lights, Hazard Lights, Exterior Lamps, Licence Plate Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Windshield Washer/Wiper Operation, Wiper Blades	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield Condition: Cracks/Chips/Pitting	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mirrors/Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn Operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Windows & Locks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Conditioning And Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dash Warning Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Seat Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Defogger/Defrost (Operation)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Air Filter(Not All Models)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Back Up Camera (If Equipped)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


	REQUIRES IMMEDIATE ATTENTION		
	MAY NEED FUTURE ATTENTION		CHECKED AND OKAY
UNDER VEHICLE			
Shock Absorbers/Suspension/Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steering Box, Linkage, Ball Joints, Dust Covers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Muffler, Exhaust, Pipe/Mounts, Catalytic Converter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Lines, Hoses, Parking Cable & Adjustment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Shaft Boots, Constant Velocity Boots, U-Joints, Transmission Linkage (If Equipped)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Transmission, Differential, Transfer Case (Check Fluid Level, Fluid Condition And Fluid Leaks)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fluid Condition And Levels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Inspect Nuts And Bolts On Body And Chassis	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fuel System Fuel Pump Noise/Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
UNDERHOOD			
Fluid Levels:Oil, Coolant, Battery, Power Steering, Brake Fluid, Washer, Auto Transmission	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Belts (Condition And Adjustment)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cooling System Hoses, Heater Hoses, Air Conditioning, Hoses And Connections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Water Pump (Noise/Leaks)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Radiator Core, Air Conditioner Condenser	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant Recovery Reservoir Fluid Level/Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Clutch Reservoir Fluid/Condition (As Equipped)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Noise	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Battery Test	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Alternator Test	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Block Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Starting	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

BRAKE & TIRE

Left Front		Right Front	
<input checked="" type="checkbox"/>	Brake Lining <u>2</u> mm	<input checked="" type="checkbox"/>	Brake Lining <u>2</u> mm
<input checked="" type="checkbox"/>	Tire Tread <u>10</u> 32nds	<input checked="" type="checkbox"/>	Tire Tread <u>10</u> 32nds
<input checked="" type="checkbox"/>	Wear Pattern <u>even</u>	<input checked="" type="checkbox"/>	Wear Pattern <u>even</u>
<input checked="" type="checkbox"/>	Tire Pressure <u>55</u> psi	<input checked="" type="checkbox"/>	Tire Pressure <u>55</u> psi
<input checked="" type="checkbox"/>	Rotor/Drum	<input checked="" type="checkbox"/>	Rotor/Drum
<input type="checkbox"/>	Alignment Check Needed	<input type="checkbox"/>	Wheel Balance Needed

Left Rear		Right Rear	
<input checked="" type="checkbox"/>	Brake Lining <u>6</u> mm	<input checked="" type="checkbox"/>	Brake Lining <u>6</u> mm
<input checked="" type="checkbox"/>	Tire Tread <u>12</u> 32nds	<input checked="" type="checkbox"/>	Tire Tread <u>12</u> 32nds
<input checked="" type="checkbox"/>	Wear Pattern <u>even</u>	<input checked="" type="checkbox"/>	Wear Pattern <u>even</u>
<input checked="" type="checkbox"/>	Tire Pressure <u>60</u> psi	<input checked="" type="checkbox"/>	Tire Pressure <u>60</u> psi
<input checked="" type="checkbox"/>	Rotor/Drum	<input checked="" type="checkbox"/>	Rotor/Drum

Brake Inspection Not Performed This Visit



Every effort is made to conduct thorough inspections, however certain inspections may take excessive time to complete on some models. In such cases, our technician will prioritize essential inspections to ensure the efficient and timely completion of your service. Ask your advisor if you have any questions.

LV3 Mechanical Ltd.

Box 566
 Fort Macleod AB T0L 0Z0
 lv3mechanical@outlook.com
 GST/HST Registration No.: 782588354RT0001

INVOICE

BILL TO

INVOICE 3146
 DATE 04-16-2026
 TERMS Due on receipt
 DUE DATE 04-16-2026

DATE	SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
04-16-2026	Hours	CHEK FOR ENGINE NOISE	GST	1	130.00	130.00
04-16-2026	Sales	942183 WATER PUMP	GST	1	185.32	185.32
04-16-2026	Sales	REPLACE PUMP	GST	3.50	130.00	455.00
04-16-2026	Sales	COOLANT	GST	3	25.58	76.74
04-17-2026	Hours	PERFORM OIL CHANGE	GST	1	45.00	45.00
04-17-2026	Sales	5W30 SYN	GST	1	13.98	13.98
04-17-2026	Sales	57502 FILTER	GST	1	14.23	14.23
04-17-2026	Sales	SHOP SUPPLIES	GST	1	25.00	25.00
04-17-2026	Sales	THERMOSTAT 655-190	GST	1	69.35	69.35
04-17-2026	Sales	FILTER 49883	GST	1	39.32	39.32

2013 FORD F150
 KM 219246

FOUND ENGINE NOISE AT FROONT OF THE MOTOR

REMOVED THE BELT AND FOUND NOISE IS GONE
 NEEDS WATER PUMP

REPLACED THE WATER PUMP AND THERMOSTAT
 REFILL WITH COOLANT
 NOTE COOLANT IN ENGINE IS VERY WEAK AND DIRTY
 ENGINE NOISE IS GONE

PERFORM OIL CHANGE
 REPLACED AIR FILTER

TAX SUMMARY

SUBTOTAL	1,053.94
GST @ 5%	52.71
TOTAL	1,106.65

BALANCE DUE **\$1,106.65**

RATE	TAX	NET
GST @ 5%	52.71	1,053.94

ALL-TRA BATTERY
1902 - 3rd AVENUE SO.
LETHBRIDGE, AB
T1J 0L6

Phone: (403) 328-3333 Fax: (403) 329-8476
 Battery Hotline: 1 (800) 414-8658



INVOICE

No. **0000868705**
 Date **18-Apr-26**
 CUSTOMER NO. **CASH**
 POS

BILL TO: THANK YOU FOR SHOPPING
 ALL-TRA BATTERY

SHIP TO: THANK YOU FOR SHOPPING

DATE	SHIP VIA	F.O.B.	TERMS
------	----------	--------	-------

18-Apr-26 Your dock

P.O. NUMBER	ORDER DATE	SALESPERSON	OUR ORDER NUMBER
-------------	------------	-------------	------------------

18-Apr-26 NICOLAS 0001360724

PART NUMBER	DESCRIPTION	QUANTITY			UNIT PRICE	EXTENDED PRICE
		REQ.	SHIPPED	B.O.		
65-1100	Ford and Dodge Battery	1	1		174.96000	174.96
IMPORT CLAMP	positive or negative single replacement import battery clamp	1	1		4.95000	4.95

CANADIAN DOLLARS

Net amount 179.91
 G.S.T. 9.00

GST Number R134323187

Total Due **\$188.91**

INTERAC ONLY PLEASE 188.91

Months Free: _____ Months Pro: _____

Change due 0.00

LV3 Mechanical Ltd.

Box 566
 Fort Macleod AB T0L 0Z0
 lv3mechanical@outlook.com
 GST/HST Registration No.: 782588354RT0001

INVOICE

BILL TO

INVOICE 3170
 DATE 04-23-2026
 TERMS Due on receipt
 DUE DATE 04-23-2026

DATE	SERVICE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
04-23-2026	Hours	RECGHAERGE AC SYSTEM	GST	1.20	130.00	156.00
04-23-2026	Sales	R134 REFRIDGERANT	GST	28	3.02	84.56
04-23-2026	Sales	SHOP SUPPLIES	GST	1	10.00	10.00
04-27-2026	Hours	REPLACE AC PUMP	GST	4	130.00	520.00
04-27-2026	Sales	COMPRESSOR 167662	GST	1	590.32	590.32
04-27-2026	Hours	REPAIR SEAT BELT	GST	1	120.00	120.00
04-29-2026	Sales	7013975 CONDENSOR	GST	1	210.32	210.32

2012 FORD F150
 KM211545
 RECOVER SYSTEM AND FOUNHD IT IS EMPTY
 VACUUM TEST AND ADD DYE
 REPLACED THE COMPRESSOR AND CONDENSOR
 RECHARGE AND HAVE CUSTOMER RETURN IN ONE WEEK TO INSPECT
 FOR LEAKS

SUBTOTAL	1,691.20
GST @ 5%	84.57
TOTAL	1,775.77
BALANCE DUE	\$1,775.77

TAX SUMMARY

	RATE	TAX	NET
GST @ 5%		84.57	1,691.20



speedyglass.ca

SPEEDY (LETHBRIDGE) 8072
1717, 2nd Avenue South
Lethbridge AB T1J 0E8
(403) 329-6311

Invoice
8072 - 18604101
Date: 2026-05-04

Bill-To:

JOB ID: 80720001860410

VEHICLE: 2013 FORD F SERIES F150 4 DOOR CREW CAB
LICENCE PLATE:

V.I.N: 1FT1R2GHU4T89000
ODOMETER:

CSR: 220379
TECHNICIAN: 220379

Table with 5 columns: PRODUCTS & SERVICES, DESCRIPTION, QTY, LABOUR, MATERIAL. Rows include DW01747GBY, KIT25, DISPO.

Summary table with 2 columns: Description, Amount. Rows include MATERIAL, LABOUR, SUB-TOTAL, GST/TPS, PST/TVP, TOTAL, TOTAL PAYABLE BY CUSTOMER, DEPOSIT PAID, MASTERCARD, BALANCE.

GST/TPS#: 868996844RT
PST/TVP#:

I recognize having read the details of this invoice, the sale conditions and warranties. For your insurance claim (if applicable), you also recognized having provided us with your consent for us to collect, use and disclose your personal information, to obtain other specific information relating to the incident that caused the glass damage and forward such information to the insurer indicated on this invoice for investigation, processing and claim settlement purposes.

Customer Signature

Date

The adhesive that we use to attach the windshield to the body takes time to set. In order to allow the adhesive to set sufficiently before driving your vehicle, please follow the instructions below:

- 1. Minimum drive-away time; vehicle should not be driven for at least 30 minutes after installation completed unless technician has stated, in the space below, that a different minimum drive-away time applies. DO NOT DRIVE THE VEHICLE BEFORE 10:43
2. After the installation, you should not do anything that could interfere with the adhesive setting process such as pushing against, touching or otherwise testing the glass or adhesive.
3. You should not take the vehicle through a car wash for first 24hours after installation. If these instructions are not followed, adhesive might not set or retain glass sufficiently, which could cause accident or damage to vehicle, or increase the risk of injury if vehicle is involved in a collision.

WINDSHIELD INSTALLATION: The warranty is not transferable or redeemable for cash, the installation is warranted against leaks and windshield manufacturing defects. (See the next page.)



SALES CONDITIONS AND WARRANTIES

Authorization

I hereby authorize the work and/or purchase of goods and services referred to on this invoice and agree to pay the total amount referred to herein. Where the work and/or goods and services are covered by an insurance policy, I authorize Belron Canada Inc. "Belron", for and on my behalf, to seek the full payment of the amount referred to under "Amount payable by insurer" directly to my insurance company or its authorized representative. I agree that this request for payment is made by Belron only to accommodate me and in the event that my insurance company or its representative fails to authorize payment of such amount, I agree to pay any unpaid residual amount. Ownership of the goods sold referred to on this invoice remains with Belron until full payment of this invoice. I agree to pay interest at 1.5% per month (18% per annum) on overdue accounts.

Personal Information

At Belron, we are committed to protecting your privacy. You consent to your personal information being collected and retained in our database, and used by Belron and disclosed to and used by third parties as required for the purpose of discharging the work, and processing and managing the account therefore and related insurance coverage, as further detailed in our Privacy Policy available at <https://www.belroncanada.com/en/privacy-policy.html>, which document provides additional information pertaining to our practices and how you may exercise your privacy rights.

Insurance Declaration

I declare the information contained herein to be true and correct to the best of my knowledge and that the loss or damage did not occur through any willful act, procurement means, or connivance of the undersigned and that the repair or replacement has been completed to my entire satisfaction and hereby authorize my insurance company to make payment directly to Belron in full settlement of its obligations under my policy for said claim.

Credit Card Authorization

The issuer of the card identified herein is authorized to pay the amount shown as total upon proper presentation. I promise to pay such total (together with any other charges due thereon) subject to and in accordance with the agreement governing the use of such card.

Warranty Conditions

Subject to the following terms and conditions, this warranty will be honoured at all Belron locations throughout Canada.

Once the invoice is paid in full, Belron guarantees the work done by its technicians for life:

- Windshield replacements are guaranteed against installation and manufacturing defects and leaks. If such defect occurs, we will provide and install the necessary parts free of charge.
 - Tempered glass windows are guaranteed for one (1) year against manufacturing defects.
 - If a chip cracks after we have repaired it, we will deduct the cost of the repair from the windshield replacement done by us.
 - The recalibration made during your windshield replacement is guaranteed for one (1) year or until the next recalibration event (as determined by the vehicle manufacturer), whichever occurs first.
- HOWEVER, BELRON SHALL NOT BE LIABLE FOR ANY DAMAGES OR DEFECTS CAUSED BY:
- IMPROPER USE, NEGLIGENCE, ALTERATION, ACCIDENT, INTERNATIONAL ACTS, INCIDENT OR ROAD HAZARD,
 - INADEQUATE REPAIR ATTEMPTED OR PERFORMED BY THE CONSUMER OR ANY THIRD PARTY, OR
 - USE OF THE VEHICLE FOR COMPETITIVE PURPOSES.

Where any automobile glass or purchased products fail due to defects in material or workmanship during normal usage during the warranty period specified herein, Belron shall repair or replace the defective part without charge. If Belron is unable to make the repair or replacement, Belron will refund the original purchase price of your warranted product.

To obtain a warranty repair, you must take your vehicle to a Belron location together with a copy of the original Belron invoice as proof of purchase and of the warranty certificate. All claims under this warranty must be reviewed for eligibility by a member of the Belron team. NO REFUNDS OR CREDITS WILL BE GRANTED FOR ANY WORK OR REPAIRS DONE BY THE CONSUMER OR ANY THIRD PARTIES.

Belron warranties apply only to complete and proper installation and repair. WARRANTIES MAY BE REDUCED OR WITHDRAWN WHEN CUSTOMERS ELECT INCOMPLETE OR IMPROPER INSTALLATION (such as installation over rusting metal, where the customer declined rust repair). Such details will be noted on the front of the invoice. ALL SEALANT WARRANTIES EXCLUDE LIABILITY WHERE LEAKS ARE CAUSED BY RUSTED METAL AND/OR BODY DETERIORATION. This warranty does not cover leakage due to deterioration of the vehicle's bodywork or damage caused by vandalism, theft, natural disaster, unlawful activity, or willful act.

To the extent permitted by law, Belron's warranty is non-transferable and becomes null and void upon a change in ownership of the vehicle repaired or the product purchased.

Limitations of Liability

THE WARRANTIES DESCRIBED ON THIS INVOICE ARE IN LIEU OF ALL OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, WRITTEN OR VERBAL. BELRON SHALL NOT BE LIABLE TO THE PURCHASER FOR ANY CLAIMS REGARDING FAILURE OR DEFECT OF THE PURCHASED GOODS OR SERVICES RESULTING IN DIRECT OR INDIRECT, INCIDENTAL OR CONSEQUENTIAL, LOSS OR DAMAGES, PERSONAL INJURY OR DEATH. IN NO CASE SHALL THE LIABILITY OF BELRON EXCEED THE PURCHASE PRICE PAID FOR THE GOODS BY THE PURCHASER.

Some provinces do not allow the exclusion or limitation of a warranty or of incidental or consequential damages, so the above limitations and exclusions may not apply to you. This warranty gives you specific legal rights and you may also have additional rights, which vary from province to province. The terms and conditions contained herein do not limit or otherwise diminish any rights to which you may be entitled under consumer protection legislation in any province.

Version française disponible sur demande.