



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	SURERUS
Inspected By:	Scott Kozlowsky
Start Date:	
Hrs / KM:	5140

UNIT #	LD 978	MAKE	CAT	MODEL	730	SERIAL #	EYE00657
--------	--------	------	-----	-------	-----	----------	----------

JOB #		MOB ☐ DEMOB ☐	COMPLETE SERVICE RECORD YES ☐ NO ☒	LAST SERVICE HRS/KMS	
-------	--	---	---	----------------------	--

SAFETY		CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	5. SPILL KIT / FIRST AID KIT	☐
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☒

CAB / ELECTRICAL		CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☐
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☐ needs belt

ATTACHMENTS		INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET	UNIT #	☐	23. BLADE / RIPPER / WINCH	☐
22. DIGGING BUCKET	UNIT #	☐	24. CABLE LENGTH:	BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL		CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	Road test OK.	
26. LEAKS / RUNNING TEST	☒	Rocker cover leak, steering cyl. leak	
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☒		
29. HARD NOSE BUSHINGS	☒		
30. UNDERCARRIAGE	☒		
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	Rear diff input seal leak	
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒		
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒		
34. PARK / SERVICE BRAKERS	☒		
35. FLUID LEVELS / FILTERS	☐	needs service (Trans filter has 1623 hrs on it!)	
36. GREASED	☐		


ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
☐	replace valve cover gasket and valve cover box gasket	①
☐	replace injector lines and sleeves in Rocker box	②
☐	set valves	③
☐	replace aut. belt	④
☐	resal steering cylinders	⑤
☐	resal pinion seal on ~~front~~ rear diff.	⑥
☐	repair lights	⑦
☐	replace Hyd attachment couplers.	⑧
☐	replace u-joints in rear driveshaft.	⑨
☐	Service: replace both differential oils (TMS), change	
☐	Trans oil + filter, change Hyd filter, change Eng oil + filter,	
☐	change fuel, air and cabin air filters	⑩

SIGNATURE

[Signature]

DATE COMPLETE

Sept 3/2019



Owner:	Suwerus
Inspected By:	Clayton F
Start Date:	
Hrs / Km:	14521 HRS

Signature _____

Date Completed

Feb 21, 2025



Mechanic Daily Report

Name: Steve White

Date: Aug 16/25

Weather

Shop Time: ☐ Main ☐ Welding ☒ Fort Nelson ☐ Paint Shop

- or -

Field Job#:

Unit # EX 316

Unit Hrs.

Work Performed: Wash stick and undercarriage R8

Install Panels and skid plates m7

Install stickers in side window m7

Take Pictures m7

* Parts Purchased ☐ Yes ☐ No

Man Hrs. 6

Unit # LD 978

Unit Hrs.

Work Performed: Wash pump area on Transmission

Help Clayton With pump Install

* Parts Purchased ☐ Yes ☐ No

Man Hrs. 1

General Remarks and General Repairs:

Work Performed: EX 305

Replace hydraulic line at back of Boom

* Parts Purchased ☐ Yes ☐ No

Man Hrs. 33

Office Use Only

P / R

Q / A

Operations

Total
Hours 10

* Please attach invoices or packing slips for parts purchased. If no paperwork available, list suppliers.



Mechanic Daily Report

Name: Clayton Foster
Date: Aug 16, 2025

Weather

Shop Time: ☐ Main ☐ Welding ☐ Fort Nelson ☐ Paint Shop

- or -

Field Job#:

Unit # L097P

Unit Hrs.

Work Performed:

Installed drive line M2- 2 HRS
drained hydraulics, Replaced Transmission pump.
Filled hydraulics and tested. M2-5 HRS

* Parts Purchased ☐ Yes ☐ No

Man Hrs. 7

Unit #

Unit Hrs.

Work Performed:

* Parts Purchased ☐ Yes ☐ No

Man Hrs.

General Remarks and General Repairs:

Work Performed:

* Parts Purchased ☐ Yes ☐ No

Man Hrs.

Office Use Only	P / R	Q / A	Operations

Total
Hours 7

* Please attach invoices or packing slips for parts purchased. If no paperwork available, list suppliers.

Mechanic Daily Report

	Name: <u>Clayton Foster</u>	
	Date: <u>Aug 15 2025</u>	
Weather:	Shop Time: ☐ Main ☒ Welding ☒ Fort Nelson ☐ Paint Shop - or - Field Job#:	

Unit #	Unit Hrs.
EX197	
Work Performed:	
Shimmered stick to quickly attach. MS-2 HRS	
DPF Issue Diagnosed and Repaired. MS-5 HRS	
7 HRS.	
* Parts Purchased	☐ Yes ☐ No

Unit #	10978	Unit Hrs.	
Work Performed:			
Front Diff Seal M2 - 3 HRS.			
* Parts Purchased ☐ Yes ☐ No			

General Remarks and General Repairs:	
Work Performed:	
* Parts Purchased	☐ Yes ☐ No

Office Use Only	P / R	Q / A	Operations

* Please attach invoices or packing slips for parts purchased. If no paperwork available, list suppliers.