



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surenus
Inspected By	Tristan Soychuk
Start Date:	May 29, 2024
Hrs / KM:	17923hr

UNIT #	DZ 145	MAKE	CAT	MODEL	D6T	SERIAL #	CAT00D6TTWCG00499		
JOB #	Shop	MOB	☒	DEMOB	☐	COMPLETE SERVICE RECORD YES	☒ NO ☐	LAST SERVICE HRS/KMS	17916hr

SAFETY	CHECKED	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	☒	
2. SEAT BELTS / ANCHORS	☒	☒	
3. BACKUP ALARM / HORN	☒	☒	
4. HANDRAILS / STEPS / GUARDS	☒	☒	
5. SPILL KIT / FIRST AID KIT	☒	☒	
6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒	☒	
7. TRACK SHOVEL / POLASKI	☒	☒	
8. LOG BOOK - FILL IN	☒	☒	

CAB / ELECTRICAL	CHECKED	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	☒	
10. ROPS / FOPS / DECALS	☒	☒	
11. DOOR LATCHES / HANDLES	☒	☒	
12. SEAT CUSHIONS / FRAME	☒	☒	
13. BATTERIES - LEVELS & POSTS	☒	☒	
14. CHARGING SYSTEM / BELTS	☒	☒	
15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒	☒	
16. WARNING LIGHTS / ALARMS	☒	☒	
17. HEATER / AIR CONDITIONING / VENTILATION	☒	☒	
18. 2 WAY RADIO / AM & FM RADIO	☒	☒	No 2way or Radio
19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒	☒	
20. POSITIVE AIR SHUT OFF	☒	☒	

ATTACHMENTS	INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT # _____	☐	☒	
22. DIGGING BUCKET UNIT # _____	☐	☒	
23. BLADE / RIPPER / WINCH	☒	☒	
24. CABLE LENGTH:			BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	
26. LEAKS / RUNNING TEST	☒	
27. ENGINE / RADIATOR	☒	
28. HARD BAR BEARINGS	☒	
29. HARD NOSE BUSHINGS	☒	
30. UNDERCARRIAGE	☒	
21. DIFF / FINAL DRIVE / TRANSMISSION	☒	
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
19	Most of the work light got burnt out	TS
7	Needs a Shovel	TS
32	Tilt cylinder needs resealed	TS
9	Needs new wiper blades	TS
1	Needs new fire extinguisher	TS
17	Heater temp control valve sticking	TS
3	Needs new back up alarm	TS
34	Park brake lever stiff	TS
21	torque impellor to housing oring is leaking	BW
4	Night Switch door handle missing	TS

SIGNATURE

DATE COMPLETE May 30, 2024



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surerus
Inspected By:	Ron Bablucik
Start Date:	Mar 23, 23
Hrs / KM:	17323

UNIT #	DZ145	MAKE	CAT	MODEL	D6T	SERIAL #	WCG 00498
JOB #		MOB ☒ DEMOB ☐	COMPLETE SERVICE RECORD YES ☒ NO ☐	LAST SERVICE HRS/KMS	17231		

SAFETY	CHECKED	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	☒	
2. SEAT BELTS / ANCHORS	☒	☒	
3. BACKUP ALARM / HORN	☒	☒	
4. HANDRAILS / STEPS / GUARDS	☒	☒	
5. SPILL KIT / FIRST AID KIT	☒	☒	
6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒	☒	
7. TRACK SHOVEL / POLASKI	☒	☒	
8. LOG BOOK - FILL IN	☒	☒	

CAB / ELECTRICAL	CHECKED	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	☒	
10. ROPS / FOPS / DECALS	☒	☒	
11. DOOR LATCHES / HANDLES	☒	☒	
12. SEAT CUSHIONS / FRAME	☒	☒	
13. BATTERIES - LEVELS & POSTS	☒	☒	
14. CHARGING SYSTEM / BELTS	☒	☒	
15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒	☒	
16. WARNING LIGHTS / ALARMS	☒	☒	
17. HEATER / AIR CONDITIONING / VENTILATION	☒	☒	
18. 2 WAY RADIO / AM & FM RADIO	☒	☒	
19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒	☒	
20. POSITIVE AIR SHUT OFF	☒	☒	NEED Belt Seat! AB

ATTACHMENTS	INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT #	☐	☒	
22. DIGGING BUCKET UNIT #	☐	☒	
23. BLADE / RIPPER / WINCH	☐	☒	
24. CABLE LENGTH:			BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	Both Side Panels Bent. AB
26. LEAKS / RUNNING TEST	☒	Broken Bolts on Crossing AB
27. ENGINE / RADIATOR	☒	Accessory Drives Leaking AB
28. HARD BAR BEARINGS	☒	Center Pin Loose AB
29. HARD NOSE BUSHINGS	☒	Ripper Grapple Lines Broken AB
30. UNDERCARRIAGE	☒	Front Grapple Broken Bolts AB
21. DIFF / FINAL DRIVE / TRANSMISSION	☒	Final Drives Leaking AB
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	Needs To Shim Blade Ball
34. PARK / SERVICE BRAKERS	☒	Needs 1000 Hr Service AB
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
☐	Final Drives Leaking ✓	AB
☐	Needs Batteries ✓	AB
☐	L.H. Door Washer Not Working	AB
☐	Lift Cylinders Leaking	AB
☐	Needs 1000 Hr Service ✓	AB
☐	Needs Fire Ext	AB
☐	Needs Track Shovel	AB
☐	Needs Seat Belt ✓	AB
☐	Positive Air Don't Work	AB
☐	R.H. Plastic Damaged in CAB ✓	AB
☐	C frame Needs Shims / New Balls	Welders
☐	Center Pin Loose Hard Bar ✓ Needs Machining	
☐	Lift Yokes Loose ✓	
☐	Pitch Link Loose ✓	



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surerus
Inspected By:	Tristan Saychuk
Start Date:	May 30, 2022
Hrs / KM:	16550.4

1/2

UNIT#	Dz 145	MAKE	CAT	MODEL	D6T	SERIAL#			
JOB #	Shop	MOB	☒	DEMOB	☐	COMPLETE SERVICE RECORD	YES ☐ NO ☐	LAST SERVICE HRS/KMS	16550

SAFETY		CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	5. SPILL KIT / FIRST AID KIT	☒
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☐

CAB / ELECTRICAL		CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☒
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☒

ATTACHMENTS		INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET	UNIT #	☒	☒	
22. DIGGING BUCKET	UNIT #	☐	☐	
23. BLADE / RIPPER / WINCH				
24. CABLE LENGTH:				

MECHANICAL		CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒		
26. LEAKS / RUNNING TEST	☒		
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☒		
29. HARD NOSE BUSHINGS	☒		
30. UNDERCARRIAGE	☒		
21. DIFF / FINAL DRIVE / TRANSMISSION	☒		
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒		
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒		
34. PARK / SERVICE BRAKERS	☒		
35. FLUID LEVELS / FILTERS	☒		
36. GREASED	☒		

ITEM#	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
9	window washer fluid needs filled	TS
30	needs new undercarriage	TS
30	needs cannon seals / track adjusters replaced	TS
28	hard bar outer bearings	TS
29	nose cone bushings	TS
32	lift cylinder yoke bushings	TS
32	Blade need linebored & new Pins, bearings & bushing	TS
30	Pivot shaft mounts need welding	TS
21	Trans hoses need replaced	TS
14	All belts need changed	TS
21	final drives duo cones need changed	TS
27	valve set need to be done	TS
27	oil cooler gasket needs replaced	TS

SIGNATURE

DATE COMPLETE

212



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	
Inspected By	
Start Date:	
Hrs / KM:	16550.4

UNIT#	02-145	MAKE		MODEL		SERIAL#	
-------	--------	------	--	-------	--	---------	--

JOB #		MOB ☐ DEMOB ☐	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	
-------	--	---	--	----------------------	--

SAFETY	CHECKED		CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☐	5. SPILL KIT / FIRST AID KIT	☐	
2. SEAT BELTS / ANCHORS	☐	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☐	
3. BACKUP ALARM / HORN	☐	7. TRACK SHOVEL / POLASKI	☐	
4. HANDRAILS / STEPS / GUARDS	☐	8. LOG BOOK - FILL IN	☐	

CAB / ELECTRICAL	CHECKED		CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☐	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☐	
10. ROPS / FOPS / DECALS	☐	16. WARNING LIGHTS / ALARMS	☐	
11. DOOR LATCHES / HANDLES	☐	17. HEATER / AIR CONDITIONING / VENTILATION	☐	
12. SEAT CUSHIONS / FRAME	☐	18. 2 WAY RADIO / AM & FM RADIO	☐	
13. BATTERIES - LEVELS & POSTS	☐	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☐	
14. CHARGING SYSTEM / BELTS	☐	20. POSITIVE AIR SHUT OFF	☐	

ATTACHMENTS	INCLUDED		CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT #	☐	23. BLADE / RIPPER / WINCH	☐	
22. DIGGING BUCKET UNIT #	☐	24. CABLE LENGTH:		BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	
26. LEAKS / RUNNING TEST	☐	
27. ENGINE / RADIATOR	☒	
28. HARD BAR BEARINGS	☒	
29. HARD NOSE BUSHINGS	☒	
30. UNDERCARRIAGE	☒	
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

ITEM#	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
27	Air to air cooler need cracks welded	TS
17	A/C needs charged	TS
17	needs dryer & condensor	TS
17	heater valve leaking & dial cable need replaced	TS
35	All filters need changed	TS
27	water pump need replaced	TS
14	Starter needs new gasket	TS
27	needs new valve cover	TS
27	needs new rocker box seal	TS
27	fan hub need to be rebuilt	TS
19	missing rear light	TS /
	install ripper	OS

SIGNATURE

[Signature]

DATE COMPLETE



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surerus
Inspected By:	Tristan Saychuk
Start Date:	May 30, 2022
Hrs / KM:	16550.4

112

UNIT#	Dz 145	MAKE	CAT	MODEL	D6T	SERIAL#	
-------	--------	------	-----	-------	-----	---------	--

JOB #	Shop	MOB ☒ DEMOB ☐	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	16550
-------	------	--	--	----------------------	-------

SAFETY		CHECKED	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	5. SPILL KIT / FIRST AID KIT	☒	
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒	
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒	
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☐	

CAB / ELECTRICAL		CHECKED	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒	
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒	
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☒	
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒	
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒	
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☒	

ATTACHMENTS		INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT #		☒	☒	
22. DIGGING BUCKET UNIT #		☐		
23. BLADE / RIPPER / WINCH				
24. CABLE LENGTH:				

MECHANICAL		CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒		
26. LEAKS / RUNNING TEST	☒		
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☒		
29. HARD NOSE BUSHINGS	☒		
30. UNDERCARRIAGE	☒		
21. DIFF / FINAL DRIVE / TRANSMISSION	☒		
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒		
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒		
34. PARK / SERVICE BRAKERS	☒		
35. FLUID LEVELS / FILTERS	☒		
36. GREASED	☒		

ITEM#	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
9	window washer fluid needs filled	TS
30	needs new undercarriage	TS
30	needs cannon seals / track adjusters replaced	TS
28	hard bar outer bearings	TS
29	nose cone bushings	TS
32	lift cylinder yoke bushings	TS
32	Blade need linebored & new Pins, bearings & bushing	TS
30	Pivot shaft mounts need welding	TS
21	Trans hoses need replaced	TS
14	All belts need changed	TS
21	final drives duo cones need changed	TS
27	valve set need to be done	TS
27	oil cooler gasket needs replaced	TS

SIGNATURE

DATE COMPLETE

212



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	
Inspected By	
Start Date:	
Hrs / KM:	16550.4

UNIT #	02-145	MAKE		MODEL		SERIAL #	
--------	--------	------	--	-------	--	----------	--

JOB #		MOB ☐ DEMOB ☐	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	
-------	--	---	--	----------------------	--

SAFETY	CHECKED		CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☐	5. SPILL KIT / FIRST AID KIT	☐	
2. SEAT BELTS / ANCHORS	☐	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☐	
3. BACKUP ALARM / HORN	☐	7. TRACK SHOVEL / POLASKI	☐	
4. HANDRAILS / STEPS / GUARDS	☐	8. LOG BOOK - FILL IN	☐	

CAB / ELECTRICAL	CHECKED		CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☐	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☐	
10. ROPS / FOPS / DECALS	☐	16. WARNING LIGHTS / ALARMS	☐	
11. DOOR LATCHES / HANDLES	☐	17. HEATER / AIR CONDITIONING / VENTILATION	☐	
12. SEAT CUSHIONS / FRAME	☐	18. 2 WAY RADIO / AM & FM RADIO	☐	
13. BATTERIES - LEVELS & POSTS	☐	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☐	
14. CHARGING SYSTEM / BELTS	☐	20. POSITIVE AIR SHUT OFF	☐	

ATTACHMENTS	INCLUDED		CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT #	☐	23. BLADE / RIPPER / WINCH	☐	
22. DIGGING BUCKET UNIT #	☐	24. CABLE LENGTH:		BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED		COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒		
26. LEAKS / RUNNING TEST	☐		
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☒		
29. HARD NOSE BUSHINGS	☒		
30. UNDERCARRIAGE	☒		
31. DIFF / FINAL DRIVE / TRANSMISSION	☒		
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒		
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒		
34. PARK / SERVICE BRAKERS	☒		
35. FLUID LEVELS / FILTERS	☒		
36. GREASED	☒		

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
27	Air to air cooler need cracks welded	TS
17	A/C needs charged	TS
17	needs dryer & condensor	TS
17	heater valve leaking & dial cable need replaced	TS
35	All filters need changed	TS
27	water pump need replaced	TS
14	Starter needs new gasket	TS
27	needs new valve cover	TS
27	needs new rocker box seal	TS
27	fan hub need to be rebuilt	TS
19	missing rear light	TS /
	install ripper	DS

SIGNATURE

DATE COMPLETE

Finning (Canada), a division of Finning International Inc.

1351 KOOTENAY WAY
KAMLOOPS, BC V2H 1K3
(250) 372-9552
(250) 372-9368 FAX

PAYER CA-0048404
SURERUS PIPELINE INC
10912 91 AVENUE
FORT ST JOHN BC V1J 6G9



CUSTOMER LOCATION CA-0048404
SURERUS PIPELINE INC
C/O FINNING (CANADA)
KAMLOOPS BC V2H 1K3

Date 04/07/24
Invoice Number 962618229
Invoice Total \$4,787.34
Payment Terms NET 60 DAYS

Due Date 02/09/24
Currency CANADIAN DOLLAR
Customer Tax Exemption No.
Customer Reference No. DZ145/2019736/M1
Order Date 14/06/24
Order Number 0060963739
Finning Contact MIKE ROUTHIER
Customer Contact SCOT KOSINSKY 250-261-8327
Customer Commitment Date 00/00/00
Actual Completion Date 03/07/24

Make CAT
Model D6T
Serial Number WCG00498
Unit Number DZ145-WCG00498
Meter Reading H 17934.00
(25/06/24)

Line No.	Qty	Item No.	Description	U/M	Sales Price
----------	-----	----------	-------------	-----	-------------

10		D6T	** AIR CONDITIONING TROUBLESHOOT FIELD		
----	--	-----	---	--	--

Customer Reference No. AIR CONDITIONER

COMPLAINT:
TROUBLESHOOT FOR AIR CONDITIONING SYSTEM BLOWING HOT AIR

CORRECTION:
JUN 14/2024
- TRAVEL TO MACHINE
- FIND MACHINE ON ROW
- CALL OPERATOR OUT OF CUT TO SAFE AREA

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This **Service Invoice** is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms

Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty

Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

The Terms and Conditions of this **Service Invoice**, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.



SERVICE INVOICE

Finning (Canada), a division of Finning International Inc.

1351 KOOTENAY WAY
KAMLOOPS, BC V2H 1K3
(250) 372-9552
(250) 372-9368 FAX

Date 04/07/24
Invoice Number 962618229
Invoice Total \$4,787.34
Payment Terms NET 60 DAYS

CUSTOMER NUMBER CA-0048404

Due Date 02/09/24

Line No.	Qty	Item No.	Description	U/M	Sales Price
			- THE A/C SYSTEM IS ONLY BLOWING HOT AIR - HOOKED GAUGES UP TO A/C SYSTEM - HIGH SIDE 125 PSI STATIC - LOW SIDE 105 PSI STATIC - SWITCHED ON A/C - FAN ON HIGH AND RPM AT 1350 RPM - HIGH SIDE PRESSURE 148 PSI - SUCTION SIDE 15 PSI - A/C PRESSURES ARE GOOD - OPENED THE RH ENGINE DOOR - SHUT-OFF THE TAPS TO THE HEATER CORE - AIR COOLED IMMEDIATELY - CHECKED THE WATER VALVE - THE VALVE ROTATES 360 DEGREES - THE VALVE HAS FAILED INTERNALLY - WILL ORDER A WATER VALVE FOR THE MACHINE - NOTICED THAT THE A/C COMPRESSOR HAS NOT CYCLED - THE COMPRESSOR STAYS ENGAGED UNTIL THE SYSTEM IS TURNED OFF VIA THE DASH SWITCH - LIKELY THAT THE HI/LOW SWITCH HAS FAILED - HAVE A SWITCH COMING - WILL T/S THE SWITCH AFTER THE WATER VALVE IS CHANGED IN THE AM NEXT DAY - TRAVEL TO FRONT FIELD, KM 5.5 FOR CELL SERVICE - INFORMED SCOT THAT THE DOZER IS DZ-145 NOT DZ-146 - ORDERED PARTS - INFORMED SCOT OF THE FINDINGS - TRAVEL FROM MACHINE		
			JUN 15/2024		

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001



SERVICE INVOICE

Finning (Canada), a division of Finning International Inc.

1351 KOOTENAY WAY
KAMLOOPS, BC V2H 1K3
(250) 372-9552
(250) 372-9368 FAX

Date 04/07/24
Invoice Number 962618229
Invoice Total \$4,787.34
Payment Terms NET 60 DAYS

CUSTOMER NUMBER CA-0048404

Due Date 02/09/24

Line No.	Qty	Item No.	Description	U/M	Sales Price
			- TRAVEL TO MACHINE		
			- OPERATOR NOW HAS A COMPLAINT THAT THERE IS NO HEAT WHEN THE TAP TURNED ON		
			- THE HEATER CONTROL IS MANUAL		
			- HAD THE OPERATOR CYCLE THE CONTROL KNOB WHILE I OBSERVED THE WATER VALVE		
			- THE WATER VALVE IS NOT MOVING		
			- THE CABLE IS CONNECTED TO THE VALVE		
			- REMOVED THE DASH		
			- THE CLAMP FOR THE CABLE HAS BROKEN		
			- USED A GEAR CLAMP AS A TEMPORARY FIX		
			- ORDERED THE CORRECT CLAMP FOR THE MACHINE		
			- TRUCKING SHOWED UP TO MOVE THE MACHINE		
			- THERE IS STILL THE ISSUE OF THE A/C COMPRESSOR CYCLING TO ADDRESS		
			JUN 17/2024		
			- ARRIVE AT MACHINE		
			- THE OPERATOR SAYS THERE IS NO HEAT IN THE MACHINE AFTER THE HEATER CORE LINES OPENED IN THE AM		
			- FELT THE LINES		
			- COOLANT LINES ARE WARM AT THE ENGINE, BUT COLD AT THE HEATER CORE		
			- HAD THE OPERATOR TURN THE CONTROL KNOB FROM HOT TO COLD		
			- FELT THE LEVER ON THE WATER VALVE		
			- WHEN THE OPERATOR CYCLES THE KNOB, THE LEVER ON THE HEATER VALVE DOES NOT MOVE		
			- REMOVED THE DASH FROM THE MACHINE		
			- THE CABLE IS ATTACHED TO THE CONTROL		
			- THERE IS A CLAMP MISSING FROM THE CABLE TO SECURE IT TO		

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001



SERVICE INVOICE

Finning (Canada), a division of Finning International Inc.

1351 KOOTENAY WAY
KAMLOOPS, BC V2H 1K3
(250) 372-9552
(250) 372-9368 FAX

Date 04/07/24
Invoice Number 962618229
Invoice Total \$4,787.34
Payment Terms NET 60 DAYS

CUSTOMER NUMBER CA-0048404

Due Date 02/09/24

Line No.	Qty	Item No.	Description	U/M	Sales Price
			THE CONTROL		
			- USED A GEAR CLAMP TO TEMPORARILY CLAMP THE CABLE		
			- THERE IS HEAT CONTROL UNTIL THE PROPER CLAMP ARRIVES		
			- TRUCKING ARRIVED AND IS TO MOVE THE MACHINE		
			- TRUCKING TO MOVE MACHINE FROM KULLAH RD BACK TO YARD IN MERRITT		
			- CANNOT FIX THE A/C COMPRESSOR NOT CUTTING OUT ISSUE		
			- TRAVEL TO NEXT MACHINE		
			JUN 18/2024		
			- TRAVEL TO MACHINE		
			- PULL DASH FROM MACHINE		
			- REMOVE TEMPERATURE GEAR CLAMP		
			- INSTALL CORRECT LOCK BRACKET ON CABLE ASSEMBLY		
			- CLOSE DASH		
			- CYCLE CONTROL KNOB		
			- WATER VALVE CYCLES WITH CONTROL KNOB		
			- MOVE TO COMPRESSOR WIRING		
			- INSPECT THE WIRING TO THE COMPRESSOR AND HI LOW SWITCH		
			- THE SWITCH INSTALLED INTO THE LINES IS A HIGH PRESSURE ONLY SWITCH		
			- REMOVED THE SWITCH AND INSTALLED THE CORRECT HI/LOW PRESSURE SWITCH		
			- NOTICED THAT THE WIRING HAS TWO RUB-THROUGH AREAS		
			- INSPECTED THE WIRING FURTHER		
			- THERE IS BARE WIRE SHOWING AND THE SENSOR OR COMPRESSOR CIRCUITS CAN SHORT OUT		
			- CHANGED THE HARNESS GROUP		
			- AFFIXED THE HARNESS AWAY FROM THE RUB POINTS		
			- STARTED THE MACHINE		

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

Finning (Canada), a division of Finning International Inc.

1351 KOOTENAY WAY
KAMLOOPS, BC V2H 1K3
(250) 372-9552
(250) 372-9368 FAX

Date 04/07/24
Invoice Number 962618229
Invoice Total \$4,787.34
Payment Terms NET 60 DAYS

Due Date 02/09/24

CUSTOMER NUMBER CA-0048404

Line No.	Qty	Item No.	Description	U/M	Sales Price
- LET THE MACHINE RUN FOR 10 MINS TO WARM-UP AND STABILIZE THE A/C SYSTEM - HOOKED UP GAUGES TO THE A/C SYSTEM - THE GAUGES CAN BE OBSERVED CYCLING - THE A/C COMPRESSOR IS NOW CYCLING - A/C SUCTION AND DISCHARGE PRESSURES ARE WITHIN SPEC FOR AMBIENT TEMPERATURE - AMBIENT TEMPERATURE 13°F SUCTION PRESSURE 10 PSI - DISCHARGE PRESS 140 PSI - THE SYSTEM IS NOW OPERATING CORRECTLY - TRAVEL FROM MACHINE					
COMPLICATION: JUN 17/2024 - MACHINE MOVED OUT OF AREA - UNABLE TO COMPLETE REPAIRS ON A/C SYSTEM					
-					
	1.00	1834273	HARNESS AS	PC	151.10
	1.00	3553148	SWITCH AS	PC	176.37
	1.00	3E4051	CAP	PC	5.61
	1.00	1291831	CLAMP	PC	13.65
		EOF			0.68
	10.25	7320-035- -ACZ-001	JOURNEYPerson FIELD	EA	2,503.00
	5.50	7320-035- -ACZ-001	JOURNEYPerson TRAVEL	EA	1,424.00

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001



SERVICE INVOICE

Page: 6 (6)

Finning (Canada), a division of Finning International Inc.

1351 KOOTENAY WAY
KAMLOOPS, BC V2H 1K3
(250) 372-9552
(250) 372-9368 FAX

Date 04/07/24
Invoice Number 962618229
Invoice Total \$4,787.34
Payment Terms NET 60 DAYS

Due Date 02/09/24

CUSTOMER NUMBER CA-0048404

Line No.	Qty	Item No.	Description	U/M	Sales Price
			Emergency Order Fee		0.68
			Labor		3,927.00
			Material		346.73
			Service Total		4,274.41
			Order total		4,274.41
			GST		213.72
			PST		299.21
			Invoice Total		\$4,787.34

Thank you for your business.

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.
GST/HST Registration Number: 101801561 RT0001

This **Service Invoice** is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms
Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty
Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.
These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations. The Terms and Conditions of this **Service Invoice**, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.