



9312 - 109th street - Fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surerus.
Inspected By:	Clayton
Start Date:	Nov 6, 2025
Hrs / Km:	7648

Unit #	EX235	Make	Komatsu	Model	PC490	Serial #	A45017
--------	-------	------	---------	-------	-------	----------	--------

Job #		Mob	☐	Demob	☐	Completed Service Record	YES ☐ NO ☐	Last Service Hrs/Kms	7690
-------	--	-----	--------------------------	-------	--------------------------	--------------------------	--	----------------------	------

SAFETY		Checked	Checked	Comments
1. FIRE EXTINGUISHER - Valid	☐	5. SPILL KIT / FIRST AID KIT	☐	
2. SEAT BELTS / ANCHORS	☐	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☐	
3. BACKUP ALARM / HORN	☐	7. TRACK SHOVEL / POLASKI	☐	
4. HANDRAILS / STEPS / GUARDS	☐	8. LOG BOOK - FILLED IN	☐	

CAB / ELECTRICAL		Checked	Checked	Comments
9. WIPERS / WINDOW MIRRORS	☐	16. GAUGES - Tach, Speed, Hour Meter, etc.	☐	
10. ROPS / FOPS / DECALS	☐	17. WARNING LIGHTS / ALARMS	☐	
11. DOOR LATCHES / HANDLES	☐	18. HEATER / AIR CONDITIONING / VENTILATION	☐	
12. SEAT CUSHIONS / FRAME	☐	19. 2 WAY RADIO / AM & FM RADIO	☐	
13. BATTERIES - levels & posts	☐	20. HEAD / SIGNAL / TAIL / DOME LIGHTS	☐	
14. CHARGING SYSTEM / BELTS	☐	21. POSITIVE AIR SHUT OFF	☐	
15. PROXIMITY & CAMERA SYSTEM CHECK	☐			

ATTACHMENTS		Included	Included	Comments
22. CLEANUP BUCKET	Unit #	☐	24. BLADE / RIPPER / WINCH	☐
23. DIGGING BUCKET	Unit #	☐	25. CABLE LENGTH:	
			BOOMLINE	FT LOADLINE

MECHANICAL		Checked	Comments
26. MECHANICAL FUNCTIONS TEST	☐		
27. LEAKS / RUNNING TEST	☐		
28. ENGINE / RADIATOR	☐		
29. HARD BAR BEARINGS	☐		
30. HARD NOSE BUSHINGS	☐		
31. UNDERCARRIAGE	☐		
32. DIFF / FINAL DRIVE / TRANSMISSION	☐		
33. HYDRAULICS / PUMP / DRIVE / CYLINDER	☐		
34. TIRES / WHEELS - cuts, wear, damage	☐		
35. PARK / SERVICE BRAKES	☐		
36. FLUID LEVELS / FILTERS	☐		
37. GREASED	☐		

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
1	needs mirror	Steve
2	Hydraulic oil over full	Steve
3	Bucket cylinder Rod end worn out (Bearings/Pins)	Steve
4	H-link needs new bushings.	Steve
5	stick to Boom Shim	SU — OK
6	needs service sticker.	Steve
7	missing big washer for walk way engine.	Steve
8	no brigade.	IAN/Steve
9	Right Boom light out	IAN
10	Topup hydraulic oil	Steve
11	Grease	Steve
12	Install bucket	Steve
13	Grind Bucket wedge	Steve

Signature S. F. T.

Date Completed Nov 19 / 25