



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Sureus Pipeline
Inspected By	Sano Zacharias
Start Date:	Dec 19 2022
Hrs / KM:	6062

UNIT #	EX236	MAKE	Komatsu	MODEL	PC490LCI-II	SERIAL #	85250
--------	-------	------	---------	-------	-------------	----------	-------

JOB #		MOB ☒ DEMOB ☐	COMPLETE SERVICE RECORD YES ☒ NO ☐	LAST SERVICE HRS/KMS	6059
-------	--	--	---	----------------------	------

SAFETY	CHECKED	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	☒	Missing fire extinguisher. Handrails
2. SEAT BELTS / ANCHORS	☒	☒	bent. missing first aid kit. No
3. BACKUP ALARM / HORN	☒	☒	safety punches
4. HANDRAILS / STEPS / GUARDS	☒	☒	
5. SPILL KIT / FIRST AID KIT	☒	☒	
6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒	☒	
7. TRACK SHOVEL / POLASKI	☒	☒	
8. LOG BOOK - FILL IN	☒	☒	

CAB / ELECTRICAL	CHECKED	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	☒	low washer fluid. Burns in seat bottom.
10. ROPS / FOPS / DECALS	☒	☒	Battery box light not working.
11. DOOR LATCHES / HANDLES	☒	☒	RAM balls thundered. Left arm
12. SEAT CUSHIONS / FRAME	☒	☒	rest cab plastic cracked badly. missing
13. BATTERIES - LEVELS & POSTS	☒	☒	hardware in cab. Handrails bent.
14. CHARGING SYSTEM / BELTS	☒	☒	
15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒	☒	
16. WARNING LIGHTS / ALARMS	☒	☒	
17. HEATER / AIR CONDITIONING / VENTILATION	☒	☒	
18. 2 WAY RADIO / AM & FM RADIO	☒	☒	
19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒	☒	
20. POSITIVE AIR SHUT OFF	☒	☒	

ATTACHMENTS	INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT # SP1400237	☒	☐	
22. DIGGING BUCKET UNIT #	☒	☐	
23. BLADE / RIPPER / WINCH	☐	☐	
24. CABLE LENGTH:			BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	☒	RAM mounts for GPS thundered. Bucket drift. Stick cylinder leak
26. LEAKS / RUNNING TEST	☒	☒	at headland. Coolant leak. Stick cylinder hoses leaking. Block
27. ENGINE / RADIATOR	☒	☒	heater cord wires exposed. Hyd leak/scap near suction line. Boom
28. HARD BAR BEARINGS	☒	☒	stroke sensor harness crushed. Bucket piping rubbing on clamps
29. HARD NOSE BUSHINGS	☒	☒	Final drive leak 1/5
30. UNDERCARRIAGE	☒	☒	Cowbell roller, right side #6
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	☒	Stick cylinder leaking. Bucket drifting. Boom cylinder leaking (Right)
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	☒	Final leaking (LPS)
33. TIRES / WHEELS - OUTF, WEAR, DAMAGE	☒	☒	
34. PARK / SERVICE BRAKERS	☒	☒	Air filters could be changed soon. Cab filters could be
35. FLUID LEVELS / FILTERS	☒	☒	changed.
36. GREASED	☒	☒	

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
1	Install Fire extinguisher. Install safety punches	Sano Zacharias
5	Install First Aid Kit	Sano Zacharias
19	Repair/replace lights	Sano Zacharias
25	T/S bucket drift, change compensators	Sano Zacharias
26	Repair coolant + hyd leaks. + install hyd cap + gaskets	Sano Zacharias
27	Replace block heater cord	Sano Zacharias
32	Reseal stick cylinder + reinstall. Reseal both boom cylinders	Sano Zacharias
11	Replace cracked cab plastics + RAM mounts, install cab	Sano Zacharias
4	Welders straighten handrails + engine hood. Install missing hardware bolts	Sano Zacharias
30	change cowbelled roller, right side # 6	Sano Zacharias
32	Reseal both finals	Sano Zacharias
	Needs wash + cab clean	Washbay

SIGNATURE

[Signature]

DATE COMPLETE April 26 / 2023



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surerus Pipeline
Inspected By:	Sano Zacharias
Start Date:	March 30 2020
Hrs / KM:	2979

UNIT #	EX 236	MAKE	Komatsu	MODEL	PC490LCi-11	SERIAL #	85250
JOB #		MOB ☒ DEMOB ☒	COMPLETE SERVICE RECORD YES ☒ NO ☐	LAST SERVICE HRS/KMS	2975	250	

SAFETY		CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	5. SPILL KIT / FIRST AID KIT	☒ All track frame steps bent. No
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒ First Aid Kit. No polaski.
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☒

CAB / ELECTRICAL		CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒ Cigarette holes in seat. No 2 way.
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☒
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☒

ATTACHMENTS		CHECKED	COMMENTS
21. CLEANUP BUCKET UNIT # SP1400-264	☒	23. BLADE / RIPPER / WINCH	☐ Damage to cleanup bucket. Bowled
22. DIGGING BUCKET UNIT # SP1400-239	☒	24. CABLE LENGTH:	BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL		CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒		Could use shims from stick to quick attach
26. LEAKS / RUNNING TEST	☒		Counterweight has cut near rad door
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☐		
29. HARD NOSE BUSHINGS	☐		
30. UNDERCARRIAGE	☒		Tracks base. Right track #1 roller leaking
31. DIFF / FINAL DRIVE / TRANSMISSION	☒		Suction hose seeping. Tightened clamps
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒		
33. TIRES / WHEELS CUTS, WEAR, DAMAGE	☐		
34. PARK / SERVICE BRAKERS	☒		Coilant low. Hyd overfull. Swing good. Right Final good. Left low - Damper
35. FLUID LEVELS / FILTERS	☒		good.
36. GREASED	☒		

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
5	Install First Aid kit in cab.	Sano Zacharias
7	Install polaski in pump room.	Sano Zacharias
	Could use wash	
35	Top up coolant and left final. no visable leaks	Sano Zacharias
21	Shim up quick attach	Sano Zacharias
12	Repair seat damage	Sano Zacharias
4	Straighten handles. Remove bent steps. Straighten guards	Sano Zacharias
9	Install holders for kick window	Sano Zacharias
8	Repair plastics in cab. Install yellow pelican box	Sano Zacharias
26	Seap on suction line. Tightened clamps	Sano Zacharias
30	Right #1 bottom roller leaking. Cleaned oil off	Sano Zacharias

SIGNATURE

DATE COMPLETE

April 9/20



9312 - 109th street - Fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Surerus
Inspected By:	Clayton / Jan
Start Date:	Nov 6, 2025
Hrs / Km:	6866

Unit #	Ex 236	Make	Komatsu	Model	490-11	Serial #	85250
--------	--------	------	---------	-------	--------	----------	-------

Job #		Mob ☐ Demob ☐	Completed Service Record	YES ☐ NO ☐	Last Service Hrs/Kms	6854
-------	--	---	--------------------------	--	----------------------	------

SAFETY		Checked	Checked	Comments
1. FIRE EXTINGUISHER - Valid	☐	5. SPILL KIT / FIRST AID KIT	☐	
2. SEAT BELTS / ANCHORS	☐	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☐	
3. BACKUP ALARM / HORN	☐	7. TRACK SHOVEL / POLASKI	☐	
4. HANDRAILS / STEPS / GUARDS	☐	8. LOG BOOK - FILLED IN	☐	

CAB / ELECTRICAL		Checked	Checked	Comments
9. WIPERS / WINDOW MIRRORS	☐	16. GAUGES - Tach, Speed, Hour Meter, etc.	☐	
10. ROPS / FOPS / DECALS	☐	17. WARNING LIGHTS / ALARMS	☐	
11. DOOR LATCHES / HANDLES	☐	18. HEATER / AIR CONDITIONING / VENTILATION	☐	
12. SEAT CUSHIONS / FRAME	☐	19. 2 WAY RADIO / AM & FM RADIO	☐	
13. BATTERIES - levels & posts	☐	20. HEAD / SIGNAL / TAIL / DOME LIGHTS	☐	
14. CHARGING SYSTEM / BELTS	☐	21. POSITIVE AIR SHUT OFF	☐	
15. PROXIMITY & CAMERA SYSTEM CHECK	☐			

ATTACHMENTS		Included	Included	Comments
22. CLEANUP BUCKET	Unit #	☐	24. BLADE / RIPPER / WINCH	☐
23. DIGGING BUCKET	Unit #	☐	25. CABLE LENGTH:	BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL		Checked	Comments
26. MECHANICAL FUNCTIONS TEST	☐		
27. LEAKS / RUNNING TEST	☐		
28. ENGINE / RADIATOR	☐		
29. HARD BAR BEARINGS	☐		
30. HARD NOSE BUSHINGS	☐		
31. UNDERCARRIAGE	☐		
32. DIFF / FINAL DRIVE / TRANSMISSION	☐		
33. HYDRAULICS / PUMP / DRIVE / CYLINDER	☐		
34. TIRES / WHEELS - cuts, wear, damage	☐		
35. PARK / SERVICE BRAKES	☐		
36. FLUID LEVELS / FILTERS	☐		
37. GREASED	☐		

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
1	swing drive oil low.	Jan.
2	Coolant low.	Jan
3	Needs batteries.	Clay
4	DEF ISSUES. low voltage	Clay.
5	Hydraulic low / ~~high pull cables~~	Clay.
6	First aid kit	✓
7	Shovel/polaski	✓

Signature

Date Completed

Nov 12, 2025



312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	
Inspected By	Tony Beattie
Start Date:	Nov 3 23
Hrs / KM:	6837H

UNIT #	Fx 236	MAKE	Kennedy	MODEL	PC490-11	SERIAL #	KMTPC281EGC085250
--------	--------	------	---------	-------	----------	----------	-------------------

JOB #	MOB ☐	DEMOb ☒	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	6398
-------	------------------------------	---	--	----------------------	------

SAFETY		CHECKED	COMMENTS	
1. FIRE EXTINGUISHER - VALID	☒	5. SPILL KIT / FIRST AID KIT	☒	
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒	
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒	
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☒	

CAB / ELECTRICAL		CHECKED	COMMENTS	
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒	
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒	
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☒	
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒	
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒	
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☒	

ATTACHMENTS		INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET	UNIT # _____	☐	☐	_____
22. DIGGING BUCKET	UNIT # _____	☐		BOOMLINE _____ FT LOADLINE _____ FT
23. BLADE / RIPPER / WINCH				
24. CABLE LENGTH:				

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	
26. LEAKS / RUNNING TEST	☒	
27. ENGINE / RADIATOR	☒	
28. HARD BAR BEARINGS	☒	
29. HARD NOSE BUSHINGS	☒	
30. UNDERCARRIAGE	☒	
21. DIFF / FINAL DRIVE / TRANSMISSION	☒	
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

[illegible]

SIGNATURE

DATE COMPLETE Sept 3, 2024