



9312 - 109th street - Fort St. John BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner	Surerus
Inspected By	Clayton Foster
Start Date	April 5, 2023
Hrs / KMS	10475 HRS

UNIT #	Ex 253	MAKE	CAT	MODEL	336F	SERIAL #	CAT0336EHFJH00966		
JOB #		MOB	☐	DEMOB	☐	COMPLETE SERVICE RECORD	YES ☐ NO ☐	LAST SERVICE HRS/KMS	10047 HRS

SAFETY		CHECK	COMMENTS
1 FIRE EXTINGUISHER - VALID	☒	5 SPILL KIT / FIRST AID KIT	☐
2 SEAT BELTS / ANCHORS	☒	6 INSPECTION DECALS / LIFT CHARTS / CERTS	☐
3 BACKUP ALARM / HORN	☒	7 TRACK SHOVEL / POLASKI	☐
4 HANDRAILS / STEPS / GUARDS	☒	8 LOG BOOK - FILL IN	☐

CAB / ELECTRICAL		CHECK	COMMENTS
9 WIPERS / WINDOW MIRRORS	☒	15 GAUGES - TACH, SPEED, HOUR METER, ETC	☒
10 ROPS / FOPS / DECALS	☒	16 WARNING LIGHTS / ALARMS	☒
11 DOOR LATCHES / HANDLES	☒	17 HEATER / AIR CONDITIONING / VENTILATION	☐
12 SEAT CUSHIONS / FRAME	☒	18 2 WAY RADIO / AM & FM RADIO	☒ not working
13 BATTERIES - LEVELS & POSTS	☒	19 HEAD / SIGNAL / TAIL / DOME LIGHTS	☐
14 CHARGING SYSTEM / BELTS	☒	20 POSITIVE AIR SHUT OFF	☒

ATTACHMENTS		CHECK	COMMENTS
21. CLEANUP BUCKET UNIT #	☐	23 BLADE / RIPPER / WINCH	☐
22. DIGGING BUCKET UNIT #	☐	24. CABLE LENGTH:	BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL		CHECK	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒		
26. LEAKS / RUNNING TEST	☒		
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☐		
29. HARD NOSE BUSHINGS	☐		
30. UNDERCARRIAGE	☒		need carrier rollers
31. DIFF / FINAL DRIVE / TRANSMISSION	☒		
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒		
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☐		
34. PARK / SERVICE BRAKERS	☒		
35. FLUID LEVELS / FILTERS	☒		
36. GREASED	☒		needs grease after wash

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
✓ 1	Right Cab side window smash out.	
1	Bucket / Thumb pin needs shims	T Barber
1	Bucket cylinder weeping.	
1	under belly pans bent.	Ritchie
✓ 1	3 carrier rollers	T Barber
✓ 1	Fuel water separator bowl cracked.	B And T
✓ 1	Right pump door broken, needs new hinge.	T Barber
✓ 1	Pump hose Leaking.	T Barber
✓ 1	Hose 296-6949	T Barber
✓ 1	bottom window wiper Blade.	
1	screen is shorting out when you turn screen	T Barber
1	stereo not working	T Barber
1	Pins bushings, Hlink, Bucket, Thumb.	T Barber

SIGNATURE

DATE COMPLETE



9312 - 109th street - fort St. John, BC
V1J 6G9

Mob / Demob Inspection Repair Report

Owner:	Sures P. Peltier
Inspected By:	Tony Baxter
Start Date:	April 12 '23
Hrs / KM:	10476H

UNIT #	Fx 253	MAKE	CAT	MODEL	336E	SERIAL #	FJH 00966
--------	--------	------	-----	-------	------	----------	-----------

JOB #		MOB ☒ DEMOB ☐	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	10476H
-------	--	--	--	----------------------	--------

SAFETY	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	
2. SEAT BELTS / ANCHORS	☒	
3. BACKUP ALARM / HORN	☒	
4. HANDRAILS / STEPS / GUARDS	☒	
5. SPILL KIT / FIRST AID KIT	☒	
6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒	
7. TRACK SHOVEL / POLASKI	☒	
8. LOG BOOK - FILL IN	☒	

CAB / ELECTRICAL	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	
10. ROPS / FOPS / DECALS	☒	
11. DOOR LATCHES / HANDLES	☒	
12. SEAT CUSHIONS / FRAME	☒	
13. BATTERIES - LEVELS & POSTS	☒	
14. CHARGING SYSTEM / BELTS	☒	
15. GAUGES - TACH, SPEED, HOUR METER, ETC	☒	
16. WARNING LIGHTS / ALARMS	☒	
17. HEATER / AIR CONDITIONING / VENTILATION	☒	
18. 2 WAY RADIO / AM & FM RADIO	☒	
19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒	
20. POSITIVE AIR SHUT OFF	☒	

ATTACHMENTS	INCLUDED	COMMENTS
21. CLEANUP BUCKET UNIT #	☐	
22. DIGGING BUCKET UNIT #	☐	
23. BLADE / RIPPER / WINCH	☐	
24. CABLE LENGTH:		BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	
26. LEAKS / RUNNING TEST	☒	
27. ENGINE / RADIATOR	☒	
28. HARD BAR BEARINGS	☒	
29. HARD NOSE BUSHINGS	☒	
30. UNDERCARRIAGE	☒	
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
☐	Quick attach pins & bushings worn	T Baxter
☐	Carrier rollers need to be replaced	T Baxter
☐	Pump access door hinge needs replacing	T Baxter
☐	Hoses at pump need to be replaced	T Baxter
☐	Operator display console loses power intermittently	T Baxter
☐	AM/FM radio not functional	T Baxter
☐	Lower guards bent & damaged	Ritche
☐	RH operator station window needs replacing	T Baxter
☐	Complete engine service / Oil, Fuel, & air filter	B Andt
☐		
☐		
☐		
☐		

SIGNATURE

[Signature]

DATE COMPLETE

May 2 '23



9312 - 109th street - fort St. John, BC
V1J 6G9

**Mob / Demob Inspection
Repair Report**

3

Owner:	Surerus Pipeline Inc.
Inspected By	Clayton Foster.
Start Date:	Nov 30, 2023.
Hrs / KM:	11234 Hrs

UNIT #	Ex 253.	MAKE	CAT	MODEL	336 E	SERIAL #	CAT0336EHFJH0966
--------	---------	------	-----	-------	-------	----------	------------------

JOB #		MOB	☐	DEMOB	☒	COMPLETE SERVICE RECORD	YES ☐ NO ☒	LAST SERVICE HRS/KMS	11161 Hrs
-------	--	-----	--------------------------	-------	-------------------------------------	-------------------------	---	----------------------	-----------

SAFETY		CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☐	5. SPILL KIT / FIRST AID KIT	☒ None.
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒ None.
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒ None.
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☒

CAB / ELECTRICAL		CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☒
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒ Radio works, no Two way.
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒ works.
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☒


ATTACHMENTS		INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET	UNIT #	☐	23. BLADE / RIPPER / WINCH	☐
22. DIGGING BUCKET	UNIT #	☐	24. CABLE LENGTH:	BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL		CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	Hydraulic system Weak all around.	
26. LEAKS / RUNNING TEST	☒	Read below; Right and Left Final drives low.	
27. ENGINE / RADIATOR	☒		
28. HARD BAR BEARINGS	☐		
29. HARD NOSE BUSHINGS	☐		
30. UNDERCARRIAGE	☒	Bent Corner Rollers. 3.	
31. DIFF / FINAL DRIVE / TRANSMISSION	☐		
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	Pump weak or Relief.	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☐		
34. PARK / SERVICE BRAKERS	☒		
35. FLUID LEVELS / FILTERS	☒		
36. GREASED	☒		

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
1	Belly pans Bent.	
2	Main Hydraulic suction Hose needs to be Replaced.	
3	Hydraulic pump making noise, probably sucking Air.	
4	Hydraulic pressures need to be checked. very weak.	
5	Fuel Filter bowl Cracked.	
6	Front window cable jumped out of Track. needs new corner piece.	
7	Horn not working.	
8	Missing front window Rubber	
9	Tracks loose.	
10	Left Final Drive Duo Cone seal Leaking possibly bearings.	
11	MISSING serial number Tag.	

SIGNATURE _____

DATE COMPLETE _____



Owner:	Sydney
Inspected By	DARTON
Start Date:	April 16/18
Hrs / KM:	4/14

[illegible]

SIGNATURE _____

DATE COMPLETE

Apr 16/18



Owner:	S. S. S. S.
Inspected By	D. D. D. D.
Start Date:	Aug 6/20
Hrs / KM:	7868

JOB #		MOB ☐	DEMOB ☐	COMPLETE SERVICE RECORD YES ☐ NO ☐	LAST SERVICE HRS/KMS	6951
-------	--	------------------------------	--------------------------------	--	----------------------	------

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	
26. LEAKS / RUNNING TEST	☒	
27. ENGINE / RADIATOR	☒	
28. HARD BAR BEARINGS	☐	N/A
29. HARD NOSE BUSHINGS	☐	
30. UNDERCARRIAGE	☒	
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	Topped up
32. HYDRAULICS / PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☐	N/A
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	
36. GREASED	☒	

[illegible]

SIGNATURE

DATE COMPLETE _____

Aug 20/2020



Mob / Demob Inspection Repair Report

Owner:	Surerus
Inspected By:	Joseph Lang
Start Date:	Dec 13 / 22
Hrs / KM:	10036

UNIT #	EX253	MAKE	CAT	MODEL	336	SERIAL #	CAT0336EHF5H00966
--------	-------	------	-----	-------	-----	----------	-------------------

JOB #	1922	MOB	☐	DEMOB	☒	COMPLETE SERVICE RECORD YES	☒	NO	☐	LAST SERVICE	9650
-------	------	-----	--------------------------	-------	-------------------------------------	-----------------------------	-------------------------------------	----	--------------------------	--------------	------

SAFETY	CHECKED	CHECKED	COMMENTS
1. FIRE EXTINGUISHER - VALID	☒	5. SPILL KIT / FIRST AID KIT	☒ - Three skid plates are bent
2. SEAT BELTS / ANCHORS	☒	6. INSPECTION DECALS / LIFT CHARTS / CERTS	☒ on bottom of cab is crushed
3. BACKUP ALARM / HORN	☒	7. TRACK SHOVEL / POLASKI	☒ bottom wiper won't work, due to
4. HANDRAILS / STEPS / GUARDS	☒	8. LOG BOOK - FILL IN	☒ damage.

CAB / ELECTRICAL	CHECKED	CHECKED	COMMENTS
9. WIPERS / WINDOW MIRRORS	☒	15. GAUGES - TACH, SPEED, HOUR METER, ETC.	☒ - Right mirror missing
10. ROPS / FOPS / DECALS	☒	16. WARNING LIGHTS / ALARMS	☒ - Inside door handle missing
11. DOOR LATCHES / HANDLES	☒	17. HEATER / AIR CONDITIONING / VENTILATION	☒ bolt
12. SEAT CUSHIONS / FRAME	☒	18. 2 WAY RADIO / AM & FM RADIO	☒ - S-Bar missing monitor
13. BATTERIES - LEVELS & POSTS	☒	19. HEAD / SIGNAL / TAIL / DOME LIGHTS	☒ - Belts a cracked need
14. CHARGING SYSTEM / BELTS	☒	20. POSITIVE AIR SHUT OFF	☒ replacing

ATTACHMENTS	INCLUDED	CHECKED	COMMENTS
21. CLEANUP BUCKET	UNIT # ☐	23. BLADE / RIPPER / WINCH	☐
22. DIGGING BUCKET	UNIT # ☐	24. CABLE LENGTH	BOOMLINE _____ FT LOADLINE _____ FT

MECHANICAL	CHECKED	COMMENTS
25. MECHANICAL FUNCTIONS TEST	☒	- Low oil pressure alarm comes on when warmed up.
26. LEAKS / RUNNING TEST	☒	
27. ENGINE RADIATOR	☒	
28. HARD BAR BEARINGS	☒	
29. HARD NOSE BUSHINGS	☒	
30. UNDERCARRIAGE	☒	Three skid plates on right side are pushed in, bottom
31. DIFF / FINAL DRIVE / TRANSMISSION	☒	of Cab crushed
32. HYDRAULICS PUMP / DRIVE / CYLINDER	☒	
33. TIRES / WHEELS - CUTS, WEAR, DAMAGE	☒	
34. PARK / SERVICE BRAKERS	☒	
35. FLUID LEVELS / FILTERS	☒	- Finals are low on oil, washer fluid low.
36. GREASED	☒	- Needs greasing

ITEM #	SPECIFIC REPAIRS REQUIRED	REPAIRED BY
4	- Three skid plates need straightening out, bottom of	
	cab needs to be cut out and weld in new bottom	
9	- Right mirror needs replacing. Right side cab window	
	separating from cab. Needs to be re-sealed	
25	- Do further diagnostics on low oil pressure alarm	
15	- S-Bar needs monitor to be operable.	
14	- Both belts are crack and need replacing	

SIGNATURE Joseph Lang

DATE COMPLETED Dec 13/22



Mechanic Daily Report

Name: <u>Paul Booth</u>
Date: <u>June 10 21</u>
Shop Time: ☐ Main ☐ Welding ☐ Fort Nelson ☐ Paint Shop - or -
Field Job#:

Weather	Shop Time: ☐ Main ☐ Welding ☐ Fort Nelson ☐ Paint Shop - or -
Field Job#:	

Unit # <u>EX 253</u>	<u>M3- 3hr M2- 7hr</u>	Unit Hrs. <u>11246</u>
Work Performed: <u>Dissassemble final drive, Assist re-assembly of</u> <u>final drive, travel motor, test hydraulic system,</u> <u>replacement of main relief valve w/ lining mechanic,</u> <u>remove and dissassemble travel motor inspect for</u> <u>damage</u>		
* Parts Purchased ☐ Yes ☐ No		
		Man Hrs. <u>10</u>

Unit #		Unit Hrs.
Work Performed:		
* Parts Purchased ☐ Yes ☐ No		
		Man Hrs.

General Remarks and General Repairs:			
Work Performed:			
* Parts Purchased ☐ Yes ☐ No			
			Man Hrs.

Office Use Only	P / R	Q / A	Operations

Total Hours <u>10</u>

* Please attach invoices or packing slips for parts purchased. If no paperwork available, list suppliers.



SERVICE INVOICE

Page: 1 (3)

Finning (Canada), a division of Finning International Inc.

10910 - 170 STREET
EDMONTON, AB T5S 1H6
(780) 483-1122
(780) 443-7995 FAX

Date 28/06/24
Invoice Number 962615660
Invoice Total \$3,321.64
Payment Terms NET 60 DAYS

PAYER CA-0048404
SURERUS PIPELINE INC
10912 91 AVENUE
FORT ST JOHN BC V1J 6G9

Due Date 27/08/24
Currency CANADIAN DOLLAR
Customer Tax Exemption No.
Customer Reference No. PO# EX253
Order Date 07/06/24
Order Number 0060962274
Finning Contact JENNIFER LARABEE
Customer Contact PAUL BOOTH
Customer Commitment Date 00/00/00
Actual Completion Date 28/06/24



Make CAT
Model 336E
Serial Number FJH00966
Unit Number EX253-FJH00966
Meter Reading H 11246.00
(07/06/24)

CUSTOMER LOCATION CA-0048404
SURERUS PIPELINE INC
5034-43 ST
GIBBONS AB T0A 1N0

Line No.	Qty	Item No.	Description	U/M	Sales Price
----------	-----	----------	-------------	-----	-------------

10		336E 336E	F/DR TRBLSHOOT IN FIELD		
----	--	--------------	-------------------------	--	--

Customer Reference No. PO# EX253

FINNING WO: 2354450

HOURS: 11,246
LOCATION: 5033 43 STREET, GIBBONS

COMPLAINT: FINAL DRIVE LEAKING AND NOISY/ SLOW HYDRAULICS

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This Service Invoice is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms

Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty

Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy

Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations. The Terms and Conditions of this Service Invoice, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.



SERVICE INVOICE

Finning (Canada), a division of Finning International Inc.

10910 - 170 STREET
EDMONTON, AB T5S 1H6
(780) 483-1122
(780) 443-7995 FAX

Date 28/06/24
Invoice Number 962615660
Invoice Total \$3,321.64
Payment Terms NET 60 DAYS

CUSTOMER NUMBER CA-0048404

Due Date 27/08/24

Line No.	Qty	Item No.	Description	U/M	Sales Price
CAUSE:					
-DUO CONE SEAL HAS FAILED ON LH FINAL					
-HYDRAULIC FUNCTIONS SLOW DUE TO CONTAMINATION FROM FAILED					
LH TRAVEL MOTOR DAMAGING MAIN RELIEF					
CORRECTION:					
JUNE 10 2024					
-INSTALL NEW DUO CONE SEAL INTO LH FINAL DRIVE AND RE					
ASSEMBLE FINAL DRIVE					
-MOUNT SPROCKET TO FINAL DRIVE AND TORQUE BOLTS TO SPEC					
-INSTALL FINAL DRIVE ONTO MACHINE					
-INSTALL LH TRAVEL MOTOR AND HOOK UP HYD LINES					
-TEST (LH FINAL DOES NOT MOVE)					
-HOOK UP HYD GAUGES TO MACHINE AND CHECK PRESSURES (HAVE					
TO RUN MACHINE AT HIGH IDLE AND CAN ONLY GET 2000 PSI)					
-REMOVE LOWER GUARD TO GAIN ACCESS TO MAIN RELIEF					
-PULL VACUUM ON HYD TANK AND REMOVE MAIN RELIEF					
-INSTALL NEW MAIN RELIEF					
-WARM UP HYD SYSTEM AND SET MAIN RELIEF PRESSURE TO 5080					
PSI AND HEAVY LIFT TO 5580 PSI					
-TEST (ALL FUNCTIONS EXCEPT LH TRAVEL WORK CORRECTLY)					
PUMP ONLY STAYS AT 400 PSI WHEN TRAVEL COMMAND					
-REMOVE HYD LINES TO LH TRAVEL MOTOR AND CAP					
-RETEST (ABLE TO ACHIEVE 5000 PSI NOW TRAVEL MOTOR HAS					
FAILED)					
1.00	3237464		VALVE GP-P R	PC	837.47

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001



SERVICE INVOICE

Finning (Canada), a division of Finning International Inc.

10910 - 170 STREET
EDMONTON, AB T5S 1H6
(780) 483-1122
(780) 443-7995 FAX

Date 28/06/24
Invoice Number 962615660
Invoice Total \$3,321.64
Payment Terms NET 60 DAYS

CUSTOMER NUMBER CA-0048404

Due Date 27/08/24

Line No.	Qty	Item No.	Description	U/M	Sales Price
	8.00	4050-035- -ACZ-001	JOURNEYPerson FIELD	EA	1,949.00
	1.50	4050-035- -ACZ-001	JOURNEYPerson TRAVEL	EA	377.00
			Labor		2,326.00
			Material		837.47
			Service Total		3,163.47
			Order total		3,163.47
			GST		158.17
			Invoice Total		\$3,321.64

Thank you for your business.

PAYMENT ADDRESS CHANGE NOTIFICATION: PLEASE REMIT TO P.O. BOX 2405, EDMONTON, AB T5J 2S1.

GST/HST Registration Number: 101801561 RT0001

This Service Invoice is subject to and incorporates by reference the Finning Parts Terms and Conditions, which can be found at www.finning.com/PartsTerms
Any Services provided by Finning are subject to Finning's Service Warranty & On-Time Completion Guarantee which can be found at www.finning.com/ServiceWarranty
Parts returns are governed by the Finning Customer Return Policy which can be found at www.finning.com/ReturnPolicy
Finning's liability, even if caused by its own negligence, and the remedies available to the Customer are limited by these Terms and Conditions.

These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations. The Terms and Conditions of this Service Invoice, including all documents incorporated by reference, is the entire agreement. No other documentation or other terms and conditions provided by the Customer prior to or subsequent to the finalization of this Order by the Customer shall be of any force or effect.