Date in Shop

...vesting 940-886-6434 119 12st N Nobleford, AB

Section I

Customer: Whitelake Colony

Address:

Vehicle VIN: #4 YMG244 752

Date work Begins April 4/23

Odometer 8221646

Section II

Complaint: Field ready Inspection

Labour Instructions: Completed full inspection + run machine. Repair list below. Run all machine functions.

All functions worked at time of inspection.

Complaint and Labor Instructions | Labour Hours | Date:

Section III

Parts and Supplies

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price
			SHOP SUPPLIES	

- Change hydraulic + Air filters. Change engine oil + filter. Change unloading gear box oil. Change unloading gearbox oil. Shorten unloading auger chains. tighten clean grain chain. Replace chopper blades. Fix hanging stationary Knives. Adjust rollers closer to Shoker frame. Clean out cab air filter box. Pto + Hyd oil level low. Flighting on 3016 rubbing on Stripper plates. Adjust to 1/4". Air up tires on 3016

Total Parts & Supplies Cost

Total Labour Hours

Section IV Outside Repairs | Price

Complaint:

Vendor's Name:

Invoice #: FPO#:

Parts

Labour

Tax

Total

Work Order Totals

Total Shop Labour Cost (Sect. II)

Total Parts & Supplies Cost (Sect.III)

Total Outside Repairs Cost (Sect. IV)

Grand Total

Work Completed by: [signature]

Signature

April 4/23 #

Date Work Completed

Picked up by:

Signature

Work Order #: