

Customer: Whitelake Colony
Address:

Vehicle VIN: # 4
333656-18

Date work Begins April 5/23

Odometer N/A

Section II

Complaint: Inspection

Complaint and Labor Instructions

Labour Instructions: Completed inspection, repair list below:

Labour Hours Date:

Section III

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price
			SHOP SUPPLIES	
			- Adjust all chains + canvas + belts. Hydraulic leak on hose from valve stack to pass through. Hyd supply line leaking. Front light bracket broken RH. Rh rear light plastic cover broke. RH up down reel cylinder leaking.	
*			Guards worn	
*			Sickle worn	

Parts and Supplies

Total Labour Hours

Section IV

Complaint:

Vendor's Name:

Invoice #:

Outside Repairs

Parts

Labour

Tax

Total

Price

Work Order Totals

Total Shop Labour Cost (Sect. II)

Total Parts & Supplies Cost (Sect. III)

Total Outside Repairs Cost (Sect. IV)

Grand Total

Work Completed by:

Picked up by:

B. L. O. H.
Signature

Signature

April 5/23 #

Date Work Completed

Work Order #:

Total Parts & Supplies Cost