

Address: White Lake Colony

Vehicle VIN: # 3
352649-19

Date work Begins April 5/23

Odometer N/A

Section II

Complaint: Inspection

Complaint and Labor Instructions

Labour Hours Date:

Labour Instructions: Completed inspection, list below:

Section III

Parts and Supplies

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price	Total Labour Hours		Price
					Section IV	Outside Repairs	
			SHOP SUPPLIES				
			- Adjust all chains + belts + canvas! Oil leak at main pump suction line. Set tire pressures + grease. Front RH light bracket worn. Pto safety end guard missing.				
			* Guards worn				
			* Sickle worn				
				Work Order Totals			
				Total Shop Labour Cost (Sect. II)			
				Total Parts & Supplies Cost (Sect. III)			
				Total Outside Repairs Cost (Sect. IV)			
				Grand Total			
				Work Completed by:		Picked up by:	
				<u>[Signature]</u> Signature		<u>[Signature]</u> Signature	
				<u>April 5/23</u> #			
				Date Work Completed		Work Order #:	
				Total Parts & Supplies Cost			