

Date in Shop

PHONE 940-886-6434 119 12st N Nobleford, AB

Section I

Customer: Whitelake Colony
Address:

Section II

Complaint: Inspection

Complaint and Labor Instructions

Labour Hours Date:

Vehicle VIN: # 2
333657-18

Labour Instructions: Completed inspection, 1st below:

Date work Begins April 5/23

Odometer N/A

Section III

Parts and Supplies

S	Vendor Invoice # or Commodity Code	Qty.	Part Description	Price	Total Labour Hours	Section IV	Outside Repairs	Price
			SHOP SUPPLIES			Complaint:	Parts	
-			Adjust <u>ALL</u> chains + belts, + canvas tension. Replace broken auger fingers. Wiring harness ripped apart on RH transport. Both RH light assemblies broken. RH + LH outer skid plates worn out. Set tire pressures + grease.			Vendor's Name:	Labour	
*			Sickle worn			Invoice #:	Tax	
*			Guards worn			FPO#:	Total	
					Work Order Totals			
					Total Shop Labour Cost (Sect. II)			
					Total Parts & Supplies Cost (Sect. III)			
					Total Outside Repairs Cost (Sect. IV)			
					Grand Total			
					Work Completed by:		Picked up by:	
					<u>B. J. D. A.</u>		Signature	
					Signature		Signature	
					<u>April 5/23</u> #		Date Work Completed	
					Date Work Completed		Work Order #:	
					Total Parts & Supplies Cost			